
November 2022

I-4 From West of Polk Parkway to West of US 27 – Phase 2 Crash Analysis Technical Memorandum



I-4 From West of Polk Parkway to West of US 27 – Phase 2 Crash Analysis Technical Memorandum

November 2022
Polk County, Florida

FPID: 442512-1-12-01
RS&H No.: 1004-009-6001

Prepared by RS&H, Inc. at the direction of Florida Department of Transportation, District 1

Table of Contents

1 Project Introduction 1
2 I-4 Interchange and Mainline Segment Crash Data 3
3 Interchange: I-4 at SR 570/Polk Parkway (West) 3
4 Mainline Segment: I-4 from SR 570/Polk Parkway (West) to SR 546/W Memorial Boulevard 7
5 Interchange: I-4 at SR 546/W Memorial Boulevard 9
6 Mainline Segment: I-4 from SR 546/W Memorial Boulevard to SR 539/Kathleen Road 13
7 Interchange: I-4 at SR 539/Kathleen Road 16
8 Mainline Segment: I-4 from SR 539/Kathleen Road to US 98 19
9 Interchange: I-4 at US 98 22
10 Mainline Segment: I-4 from US 98 to N Socrum Loop Road & SR 33/Lakeland Hills Boulevard 26
11 Interchange: I-4 at N Socrum Loop Road & SR 33/Lakeland Hills Boulevard 29
12 Mainline Segment: I-4 from N Socrum Loop Road & SR 33/Lakeland Hills Boulevard to SR 33/Lakeland Hills Boulevard/Commonwealth Avenue 34
13 Interchange: I-4 at SR 33/Lakeland Hills Boulevard/Commonwealth Avenue 37
14 Mainline Segment: I-4 from SR 33/Lakeland Hills Boulevard/Commonwealth Avenue to SR 570/Polk Parkway (East) 40
15 Interchange: I-4 at SR 570/Polk Parkway (East) 43
16 Mainline Segment: I-4 from SR 570/Polk Parkway (East) to SR 559 47
17 Interchange: I-4 at SR 559 49
18 Mainline Segment: I-4 from SR 559 to SR 557 53
19 Interchange: I-4 at SR 557 56
20 Mainline Segment: I-4 from SR 557 to West of US 27 59
21 Full I-4 Study Corridor Crashes 62
22 Review of Most Recent Data (January 2020 – May 2022) 108
23 Next Steps 153

List of Tables

Table 2-1: Districtwide Average Crash Rates (2015-2019) 3
Table 3-1: SR 570/Polk Parkway (West) Interchange Crash Summary by Severity and Conditions (2015-2019) 4
Table 3-2: SR 570/Polk Parkway (West) Interchange Crash Summary by Crash Types (2015-2019) 5
Table 3-3: SR 570/Polk Parkway (West) Interchange Crash Summary by Location (2015-2019) 5
Table 3-4: SR 570/Polk Parkway (West) Interchange Contributing Causes of Crashes (2015-2019) 6
Table 3-5: SR 570/Polk Parkway (West) Interchange KABCO Crash Costs (2015-2019) 6
Table 4-1: I-4 Segment (SR 570-W to SR 546) Crash Summary by Severity and Conditions (2015-2019) 8
Table 4-2: I-4 Segment (SR 570-W to SR 546) Crash Summary by Crash Types (2015-2019) 8
Table 4-3: I-4 Segment (SR 570-W to SR 546) Crash Rate Summary (2015-2019) 9
Table 4-4: I-4 Segment (SR 570-W to SR 546) Contributing Causes of Crashes (2015-2019) 9
Table 4-5: I-4 Segment (SR 570-W to SR 546) KABCO Crash Costs (2015-2019) 9
Table 5-1: SR 546/W Memorial Boulevard Interchange Crash Summary by Severity and Conditions (2015-2019) 10
Table 5-2: SR 546/W Memorial Boulevard Interchange Crash Summary by Crash Types (2015-2019) 11
Table 5-3: SR 546/W Memorial Boulevard Interchange Crash Summary by Location (2015-2019) 12
Table 5-4: SR 546/W Memorial Boulevard Interchange Contributing Causes of Crashes (2015-2019) 12
Table 5-5: SR 546/W Memorial Boulevard Interchange KABCO Crash Costs (2015-2019) 13
Table 6-1: I-4 Segment (SR 546 to SR 539) Crash Summary by Severity and Conditions (2015-2019) 14
Table 6-2: I-4 Segment I-4 Segment (SR 546 to SR 539) Crash Summary by Crash Types (2015-2019) 15
Table 6-3: I-4 Segment I-4 Segment (SR 546 to SR 539) Crash Rate Summary (2015-2019) 15
Table 6-4: I-4 Segment (SR 546 to SR 539) Contributing Causes of Crashes (2015-2019) 15
Table 6-5: I-4 Segment (SR 546 to SR 539) KABCO Crash Costs (2015-2019) 16
Table 7-1: SR 539/Kathleen Road Interchange Crash Summary by Severity and Conditions (2015-2019) 17
Table 7-2: SR 539/Kathleen Road Interchange Crash Summary by Crash Types (2015-2019) 17
Table 7-3: SR 539/Kathleen Road Interchange Crash Summary by Location (2015-2019) 18
Table 7-4: SR 546/W Memorial Boulevard Interchange Contributing Causes of Crashes (2015-2019) 18
Table 7-5: SR 539/Kathleen Road Interchange KABCO Crash Costs (2015-2019) 19
Table 8-1: I-4 Segment (SR 539 to US 98) Crash Summary by Severity and Conditions (2015-2019) 20
Table 8-2: I-4 Segment (SR 539 to US 98) Crash Summary by Crash Types (2015-2019) 21
Table 8-3: I-4 Segment (SR 539 to US 98) Crash Rate Summary (2015-2019) 21
Table 8-4: I-4 Segment (SR 539 to US 98) Contributing Causes of Crashes (2015-2019) 21
Table 8-5: I-4 Segment (SR 539 to US 98) KABCO Crash Costs (2015-2019) 22
Table 9-1: US 98 Interchange Crash Summary by Severity and Conditions (2015-2019) 23
Table 9-2: US 98 Interchange Crash Summary by Crash Types (2015-2019) 24
Table 9-3: US 98 Interchange Crash Summary by Location (2015-2019) 25
Table 9-4: US 98 Interchange Contributing Causes of Crashes (2015-2019) 25
Table 9-5: US 98 Interchange KABCO Crash Costs (2015-2019) 26
Table 10-1: I-4 Segment (US 98 to Socrum Loop Rd) Crash Summary by Severity and Conditions (2015-2019) 27
Table 10-2: I-4 Segment (US 98 to Socrum Loop Rd) Crash Summary by Crash Types (2015-2019) 28

Table 10-3: I-4 Segment (US 98 to Socrum Loop Rd) Crash Rate Summary (2015-2019) 28
Table 10-4: I-4 Segment (US 98 to Socrum Loop Rd) Contributing Causes of Crashes (2015-2019) 28
Table 10-5: I-4 Segment (US 98 to Socrum Loop Rd) KABCO Crash Costs (2015-2019) 29
Table 11-1: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Crash Summary by Severity and Conditions (2015-2019) 30
Table 11-2: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Crash Summary by Crash Types (2015-2019) 31
Table 11-3: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Crash Summary by Location (2015-2019) 32
Table 11-4: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Contributing Causes of Crashes (2015-2019) 32
Table 11-5: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange KABCO Crash Costs (2015-2019) 33
Table 12-1: I-4 Segment (Socrum Loop Rd to SR 33) Crash Summary by Severity and Conditions (2015-2019) 35
Table 12-2: I-4 Segment (Socrum Loop Rd to SR 33) Crash Summary by Crash Types (2015-2019) 35
Table 12-3: I-4 Segment (Socrum Loop Rd to SR 33) Crash Rate Summary (2015-2019) 36
Table 12-4: I-4 Segment (Socrum Loop Rd to SR 33) Contributing Causes of Crashes (2015-2019) 36
Table 12-5: I-4 Segment (Socrum Loop Rd to SR 33) KABCO Crash Costs (2015-2019) 36
Table 13-1: SR 33 Interchange Crash Summary by Severity and Conditions (2015-2019) 37
Table 13-2: SR 33 Interchange Crash Summary by Crash Types (2015-2019) 38
Table 13-3: SR 33 Interchange Crash Summary by Location (2015-2019) 38
Table 13-4: SR 33 Interchange Contributing Causes of Crashes (2015-2019) 39
Table 13-5: SR 33 Interchange KABCO Crash Costs (2015-2019) 39
Table 14-1: I-4 Segment (SR 33 to SR 570-E) Crash Summary by Severity and Conditions (2015-2019) 41
Table 14-2: I-4 Segment (SR 33 to SR 570-E) Crash Summary by Crash Types (2015-2019) 42
Table 14-3: I-4 Segment (SR 33 to SR 570-E) Crash Rate Summary (2015-2019) 42
Table 14-4: I-4 Segment (SR 33 to SR 570-E) Contributing Causes of Crashes (2015-2019) 43
Table 14-5: I-4 Segment (SR 33 to SR 570-E) KABCO Crash Costs (2015-2019) 43
Table 15-1: SR 570/Polk Parkway (East) Interchange Crash Summary by Severity and Conditions (2015-2019) 44
Table 15-2: SR 570/Polk Parkway (East) Interchange Crash Summary by Crash Types (2015-2019) 44
Table 15-3: SR 570/Polk Parkway (East) Interchange Crash Summary by Location (2015-2019) 45
Table 15-4: SR 570/Polk Parkway (East) Interchange Contributing Causes of Crashes (2015-2019) 45
Table 15-5: SR 570/Polk Parkway (East) Interchange KABCO Crash Costs (2015-2019) 46
Table 16-1: I-4 Segment (SR 570-E to SR 559) Crash Summary by Severity and Conditions (2015-2019) 48
Table 16-2: I-4 Segment (SR 570-E to SR 559) Crash Summary by Crash Types (2015-2019) 48
Table 16-3: I-4 Segment (SR 570-E to SR 559) Crash Rate Summary (2015-2019) 49
Table 16-4: I-4 Segment (SR 570-E to SR 559) Contributing Causes of Crashes (2015-2019) 49
Table 16-5: I-4 Segment (SR 570-E to SR 559) KABCO Crash Costs (2015-2019) 49
Table 17-1: SR 559 Interchange Crash Summary by Severity and Conditions (2015-2019) 50
Table 17-2: SR 559 Interchange Crash Summary by Crash Types (2015-2019) 51
Table 17-3: SR 559 Interchange Crash Summary by Location (2015-2019) 51

Table 17-4: SR 559 Interchange Contributing Causes of Crashes (2015-2019) 52
Table 17-5: SR 559 Interchange KABCO Crash Costs (2015-2019) 52
Table 18-1: I-4 Segment (SR 559 to SR 557) Crash Summary by Severity and Conditions (2015-2019) 54
Table 18-2: I-4 Segment (SR 559 to SR 557) Crash Summary by Crash Types (2015-2019) 54
Table 18-3: I-4 Segment (SR 559 to SR 557) Crash Rate Summary (2015-2019) 55
Table 18-4: I-4 Segment (SR 559 to SR 557) Contributing Causes of Crashes (2015-2019) 55
Table 18-5: I-4 Segment (SR 559 to SR 557) KABCO Crash Costs (2015-2019) 55
Table 19-1: SR 557 Interchange Crash Summary by Severity and Conditions (2015-2019) 57
Table 19-2: SR 557 Interchange Crash Summary by Crash Types (2015-2019) 57
Table 19-3: SR 557 Interchange Crash Summary by Location (2015-2019) 58
Table 19-4: SR 557 Interchange Contributing Causes of Crashes (2015-2019) 58
Table 19-5: SR 557 Interchange KABCO Crash Costs (2015-2019) 59
Table 20-1: I-4 Segment (SR 557 to West of US 27) Crash Summary by Severity and Conditions (2015-2019) 60
Table 20-2: I-4 Segment (SR 557 to West of US 27) Crash Summary by Crash Types (2015-2019) 61
Table 20-3: I-4 Segment (SR 557 to West of US 27) Crash Rate Summary (2015-2019) 61
Table 20-4: I-4 Segment (SR 557 to West of US 27) Contributing Causes of Crashes (2015-2019) 62
Table 20-5: I-4 Segment (SR 557 to West of US 27) KABCO Crash Costs (2015-2019) 62
Table 22-1: I-4 Mainline and Cross Streets Crash Summary by Crash Types (2020-May 2022) 108

List of Figures

Figure 1-1: Project Location Map 2
Figure 3-1: SR 570/Polk Parkway (West) Interchange Crash Data Heat Map (2015-2019) 7
Figure 5-1: SR 546/W Memorial Boulevard Interchange Crash Data Heat Map (2015-2019) 13
Figure 7-1: SR 539/Kathleen Road Interchange Crash Data Heat Map (2015-2019) 19
Figure 9-1: US 98 Interchange Crash Data Heat Map (2015-2019) 26
Figure 11-1: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Crash Data Heat Map (2015-2019) 33
Figure 13-1: SR 33 Interchange Crash Data Heat Map (2015-2019) 40
Figure 15-1: SR 570/Polk Parkway (East) Interchange Crash Data Heat Map (2015-2019) 46
Figure 17-1: SR 559 Interchange Crash Data Heat Map (2015-2019) 53
Figure 19-1: SR 557 Interchange Crash Data Heat Map (2015-2019) 59
Figure 21-1: I-4 Master Plan Study Crashes by Type (2015 – 2019) 64
Figure 21-2: I-4 Master Plan Study Crashes Heat Map (2015 – 2019) 86
Figure 22-1: I-4 Master Plan Study Crashes by Type (2020 – May 2022) 109
Figure 22-2: I-4 Master Plan Study Crashes Heat Map (2020 – May 2022) 131

List of Appendices

Appendix A – Crash Data
Appendix B – Additional Crash Data Maps

1 Project Introduction


The primary objective of the I-4 Master Plan Study from west of Polk Parkway (SR 570) to West of US 27 is to evaluate the impact of managed lanes along I-4 and to identify safety improvement needs along the corridor that can be addressed in the near term. Impacts on the social, economic, cultural, natural, and physical environment will be analyzed. A safety analysis is also required in accordance with Part 1, Chapter 2 of the PD&E Manual. This technical memorandum documents the analysis of historical crash data collected from the Florida Department of Transportation (FDOT) State Safety Office GIS Query Tool (SSOGis) and Signal 4 Analytics (S4) for the I-4 study corridor, including all nine I-4 study interchanges listed below and depicted in the project location map, **Figure 1-1**.

- SR 570/Polk Parkway (West)
- SR 546/W Memorial Boulevard
- SR 539/Kathleen Road
- US 98
- N Socrum Loop Road & SR 33/Lakeland Hills Boulevard
- SR 33/Lakeland Hills Boulevard/Commonwealth Avenue
- SR 570/Polk Parkway (East)
- SR 559
- SR 557

The following mainline segments between interchanges were also analyzed. The segment west of the SR 570/Polk Parkway W interchange was not analyzed as the crash data was already analyzed as part of the interchange study area.

- I-4 from SR 570/Polk Pkwy W to SR 546/W Memorial Blvd
- I-4 from SR 546/W Memorial Blvd to SR 539/Kathleen Rd
- I-4 from SR 539/Kathleen Rd to US 98
- I-4 from US 98 to N Socrum Loop Road & SR 33/Lakeland Hills Boulevard
- I-4 from N Socrum Loop Road & SR 33/Lakeland Hills Boulevard to SR 33/Lakeland Hills Boulevard/Commonwealth Avenue
- I-4 from SR 33/Lakeland Hills Boulevard/Commonwealth Avenue to SR 570/Polk Pkwy E
- I-4 from SR 570/Polk Pkwy E to SR 559
- I-4 from SR 559 to SR 557
- I-4 from SR 557 to West of US 27

Following the review and analysis of crash data, safety improvement recommendations will be developed and presented in the study's *Facility Operations and Preservation Element Report*, which is scheduled to be submitted in mid-2023.



Legend

- I-4 Study Interchanges

Figure 1-1: Project Location Map

2 I-4 Interchange and Mainline Segment Crash Data

The following sections provide a summary of the most recent available five years of certified crash data (January 2015 – December 2019) obtained from FDOT's SSOGis. Tables summarizing the crash history for interchange and mainline segments by year, severity, condition, and type are provided. Included in this crash study is a breakdown of crashes by location, comparing calculated crash rates with that of the most recent five-year districtwide average crash rates. Crash rates, expressed in the number of crashes per million vehicle miles (MVM) traveled, were computed based on the following equation:

$$Crash\ Rate\ (MVM) = \frac{Total\ Number\ of\ Crashes * 1{,}000{,}000}{AADT * 365 * Number\ of\ Years * Length\ of\ Roadway\ Segment}$$

The most recent districtwide average crash rates (2015-2019) that were used in this study are provided in **Table 2-1** below. Raw crash data for the I-4 mainline and nine study interchanges can be found in the **Appendix A**.

Table 2-1: Districtwide Average Crash Rates (2015-2019)

Crash Rate Category	Average Crash Rate (MVM)
Interstate Urban	0.582
Interstate Rural	0.435
Urban 4-5 Lane, 2-way, Divided/Raised Median	2.606
Urban 6+ Lane, 2-way, Divided/Raised Median	2.731
Suburban 2-3 Lane, 2-way, Divided/Raised Median	4.774
Suburban 4-5 Lane, 2-way, Divided/Raised Median	1.509
Rural 2-3 Lane, 2-way, Undivided	0.757

In addition to the review of certified data, a review of the latest available uncertified crash data (January 2020 through May 2022) was also conducted to identify any significant changes in crash patterns or trends. The review of uncertified data is discussed in **Section 22**.

3 Interchange: I-4 at SR 570/Polk Parkway (West)

The SR 570/Polk Parkway (West) interchange is a system-to-system interchange. According to the collected crash data, 147 total crashes occurred within the interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 3-1**. As listed in the table, an average of 29 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 60 resulted in injuries and none resulted in fatalities.

A total of 51 crashes (34.7%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 10 crashes per year. Additionally, a total of 52 crashes (35.4%) occurred on wet roadway surface conditions, averaging 10 crashes per year.

Table 3-1: SR 570/Polk Parkway (West) Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	24	9	0	11	13
2016	24	11	0	10	6
2017	29	8	0	11	9
2018	41	20	0	11	11
2019	29	12	0	8	13
2015-2019	147	60	0	51	52
Average	29	12	0	10	10
Percent	-	40.8%	0.0%	34.7%	35.4%

Table 3-2 summarizes crashes by type. According to the summary, off road crashes account for the most crashes (33.3% of total) within the study area, followed by rear end (24.5% of total) and sideswipe (16.3% of total) crashes. One pedestrian related crash and no bicycle related crashes were reported in the most recent available five years.

- The pedestrian crash (HSMV #: 87277087) occurred in daylight conditions on August 24, 2018, on I-4 east of Polk Parkway (West). A vehicle traveling in the eastbound on I-4 in the inside lane and struck a pedestrian that had crossed over the median barrier and into the eastbound travel lanes. The pedestrian was fleeing from police.

Table 3-2: SR 570/Polk Parkway (West) Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	**0**	**0**	0.0%
Animal	0	0	0	0	0	**0**	**0**	0.0%
Bicycle	0	0	0	0	0	**0**	**0**	0.0%
Head On	1	0	0	0	0	**1**	**0.2**	0.7%
Left Turn	0	0	0	0	0	**0**	**0**	0.0%
Pedestrian	0	0	0	1	0	**1**	**0.2**	0.7%
Rear End	4	6	5	12	9	**36**	**7.2**	24.5%
Right Turn	0	0	0	0	0	**0**	**0**	0.0%
Rollover	0	3	2	2	0	**7**	**1.4**	4.8%
Sideswipe	5	2	8	7	2	**24**	**4.8**	16.3%
Off Road	8	6	10	11	14	**49**	**9.8**	33.3%
Other	6	7	4	8	4	**29**	**5.8**	19.7%
Total	**24**	**24**	**29**	**41**	**29**	**147**	**29.4**	100.0%

As shown in **Table 3-3**, 9 crashes occurred along SR 570/Polk Parkway (west), accounting for 6.1% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this interchange occurred on I-4. A heat map of the crash data is provided at the end of this section (**Figure 3-1**). 83 crashes occurred on I-4, including merge/diverge influence areas, with 35 (42.2%) resulting in an injury. Lastly, 55 crashes occurred on the interchange ramps, 20 (36.4%) of which resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas.

Table 3-3: SR 570/Polk Parkway (West) Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	**83**	0	35	48	0.308	0.582
Polk Pkwy W from New Tampa Hwy to I-4	**9**	0	5	4	0.406	0.582[1]
Polk Pkwy Ramps	**55**	0	20	35	N/A	N/A
Total Interchange and Segments	**147**	**0**	**60**	**87**	-	-
[1]Using best comparable system: Districtwide Urban Interstate Average Crash Rate						

The top five contributing causes to crashes is shown below in **Table 3-4**. The most common cause, 42.9% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 3-4: SR 570/Polk Parkway (West) Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	63	42.9%
Drove Too Fast for Conditions	18	12.2%
No Contributing Action	16	10.9%
Other Contributing Action	10	6.8%
Failed to Keep in Proper Lane	9	6.1%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 3-5** presents the total cost of the five years of crash data.

Table 3-5: SR 570/Polk Parkway (West) Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	0	$10,890,000	$0
(A) - Severe Injury	5	$888,030	$4,440,150
(B) - Moderate Injury	26	$180,180	$4,684,680
(C) - Minor Injury	29	$103,950	$3,014,550
(O) - Property Damage Only	87	$7,700	$669,900
Total			**$12,809,280**




Figure 3-1: SR 570/Polk Parkway (West) Interchange Crash Data Heat Map (2015-2019)

4 Mainline Segment: I-4 from SR 570/Polk Parkway (West) to SR 546/W Memorial Boulevard

The I-4 mainline segment between SR 570/Polk Parkway (West) and SR 546/W Memorial Boulevard is a 6-lane divided Urban Interstate facility with a westbound auxiliary lane. According to the collected crash data, 34 total crashes occurred along the mainline segment during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 4-1**. As listed in the table, an average of 7 crashes occurred per year during the most recent available five years. Of these crashes, 14 resulted in injuries while none resulted in fatalities.

A total of 14 (41.2% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 3 crashes per year. Additionally, a total of 6 crashes (17.6% of total) occurred on wet roadway surface conditions, averaging one crash per year.

Table 4-1: I-4 Segment (SR 570-W to SR 546) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	6	1	0	4	2
2016	6	5	0	4	1
2017	5	2	0	3	1
2018	9	2	0	1	2
2019	8	4	0	2	0
2015-2019	34	14	0	14	6
Average	7	3	0	3	1
Percent	-	41.2%	0.0%	41.2%	17.6%

Table 4-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (38.2% of total), followed by sideswipe (23.5% of total). One pedestrian related crash and no bicycle related crashes were reported in the most recent available five years.

- The pedestrian crash (HSMV #: 85243959) occurred at dusk on August 18, 2016, on I-4 east of Polk Parkway (West). An eastbound vehicle swerved into the median to avoid a rear end collision with slow traffic ahead. As a result, the vehicle struck a pedestrian standing in the median.

Table 4-2: I-4 Segment (SR 570-W to SR 546) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	0	0	0.0%
Animal	0	1	0	0	0	1	0.2	2.9%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	0	0	0	0	0	0.0%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	1	0	0	0	1	0.2	2.9%
Rear End	2	1	2	3	5	13	2.6	38.2%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	0	0	0	1	1	2	0.4	5.9%
Sideswipe	1	2	1	4	0	8	1.6	23.5%
Off Road	1	0	1	0	0	2	0.4	5.9%
Other	2	1	1	1	2	7	1.4	20.6%
Total	6	6	5	9	8	34	6.8	100.0%

As shown in **Table 4-3**, the crash rate for this segment of I-4 does not exceed the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 4-3: I-4 Segment (SR 570-W to SR 546) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	34	0	14	20	0.176	0.582

The top three contributing causes to crashes is shown below in **Table 4-4**. The most common cause, 32.3% of all crashes, was driving in a careless or negligent manner.

Table 4-4: I-4 Segment (SR 570-W to SR 546) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	11	32.4%
No Contributing Action	7	20.6%
Other Contributing Action	6	17.6%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 4-5** presents the total cost of the five years of crash data.

Table 4-5: I-4 Segment (SR 570-W to SR 546) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	0	$10,890,000	$0
(A) - Severe Injury	0	$888,030	$0
(B) - Moderate Injury	7	$180,180	$1,261,260
(C) - Minor Injury	7	$103,950	$727,650
(O) - Property Damage Only	20	$7,700	$154,000
	Total		**$2,142,910**

5 Interchange: I-4 at SR 546/W Memorial Boulevard

The SR 546/W Memorial Boulevard interchange is a partial diamond interchange with a signalized intersection for all westbound I-4 movements. Eastbound on and off-ramp movements are free flowing. According to the collected crash data, 134 total crashes occurred

within the interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 5-1**. As listed in the table, an average of 27 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 48 resulted in injuries and 1 resulted in fatalities.

- The fatal crash (HSMV #: 82057993) occurred in daylight conditions on June 21, 2016, on I-4 east of Memorial Boulevard. The crash report states the fatalities occurred on westbound I-4. It was a multi-vehicle collision involving 7 total vehicles. The crash initiated when an eastbound vehicle was attempting a lane change from the middle to the inside lane. It struck a vehicle in the inside lane and spun through the median and into westbound traffic. A total of 4 fatalities were reported from this crash.

A total of 64 crashes (47.8%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 13 crashes per year. Additionally, a total of 38 crashes (28.4%) occurred on wet roadway surface conditions, averaging 8 crashes per year.

Table 5-1: SR 546/W Memorial Boulevard Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	19	10	0	7	6
2016	27	8	1	10	6
2017	36	15	0	19	11
2018	28	7	0	13	8
2019	24	8	0	15	7
2015-2019	134	48	1	64	38
Average	27	10	0	13	8
Percent	-	35.8%	0.7%	47.8%	28.4%

Table 5-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (26.9% of total) within the study area, followed by sideswipe (24.6% of total) and off road (21.6% of total) crashes. There were no pedestrian or bicycle related crashes reported in the most recent available five years.

Table 5-2: SR 546/W Memorial Boulevard Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	**0**	**0**	**0.0%**
Animal	0	1	1	0	0	**2**	**0.4**	**1.5%**
Bicycle	0	0	0	0	0	**0**	**0**	**0.0%**
Head On	0	0	0	0	0	**0**	**0**	**0.0%**
Left Turn	0	0	0	0	0	**0**	**0**	**0.0%**
Pedestrian	0	0	0	0	0	**0**	**0**	**0.0%**
Rear End	2	7	7	9	11	**36**	**7.2**	**26.9%**
Right Turn	0	0	0	0	0	**0**	**0**	**0.0%**
Rollover	0	0	2	0	1	**3**	**0.6**	**2.2%**
Sideswipe	2	5	12	10	4	**33**	**6.6**	**24.6%**
Off Road	10	6	5	3	5	**29**	**5.8**	**21.6%**
Other	5	8	9	6	3	**31**	**6.2**	**23.1%**
Total	***19***	***27***	***36***	***28***	***24***	134	26.8	100.0%

As shown in **Table 5-3**, 8 crashes occurred along SR 546 (W Memorial Blvd), accounting for 6.0% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this interchange occurred on I-4. A heat map of the crash data is provided at the end of this section (**Figure 5-1**). 87 crashes occurred on I-4, including merge/diverge influence areas, with 29 (33.3%) resulting in an injury. Lastly, 39 crashes occurred on the interchange ramps, 14 (35.9%) of which resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas.

Table 5-3: SR 546/W Memorial Boulevard Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	87	1	29	57	0.416	0.582
W Memorial Blvd from I-4 to Nature's Own Facility	8	0	5	3	0.529	2.606[1]
W Memorial Blvd Ramps	39	0	14	25	N/A	N/A
Total Interchange and Segments	134	1	48	85	-	-
[1]Using Districtwide Urban 4-5 Lane Divided/Raised Median Crash rate						

The top five contributing causes to crashes is shown below in **Table 5-4**. The most common cause, 38.1% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 5-4: SR 546/W Memorial Boulevard Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Matter	51	38.1%
No Contributing Action	21	15.7%
Failed To Keep in Proper Lane	17	12.7%
Other Contributing Action	9	6.7%
Improper Turn	4	3.0%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 5-5** presents the total cost of the five years of crash data.

Table 5-5: SR 546/W Memorial Boulevard Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	1	$10,890,000	$10,890,000
(A) - Severe Injury	8	$888,030	$7,104,240
(B) - Moderate Injury	20	$180,180	$3,603,600
(C) - Minor Injury	20	$103,950	$2,079,000
(O) - Property Damage Only	85	$7,700	$654,500
	Total		**$24,331,340**




Figure 5-1: SR 546/W Memorial Boulevard Interchange Crash Data Heat Map (2015-2019)

6 Mainline Segment: I-4 from SR 546/W Memorial Boulevard to SR 539/Kathleen Road

The I-4 mainline segment between SR 546/W Memorial Boulevard and SR 539/Kathleen Road is a 6-lane divided Urban Interstate facility. According to the collected crash data, 67 total crashes occurred along the mainline segment during the five-year period. A summary of crashes sorted

by severity and environmental conditions is provided in **Table 6-1**. As listed in the table, an average of 13 crashes occurred per year during the most recent available five years. Of these crashes, 17 resulted in injuries while 1 resulted in a fatality.

- The fatal crash (HSMV # 84877538) occurred in dark-lighted conditions on June 3, 2016, on I-4 east of W Memorial Boulveard. The crash initiated when a driver attempted to change lanes and lost control of the vehicle. The vehicle overturned and rotated causing the driver to eject from the driver's side window as the vehicle overturned. The driver was pronounced dead at the scene. The driver had a BAC of 0.370.

A total of 29 (43.3% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 6 crashes per year. Additionally, a total of 23 crashes (34.3% of total) occurred on wet roadway surface conditions, averaging 5 crashes per year.

Table 6-1: I-4 Segment (SR 546 to SR 539) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	6	2	0	3	2
2016	21	6	1	9	9
2017	12	3	0	5	1
2018	18	3	0	8	6
2019	10	3	0	4	5
2015-2019	**67**	**17**	**1**	**29**	**23**
Average	**13**	**3**	**0**	**6**	**5**
Percent	-	**25.4%**	**1.5%**	**43.3%**	**34.3%**

Table 6-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (28.4% of total), followed by off road (23.9% of total) and sideswipe (17.9% of total) crashes. There were no pedestrian or bicycle related crashes reported in the most recent available five years.

Table 6-2: I-4 Segment I-4 Segment (SR 546 to SR 539) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	0	0	0.0%
Animal	0	0	0	0	0	0	0	0.0%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	0	0	0	0	0	0.0%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	0	0	0	0	0	0	0.0%
Rear End	3	3	5	4	4	19	3.8	28.4%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	0	4	0	2	0	6	1.2	9.0%
Sideswipe	2	2	1	3	4	12	2.4	17.9%
Off Road	1	5	4	4	2	16	3.2	23.9%
Other	0	7	2	5	0	14	2.8	20.9%
Total	6	21	12	18	10	67	13.4	100.0%

As shown in **Table 6-3**, the crash rate for this segment of I-4 does not exceed the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 6-3: I-4 Segment I-4 Segment (SR 546 to SR 539) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	67	1	17	49	0.272	0.582

The top four contributing causes to crashes is shown below in **Table 6-4**. The most common cause, 38.8% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 6-4: I-4 Segment (SR 546 to SR 539) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	26	38.8%
No Contributing Action	13	19.4%
Other Contributing Action	9	13.4%
Ran Off Roadway	4	6.0%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 6-5** presents the total cost of the five years of crash data.

Table 6-5: I-4 Segment (SR 546 to SR 539) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	1	$10,890,000	$10,890,000
(A) - Severe Injury	1	$888,030	$888,030
(B) - Moderate Injury	8	$180,180	$1,441,440
(C) - Minor Injury	8	$103,950	$831,600
(O) - Property Damage Only	49	$7,700	$377,300
Total			**$14,428,370**

7 Interchange: I-4 at SR 539/Kathleen Road

The SR 539/Kathleen Road interchange is a traditional diamond interchange with signalized ramp terminal intersections. According to the collected crash data, 242 total crashes occurred within the interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 7-1**. As listed in the table, an average of 48 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 93 resulted in injuries and 1 resulted in a fatality.

- The fatal crash (HSMV #: 87157642) occurred in dark-not lighted conditions on February 24, 2019, on I-4 west of Kathleen Road. A pedestrian was in the westbound paved shoulder of I-4. A vehicle struck the pedestrian who had crossed into the westbound travel lanes. The pedestrian was pronounced dead on the scene and later had a positive drug test result.

A total of 83 crashes (34.3%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 17 crashes per year. Additionally, a total of 66 crashes (27.3%) occurred on wet roadway surface conditions, averaging 13 crashes per year.

Table 7-1: SR 539/Kathleen Road Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	36	20	0	13	10
2016	43	16	0	13	11
2017	50	19	0	19	15
2018	50	19	0	17	16
2019	63	19	1	21	14
2015-2019	242	93	1	83	66
Average	48	19	0	17	13
Percent	-	38.4%	0.4%	34.3%	27.3%

Table 7-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (47.5% of total) within the study area, followed by off road (17.4% of total) and sideswipe (14.9% of total) crashes. There was 1 pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The one pedestrian crash (HSMV #: 87157642) was the fatal crash previously summarized.

Table 7-2: SR 539/Kathleen Road Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	1	0	1	2	0.4	0.8%
Animal	0	0	0	0	0	0	0	0.0%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	1	0	0	1	0.2	0.4%
Left Turn	0	0	2	1	4	7	1.4	2.9%
Pedestrian	0	0	0	0	1	1	0.2	0.4%
Rear End	22	18	25	24	26	115	23	47.5%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	1	1	1	0	0	3	0.6	1.2%
Sideswipe	2	3	8	10	13	36	7.2	14.9%
Off Road	7	13	8	7	7	42	8.4	17.4%
Other	4	8	4	8	11	35	7	14.5%
Total	36	43	50	50	63	242	48.4	100.0%

As shown in **Table 7-3**, 65 crashes occurred along Kathleen Road, accounting for 26.9% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this

interchange occurred on I-4. A heat map of the crash data is provided at the end of this section (**Figure 7-1**). 144 crashes occurred on I-4, including merge/diverge influence areas, with 51 (35.4%) resulting in an injury. Lastly, 33 crashes occurred on the interchange ramps, 16 (48.5%) of which resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas.

Table 7-3: SR 539/Kathleen Road Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	144	1	51	92	0.739	0.582
Kathleen Rd from Mall Hill Dr to Interstate Dr	65	0	26	39	1.010	2.606[1]
Kathleen Rd Ramps	33	0	16	17	N/A	N/A
Total Interchange and Segments	242	1	93	148	-	-
[1]Using Districtwide Urban 4-5 Lane Divided/Raised Median Average Crash rate						

The top five contributing causes to crashes is shown below in **Table 7-4**. The most common cause, 43.8% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 7-4: SR 546/W Memorial Boulevard Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Matter	106	43.8%
No Contributing Action	39	16.1%
Other Contributing Action	21	8.7%
Failed To Keep in Proper Lane	12	5.0%
Ran Off Roadway	10	4.1%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 7-5** presents the total cost of the five years of crash data.

Table 7-5: SR 539/Kathleen Road Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	1	$10,890,000	$10,890,000
(A) - Severe Injury	8	$888,030	$7,104,240
(B) - Moderate Injury	35	$180,180	$6,306,300
(C) - Minor Injury	50	$103,950	$5,197,500
(O) - Property Damage Only	148	$7,700	$1,139,600
	Total		**$30,637,640**




Figure 7-1: SR 539/Kathleen Road Interchange Crash Data Heat Map (2015-2019)

8 Mainline Segment: I-4 from SR 539/Kathleen Road to US 98

The I-4 mainline segment between SR 539/Kathleen Road and US 98 is a 6-lane divided Urban Interstate facility. According to the collected crash data, 33 total crashes occurred along the mainline segment during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 8-1**. As listed in the table, an average of 7 crashes

occurred per year during the most recent available five years. Of these crashes, 13 resulted in injuries while two resulted in a fatality.

- The first fatal crash (HSMV #: 87139818) occurred in dark-not lighted conditions on May 3, 2018, on I-4 east of Kathleen Road. A pedestrian was in the westbound paved shoulder of I-4. It was dark, unlit conditions and a vehicle struck the pedestrian in the outside shoulder. The driver of the vehicle did not stop after the crash and the pedestrian was pronounced dead on the scene.
- The second fatal crash (HSMV #: 87235552) occurred in daylight conditions on November 11, 2018, on I-4 west of US 98. A westbound vehicle experienced a tire blowout and ran off the roadway to the right. The vehicle then struck a light post, and the driver was pronounced dead on the scene.

A total of 13 (39.4% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 3 crashes per year. Additionally, a total of 11 crashes (33.3% of total) occurred on wet roadway surface conditions, averaging 2 crashes per year.

Table 8-1: I-4 Segment (SR 539 to US 98) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	9	5	0	5	3
2016	9	3	0	2	2
2017	3	1	0	3	2
2018	6	1	2	1	2
2019	6	3	0	2	2
2015-2019	33	13	2	13	11
Average	7	3	0	3	2
Percent	-	39.4%	6.1%	39.4%	33.3%

Table 8-2 summarizes crashes by type. According to the summary, sideswipe and off road crashes account for the most crashes (each 33.3% of total), followed by rear end (18.2% of total) crashes. There was 1 pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The one pedestrian crash (HSMV #: 87139818) was the first fatal crash previously summarized.

Table 8-2: I-4 Segment (SR 539 to US 98) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	0	0	0.0%
Animal	0	0	0	0	0	0	0	0.0%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	0	0	0	0	0	0.0%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	0	0	1	0	1	0.2	3.0%
Rear End	4	1	0	0	1	6	1.2	18.2%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	0	0	0	0	0	0	0	0.0%
Sideswipe	1	5	1	3	1	11	2.2	33.3%
Off Road	4	2	2	0	3	11	2.2	33.3%
Other	0	1	0	2	1	4	0.8	12.1%
Total	9	9	3	6	6	33	6.6	100.0%

As shown in **Table 8-3**, the crash rate for this segment of I-4 does not exceed the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 8-3: I-4 Segment (SR 539 to US 98) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	33	2	13	18	0.524	0.582

The top three contributing causes to crashes is shown below in **Table 8-4**. The most common cause, 33.3% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 8-4: I-4 Segment (SR 539 to US 98) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	11	33.3%
No Contributing Action	7	21.2%
Failed to Keep in Proper Lane	3	9.1%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 8-5** presents the total cost of the five years of crash data.

Table 8-5: I-4 Segment (SR 539 to US 98) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	2	$10,890,000	$21,780,000
(A) - Severe Injury	3	$888,030	$2,664,090
(B) - Moderate Injury	6	$180,180	$1,081,080
(C) - Minor Injury	4	$103,950	$415,800
(O) - Property Damage Only	18	$7,700	$138,600
Total			**$26,079,570**

9 Interchange: I-4 at US 98

The US 98 interchange is a single point urban interchange (SPUI). According to the collected crash data, 572 total crashes occurred within the interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 9-1**. As listed in the table, an average of 114 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 223 resulted in injuries and 3 resulted in a fatality.

- The first fatal crash (HSMV #: 87795684) occurred in daylight conditions on April 13, 2018, on US 98. A vehicle was traveling southbound in the outside lane while a motorcycle was traveling southbound in the center lane. The vehicle made an improper lane change into the center lane, causing the motorcyclist to become ejected from the motorcycle. The motorcyclist was pronounced dead after being transported.
- The second fatal crash (HSMV#: 87796322) occurred in dark-lighted conditions on June 5, 2018, at the intersection of US 98 and Griffin Road. A vehicle was traveling southbound through the intersection when a cyclist road into the crosswalk, in front of the vehicle. The vehicle struck the cyclist, ejecting them from the bicycle. The cyclist was pronounced dead at the scene.
- The third fatal crash (HSMV #: 87208694) occurred in daylight conditions on March 26, 2019, on I-4 east of US 98. An eastbound vehicle departed the roadway, collided with the cable barrier, overturned several times, and came to rest in the westbound lanes. A rear seat passenger was fully ejected and pronounced dead at the scene.

A total of 196 crashes (34.3%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 39 crashes per year. Additionally, a total of 113 crashes (19.8%) occurred on wet roadway surface conditions, averaging 23 crashes per year.

Table 9-1: US 98 Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	98	47	0	38	19
2016	115	48	0	40	26
2017	111	36	0	38	31
2018	119	39	2	42	22
2019	129	53	1	38	15
2015-2019	572	223	3	196	113
Average	114	45	1	39	23
Percent	-	39.0%	0.5%	34.3%	19.8%

Table 9-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (47.2% of total) within the study area, followed by sideswipe (20.6% of total) and off road (8.9% of total) crashes. There were 6 pedestrian related crashes and 5 bicycle related crashes reported in the most recent available five years.

- The first bicycle crash (HSMV #: 87343492) occurred in daylight conditions on October 2, 2017, at the intersection of US 98 and Griffin Road. A vehicle was exiting the shopping center in the southeast quadrant onto westbound Griffin Road and failed to observe the cyclist on the sidewalk. The cyclist was transported to the hospital with injuries.
- The first pedestrian crash (HSMV #: 88842918) occurred in dark-lighted conditions on November 1, 2018, at the intersection of US 98 and Griffin Road. A vehicle had just made a turn to proceed southbound on US 98 when the pedestrian crossed into traffic. The vehicle was unable to stop and struck the pedestrian. The pedestrian was not transported but complained of injuries.
- The second bicycle crash (HSMV #: 88843789) occurred in daylight conditions on January 15, 2019, at the intersection of US 98 and Griffin Road. An eastbound driver was attempting a U-turn just east of the intersection and failed to see the cyclist in the median. The mirror clipped the cyclist and knocked them to the ground. The cyclist was transported to the hospital with injuries.
- The third bicycle crash (HSMV #: 85730228) occurred in dark-lighted conditions on May 12, 2015, at the intersection of US 98 and Pyramid Parkway. The cyclist was in the southbound turn lane on US 98 when a southbound vehicle drove past them, clipping them in the process and knocking them down. The vehicle never stopped at the cyclist was transported to the hospital with injuries.
- The fourth bicycle crash (HSMV #: 86127798) occurred in daylight conditions on October 13, 2015, on US 98 north of I-4. A vehicle was westbound exiting the mall when it struck a cyclist traveling southbound on the sidewalk. The cyclist was transported to the hospital with injuries.
- The fifth bicycle crash (HSMV #: 86346005) occurred in daylight conditions on May 3, 2016, on US 98 north of I-4. A vehicle was eastbound exiting the McDonald's when it struck a cyclist traveling northbound on the sidewalk. The cyclist was transported to the hospital with injuries.

- The sixth bicycle crash (HSMV #: 87797141) occurred at dusk on August 18, 2018, at the intersection of US 98 and Breezewood Drive. A vehicle was westbound on Breezewood Drive when it struck a cyclist traveling southbound on the sidewalk. The cyclist was treated for injuries on scene.
- The seventh bicycle crash (HSMV #: 89348589) occurred at dawn on December 26, 2019, at the intersection of US 98 and westbound I-4 ramps. A vehicle was making a left turn from the off-ramp onto US 98 when a cyclist crossed into the path of the vehicle. The vehicle struck the cyclist, knocking them down. The cyclist was transported to the hospital with injuries.
- The second pedestrian crash (HSMV #: 85730594) occurred in dark-lighted conditions on August 19, 2015, at the intersection of US 98 and Lakeland Park Center Drive. A southbound vehicle realized too late that a pedestrian was lying in the travel lane and ran them over. The pedestrian was transported to the hospital with injuries.
- The eighth bicycle crash (HSMV #: 87796322) was the second fatal crash previously summarized.
- The third pedestrian crash (HSMV #: 89347224) occurred in daylight conditions on September 4, 2019, on US 98 south of I-4. A southbound vehicle was approaching the intersection of US 98 and Pyramid Parkway when a pedestrian ran out into the southbound travel lanes. The vehicle struck the pedestrian who was later transported to the hospital with injuries. It was reported that the pedestrian was intending to cause self-harm with this crash.

Table 9-2: US 98 Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	4	2	5	0	3	14	2.8	2.4%
Animal	0	0	1	0	0	1	0.2	0.2%
Bicycle	2	0	1	1	1	5	1	0.9%
Head On	1	3	0	1	1	6	1.2	1.0%
Left Turn	6	3	5	4	3	21	4.2	3.7%
Pedestrian	1	1	0	2	2	6	1.2	1.0%
Rear End	44	50	49	65	62	270	54	47.2%
Right Turn	0	0	0	0	2	2	0.4	0.3%
Rollover	3	1	0	1	1	6	1.2	1.0%
Sideswipe	15	27	19	25	32	118	23.6	20.6%
Off Road	6	17	10	10	8	51	10.2	8.9%
Other	16	11	21	10	14	72	14.4	12.6%
Total	98	115	111	119	129	572	114.4	100.0%

As shown in **Table 9-3**, 407 crashes occurred along US 98, accounting for 71.2% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this interchange occurred on US 98. A heat map of the crash data is provided at the end of this section (**Figure 9-1**). 119 crashes occurred on I-4, including merge/diverge influence areas, with 40 (33.6%) resulting in an injury. Lastly, 46 crashes occurred on the interchange ramps, 14 (30.4%) of which

resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas. The crash rate for I-4 and US 98 exceeds the districtwide average crash rate for similar facilities.

Table 9-3: US 98 Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	119	1	40	78	0.638	0.582
US 98 from Griffin Rd to Mall Access 2	407	3	168	236	4.482	2.731[1]
US 98 Ramps	46	0	14	32	N/A	N/A
Total Interchange and Segments	572	4	222	346	-	-
[1]Using Districtwide Urban 6+ Lane Divided/Raised Median Average Crash rate						

The top five contributing causes to crashes is shown below in **Table 9-4**. The most common cause, 34.1% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 9-4: US 98 Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	195	34.1%
No Contributing Action	89	15.6%
Other Contributing Action	63	11.0%
Followed Too Closely	52	9.1%
Failed to Yield Right-of-Way	44	7.7%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 9-5** presents the total cost of the five years of crash data.

Table 9-5: US 98 Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	4	$10,890,000	$43,560,000
(A) - Severe Injury	17	$888,030	$15,096,510
(B) - Moderate Injury	68	$180,180	$12,252,240
(C) - Minor Injury	137	$103,950	$14,241,150
(O) - Property Damage Only	346	$7,700	$2,664,200
	Total		**$87,814,100**




Figure 9-1: US 98 Interchange Crash Data Heat Map (2015-2019)

10 Mainline Segment: I-4 from US 98 to N Socrum Loop Road & SR 33/Lakeland Hills Boulevard

The I-4 mainline segment between US 98 and N Socrum Loop Road/SR 33/Lakeland Hills Boulevard is a 6-lane divided Urban Interstate facility. According to the collected crash data, 105 total crashes occurred along the mainline segment during the five-year period. A summary of

crashes sorted by severity and environmental conditions is provided in **Table 10-1**. As listed in the table, an average of 21 crashes occurred per year during the most recent available five years. Of these crashes, 24 resulted in injuries while 3 resulted in a fatality.

- The first fatal crash (HSMV #: 85390366) occurred in dark-not lighted conditions on January 14, 2017, on I-4 east of US 98. A westbound vehicle was traveling the wrong way in the eastbound lanes and had a head-on collision with an eastbound vehicle. The driver of the eastbound vehicle was pronounced dead at the scene.
- The second fatal crash (HSMV #: 84877545) occurred at dawn on June 24, 2017, on I-4 east of US 98. The driver of a westbound vehicle lost control of the vehicle and departed the roadway onto the outside shoulder. The vehicle began to rotate and eventually overturn numerous times, ejecting the driver. The driver was pronounced dead at the scene.
- The third fatal crash (HSMV #: 87162252) occurred in dark-not lighted conditions on May 5, 2018, on I-4 west of N Socrum Loop Road/Lakeland Hills Boulevard. A pedestrian was in the inside lane of westbound I-4 wearing dark clothing. The pedestrian was struck by a vehicle and propelled into the center median. The pedestrian was pronounced dead at the scene.

A total of 46 (43.8% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 9 crashes per year. Additionally, a total of 49 crashes (46.7% of total) occurred on wet roadway surface conditions, averaging 10 crashes per year.

Table 10-1: I-4 Segment (US 98 to Socrum Loop Rd) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	10	2	0	4	7
2016	24	6	0	12	6
2017	21	3	2	10	10
2018	25	5	1	10	13
2019	25	8	0	10	13
2015-2019	**105**	**24**	**3**	**46**	**49**
Average	**21**	**5**	**1**	**9**	**10**
Percent	-	**22.9%**	**2.9%**	**43.8%**	**46.7%**

Table 10-2 summarizes crashes by type. According to the summary, off road crashes account for the most crashes (33.3% of total), followed by rear end (20.0% of total) and sideswipe (14.3% of total) crashes. There was 1 pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The pedestrian crash (HSMV #: 87162252) was the third fatal crash previously summarized.

Table 10-2: I-4 Segment (US 98 to Socrum Loop Rd) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	0	0	0.0%
Animal	0	1	0	0	0	1	0.2	1.0%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	2	0	1	3	0.6	2.9%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	0	0	1	0	1	0.2	1.0%
Rear End	0	2	7	7	5	21	4.2	20.0%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	0	0	2	3	1	6	1.2	5.7%
Sideswipe	1	6	2	2	4	15	3	14.3%
Off Road	6	8	4	8	9	35	7	33.3%
Other	3	7	4	4	5	23	4.6	21.9%
Total	10	24	21	25	25	105	21	100.0%

As shown in **Table 10-3**, the crash rate for this segment of I-4 exceeds the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 10-3: I-4 Segment (US 98 to Socrum Loop Rd) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	105	3	24	78	0.587	0.582

The top four contributing causes to crashes is shown below in **Table 10-4**. The most common cause, 37.1% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 10-4: I-4 Segment (US 98 to Socrum Loop Rd) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	39	37.1%
No Contributing Action	17	16.2%
Drove Too Fast for Conditions	14	13.3%
Other Contributing Action	11	10.5%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 10-5** presents the total cost of the five years of crash data.

Table 10-5: I-4 Segment (US 98 to Socrum Loop Rd) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	3	$10,890,000	$32,670,000
(A) - Severe Injury	4	$888,030	$3,552,120
(B) - Moderate Injury	11	$180,180	$1,981,980
(C) - Minor Injury	9	$103,950	$935,550
(O) - Property Damage Only	78	$7,700	$600,600
Total			**$39,740,250**

11 Interchange: I-4 at N Socrum Loop Road & SR 33/Lakeland Hills Boulevard

The N Socrum Loop Road & SR 33/Lakeland Hills Boulevard interchange is a unconventional interchange with eastbound I-4 connected to SR 33/Lakeland Hills Boulevard and westbound I-4 connected to N Socrum Loop Road. According to the collected crash data, 241 total crashes occurred within the interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 11-1**. As listed in the table, an average of 48 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 113 resulted in injuries and 4 resulted in a fatality.

- The first fatal crash (HSMV #: 84545393) occurred in dark-not lighted conditions on May 5, 2015, on I-4 approaching the eastbound off-ramp. A motorcyclist was approaching a semi-truck and attempted to change lanes but did so too late. The motorcycle struck the truck trailer, and the motorcyclist was fully ejected and pronounced dead at the scene.
- The second fatal crash (HSMV #: 86346786) occurred in dark-lighted conditions on May 6, 2016, at the intersection of Lakeland Hills Boulevard and the eastbound I-4 off ramp. A motorcycle heading eastbound on the I-4 off-ramp did not stop at the intersection and struck the semi-truck that was traveling southbound through the intersection. The motorcyclist was pronounced dead at the scene.
- The third fatal crash (HSMV #: 87795113) occurred in dark-lighted conditions on February 27, 2018, at the intersection of N Socrum Loop Road and Lakeland Park Boulevard. A northbound motorcycle was stopped at the traffic light when it was rear ended by another vehicle. The motorcyclist was fully ejected and pronounced dead at the scene.
- The fourth fatal crash (HSMV #: 87276855) occurred in dark-not lighted conditions on June 2, 2019, on I-4 west of the westbound on ramps at N Socrum Loop Road. A vehicle was traveling

westbound when a pedestrian crossed the westbound travel lanes and was struck. The pedestrian was pronounced dead at the scene.

A total of 102 crashes (42.3%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 20 crashes per year. Additionally, a total of 74 crashes (30.7%) occurred on wet roadway surface conditions, averaging 15 crashes per year.

Table 11-1: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	54	24	1	21	21
2016	34	20	1	13	8
2017	53	21	0	21	19
2018	58	29	1	26	12
2019	42	19	1	21	14
2015-2019	241	113	4	102	74
Average	48	23	1	20	15
Percent	-	46.9%	1.7%	42.3%	30.7%

Table 11-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (27.0% of total) within the study area, followed by left turn (21.2% of total) and off road (18.3% of total) crashes. There was 1 pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The pedestrian crash (HSMV #: 87276855) was the fourth fatal crash previously summarized.

Table 11-2: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	2	2	1	2	0	7	1.4	2.9%
Animal	0	0	0	0	0	0	0	0.0%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	0	0	0	0	0	0.0%
Left Turn	8	9	12	16	6	51	10.2	21.2%
Pedestrian	0	0	0	0	1	1	0.2	0.4%
Rear End	12	7	17	18	11	65	13	27.0%
Right Turn	0	1	1	0	0	2	0.4	0.8%
Rollover	3	0	4	3	6	16	3.2	6.6%
Sideswipe	4	3	6	5	6	24	4.8	10.0%
Off Road	16	8	6	5	9	44	8.8	18.3%
Other	9	4	6	9	3	31	6.2	12.9%
Total	54	34	53	58	42	241	48.2	100.0%

As shown in **Table 11-3**, 47 crashes occurred along N Socrum Loop Rd, accounting for 19.5% of total crashes in the interchange area. 82 crashes occurred along Lakeland Hills Boulevard, accounting for 34.0% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this interchange occurred on Lakeland Hills Boulevard. A heat map of the crash data is provided at the end of this section (**Figure 11-1**). 60 crashes occurred on I-4, including merge/diverge influence areas, with 20 (33.3%) resulting in an injury. Lastly, 52 crashes occurred on the interchange ramps, 24 (46.2%) of which resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas.

Table 11-3: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	60	2	20	38	0.342	0.582
N Socrum Loop Rd from Lakeland Hills Blvd to Old Combee Rd	47	1	25	21	1.463	2.606[1]
Lakeland Hills Blvd from Socrum Loop Rd to Old Combee Rd	82	1	44	37	2.192	2.606[1]
N Socrum Loop Rd/Lakeland Hills Blvd Ramps	52	0	24	28	N/A	N/A
Total Interchange and Segments	241	4	113	124	-	-

[1]Using Districtwide Urban 4-5 Lane Divided/Raised Median Average Crash rate

The top five contributing causes to crashes is shown below in **Table 11-4**. The most common cause, 26.1% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 11-4: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	63	26.1%
No Contributing Action	34	14.1%
Other Contributing Action	29	12.0%
Failed to Yield Right-of-Way	28	11.6%
Drove Too Fast for Conditions	14	5.8%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B),

Minor Injury (C), and Property Damage Only (O). **Table 11-5** presents the total cost of the five years of crash data.

Table 11-5: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	4	$10,890,000	$43,560,000
(A) - Severe Injury	4	$888,030	$3,552,120
(B) - Moderate Injury	31	$180,180	$5,585,580
(C) - Minor Injury	78	$103,950	$8,108,100
(O) - Property Damage Only	124	$7,700	$954,800
	Total		**$61,760,600**




Figure 11-1: N Socrum Loop Road & SR 33/Lakeland Hills Boulevard Interchange Crash Data Heat Map (2015-2019)

12 Mainline Segment: I-4 from N Socrum Loop Road & SR 33/Lakeland Hills Boulevard to SR 33/Lakeland Hills Boulevard/Commonwealth Avenue

The I-4 mainline segment between N Socrum Loop Road/SR 33/Lakeland Hills Boulevard and SR 33/Lakeland Hills Boulevard/Commonwealth Avenue is a 6-lane divided Urban Interstate facility. According to the collected crash data, 195 total crashes occurred along the mainline segment during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 12-1**. As listed in the table, an average of 39 crashes occurred per year during the most recent available five years. Of these crashes, 52 resulted in injuries while 4 resulted in a fatality.

- The first fatal crash (HSMV #: 83771097) occurred in daylight conditions on February 13, 2015, on I-4 west of SR 33. For unknown reasons, a westbound vehicle lost control and traveled over the median into the eastbound travel lanes and collided with an eastbound vehicle. The driver of the westbound vehicle was pronounced dead at the scene.
- The second fatal crash (HSMV #: 83834010) occurred in dark-not lighted conditions on February 25, 2015, on I-4 west of SR 33. A westbound vehicle was stopped in the inside travel lane when it was rear ended by another westbound vehicle. The driver of the vehicle in motion was pronounced dead at the scene.
- The third fatal crash (HSMV #: 85194227) occurred in dark-not lighted conditions on August 13, 2016, on I-4 east of Old Combee Road. An eastbound vehicle departed the roadway, began rotating, overturned several times, and came to rest in the eastbound shoulder. A rear seat passenger was fully ejected and pronounced dead at the scene.
- The fourth fatal crash (HSMV#: 87198625) occurred in daylight conditions on August 3, 2018, on I-4 west of SR 33. A driver had a tire blowout at lost control of the vehicle causing it to veer into the median and overturning. The front seat passenger was fully ejected and was pronounced dead at the scene.

A total of 86 (44.1% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 17 crashes per year. Additionally, a total of 74 crashes (37.9% of total) occurred on wet roadway surface conditions, averaging 15 crashes per year.

Table 12-1: I-4 Segment (Socrum Loop Rd to SR 33) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	33	7	2	13	11
2016	43	10	1	20	13
2017	35	9	0	16	14
2018	47	17	1	18	23
2019	37	9	0	19	13
2015-2019	195	52	4	86	74
Average	39	10	1	17	15
Percent	-	26.7%	2.1%	44.1%	37.9%

Table 12-2 summarizes crashes by type. According to the summary, off road crashes account for the most crashes (33.3% of total), followed by rear end (20.0% of total) and sideswipe (17.9% of total) crashes. There were no pedestrian or bicycle related crashes reported in the most recent available five years.

Table 12-2: I-4 Segment (Socrum Loop Rd to SR 33) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	0	0	0.0%
Animal	0	0	0	0	0	0	0	0.0%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	1	0	0	1	0	2	0.4	1.0%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	0	0	0	0	0	0	0.0%
Rear End	4	9	8	9	9	39	7.8	20.0%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	0	2	2	6	1	11	2.2	5.6%
Sideswipe	7	7	5	5	11	35	7	17.9%
Off Road	15	13	14	14	9	65	13	33.3%
Other	6	12	6	12	7	43	8.6	22.1%
Total	33	43	35	47	37	195	39	100.0%

As shown in **Table 12-3**, the crash rate for this segment of I-4 does not exceed the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 12-3: I-4 Segment (Socrum Loop Rd to SR 33) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	195	4	52	139	0.394	0.582

The top five contributing causes to crashes is shown below in **Table 12-4**. The most common cause, 30.2% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 12-4: I-4 Segment (Socrum Loop Rd to SR 33) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	59	30.3%
No Contributing Action	36	18.5%
Failed to Keep in Proper Lane	19	9.7%
Drove Too Fast for Conditions	18	9.2%
Other Contributing Action	18	9.2%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 12-5** presents the total cost of the five years of crash data.

Table 12-5: I-4 Segment (Socrum Loop Rd to SR 33) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	4	$10,890,000	$43,560,000
(A) - Severe Injury	11	$888,030	$9,768,330
(B) - Moderate Injury	18	$180,180	$3,243,240
(C) - Minor Injury	23	$103,950	$2,390,850
(O) - Property Damage Only	139	$7,700	$1,070,300
Total			**$60,032,720**

13 Interchange: I-4 at SR 33/Lakeland Hills Boulevard/Commonwealth Avenue

The SR 33 interchange is a traditional diamond interchange with stop-controlled ramp terminal intersections. According to the collected crash data, 269 total crashes occurred within the interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 13-1**. As listed in the table, an average of 54 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 88 resulted in injuries and 1 resulted in a fatality.

- The fatal crash (HSMV #: 89346782) occurred in daylight conditions on July 26, 2019, at the intersection of SR 33 and Tomkow Road. A southeastbound vehicle on Tomkow Road failed to yield right-of-way to traffic on SR 33 and attempted to cross SR 33. A southwestbound vehicle on SR 33 then collided with this vehicle which caused a collision with a northeastbound vehicle on SR 33. The front seat passenger of the southwestbound vehicle was transported but ultimately was pronounced dead at the hospital.

A total of 104 crashes (38.7%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 21 crashes per year. Additionally, a total of 92 crashes (34.2%) occurred on wet roadway surface conditions, averaging 18 crashes per year.

Table 13-1: SR 33 Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	37	13	0	13	19
2016	47	20	0	13	14
2017	52	9	0	21	14
2018	65	26	0	28	25
2019	68	20	1	29	20
2015-2019	**269**	**88**	**1**	**104**	**92**
Average	**54**	**18**	**0**	**21**	**18**
Percent	-	**32.7%**	**0.4%**	**38.7%**	**34.2%**

Table 13-2 summarizes crashes by type. According to the summary, off road crashes account for the most crashes (29.7% of total) within the study area, followed by rear end (23.8% of total) and sideswipe (8.9% of total) crashes. There were no pedestrian or bicycle related crashes reported in the most recent available five years.

Table 13-2: SR 33 Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	1	0	2	6	5	14	2.8	5.2%
Animal	1	1	0	0	0	2	0.4	0.7%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	1	1	0	2	0.4	0.7%
Left Turn	3	3	6	6	5	23	4.6	8.6%
Pedestrian	0	0	0	0	0	0	0	0.0%
Rear End	7	16	12	9	20	64	12.8	23.8%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	3	0	2	1	4	10	2	3.7%
Sideswipe	3	2	5	7	7	24	4.8	8.9%
Off Road	10	14	16	21	19	80	16	29.7%
Other	9	11	8	14	8	50	10	18.6%
Total	37	47	52	65	68	269	53.8	100.0%

As shown in **Table 13-3**, 71 crashes occurred along SR 33, accounting for 26.4% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this interchange occurred on I-4. A heat map of the crash data is provided at the end of this section (**Figure 13-1**). 152 crashes occurred on I-4, including merge/diverge influence areas, with 45 (29.6%) resulting in an injury. Lastly, 46 crashes occurred on the interchange ramps, 27 (58.7%) of which resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas. The crash rate for I-4 exceeds the districtwide average crash rate for similar facilities.

Table 13-3: SR 33 Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	152	0	45	107	0.913	0.582
SR 33 from University Blvd to Tomkow Rd	71	1	27	43	3.045	4.774[1]
SR 33 Ramps	46	0	16	30	N/A	N/A
Total Interchange and Segments	269	1	88	180	-	-
[1]Using Districtwide Suburban 2.-3 Lane, 2-way, Divided/Raised Median Average Crash rate						

The top three contributing causes to crashes is shown below in **Table 13-4**. The most common cause, 34.2% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 13-4: SR 33 Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	92	34.2%
Failed to Yield Right-of-Way	32	11.9%
No Contributing Action	32	11.9%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 13-5** presents the total cost of the five years of crash data.

Table 13-5: SR 33 Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	1	$10,890,000	$10,890,000
(A) - Severe Injury	9	$888,030	$7,992,270
(B) - Moderate Injury	27	$180,180	$4,864,860
(C) - Minor Injury	52	$103,950	$5,405,400
(O) - Property Damage Only	180	$7,700	$1,386,000
	Total		**$30,538,530**




Figure 13-1: SR 33 Interchange Crash Data Heat Map (2015-2019)

14 Mainline Segment: I-4 from SR 33/Lakeland Hills Boulevard/Commonwealth Avenue to SR 570/Polk Parkway (East)

The I-4 mainline segment between SR 33/Lakeland Hills Boulevard/Commonwealth Avenue and SR 570/Polk Parkway (East) is a 6-lane divided Rural Interstate facility. According to the collected crash data, 145 total crashes occurred along the mainline segment during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 14-1**. As listed in the table, an average of 29 crashes occurred per year during the most recent available five years. Of these crashes, 62 resulted in injuries while 2 resulted in a fatality.

- The second fatal crash (HSMV #: 84535784) occurred in dark-not lighted conditions on January 3, 2015, on I-4 west of Polk Parkway (East). A driver of a semi-truck had broken down on the shoulder and was stepping out into the travel lanes, attempting to flag down some help. An eastbound vehicle struck the pedestrian in the center lane and a second vehicle struck the pedestrian in the outside lane. The pedestrian was pronounced dead at the scene.

- The second fatal crash (HSMV #: 85501136) occurred in daylight conditions on July 11, 2017, on I-4 west of Polk Parkway (East). A vehicle was traveling westbound in the outside lane approaching two vehicles on the shoulder. The drivers were performing maintenance on the vehicles on the shoulder and had properly displayed advance warning triangle deflectors on the shoulder. The westbound vehicle left the travel lane and collided with the vehicles on the shoulder. The driver of the westbound vehicle was pronounced dead at the scene.

A total of 54 (37.2% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 11 crashes per year. Additionally, a total of 48 crashes (33.1% of total) occurred on wet roadway surface conditions, averaging 10 crashes per year.

Table 14-1: I-4 Segment (SR 33 to SR 570-E) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	27	12	1	12	5
2016	23	5	0	9	8
2017	24	12	1	7	6
2018	50	24	0	18	23
2019	21	9	0	8	6
2015-2019	145	62	2	54	48
Average	29	12	0	11	10
Percent	-	42.8%	1.4%	37.2%	33.1%

Table 14-2 summarizes crashes by type. According to the summary, off road crashes account for the most crashes (26.9% of total), followed by rear end (24.8% of total) and sideswipe (17.2% of total) crashes. There was one (1) pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The pedestrian crash (HSMV #: 84535784) was the first fatal crash previously summarized.

Table 14-2: I-4 Segment (SR 33 to SR 570-E) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	1	0	0	0	1	0.2	0.7%
Animal	0	0	0	0	1	1	0.2	0.7%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	0	0	1	1	0.2	0.7%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	1	0	0	0	0	1	0.2	0.7%
Rear End	6	3	5	14	8	36	7.2	24.8%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	1	2	0	2	0	5	1	3.4%
Sideswipe	3	6	3	10	3	25	5	17.2%
Off Road	7	8	10	11	3	39	7.8	26.9%
Other	9	3	6	13	5	36	7.2	24.8%
Total	27	23	24	50	21	145	29	100.0%

As shown in **Table 14-3**, the crash rate for this segment of I-4 does not exceed the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 14-3: I-4 Segment (SR 33 to SR 570-E) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	145	1	62	82	0.433	0.435

The top five contributing causes to crashes is shown below in **Table 14-4**. The most common cause, 41.4% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 14-4: I-4 Segment (SR 33 to SR 570-E) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	60	41.4%
No Contributing Action	32	22.1%
Other Contributing Action	13	9.0%
Failed to Keep in Proper Lane	8	5.5%
Ran Off Roadway	6	4.1%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 14-5** presents the total cost of the five years of crash data.

Table 14-5: I-4 Segment (SR 33 to SR 570-E) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	1	$10,890,000	$10,890,000
(A) - Severe Injury	6	$888,030	$5,328,180
(B) - Moderate Injury	23	$180,180	$4,144,140
(C) - Minor Injury	33	$103,950	$3,430,350
(O) - Property Damage Only	82	$7,700	$631,400
Total			**$24,424,070**

15 Interchange: I-4 at SR 570/Polk Parkway (East)

The SR 570/Polk Parkway (East) interchange is a system-to-system interchange. According to the collected crash data, 197 total crashes occurred within the interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 15-1**. As listed in the table, an average of 39 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 70 resulted in injuries and 1 resulted in a fatality.

- The fatal crash (HSMV #: 85254516) occurred in dark-lighted conditions on February 2, 2016, on I-4 just west of Polk Parkway (East). An eastbound vehicle made an improper lane change which resulted in a collision with an eastbound motorcycle. This caused the driver of the motorcycle to be fully ejected. The motorcyclist was transported but later pronounced dead at the hospital.

A total of 94 crashes (47.7%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 19 crashes per year. Additionally, a total of 71 crashes (36.0%) occurred on wet roadway surface conditions, averaging 14 crashes per year.

Table 15-1: SR 570/Polk Parkway (East) Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	29	8	0	13	12
2016	48	16	1	28	14
2017	35	16	0	18	9
2018	33	10	0	11	16
2019	52	20	0	24	20
2015-2019	197	70	1	94	71
Average	39	14	0	19	14
Percent	-	35.5%	0.5%	47.7%	36.0%

Table 15-2 summarizes crashes by type. According to the summary, off road crashes account for the most crashes (34.5% of total) within the study area, followed by rear end (21.3% of total) and sideswipe (19.3% of total) crashes. There were no pedestrian or bicycle related crashes reported in the most recent available five years.

Table 15-2: SR 570/Polk Parkway (East) Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	0	0	0.0%
Animal	0	0	0	0	0	0	0	0.0%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	0	0	1	1	0.2	0.5%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	0	0	0	0	0	0	0.0%
Rear End	4	11	5	8	14	42	8.4	21.3%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	0	2	1	3	2	8	1.6	4.1%
Sideswipe	5	11	6	4	12	38	7.6	19.3%
Off Road	13	16	13	13	13	68	13.6	34.5%
Other	7	8	10	5	10	40	8	20.3%
Total	29	48	35	33	52	197	39.4	100.0%

As shown in **Table 15-3**, 3 crashes occurred along Polk Parkway (East), accounting for 1.5% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this interchange occurred on I-4. A heat map of the crash data is provided at the end of this section (**Figure 15-1**). 160 crashes occurred on I-4, including merge/diverge influence areas, with 50 (31.3%) resulting in an injury. Lastly, 34 crashes occurred on the interchange ramps, 19 (55.9%) of which resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas. The crash rate for I-4 exceeds the districtwide average crash rate for similar facilities.

Table 15-3: SR 570/Polk Parkway (East) Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	**160**	1	50	109	0.730	0.582
Polk Pkwy E from I-4 to 0.5 miles from I-4	**3**	0	1	2	0.350	0.582[1]
Polk Pkwy E Ramps	**34**	0	19	15	N/A	N/A
Total Interchange and Segments	**197**	**1**	**70**	**126**	-	-
[1]**Using best comparable system: Districtwide Urban Interstate Average Crash rate**						

The top five contributing causes to crashes is shown below in **Table 15-4**. The most common cause, 36.6% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 15-4: SR 570/Polk Parkway (East) Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	72	36.6%
No Contributing Action	28	14.2%
Other Contributing Action	18	9.1%
Failed To Keep in Proper Lane	18	9.1%
Drove Too Fast for Conditions	16	8.1%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B),

Minor Injury (C), and Property Damage Only (O). **Table 15-5** presents the total cost of the five years of crash data.

Table 15-5: SR 570/Polk Parkway (East) Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	1	$10,890,000	$10,890,000
(A) - Severe Injury	2	$888,030	$1,776,060
(B) - Moderate Injury	25	$180,180	$4,504,500
(C) - Minor Injury	43	$103,950	$4,469,850
(O) - Property Damage Only	126	$7,700	$970,200
	Total		**$22,610,610**




Figure 15-1: SR 570/Polk Parkway (East) Interchange Crash Data Heat Map (2015-2019)

16 Mainline Segment: I-4 from SR 570/Polk Parkway (East) to SR 559

The I-4 mainline segment between SR 570/Polk Parkway (East) and SR 559 is a 6-lane divided Urban Interstate facility. According to the collected crash data, 155 total crashes occurred along the mainline segment during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 16-1**. As listed in the table, an average of 31 crashes occurred per year during the most recent available five years. Of these crashes, 54 resulted in injuries while 4 resulted in a fatality.

- The first fatal crash (HSMV #: 85209213) occurred in dark-not lighted conditions on February 16, 2016, on I-4 west of Berkley Road. An eastbound driver lost control of their vehicle which traveled into the center median, collided with the cable barrier and guardrail and overturned. The front seat passenger was pronounced dead at the scene.
- The second fatal crash (HSMV #: 85386314) occurred in daylight conditions on March 21, 2017, on I-4 east of Berkley Road. Two vehicles were traveling eastbound on I-4: one in the center lane and one in the outside lane. The vehicle in the center lane made an improper lane change into the already occupied outside lane, colliding with the other vehicle. The vehicle in the outside lane departed the roadway onto the shoulder and overturned multiple times. The driver of this vehicle was pronounced dead at the scene.
- The third fatal crash (HSMV #: 87234404) occurred in dark-lighted conditions on December 16, 2018, on I-4 west of Berkley Road. Two vehicles were traveling eastbound on I-4: one in the center lane and one in the inside lane. The vehicle in the center lane made an improper lane change into the already occupied inside lane, colliding with the other vehicle. The vehicle in the inside lane departed the roadway into the median and overturned multiple times. The driver of this vehicle was transported but was pronounced dead at the hospital.
- The fourth fatal crash (HSMV #: 88036083) occurred in daylight conditions on July 8, 2019, on I-4 east of Polk Parkway (East). A westbound vehicle was traveling in the center lane approaching two vehicles parked on the inside shoulder. One vehicle was a Road Ranger who had just completed a tire change on the other vehicle. The westbound vehicle left the travel lane and collided with both vehicles on the shoulder. The driver of the westbound vehicle was pronounced dead at the scene.

A total of 60 (38.7% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 12 crashes per year. Additionally, a total of 42 crashes (27.1% of total) occurred on wet roadway surface conditions, averaging 8 crashes per year.

Table 16-1: I-4 Segment (SR 570-E to SR 559) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	30	13	0	12	9
2016	40	15	1	17	9
2017	22	8	1	5	8
2018	30	9	1	13	7
2019	33	9	1	13	9
2015-2019	155	54	4	60	42
Average	31	11	1	12	8
Percent	-	34.8%	2.6%	38.7%	27.1%

Table 16-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (31.0% of total), followed by off road (27.1% of total) and sideswipe (21.9% of total) crashes. There were no pedestrian or bicycle related crashes reported in the most recent available five years.

Table 16-2: I-4 Segment (SR 570-E to SR 559) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	0	0	0.0%
Animal	1	0	0	0	0	1	0.2	0.6%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	0	0	0	0	0	0.0%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	0	0	0	0	0	0	0.0%
Rear End	9	17	6	7	9	48	9.6	31.0%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	2	0	0	1	2	5	1	3.2%
Sideswipe	5	10	4	4	11	34	6.8	21.9%
Off Road	10	8	9	10	5	42	8.4	27.1%
Other	3	5	3	8	6	25	5	16.1%
Total	30	40	22	30	33	155	31	100.0%

As shown in **Table 16-3**, the crash rate for this segment of I-4 does not exceed the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 16-3: I-4 Segment (SR 570-E to SR 559) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	155	4	54	97	0.489	0.582

The top five contributing causes to crashes is shown below in **Table 16-4**. The most common cause, 32.3% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 16-4: I-4 Segment (SR 570-E to SR 559) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	50	32.3%
Failed to Keep in Proper Lane	20	12.9%
Other Contributing Action	20	12.9%
No Contributing Action	18	11.6%
Ran Off Roadway	12	7.7%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 16-5** presents the total cost of the five years of crash data.

Table 16-5: I-4 Segment (SR 570-E to SR 559) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	4	$10,890,000	$43,560,000
(A) - Severe Injury	1	$888,030	$888,030
(B) - Moderate Injury	25	$180,180	$4,504,500
(C) - Minor Injury	28	$103,950	$2,910,600
(O) - Property Damage Only	97	$7,700	$746,900
Total			**$52,610,030**

17 Interchange: I-4 at SR 559

The SR 559 interchange is a traditional diamond interchange with stop-controlled ramp terminal intersections. According to the collected crash data, 203 total crashes occurred within the

interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 17-1**. As listed in the table, an average of 41 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 61 resulted in injuries and 2 resulted in a fatality.

- The first fatal crash (HSMV #: 84558745) occurred in daylight conditions on July 20, 2015, on I-4 just east of SR 559. The driver of a westbound vehicle lost control and the vehicle departed the roadway onto the outside shoulder. The vehicle struck the embankment and later a concrete bridge support at the interchange. The back row passenger was pronounced dead at the scene.
- The second fatal crash (HSMV #: 88141132) occurred in daylight conditions on December 22, 2019, on I-4 east of SR 559. An eastbound vehicle in the center travel lane made an improper lane change and collided with a vehicle already occupying the inside lane. The driver of the vehicle making the lane change lost control and the vehicle spun, striking the guardrail. The unrestrained child passenger in the back row was pronounced dead at the scene.

A total of 78 crashes (38.4%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 16 crashes per year. Additionally, a total of 45 crashes (22.2%) occurred on wet roadway surface conditions, averaging 9 crashes per year.

Table 17-1: SR 559 Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	39	14	1	17	6
2016	59	21	0	23	12
2017	28	5	0	10	5
2018	32	8	0	11	6
2019	45	13	1	17	16
2015-2019	**203**	**61**	**2**	**78**	**45**
Average	***41***	***12***	***0***	***16***	***9***
Percent	**-**	***30.0%***	***1.0%***	***38.4%***	***22.2%***

Table 17-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (24.1% of total) within the study area, followed by off road (20.7% of total) and sideswipe (17.2% of total) crashes. There was 1 pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The pedestrian crash (HSMV #: 85286033) occurred in daylight conditions on May 27, 2016, on SR 559 south of I-4. This crash occurred while the new northbound lanes were under construction. A pedestrian was attempting to cross at an unmarked location and was struck by a northbound vehicle. The pedestrian was transported to the hospital with injuries.

Table 17-2: SR 559 Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	1	2	0	3	1	7	1.4	3.4%
Animal	1	0	0	0	0	1	0.2	0.5%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	1	0	0	1	0.2	0.5%
Left Turn	4	5	1	2	12	24	4.8	11.8%
Pedestrian	0	1	0	0	0	1	0.2	0.5%
Rear End	11	13	7	8	10	49	9.8	24.1%
Right Turn	1	3	0	0	1	5	1	2.5%
Rollover	0	0	0	2	1	3	0.6	1.5%
Sideswipe	5	9	6	10	5	35	7	17.2%
Off Road	10	15	3	3	11	42	8.4	20.7%
Other	6	11	10	4	4	35	7	17.2%
Total	39	59	28	32	45	203	40.6	100.0%

As shown in **Table 17-3**, 66 crashes occurred along SR 559, accounting for 32.5% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this interchange occurred on I-4. A heat map of the crash data is provided at the end of this section (**Figure 17-1**). 97 crashes occurred on I-4, including merge/diverge influence areas, with 26 (26.8%) resulting in an injury. Lastly, 40 crashes occurred on the interchange ramps, 17 (42.5%) of which resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas. The crash rate for SR 559 exceeds the districtwide average crash rate for similar facilities.

Table 17-3: SR 559 Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	97	2	26	69	0.543	0.582
SR 559 from C Fred Jones Blvd to Le Lynn RV Resort	66	0	18	48	3.558	1.509[1]
SR 559 Ramps	40	0	17	23	N/A	N/A
Total Interchange and Segments	203	2	61	140	-	-
[1]Using Districtwide Suburban 4-5 Lane, 2-way, Divided/Raised Median Average Crash rate						

The top five contributing causes to crashes is shown below in **Table 17-4**. The most common cause, 31.5% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 17-4: SR 559 Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	64	31.5%
Failed to Yield Right-of-Way	30	14.8%
No Contributing Action	27	13.3%
Other Contributing Action	20	9.9%
Failed to Keep in Proper Lane	11	5.4%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 17-5** presents the total cost of the five years of crash data.

Table 17-5: SR 559 Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	2	$10,890,000	$21,780,000
(A) - Severe Injury	10	$888,030	$8,880,300
(B) - Moderate Injury	17	$180,180	$3,063,060
(C) - Minor Injury	34	$103,950	$3,534,300
(O) - Property Damage Only	140	$7,700	$1,078,000
Total			**$38,335,660**




Figure 17-1: SR 559 Interchange Crash Data Heat Map (2015-2019)

18 Mainline Segment: I-4 from SR 559 to SR 557

The I-4 mainline segment between SR 559 to SR 557 is a 6-lane divided Rural Interstate facility. According to the collected crash data, 199 total crashes occurred along the mainline segment during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 18-1**. As listed in the table, an average of 40 crashes occurred per year during the most recent available five years. Of these crashes, 70 resulted in injuries while one resulted in a fatality.

- The fatal crash (HSMV #: 89013119) occurred in dark-not lighting conditions on August 9, 2019, on I-4 west of CR 557. A pedestrian was standing in the eastbound travel lanes. An eastbound vehicle tried to avoid colliding with the pedestrian but the pedestrian kept moving towards where the vehicle was heading. Another vehicle was sideswiped in the process of trying to avoid the pedestrian. All occupants of that vehicle were transported with injuries. The pedestrian was pronounced dead at the scene.

A total of 86 (43.2% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 17 crashes per year. Additionally, a total of 61 crashes (30.7% of total) occurred on wet roadway surface conditions, averaging 12 crashes per year.

Table 18-1: I-4 Segment (SR 559 to SR 557) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	33	12	0	14	7
2016	41	11	0	19	11
2017	31	8	0	12	10
2018	48	23	0	22	16
2019	46	16	1	19	17
2015-2019	199	70	1	86	61
Average	40	14	0	17	12
Percent	-	35.2%	0.5%	43.2%	30.7%

Table 18-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (32.2% of total), followed by off road (20.1% of total) and sideswipe (19.1% of total) crashes. There was 1 pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The pedestrian crash (HSMV #: 89013119) was the fatal crash previously summarized.

Table 18-2: I-4 Segment (SR 559 to SR 557) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	0	0	0	0	0	0	0.0%
Animal	0	1	0	0	0	1	0.2	0.5%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	1	0	0	0	0	1	0.2	0.5%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	0	0	0	1	1	0.2	0.5%
Rear End	9	12	8	17	18	64	12.8	32.2%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	2	3	2	2	1	10	2	5.0%
Sideswipe	4	3	5	11	15	38	7.6	19.1%
Off Road	9	8	7	12	4	40	8	20.1%
Other	8	14	9	6	7	44	8.8	22.1%
Total	33	41	31	48	46	199	39.8	100.0%

As shown in **Table 18-3**, the crash rate for this segment of I-4 does not exceed the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 18-3: I-4 Segment (SR 559 to SR 557) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	199	0	71	128	0.365	0.435

The top five contributing causes to crashes is shown below in **Table 18-4**. The most common cause, 35.2% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 18-4: I-4 Segment (SR 559 to SR 557) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	70	35.2%
No Contributing Action	27	13.6%
Failed to Keep in Proper Lane	19	9.6%
Other Contributing Action	18	9.1%
Ran Off Roadway	10	5.0%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 18-5** presents the total cost of the five years of crash data.

Table 18-5: I-4 Segment (SR 559 to SR 557) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	0	$10,890,000	$0
(A) - Severe Injury	5	$888,030	$4,440,150
(B) - Moderate Injury	27	$180,180	$4,864,860
(C) - Minor Injury	39	$103,950	$4,054,050
(O) - Property Damage Only	128	$7,700	$985,600
Total			**$14,344,660**

19 Interchange: I-4 at SR 557

The SR 557 interchange is a partial cloverleaf interchange with stop-controlled intersections. According to the collected crash data, 215 total crashes occurred within the interchange area during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 19-1**. As listed in the table, an average of 43 crashes occurred per year in the interchange area during the most recent available five years. Of these crashes, 79 resulted in injuries and 4 resulted in a fatality.

- The first fatal crash (HSMV #: 83783653) occurred in dark-not lighted conditions on November 2, 2015, at the intersection of CR 557 and the eastbound I-4 ramps. A semi-truck was westbound at the intersection with a northbound vehicle approaching from the south. The semi-truck failed to yield right-of-way to CR 557 traffic and turned out in front of the northbound vehicle. The northbound vehicle struck the trailer of the semi-truck. The driver of the northbound vehicle was transported but later pronounced dead at the hospital.
- The second fatal crash (HSMV #: 86446490) occurred in daylight conditions on November 12, 2016, on CR 557 north of I-4. The narrative in the long form is very brief but from the inputted fields this crash seemed to involve a semi-truck making a northbound left-turn onto the westbound I-4 on ramp and a southbound motorcycle on CR 557. The semi-truck failed to yield right-of-way and the motorcycle struck the semi-truck. The motorcyclist was pronounced dead.
- The third fatal crash (HSMV #: 87265140) occurred in daylight conditions on August 29, 2018, on I-4 at the interchange of CR 557. The driver of a westbound vehicle lost control and collided with the interchange embankment causing the vehicle to become airborne and ultimately roll. The driver was under the influence of multiple substances. The front seat passenger was pronounced dead at the scene and rear seat passenger was transported but later pronounced dead at the hospital.
- The fourth fatal crash (HSMV #: 87288468) occurred in dark-lighted conditions on August 30, 2018, on I-4 west of CR 557. A pedestrian was on the westbound outside shoulder after stopping their vehicle after an argument with other occupants of the vehicle. The pedestrian then stepped out into the westbound travel lanes where a vehicle struck the pedestrian. The pedestrian was pronounced dead at the scene.

A total of 100 crashes (46.5%) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 20 crashes per year. Additionally, a total of 74 crashes (34.4%) occurred on wet roadway surface conditions, averaging 15 crashes per year.

Table 19-1: SR 557 Interchange Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	27	12	1	13	10
2016	47	21	1	25	12
2017	38	12	0	17	16
2018	38	6	2	17	17
2019	65	28	0	28	19
2015-2019	215	79	4	100	74
Average	43	16	1	20	15
Percent	-	36.7%	1.9%	46.5%	34.4%

Table 19-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (32.1% of total) within the study area, followed by off road (23.3% of total) and sideswipe (13.0% of total) crashes. There was 1 pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The pedestrian crash (HSMV #: 87288468) was the fourth fatal crash previously summarized.

Table 19-2: SR 557 Interchange Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	2	0	1	0	0	3	0.6	1.4%
Animal	0	0	0	0	0	0	0	0.0%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	1	0	0	1	0.2	0.5%
Left Turn	3	3	0	0	2	8	1.6	3.7%
Pedestrian	0	0	0	1	0	1	0.2	0.5%
Rear End	7	16	9	13	24	69	13.8	32.1%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	2	2	2	2	5	13	2.6	6.0%
Sideswipe	4	6	7	2	9	28	5.6	13.0%
Off Road	8	9	10	8	15	50	10	23.3%
Other	1	11	8	12	10	42	8.4	19.5%
Total	27	47	38	38	65	215	43	100.0%

As shown in **Table 19-3**, 26 crashes occurred along SR 557, accounting for 12.1% of total crashes in the interchange area. It is noted that the heaviest concentration of crashes at this

interchange occurred on I-4. A heat map of the crash data is provided at the end of this section (**Figure 19-1**). 128 crashes occurred on I-4, including merge/diverge influence areas, with 46 (35.9%) resulting in an injury. Lastly, 61 crashes occurred on the interchange ramps, 18 (29.5%) of which resulted in an injury. It should be noted that some of the crashes along the interchange ramps may have been influenced by the merge/diverge influence areas. The crash rates for I-4 and SR 557 exceed the districtwide average crash rates for similar facilities.

Table 19-3: SR 557 Interchange Crash Summary by Location (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	**128**	2	46	80	0.705	0.482
SR 557 from 0.35 miles south of I-4 to 0.35 miles north of I-4	**26**	0	15	11	1.418	0.757[1]
SR 557 Ramps	**61**	2	18	41	N/A	N/A
Total Interchange and Segments	**215**	**4**	**79**	**132**	-	-
[1]Using Districtwide Rural 2-3 Lane, 2-way, Undivided Average Crash rate						

The top four contributing causes to crashes is shown below in **Table 19-4**. The most common cause, 32.6% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 19-4: SR 557 Interchange Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	70	32.6%
No Contributing Action	29	13.5%
Drove Too Fast for Conditions	22	10.2%
Other Contributing Action	17	7.9%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 19-5** presents the total cost of the five years of crash data.

Table 19-5: SR 557 Interchange KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	4	$10,890,000	$43,560,000
(A) - Severe Injury	7	$888,030	$6,216,210
(B) - Moderate Injury	27	$180,180	$4,864,860
(C) - Minor Injury	45	$103,950	$4,677,750
(O) - Property Damage Only	132	$7,700	$1,016,400
	Total		**$60,335,220**




Figure 19-1: SR 557 Interchange Crash Data Heat Map (2015-2019)

20 Mainline Segment: I-4 from SR 557 to West of US 27

The I-4 mainline segment between SR 557 to west of US 27 is a 6-lane divided Rural Interstate facility. According to the collected crash data, 588 total crashes occurred along the mainline segment during the five-year period. A summary of crashes sorted by severity and environmental conditions is provided in **Table 20-1**. As listed in the table, an average of 118

crashes occurred per year during the most recent available five years. Of these crashes, 208 resulted in injuries while 4 resulted in a fatality.

- The first fatal crash (HSMV #: 86312359) occurred in dark-not lighted conditions on January 8, 2017, on I-4 west of US 27. The narrative in the long form is very brief but from the inputted fields this crash seemed to involve a disabled vehicle in the eastbound travel lane with the driver trying to push the vehicle onto the shoulder. This vehicle may have been disabled by some debris upstream. Another eastbound vehicle was avoiding this debris when it struck the individual pushing their vehicle. This pedestrian was pronounced dead after the collision.
- The second fatal crash (HSMV #: 85185760) occurred in daylight conditions on July 8, 2017, on I-4 at mile marker 51. A driver of an eastbound vehicle failed to notice stopped traffic and swerved to avoid a rear end collision but overcorrected, causing the vehicle to overturn multiple times and eject the driver. The driver was transported but pronounced dead at the hospital.
- The third fatal crash (HSMV #: 85574395) occurred in daylight conditions on February 18, 2018, on I-4 east of CR 557. The driver of an eastbound vehicle lost control and drove into the median, causing a collision with the cable barriers and subsequent rollover. The vehicle rolled into the westbound travel lanes, striking a westbound vehicle. The driver of the eastbound vehicle was transported but later pronounced dead at the hospital.
- The fourth fatal crash (HSMV #: 87288474) occurred at dusk on October 4, 2018, on I-4 east of CR 557. The driver of a westbound vehicle lost control and ran off the roadway onto the outside shoulder. The vehicle struck a wire fence, entered a water filled marsh and began to overturn. The driver was pronounced dead at the scene.

A total of 215 (36.6% of total) were reported to have occurred during dark conditions (at night, dawn, or dusk), averaging 43 crashes per year. Additionally, a total of 128 crashes (21.8% of total) occurred on wet roadway surface conditions, averaging 26 crashes per year.

Table 20-1: I-4 Segment (SR 557 to West of US 27) Crash Summary by Severity and Conditions (2015-2019)

Year	Total Number of Crashes	Injury Crashes	Fatal Crashes	Dark Conditions Crashes	Wet Conditions Crashes
2015	100	35	0	44	24
2016	101	41	0	37	13
2017	94	23	2	22	18
2018	144	62	2	51	28
2019	149	47	0	61	45
2015-2019	**588**	**208**	**4**	**215**	**128**
Average	**118**	**42**	**1**	**43**	**26**
Percent	-	**35.4%**	**0.7%**	**36.6%**	**21.8%**

Table 20-2 summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (45.2% of total), followed by off road (18.2% of total) and sideswipe (12.9%

of total) crashes. There was 1 pedestrian related crash and no bicycle related crashes reported in the most recent available five years.

- The pedestrian crash (HSMV #: 86312359) was the first fatal crash previously summarized.

Table 20-2: I-4 Segment (SR 557 to West of US 27) Crash Summary by Crash Types (2015-2019)

Crash Type	2015	2016	2017	2018	2019	2015-2019	Per year	Percent
Angle	0	2	0	0	2	4	0.8	0.7%
Animal	0	2	0	0	2	4	0.8	0.7%
Bicycle	0	0	0	0	0	0	0	0.0%
Head On	0	0	0	0	0	0	0	0.0%
Left Turn	0	0	0	0	0	0	0	0.0%
Pedestrian	0	0	1	0	0	1	0.2	0.2%
Rear End	36	45	46	74	65	266	53.2	45.2%
Right Turn	0	0	0	0	0	0	0	0.0%
Rollover	4	7	0	7	4	22	4.4	3.7%
Sideswipe	16	13	12	16	19	76	15.2	12.9%
Off Road	23	14	16	26	28	107	21.4	18.2%
Other	21	18	19	21	29	108	21.6	18.4%
Total	100	101	94	144	149	588	117.6	100.0%

As shown in **Table 20-3**, the crash rate for this segment of I-4 exceeds the districtwide average rate for similar facilities. **Figure 21-1** and **Figure 21-2** in **Section 21** show the crash types and heat map for the entire study corridor.

Table 20-3: I-4 Segment (SR 557 to West of US 27) Crash Rate Summary (2015-2019)

Location	Total	Fatal Crashes	Injury Crashes	Property Damage Only	Study Crash Rate (per MVM)	Districtwide Crash Rate
On I-4	588	4	208	376	0.561	0.435

The top five contributing causes to crashes is shown below in **Table 20-4**. The most common cause, 46.8% of all crashes, was driving in a careless or negligent manner. This can include actions such as aggressive driving, following too closely, texting and driving, and failure to indicate lane changes.

Table 20-4: I-4 Segment (SR 557 to West of US 27) Contributing Causes of Crashes (2015-2019)

Contributing Cause	Number of Crashes	Percent of all Crashes
Careless or Negligent Manner	275	46.8%
No Contributing Action	70	11.9%
Other Contributing Action	66	11.2%
Failed to Keep in Proper Lane	32	5.4%
Ran Off Roadway	24	4.1%

A "cost to society" estimate was also calculated with the crash data at this interchange using KABCO crash costs as defined in the 2019 FDOT Design Manual (FDM). The KABCO scale defines an average cost per crash based on severity: Fatal (K), Severe Injury (A), Moderate Injury (B), Minor Injury (C), and Property Damage Only (O). **Table 20-5** presents the total cost of the five years of crash data.

Table 20-5: I-4 Segment (SR 557 to West of US 27) KABCO Crash Costs (2015-2019)

Crash Severity	Occurrences	FDOT KABCO Crash Costs	Total Cost
(K) - Fatal	4	$10,890,000	$43,560,000
(A) - Severe Injury	11	$888,030	$9,768,330
(B) - Moderate Injury	71	$180,180	$12,792,780
(C) - Minor Injury	126	$103,950	$13,097,700
(O) - Property Damage Only	376	$7,700	$2,895,200
Total			**$82,114,010**

21 Full I-4 Study Corridor Crashes

Figure 21-1 on the following pages displays all crashes that occurred in the most recent available five years of certified data along the I-4 corridor as well as the study interchange cross streets and ramps. Crashes are symbolized by the most common crash types including rear end, off road, sideswipe, rollover, and left turn. All pedestrian and bicycle related crashes are also displayed with different symbology. About 54.8% of all I-4 mainline crashes occurred in the eastbound direction while about 45.2% of all I-4 mainline crashes occurred in the westbound direction.

Figure 21-2 displays the hot spots along the I-4 mainline with fatal crashes called out. Most hot spots are located at the interchange ramp junctions but there are a few spots not associated with an interchange ramp. Between the US 98 and N Socrum Loop Road & SR 33/Lakeland Hills Boulevard interchange, near the Carpenters Way bridge, there is a dense cluster of crashes. There are a few clusters of crashes just west of the SR 33 interchange. There are also a few hot

spots between the SR 557 interchange and the US 27 interchange. Additional heat maps for wet weather, dark conditions, and crash severity (fatal and injury) are provided in **Appendix B**.

N

0 0.25 0.5 Miles

BEGIN STUDY

INTERSTATE 4

92

POLK PKWY

TOLL 570

COUNTY LINE RD

ALLEN K BREED HWY

OLD TAMPA HWY/CR542




Sheet 1 of 22

Legend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- All Other
- Bicycle
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

N GALLOWAY RD

INTERSTATE 4

W 10TH ST

WABASH AVE

546

92



Sheet 3 of 22


FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)




FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


Miles
0 0.25 0.5

98

INTERSTATE 4

33

LAKELAND HILLS BLVD



Sheet 6 of 22

FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


Miles
0 0.25 0.5

N SOCRUM LOOP RD

INTERSTATE 4

33

OLD COMBEE RD



Sheet 7 of 22

FDOT

Legend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- All Other
- Bicycle
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

N SOCRUM LOOP RD

OLD POLK CITY RD

INTERSTATE 4

33

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 8 of 22

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

Miles
0 0.25 0.5

UNIVERSITY BLVD

INTERSTATE 4

33



Sheet 9 of 22


FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 10 of 22

FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5


OLD POLK CITY RD

33

INTERSTATE 4

RESEARCH WAY

UNIVERSITY BLVD



Sheet 11 of 22

FDOT

Legend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- All Other
- Bicycle
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

OLD POLK CITY RD

33


INTERSTATE 4

TOLL 570

POLK PKWY

MOUNT OLIVE RD

RESEARCH WAY



Sheet 12 of 22


FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Legend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- All Other
- Bicycle
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

BERKLEY RD/SR-559

559

INTERSTATE 4

98

Lakeland

Auburndale

City

Sheet 14 of 22

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

CR 557A

559

INTERSTATE 4

98

Auburndale

Lakeland

City

Sheet 15 of 22

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type


Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

CR 557A

INTERSTATE 4



Sheet 16 of 22

FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

557

CR-557

INTERSTATE 4

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 17 of 22

FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

557

INTERSTATE 4

CR-557

98

Auburndale

Lakeland

City


Sheet 18 of 22

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 19 of 22


FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5




Sheet 21 of 22

Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)




Legend

- Rear End
- Sideswipe
- Left Turn
- Bicycle
- Off Road
- Rollover
- All Other
- Pedestrian

Figure 21-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Crash Density

Low

High

Fatal Crashes (0)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Crash Density

Low

High

Fatal Crashes (1)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)





Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



Crash Density


Low

High

Fatal Crashes (4)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Crash Density

Low

High

Fatal Crashes (5)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)





Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Crash Density


Low

High

Fatal Crashes (4)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 8 of 22

Crash Density

Low

High

Fatal Crashes (3)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)





Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 10 of 22

FDOT

Crash Density


Low

High

Fatal Crashes (2)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Crash Density

Low

High

Fatal Crashes (2)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

OLD POLK CITY RD

33

Crash ID: 88036083
Crash Type: Other
Lighting: Daylight
Road Surface: Dry

MOUNT OLIVE RD

INTERSTATE 4


Crash ID: 85501136
Crash Type: Other
Lighting: Daylight
Road Surface: Dry

Crash ID: 85254516
Crash Type: Rear End
Lighting: Dark - Lighted
Road Surface: Dry

TOLL 570

POLK PKWY

RESEARCH WAY



Sheet 12 of 22

FDOT

Crash Density


Low

High

Fatal Crashes (3)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Crash Density

Low

High

Fatal Crashes (4)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

559


Crash ID: 84558745
Crash Type: Off Road
Lighting: Daylight
Road Surface: Dry

INTERSTATE 4

Crash ID: 85386314
Crash Type: Sideswipe
Lighting: Daylight
Road Surface: Dry

Crash ID: 88141132
Crash Type: Off Road
Lighting: Daylight
Road Surface: Wet

BERKLEY RD/SR-559



Sheet 14 of 22

FDOT

Crash Density

Low

High

Fatal Crashes (3)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)




Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)




Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

Crash ID: 87265140
Crash Type: Other
Lighting: Daylight
Road Surface: Dry


Crash ID: 87288468
Crash Type: Pedestrian
Lighting: Dark - Lighted
Road Surface: Wet

Crash ID: 89013119
Crash Type: Pedestrian
Lighting: Dark - Not Lighted
Road Surface: Dry

INTERSTATE 4

557

CR-557



Sheet 17 of 22

FDOT

Crash Density


Low

High

Fatal Crashes (3)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Crash Density

Low

High

Fatal Crashes (3)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map


Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

Crash ID: 87288474
Crash Type: Off Road
Lighting: Dusk
Road Surface: Dry

Crash ID: 85574395
Crash Type: Rollover
Lighting: Daylight
Road Surface: Dry



Sheet 19 of 22

Crash Density
Low
High

Fatal Crashes (2)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

Miles
0 0.25 0.5

Crash ID: 85185760
Crash Type: Other
Lighting: Daylight
Road Surface: Dry

Crash ID: 87288474
Crash Type: Off Road
Lighting: Dusk
Road Surface: Dry

Crash ID: 85574395
Crash Type: Rollover
Lighting: Daylight
Road Surface: Dry



Sheet 20 of 22

FDOT

Crash Density
Low
High

Fatal Crashes (3)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map


Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

Crash ID: 86312359
Crash Type: Pedestrian
Lighting: Dark - Not Lighted
Road Surface: Dry

Crash ID: 85185760
Crash Type: Other
Lighting: Daylight
Road Surface: Dry



Sheet 21 of 22

Crash Density
Low
High

Fatal Crashes (2)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


0 0.25 0.5 Miles

END STUDY

27

INTERSTATE 4

Crash ID: 86312359
Crash Type: Pedestrian
Lighting: Dark - Not Lighted
Road Surface: Dry



Sheet 22 of 22

FDOT

Crash Density

Low

High

Fatal Crashes (1)

Figure 21-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

22 Review of Most Recent Data (January 2020 – May 2022)


The most recent available (uncertified) crash data for 2020 – May 2022 was collected from SSOGIS and Signal Four Analytics in order to compare crash trends and hotspots with the certified data from 2015 – 2019.

Figure 22-1 on the following pages displays all crashes that occurred in the most recent available two and a half years along the I-4 corridor as well as the study interchange cross streets and ramps. Crashes are symbolized the same as **Figure 21-1**. **Figure 22-2** displays the hot spots along the I-4 mainline with fatal crashes called out.

The intent of reviewing the most recent crash data was to compare trends and hot spots to the five-year certified data set. No major changes in crash frequency or hotspot locations were observed when comparing the two data sets. **Table 22-1** summarizes crashes by type. According to the summary, rear end crashes account for the most crashes (36.4% of total) within the study area, followed by sideswipe (18.7% of total) and off road (18.6% of total) crashes, which is similar to the 5-year certified data. There were five pedestrian related crashes and two bicycle related crashes reported in the most recent available two and a half years.

Table 22-1: I-4 Mainline and Cross Streets Crash Summary by Crash Types (2020-May 2022)

Crash Type	2020	2021	2022	2020-2022	Per year	Percent
Angle	13	15	1	**29**	**10**	**1.3%**
Animal	0	1	0	**1**	**0**	**0.0%**
Bicycle	3	3	0	**6**	**2**	**0.3%**
Head On	3	3	1	**7**	**2**	**0.3%**
Left Turn	58	37	10	**105**	**35**	**4.8%**
Pedestrian	6	8	1	**15**	**5**	**0.7%**
Rear End	368	293	130	**791**	**264**	**36.4%**
Right Turn	5	4	2	**11**	**4**	**0.5%**
Rollover	37	20	8	**65**	**22**	**3.0%**
Sideswipe	204	146	57	**407**	**136**	**18.7%**
Off Road	197	168	39	**404**	**135**	**18.6%**
Other	150	140	42	**332**	**111**	**15.3%**
Total	***1044***	***838***	***291***	***2173***	***724***	***100.0%***




FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 2 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

Miles
0 0.25 0.5

INTERSTATE 4

W 10TH ST

N GALLOWAY RD

WABASH AVE

92

546

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 3 of 22

FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

KNIGHTS STATION RD

GRIFFIN RD

PROVIDENCE RD

539

KATHLEEN RD


INTERSTATE 4

W 10TH ST

WABASH AVE

N BRUNNELL PKWY

N GALLOWAY RD



Sheet 4 of 22

FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

98

INTERSTATE 4

33


LAKELAND HILLS BLVD

GRIFFIN RD

KATHLEEN RD

PROVIDENCE RD

N FLORIDA AVE



Sheet 5 of 22

FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

98

INTERSTATE 4

33

LAKELAND HILLS BLVD

Lakeland

Auburndale

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 6 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

Miles
0 0.25 0.5

N SOCRUM LOOP RD

INTERSTATE 4

33

OLD COMBEE RD

98

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Lakeland

Auburndale

City

Sheet 7 of 22

FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

N SOCRUM LOOP RD

OLD POLK CITY RD

INTERSTATE 4

33

98

Lakeland

Auburndale

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 8 of 22


FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 9 of 22

FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N


0 0.25 0.5 Miles

OLD POLK CITY RD

33

INTERSTATE 4

UNIVERSITY BLVD



Sheet 10 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)




Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 12 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

INTERSTATE 4

MOUNT OLIVE RD

BERKLEY RD/SR-559

559

POLK PKWY

TOLL 570



Sheet 13 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

Miles

0 0.25 0.5

559

4

BERKLEY RD/SR-559

98

Auburndale

Lakeland

City

Sheet 14 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)


N

0 0.25 0.5 Miles

CR 557A

559

INTERSTATE 4



Sheet 15 of 22

FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type


Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

CR 557A

INTERSTATE 4



Sheet 16 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

557

INTERSTATE 4

CR-557

98

Auburndale

Lakeland

City

Sheet 17 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

INTERSTATE 4

557

CR-557

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 18 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian


Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

INTERSTATE 4



Ledgend


- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

Miles
0 0.25 0.5



Sheet 20 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian


Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

Miles
0 0.25 0.5

INTERSTATE 4



Sheet 21 of 22

FDOT

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

END STUDY

27

INTERSTATE 4

98

Auburndale

Lakeland

City


Sheet 22 of 22

Ledgend

- Rear End
- Off Road
- Sideswipe
- Rollover
- Left Turn
- Other
- Bicycle
- Pedestrian

Figure 22-1: I-4 Master Plan Study Crashes by Type

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



FDOT

Crash Density

Low

High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)





Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



FDOT

Crash Density


Low

High

Fatal Crashes (2)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 4 of 22

FDOT

Crash Density

Low

High

Fatal Crashes (2)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

INTERSTATE 4

98

539

33

LAKELAND HILLS BLVD

GRIFFIN RD

KATHLEEN RD


PROVIDENCE RD

N FLORIDA AVE

Crash ID: 88262379
Crash Type: Other
Lighting: Daylight
Road Surface: Wet

Crash ID: 88309194
Crash Type: Sideswipe
Lighting: Daylight
Road Surface: Dry

Crash ID: 24894757
Crash Type: Pedestrian
Lighting: Daylight
Road Surface: Dry



Sheet 5 of 22

FDOT

Crash Density
Low
High

Fatal Crashes (3)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

N SOCRUM LOOP RD

LAKELAND HILLS BLVD


33

98

INTERSTATE 4

Crash ID: 88335717
Crash Type: Off Road
Lighting: Dark - Lighted
Road Surface: Dry

Crash ID: 88262379
Crash Type: Other
Lighting: Daylight
Road Surface: Wet



Sheet 6 of 22

FDOT

Crash Density

Low

High

Fatal Crashes (2)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles


INTERSTATE 4

N SOCRUM LOOP RD

33

OLD COMBEE RD

Crash ID: 88335717
Crash Type: Off Road
Lighting: Dark - Lighted
Road Surface: Dry



Sheet 7 of 22


FDOT

Crash Density
Low
High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 8 of 22

FDOT

Crash Density


Low

High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 9 of 22

Crash Density


Low

High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



FDOT

Crash Density


Low

High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 11 of 22

FDOT

Crash Density

Low

High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

OLD POLK CITY RD

33

Crash ID: 88127694
Crash Type: Off Road
Lighting: Dark - Lighted
Road Surface: Dry

MOUNT OLIVE RD


INTERSTATE 4

Crash ID: 85520468
Crash Type: Rollover
Lighting: Dawn
Road Surface: Dry

POLK PKWY

TOLL 570

RESEARCH WAY



Sheet 12 of 22

FDOT

Crash Density
Low
High

Fatal Crashes (2)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)





Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 14 of 22

FDOT

Crash Density

Low

High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)


N

0 0.25 0.5 Miles

CR 557A

559

INTERSTATE 4



Sheet 15 of 22

FDOT

Crash Density


Low

High

Fatal Crashes (0)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



Sheet 16 of 22

FDOT

Crash Density

Low

High

Fatal Crashes (0)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N


0 0.25 0.5 Miles

Crash ID: 88454958
Crash Type: Unknown
Lighting: Dark - Not Lighted
Road Surface: Dry

557

INTERSTATE 4

CR-557



Sheet 17 of 22

FDOT

Crash Density
Low
High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)



FDOT

Crash Density

Low

High

Fatal Crashes (1)


Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

Crash ID: 88454958
Crash Type: Unknown
Lighting: Dark - Not Lighted
Road Surface: Dry



Sheet 19 of 22

Crash Density
Low
High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map


Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

Miles
0 0.25 0.5

Crash ID: 25109965
Crash Type: Rollover
Lighting: Dusk
Road Surface: Dry

INTERSTATE 4



Sheet 20 of 22


FDOT

Crash Density
Low
High

Fatal Crashes (1)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022)
and S4 Analytics (2020 - May 2022)



FDOT

Crash Density

Low

High

Fatal Crashes (3)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

N

0 0.25 0.5 Miles

END STUDY

Crash ID: 24683823
Crash Type: Off Road
Lighting: Daylight
Road Surface: Wet

Crash ID: 88390089
Crash Type: Off Road
Lighting: Dark - Not Lighted
Road Surface: Dry

27

INTERSTATE 4



Sheet 22 of 22

FDOT

Crash Density
Low
High

Fatal Crashes (2)

Figure 22-2: I-4 Master Plan Study Crashes Heat Map

Crash Data Source: FDOT SSOGis (2020 - May 2022) and S4 Analytics (2020 - May 2022)

23 Next Steps

Based on a detailed review of the certified and uncertified historical crash data analyzed in Phase 2, safety needs and areas of concern will be identified and further evaluated as part of the Phase 2 Master Plan Study. Following this evaluation, safety improvement recommendations will be presented to address correctable safety concerns in future study documents. The *Facility Operations and Preservation Element Report* will present short term improvements while the *Facility Enhancement Element Report* will recommend large-scale, long-term improvements.

Appendix A – Crash Data

2015 – 2019

Certified SSOGIS

Interchange: I-4 at SR 570/Polk Parkway (West) (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	83790726	1/30/2015	1832	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
2	81955247	2/4/2015	840	POLK PKWY	SR 570 WB	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
3	84551359	3/31/2015	1105	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
4	84501395	4/21/2015	1504	SR 400	MM 26	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
5	84527397	5/22/2015	1320	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
6	83741191	5/24/2015	0	POLK PKWY	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	02 CLOUDY	2	0	1	0	0
7	84516877	6/4/2015	1715	SR 570	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
8	84531287	7/14/2015	1710	POLK PKWY	SR 570 WB	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
9	84531303	8/7/2015	700	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
10	81977394	8/15/2015	35	POLK PKWY	SR 570 WB	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	2	0	0
11	81977401	8/15/2015	38	POLK PKWY	SR 570 WB	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
12	84876270	8/24/2015	715	SR 400	MILE MARKER #27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
13	81955254	8/26/2015	1055	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
14	83785211	8/28/2015	2245	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
15	84489399	9/5/2015	1726	I 4	COUNTY LINE RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
16	85161078	9/12/2015	932	POLK PKWY	SR 570 WB	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
17	84541370	9/21/2015	340	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
18	85154050	10/17/2015	1710	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
19	85152915	10/21/2015	824	SR 400	POLK PKWY	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
20	84862151	10/23/2015	155	I 4	POLK PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
21	86084787	11/19/2015	752	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	3	0	0
22	86084843	11/21/2015	100	I 4	POLK PKWY	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
23	81977404	11/24/2015	1820	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
24	85150389	12/26/2015	425	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
25	81955256	1/3/2016	425	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
26	85254512	1/13/2016	1514	I 4	COUNTY LINE RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
27	85148533	3/10/2016	1020	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
28	85226942	3/14/2016	1135	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	2	0	0
29	85246902	3/15/2016	1235	SR 400	MM 26	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
30	83788390	3/19/2016	407	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
31	83666837	3/23/2016	2030	SR 570	SR 400	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
32	85254895	4/26/2016	1900	I 4	COUNTY LINE RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
33	85274109	4/28/2016	1510	SR 400	MILE MARKER #26	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
34	85252571	5/4/2016	1040	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
35	85294948	5/6/2016	1901	I 4	POLK PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
36	86444929	5/12/2016	700	SR 400	COUNTYLINE RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
37	83786267	5/23/2016	805	SR 570	SR 400	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
38	85254629	6/2/2016	2140	I 4	POLK PKWY	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	2	0	0
39	85263333	6/5/2016	1404	I 4	MILE MARKER #26	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
40	85161083	6/25/2016	2026	SR 570	CLARK RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
41	85351931	8/23/2016	640	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	03 DAWN	04 FOG, SMOG, SMOKE	2	0	0	0	0
42	83666846	9/1/2016	1135	SR 570	SR 400	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
43	85341118	10/17/2016	800	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
44	85341122	10/21/2016	930	SR 400	MILE MARKER #26	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
45	85161087	10/30/2016	1630	SR 570	SR 600	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
46	83685091	11/13/2016	615	SR 570	SR 400	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
47	84881128	11/25/2016	1700	I 4	CLARK RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
48	85363536	12/20/2016	820	SR 570	I 4	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	77 OTHER EXPLAIN IN NARRATIVE	01 DAYLIGHT	04 FOG, SMOG, SMOKE	1	0	1	0	0
49	85383709	1/26/2017	1700	SR 400	MM 26	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
50	85420918	2/15/2017	600	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
51	85442328	3/5/2017	1715	SR 570	I 4	01 OVERTURN/ROLLOVER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
52	85411921	3/18/2017	1100	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
53	81955272	5/31/2017	1815	SR 570	SR 400	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
54	81955273	6/6/2017	1640	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
55	85185757	6/11/2017	1240	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
56	85474720	6/15/2017	1640	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
57	85534280	6/16/2017	1055	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
58	83666856	7/10/2017	1945	SR 570	SR 400	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	1	0	0
59	85151368	7/19/2017	47	I 4	MM 27	27 GUARDRAIL FACE	88 UNKNOWN	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
60	85494953	7/30/2017	1450	SR 570	I 4	27 GUARDRAIL FACE	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
61	81955275	8/11/2017	515	SR 570	SR 400	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
62	85474741	8/16/2017	1800	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
63	85573849	8/24/2017	832	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
64	85148548	8/25/2017	1840	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
65	85148549	8/25/2017	1955	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	03 RAIN	2	0	2	1	0
66	85148550	8/26/2017	1525	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
67	85148551	8/26/2017	1615	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
68	85568618	8/31/2017	1940	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	3	0	0	0	0
69	85501763	9/18/2017	627	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
70	83789908	10/7/2017	705	SR 570	SR 400	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
71	85568638	10/12/2017	1350	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
72	85532615	10/24/2017	2245	SR 400	MILE MARKER #26	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
73	85494958	10/26/2017	712	SR 570	SR 600	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
74	85577814	11/10/2017	420	I 4	HILLSBOROUGH CO LINE	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
75	85494964	12/5/2017	1027	SR 570	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
76	85532626	12/16/2017	2109	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
77	85573888	12/20/2017	1655	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
78	81977415	2/12/2018	5	POLK PKWY	OLD TAMPA HIGHWAY	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
79	87147980	3/6/2018	239	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
80	85163017	3/15/2018	752	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
81	85603199	3/22/2018	1720	SR 400	MM 26	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
82	87139813	3/31/2018	2320	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	4	0	0
83	87795567	4/3/2018	1653	SR 570	US 92	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
84	85595332	4/11/2018	1550	SR 400	MM 26	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
85	85603207	4/13/2018	1735	SR 400	MM 26	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Interchange: I-4 at SR 570/Polk Parkway (West) (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	87157583	5/2/2018	1505	I 4	COUNTY LINE RD	27 GUARDRAIL FACE	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
87	85595339	5/4/2018	1255	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
88	87196876	5/11/2018	1258	I 4	CLARK RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	6	0	1	0	0
89	87195898	5/12/2018	1200	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
90	87189052	5/15/2018	2330	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
91	85150801	5/17/2018	830	SR 570	SR 400	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
92	85163020	5/26/2018	1234	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
93	87158159	6/15/2018	320	SR 400	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
94	85595349	6/22/2018	1130	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
95	87157597	6/23/2018	1234	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
96	85595354	7/3/2018	1500	SR 400	MM 27	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
97	87195910	7/3/2018	1520	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
98	87170456	7/13/2018	241	SR 570	I 4	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
99	85595357	8/1/2018	2110	SR 400	MM 27	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
100	87276939	8/23/2018	1636	SR 400	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
101	87277087	8/23/2018	1645	SR 400	MM 27	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	1	0
102	87170460	8/27/2018	1407	SR 400	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
103	85148571	8/30/2018	1350	SR 570	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
104	87276687	9/2/2018	2125	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
105	87112623	9/4/2018	1435	SR 400	MM 27	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
106	87195940	10/4/2018	615	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
107	87157616	10/5/2018	2240	I 4	SR 570	07 THROWN OR FALLING OBJECT	88 UNKNOWN	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
108	87220289	10/8/2018	1100	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
109	87195942	10/11/2018	1745	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
110	87288480	10/19/2018	1245	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
111	87188747	11/1/2018	1807	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
112	87208595	11/5/2018	1140	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
113	88036018	11/10/2018	1330	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	2	0	0
114	87188751	11/30/2018	1216	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
115	87174305	12/3/2018	845	SR 570	SR 400	27 GUARDRAIL FACE	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
116	88036023	12/3/2018	1240	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
117	87276710	12/16/2018	1715	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
118	85148575	12/18/2018	1350	SR 570	SR 400	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
119	88056102	1/8/2019	1525	SR 400	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
120	87235566	1/10/2019	1419	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	4	0	1	0	0
121	88063467	1/17/2019	2255	SR 570	I 4	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
122	87188757	2/2/2019	1005	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	1	0	0	0	0
123	87188759	2/9/2019	720	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
124	88070821	2/17/2019	1220	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
125	82831868	2/25/2019	1300	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
126	88063469	2/25/2019	1320	SR 570	I 4	15 PARKED MOTOR VEHICLE	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
127	87276981	3/5/2019	1209	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
128	87288505	3/8/2019	1200	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
129	87189666	3/23/2019	140	SR 400	MM 27	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
130	87174309	4/8/2019	730	SR 570	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	1	0	0
131	88046254	4/29/2019	3	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
132	87276849	5/11/2019	1150	I 4	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	3	0	0
133	88089074	5/17/2019	1749	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
134	88141208	5/26/2019	1912	SR 400	MILE MARKER #26	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
135	87188767	6/5/2019	1609	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
136	87188768	6/9/2019	1533	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
137	89012131	6/11/2019	2201	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
138	85364878	6/21/2019	2020	SR 570	SR 400	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
139	87221115	6/26/2019	2055	SR 400	EB ENT FROM CLARK RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
140	88046257	7/20/2019	1630	SR 400	SR 570	15 PARKED MOTOR VEHICLE	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
141	88168901	7/21/2019	1915	SR 400	MILE MARKER #27	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
142	87188774	8/15/2019	703	SR 570	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
143	89012968	8/17/2019	1836	SR 570	US 92	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
144	85150816	8/18/2019	715	SR 570	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
145	88226771	11/8/2019	17	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
146	88162167	12/22/2019	745	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	5	0	0
147	88166328	12/24/2019	1955	I 4	POLK PKWY	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0

Mainline Segment: I-4 from SR 570/Polk Parkway (West) to SR 546/W Memorial Boulevard (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84535793	2/4/2015	1023	I 4	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
2	84564621	6/15/2015	2231	I 4	MILE MARKER #28	17 STRUCK BY FALLING, SHIFTING CA	88 UNKNOWN	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
3	84894689	6/23/2015	1441	I 4	CR 542A	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
4	84879768	8/1/2015	425	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
5	85169035	9/25/2015	621	I 4	COUNTY LINE RD	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
6	85212840	11/29/2015	1928	I 4	HILLSBOROUGH COUNTY LINE	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
7	85686955	1/12/2016	2338	I 4	POLK PKWY	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
8	85152950	2/20/2016	1126	SR 400	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
9	85224987	5/7/2016	138	I 4	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
10	84498295	6/18/2016	1220	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	3	0	0
11	85243959	8/17/2016	1928	I 4	MILE MARKER #28	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	1	1	0
12	85371229	11/19/2016	2020	I 4	GALLOWAY RD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
13	85447326	5/9/2017	1015	I 4	POLK PKWY	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
14	85503707	5/25/2017	2055	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
15	85503539	5/27/2017	130	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
16	85579438	8/12/2017	1255	SR 400	CR 542A	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	3	0	0	0	0
17	85499062	12/13/2017	930	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	85499069	1/4/2018	1421	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
19	87139817	4/23/2018	946	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
20	87208560	8/3/2018	1550	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
21	85157999	8/23/2018	1734	I 4	GALLOWAY RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	4	0	0	0	0
22	87195934	9/6/2018	2310	SR 400	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
23	87276873	9/12/2018	1720	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
24	81953846	11/15/2018	1130	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
25	87289581	12/19/2018	835	I 4	COUNTY LINE RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	08 WATER (STANDING/MOVING)	01 DAYLIGHT	03 RAIN	1	0	0	0	0
26	88056096	12/21/2018	835	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
27	88056116	2/16/2019	1305	SR 400	GALLOWAY RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
28	88105778	4/27/2019	1425	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
29	88035718	5/6/2019	1056	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
30	88032068	6/6/2019	1545	SR 400	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
31	88168895	7/7/2019	143	SR 400	COUNTY LINE RD	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
32	88173762	7/12/2019	1342	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
33	88056162	9/12/2019	515	SR 400	MEMORIAL BLVD W	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
34	88173796	10/29/2019	728	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	88 UNKNOWN	88 UNKNOWN	77 OTHER (SEE NARRATIVE)	2	0	1	0	0

Interchange: I-4 at SR 546/W Memorial Boulevard (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	81955277	2/4/2015	1020	I 4	SR 539	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
2	84535794	2/21/2015	619	SR 400	SWINDELL RD	21 BRIDGE PIER OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	1	0	0
3	85601602	2/28/2015	20	SR 400	MEMORIAL BLVD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
4	87139822	3/22/2015	1820	SR 546	I 4	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
5	85568666	4/2/2015	2220	I 4	MEMORIAL AVE	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
6	85473452	5/10/2015	1034	SR 400	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
7	84890355	5/23/2015	1600	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
8	85346674	5/25/2015	705	SR 400	MEMORIAL BLVD	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
9	86347187	5/31/2015	746	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
10	84531311	8/1/2015	435	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	02 CLOUDY	4	0	1	0	0
11	85346737	8/1/2015	1015	SR 400	MM 28	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
12	85573848	8/6/2015	1525	SR 400	SR 546	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
13	85473865	8/7/2015	1050	SR 400	MM 28	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
14	85478671	8/7/2015	610	SR 400	MM 28	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
15	82057993	8/20/2015	1150	SR 400	MM 28	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
16	88111917	9/1/2015	1524	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
17	84894677	10/27/2015	600	SR 400	SR 546	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
18	85256713	11/10/2015	725	I 4	MEMORIAL BLVD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
19	87288472	12/6/2015	49	I 4	SR 546	30 CONCRETE TRAFFIC BARRIER	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
20	85601604	1/26/2016	1330	I 4	SWINDELL RD	27 GUARDRAIL FACE	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
21	84894708	1/31/2016	2156	I 4	GALLOWAY RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
22	88168930	1/31/2016	1530	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
23	87208566	2/17/2016	630	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
24	88168949	2/18/2016	220	SR 546	CRUTCHFIELD RD	09 OTHER NON-COLLISION	88 UNKNOWN	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
25	85595317	3/4/2016	1110	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	4	0	5	0	0
26	85601625	3/7/2016	1600	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
27	85336102	3/9/2016	1135	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
28	89012442	4/10/2016	5	SR 546	CRUTCHFIELD RD	09 OTHER NON-COLLISION	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
29	85223336	4/17/2016	700	SR 400	MM 28	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	02 CLOUDY	1	0	0	0	0
30	88843611	4/24/2016	2031	US 92	CRUTCHFIELD RD	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
31	85223340	5/3/2016	1122	SR 400	MM 28	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
32	85223324	6/20/2016	755	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	7	4	2	0	0
33	85420899	6/27/2016	1625	SR 400	GALLOWAY RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
34	85425512	6/30/2016	2004	I 4	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	02 CLOUDY	2	0	5	0	0
35	87208573	7/17/2016	450	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
36	87870009	7/25/2016	915	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
37	87208549	8/2/2016	1610	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
38	85503565	8/7/2016	1300	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
39	88056105	9/12/2016	1030	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
40	87344126	9/19/2016	1440	I 4	MEMORIAL BLVD W	13 ANIMAL	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
41	85503697	10/1/2016	845	SR 400	SR 546	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
42	85603206	10/19/2016	1839	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
43	87157615	10/27/2016	50	MEMORIAL BLVD	SR 400	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
44	88220056	11/12/2016	6	MEMORIAL BLVD	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
45	87344406	11/15/2016	1325	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
46	88102881	11/23/2016	1440	SR 400	MEMORIAL BLVD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
47	87216869	1/11/2017	1711	SR 400	SR 546	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
48	87223332	1/12/2017	1331	SR 400	SR 546	13 ANIMAL	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
49	85138966	2/7/2017	1015	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
50	85605705	2/22/2017	651	SR 400	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
51	87195967	2/26/2017	612	SR 546	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
52	85230107	3/13/2017	1410	SR 400	SR 546	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	6	0	0	0	0
53	89011087	3/19/2017	1655	SR 546	CRUTCHFIELD RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
54	86632553	4/4/2017	1639	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
55	85351943	4/19/2017	245	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
56	82254418	4/20/2017	2329	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
57	82778768	4/28/2017	1140	SR 400	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
58	87276951	5/12/2017	1435	SR 546	SR 400	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
59	85243940	5/23/2017	839	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
60	85149879	5/29/2017	2050	SR 400	SR 546	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
61	85351948	6/16/2017	529	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	06 DARK-UNKNOWN LIGHTING	01 CLEAR	2	0	0	0	0
62	87108823	6/18/2017	2105	SR 400	MILE MARKER #28	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
63	83741215	6/19/2017	1024	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
64	87123192	7/7/2017	2050	I 4	GALLOWAY RD	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
65	85729689	7/20/2017	2048	I 4	MILE MARKER #28	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
66	86128397	7/20/2017	1425	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
67	85356839	7/30/2017	525	SR 400	SR 546	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
68	85370256	7/30/2017	600	SR 400	MEMORIAL BLVD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
69	84558689	8/22/2017	1948	I 4	MEMORIAL BLVD	01 OVERTURN/ROLLOVER	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
70	86128549	10/12/2017	1550	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
71	85443868	10/14/2017	2332	SR 400	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
72	86634098	10/22/2017	640	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
73	88111918	10/22/2017	239	I 4	MEMORIAL BLVD	27 GUARDRAIL FACE	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
74	85246896	10/30/2017	1030	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
75	85517635	11/2/2017	1340	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
76	85425551	11/14/2017	1720	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
77	87186891	11/25/2017	1615	SR 546	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
78	87186903	11/25/2017	223	MEMORIAL BLVD	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
79	87170424	12/7/2017	1935	MEMORIAL BLVD W	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
80	88056089	12/8/2017	23	I 4	MEMORIAL BLVD W	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
81	87139821	12/14/2017	1633	SR 546	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
82	85170855	12/20/2017	1755	SR 400	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
83	85180697	1/8/2018	230	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	3	0	1	0	0
84	83784048	1/22/2018	710	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
85	87195941	2/12/2018	2115	MEMORIAL BLVD	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0

Interchange: I-4 at SR 546/W Memorial Boulevard (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85370265	2/27/2018	1430	SR 400	SR 546	15 PARKED MOTOR VEHICLE	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
87	86634391	3/30/2018	2152	SR 400	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	4	0	0
88	85443865	4/4/2018	632	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
89	85252569	4/13/2018	1330	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
90	87344446	5/1/2018	740	I 4	MEMORIAL BLVD W	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
91	88130265	5/16/2018	1423	MEMORIAL BLVD	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
92	85409156	5/20/2018	727	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
93	88036033	6/14/2018	2050	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
94	88844856	6/19/2018	700	MEMORIAL BLVD	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
95	85520427	6/24/2018	1813	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
96	88166321	6/28/2018	605	MEMORIAL BLVD	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	03 DAWN	02 CLOUDY	2	0	0	0	0
97	83790485	7/17/2018	1420	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
98	85341089	7/30/2018	0	SR 400	SR 546	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
99	84531300	8/16/2018	1035	SR 400	SR 546	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
100	85254515	8/26/2018	2132	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	02 CLOUDY	2	0	0	0	0
101	88220064	9/17/2018	1250	MEMORIAL BLVD	CRUTCHFIELD RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
102	88041732	9/20/2018	845	I 4	SR 546	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
103	86939412	10/4/2018	1300	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
104	85524849	10/5/2018	150	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
105	88111905	10/6/2018	2040	I 4	SR 546	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
106	88070812	10/13/2018	1835	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	02 CLOUDY	2	0	0	0	0
107	85151238	10/27/2018	2026	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
108	84531302	11/21/2018	1830	I 4	CR 542A	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
109	89371829	12/12/2018	1145	MEMORIAL BLVD	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
110	85420039	12/13/2018	1115	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
111	88089811	12/31/2018	1215	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
112	85524874	1/10/2019	1355	SR 400	GALLOWAY RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
113	85524911	1/12/2019	1300	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
114	85528183	1/19/2019	230	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
115	84531305	1/28/2019	1816	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
116	85532627	3/25/2019	608	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
117	87196554	4/7/2019	1434	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
118	87276741	5/5/2019	615	SR 400	MEMORIAL BLVD W	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
119	86346243	5/9/2019	2037	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
120	85596607	5/11/2019	1405	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	3	0	0
121	85543379	5/13/2019	200	I 4	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
122	88070857	6/28/2019	407	SR 400	MEMORIAL BLVD W	24 CURB	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
123	85420043	7/13/2019	2305	SR 400	MM 28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
124	85157997	7/25/2019	130	I 4	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
125	87277108	10/12/2019	550	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
126	85534252	10/15/2019	1248	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
127	87276895	11/3/2019	1215	I 4	SR 546	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
128	86346342	11/13/2019	1915	I 4	MEMORIAL BLVD W	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	2	0	0	0	0
129	88215612	11/13/2019	305	SR 400	MEMORIAL BLVD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
130	84625925	11/30/2019	525	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
131	84879745	12/11/2019	1444	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
132	85568639	12/11/2019	1625	I 4	GALLOWAY RD N	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
133	85254592	12/15/2019	2250	I 4	SR 546	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
134	87277091	12/26/2019	2348	I 4	SR 546	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0

Mainline Segment: I-4 from SR 546/W Memorial Boulevard to SR 539/Kathleen Road (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84535783	1/1/2015	432	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	0	0
2	84879724	4/12/2015	1515	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
3	84489384	8/15/2015	2052	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	2	0	0
4	84489391	8/23/2015	2040	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	2	0	0
5	84531321	9/19/2015	840	SR 400	MM 29	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
6	84878164	10/8/2015	1620	I 4	10TH ST W	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
7	85254851	1/5/2016	1828	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	4	0	0
8	85223317	1/7/2016	1315	I 4	MEMORIAL BLVD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
9	85226927	1/27/2016	850	SR 400	10TH ST W	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
10	85254522	2/15/2016	331	I 4	10TH ST W	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
11	85286009	2/28/2016	1531	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
12	85246894	3/7/2016	815	SR 400	MM 29	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
13	85254882	3/30/2016	35	I 4	SR 539	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
14	84877538	6/2/2016	2315	SR 400	KATHLEEN RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	1	0	0	0
15	85226966	6/6/2016	555	SR 400	10TH ST	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
16	85286041	6/6/2016	849	SR 400	KATHLEEN RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
17	85346678	7/10/2016	808	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	85256708	7/14/2016	830	SR 400	MM 30	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
19	85254659	8/2/2016	2015	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
20	85336094	9/27/2016	2040	SR 400	MEMORIAL BLVD W	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
21	85396932	9/27/2016	515	I 4	SR 539	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
22	85386980	10/2/2016	1522	I 4	MILE MARKER #30	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
23	85308907	10/5/2016	1830	SR 400	MM 29	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
24	85341113	10/6/2016	1225	I 4	MM 29	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
25	85420008	11/2/2016	1520	SR 400	BELLE VISTA DR	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
26	85371226	11/8/2016	1145	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
27	85411886	12/8/2016	1245	SR 400	SR 546	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
28	85371245	2/12/2017	300	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	04 FOG, SMOG, SMOKE	2	0	0	0	0
29	85420936	3/11/2017	1620	SR 400	MM 30	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
30	85501095	4/22/2017	1502	I 4	10TH ST W	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
31	85425531	4/28/2017	1344	SR 400	MILE MARKER #29	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
32	85371262	5/20/2017	1700	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
33	85474722	6/16/2017	1755	SR 400	MM 29	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
34	85473455	7/4/2017	400	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
35	85473456	7/8/2017	2300	SR 400	SR 539	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
36	85516101	8/8/2017	1800	SR 400	MM 30	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
37	85501759	8/31/2017	153	SR 400	MM 29	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
38	85574381	12/1/2017	948	I 4	10TH ST W	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
39	84890401	12/12/2017	300	I 4	MILE MARKER #29	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
40	85528176	1/31/2018	2020	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
41	87162239	3/22/2018	915	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
42	85574417	4/27/2018	2306	I 4	MEMORIAL BLVD W	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
43	87123181	5/7/2018	1240	SR 400	SR 546	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
44	87158148	5/17/2018	1730	SR 400	MM 30	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
45	87170438	5/29/2018	842	SR 400	KATHLEEN RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
46	87170440	5/31/2018	846	SR 400	MEMORIAL BLVD W	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
47	87196509	7/1/2018	1753	SR 400	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
48	87186901	7/27/2018	35	SR 400	SR 539	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
49	87186900	7/27/2018	110	SR 400	SR 539	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
50	87198627	8/4/2018	2130	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
51	87196001	8/5/2018	1618	SR 400	MILE MARKER #30	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
52	87112621	8/17/2018	2255	SR 400	MM 30	18 OTHER NON-FIXED OBJECT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
53	87276940	8/24/2018	1729	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
54	87208570	8/29/2018	1400	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
55	87871313	9/7/2018	1618	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
56	88032028	11/18/2018	1050	SR 400	SR 539	05 CARGO/EQUIPMENT LOSS OR SHIFT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
57	87276963	12/16/2018	1733	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
58	88056107	1/19/2019	705	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
59	88035259	1/19/2019	230	SR 400	MEMORIAL BLVD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
60	88036036	1/27/2019	845	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
61	88036043	2/12/2019	1215	SR 400	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
62	88032056	4/24/2019	820	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
63	87259964	5/18/2019	918	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
64	87288528	6/27/2019	2315	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	3	0	0	0	0
65	88184230	8/19/2019	835	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
66	88111950	8/31/2019	2203	SR 400	10TH ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	2	0	5	0	0
67	87188776	10/18/2019	2121	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0

Interchange: I-4 at SR 539/Kathleen Road (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84484413	1/1/2015	1925	I 4	KATHLEEN RD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	0	0	0
2	84498124	1/16/2015	1515	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
3	84865529	2/12/2015	1546	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
4	85729261	2/19/2015	1455	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
5	84951659	2/22/2015	1737	SR 539	KENDRICK LN	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
6	85729323	2/25/2015	1611	SR 539	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
7	85729352	2/25/2015	1421	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
8	84525660	3/5/2015	1825	I 4	KATHLEEN RD	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
9	85729584	3/11/2015	700	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	3	0	0	0	0
10	84879717	3/30/2015	2005	SR 400	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
11	84892545	3/31/2015	839	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
12	84889741	4/4/2015	2320	I 4	KATHLEEN RD	08 RAN INTO WATER/CANAL	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
13	84879723	4/5/2015	1700	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	3	0	0
14	84879730	4/19/2015	1450	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
15	85730517	5/28/2015	1430	SR 539	FAIRBANKS ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	2	0	0
16	84551376	6/1/2015	558	I 4	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
17	84889759	6/4/2015	725	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	5	0	0	0	0
18	84865566	6/8/2015	2037	SR 400	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
19	85730419	6/19/2015	2117	KATHLEEN RD	0	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
20	84558738	6/30/2015	740	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
21	84545421	7/1/2015	835	SR 400	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
22	84531284	7/7/2015	1845	SR 400	MM 31	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
23	86126698	7/22/2015	1201	SR 539	I 4	24 CURB	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
24	85728910	7/24/2015	2148	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
25	84677411	8/4/2015	1650	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
26	85149859	9/11/2015	1445	SR 400	KATHLEEN RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
27	84894713	9/23/2015	1903	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
28	84865602	9/24/2015	2117	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	1	0	0
29	84894994	9/24/2015	2040	SR 400	SR 700	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
30	84531326	9/25/2015	500	I 4	SR 539	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
31	86127438	9/27/2015	1200	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
32	85144982	9/28/2015	1215	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
33	86127313	10/13/2015	1450	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
34	85154066	11/22/2015	500	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
35	85152926	11/29/2015	1844	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
36	85149902	12/27/2015	1150	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
37	85149905	1/3/2016	635	SR 400	KATHLEEN RD	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
38	86129033	1/22/2016	1836	I 4	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
39	86345578	2/22/2016	1455	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
40	86345675	2/23/2016	738	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
41	85230066	3/10/2016	1100	I 4	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	2	0	0
42	86345845	3/31/2016	756	SR 539	KENDRICK LN	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
43	85223352	4/6/2016	925	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
44	85286022	4/6/2016	1535	SR 400	KATHLEEN RD	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
45	85254887	4/13/2016	2135	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
46	85230081	4/17/2016	1041	I 4	SR 539	14 MOTOR VEHICLE IN TRANSPORT	06 REAR TO SIDE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
47	86346274	4/20/2016	816	SR 539	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
48	85246921	4/22/2016	620	SR 400	MM 31	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
49	86346645	5/5/2016	1115	KATHLEEN RD	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
50	86346511	5/8/2016	2155	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
51	86346827	5/9/2016	943	KATHLEEN RD	0	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
52	86346389	5/11/2016	658	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
53	85290616	5/13/2016	4	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
54	85341052	5/25/2016	620	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
55	85341053	5/25/2016	1220	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
56	83667229	6/5/2016	2128	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
57	85180717	6/7/2016	1540	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	2	0	0
58	85243936	6/12/2016	1713	I 4	MILE MARKER #31	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
59	85254568	6/29/2016	2112	SR 400	SR 539	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
60	83784086	7/6/2016	1210	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
61	85254645	7/6/2016	145	I 4	MM 31	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
62	85341076	7/6/2016	1040	SR 400	MM 31	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
63	85274124	7/7/2016	1345	SR 400	KATHLEEN RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
64	85254579	7/21/2016	2134	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	3	0	0	0	0
65	85290642	7/22/2016	1818	I 4	KATHLEEN RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
66	85356806	8/6/2016	1700	I 4	SR 539	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
67	85256717	8/7/2016	1225	SR 400	MM 31	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
68	85302766	8/9/2016	805	SR 400	MILE MARKER #31	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
69	85351924	8/9/2016	1130	SR 400	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
70	86347640	8/12/2016	1720	KATHLEEN RD	BELLE GROVE ST	24 CURB	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
71	85346690	8/30/2016	818	I 4	MILE MARKER #33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
72	85336091	9/10/2016	1900	SR 400	SR 539	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
73	85308896	9/13/2016	1750	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
74	85154671	10/8/2016	1600	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
75	85356832	10/14/2016	2100	I 4	KATHELEEN RD	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
76	85420898	11/23/2016	650	I 4	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
77	83685102	12/11/2016	900	I 4	KATHLEEN RD	09 OTHER NON-COLLISION	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
78	85411891	12/18/2016	1530	I 4	KATHLEEN RD	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
79	85383701	12/30/2016	1050	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
80	86633657	1/3/2017	2147	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
81	86635105	1/5/2017	735	KATHLEEN RD	INTERSTATE DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
82	83790475	1/12/2017	1150	I 4	KATHLEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
83	85420021	1/29/2017	1215	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
84	86633849	2/9/2017	2145	SR 539	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
85	83788407	2/14/2017	1730	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0

Interchange: I-4 at SR 539/Kathleen Road (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85420917	2/14/2017	920	I 4	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
87	85478616	2/19/2017	1612	I 4	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
88	85370286	2/21/2017	2230	SR 400	SR 539	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
89	85409151	3/3/2017	2020	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
90	85420935	3/11/2017	1335	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
91	86634443	3/29/2017	1541	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
92	85370297	4/2/2017	234	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
93	85425525	4/9/2017	1538	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
94	86634658	4/14/2017	2008	SR 539	LAVON ST	24 CURB	00 NOT CODED	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
95	86634667	4/16/2017	745	SR 539	ELLIOT ST W	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
96	85503527	4/28/2017	1245	SR 400	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
97	86635417	5/12/2017	2130	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
98	86635476	5/17/2017	1320	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
99	86818568	5/21/2017	2121	SR 539	FAIRBANKS ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
100	85447331	5/23/2017	850	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
101	85447335	5/24/2017	550	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
102	87342048	5/28/2017	1316	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
103	85501109	6/1/2017	1527	I 4	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
104	85503540	6/1/2017	2330	SR 400	KATHLEEN RD	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
105	85442358	6/7/2017	1740	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
106	85503543	6/9/2017	445	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
107	85503711	6/9/2017	440	SR 400	SR 539	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
108	85474723	6/17/2017	1900	SR 400	MM 31	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
109	85503551	6/27/2017	1630	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
110	87342522	7/10/2017	1217	SR 539	INTERSTATE DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
111	87342587	7/14/2017	1630	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
112	85443867	7/20/2017	1931	SR 400	SR 539	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
113	85503560	7/20/2017	1125	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
114	85474734	7/29/2017	1920	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	02 CLOUDY	2	0	0	0	0
115	87342918	8/13/2017	1117	SR 539	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
116	85501754	8/25/2017	104	I 4	KATHLEEN RD	27 GUARDRAIL FACE	88 UNKNOWN	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
117	83780760	8/29/2017	706	I 4	KATHLEEN RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
118	87343149	9/1/2017	635	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
119	85568619	9/2/2017	1920	SR 400	KATHLEEN RD	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
120	87343414	9/23/2017	1500	SR 539	KENDRICK LN	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
121	87343803	10/25/2017	2233	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
122	85601605	11/2/2017	1510	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
123	85601614	11/12/2017	1720	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
124	87344047	11/17/2017	845	SR 539	FAIRBANKS ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
125	85574376	11/22/2017	1811	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
126	87139753	12/4/2017	1146	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
127	87139757	12/8/2017	1321	SR 400	KATHLEEN RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
128	87344457	12/18/2017	1542	SR 539	FAIRBANKS ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
129	87344464	12/18/2017	2200	KATHLEEN RD	FAIRBANKS ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
130	87139767	12/31/2017	1352	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
131	87344652	1/7/2018	1250	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
132	87344769	1/17/2018	745	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	8	0	0
133	85579502	1/25/2018	1040	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
134	87795067	2/20/2018	1105	SR 539	INTERSTATE DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
135	87795196	3/4/2018	1746	SR 539	BELLE GROVE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
136	87123163	3/14/2018	645	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
137	85603203	3/29/2018	1705	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
138	87195891	4/17/2018	1715	SR 400	KATHLEEN RD	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
139	87667600	4/17/2018	1051	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
140	87108824	5/1/2018	1005	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
141	87123185	5/17/2018	2115	SR 400	KATHLEEN RD	23 CULVERT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
142	87158149	5/18/2018	1755	SR 400	MM 31	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
143	87195908	5/31/2018	1050	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
144	87196506	6/14/2018	1555	I 4	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
145	87796546	6/19/2018	1720	KATHLEEN RD	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	4	0	0	0	0
146	87158160	6/20/2018	320	SR 400	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
147	87158167	7/11/2018	305	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
148	87234301	7/15/2018	36	I 4	SR 539	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
149	87235520	7/24/2018	709	SR 400	KATHLEEN RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
150	87235521	7/24/2018	738	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
151	87195923	8/9/2018	1200	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
152	87162283	8/10/2018	333	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	2	0	0
153	87208567	8/16/2018	1310	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
154	87277088	8/24/2018	1648	SR 400	MM 31	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
155	87195931	8/29/2018	1640	SR 400	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
156	87235534	9/5/2018	2101	SR 400	KATHLEEN RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
157	87208575	10/7/2018	730	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
158	85158003	10/13/2018	1328	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
159	87797748	10/15/2018	802	SR 539	KENDRICK LN	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
160	88842911	10/31/2018	1503	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
161	85158005	11/1/2018	2100	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	2	0	0
162	87285503	11/1/2018	2248	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
163	88843037	11/9/2018	1511	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
164	87196028	11/10/2018	1831	SR 400	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
165	87234401	11/11/2018	1435	I 4	US 98	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
166	88843064	11/14/2018	756	KATHLEEN RD	MALL HILL DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
167	87277120	11/18/2018	709	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
168	87288485	11/20/2018	2034	I 4	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
169	87236030	11/29/2018	2335	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
170	88843226	11/29/2018	631	SR 539	BELLE GROVE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	2	0	0

Interchange: I-4 at SR 539/Kathleen Road (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	88044151	12/4/2018	1121	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
172	87273114	12/5/2018	1133	I 4	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
173	87216866	12/8/2018	725	I 4	KATHLEEN RD	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
174	88843411	12/13/2018	1744	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
175	87277131	12/16/2018	1553	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	3	0	0
176	88843475	12/18/2018	1900	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
177	88843490	12/19/2018	650	KATHLEEN RD	KATHLEEN RD	24 CURB	00 NOT CODED	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
178	88036027	12/20/2018	640	SR 400	KATHLEEN	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
179	88843593	12/28/2018	1045	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
180	88843682	1/6/2019	1121	SR 539	BELLE GROVE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
181	87270587	2/17/2019	1517	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
182	87277151	2/21/2019	735	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
183	87157642	2/23/2019	610	SR 400	KATHLEEN RD	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	1	1	1	0
184	87157643	2/23/2019	1215	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
185	87217019	2/23/2019	955	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
186	87270590	2/26/2019	602	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
187	89009309	2/26/2019	609	SR 400	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
188	88032043	3/13/2019	1000	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
189	87189664	3/19/2019	2255	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
190	88844624	3/19/2019	1254	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
191	88844640	3/20/2019	1623	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
192	88844701	3/20/2019	2045	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
193	87300476	3/21/2019	1544	SR 400	KATHLEEN RD	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
194	85531351	4/1/2019	1530	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
195	88089754	4/3/2019	1450	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
196	87289602	4/8/2019	740	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	2	0	0
197	88111908	4/8/2019	816	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
198	88111909	4/14/2019	639	SR 400	KATHLEEN RD	21 BRIDGE PIER OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	01 CLEAR	1	0	1	0	0
199	87276842	4/23/2019	1532	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
200	87276737	4/24/2019	840	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
201	88845134	4/29/2019	1130	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
202	89010771	5/2/2019	527	I 4	BELLA VISTA ST W	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
203	89009109	5/3/2019	435	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
204	88111915	5/5/2019	1732	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
205	88845297	5/7/2019	823	SR 539	KENDRICK LN	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
206	88845570	5/11/2019	1051	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
207	87288518	5/14/2019	1500	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
208	88845341	5/16/2019	715	SR 539	ELLIOT ST W	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
209	87288522	5/25/2019	1105	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
210	87283702	5/30/2019	2326	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	1	0	0
211	88845514	6/3/2019	1755	I 4	KATHLEEN RD	34 TRAFFIC SIGN SUPPORT	00 NOT CODED	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
212	88845626	6/15/2019	2035	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
213	88141222	6/23/2019	543	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
214	87288527	6/25/2019	435	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
215	87288531	7/19/2019	840	I 4	KATHLEEN RD	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
216	88141230	7/20/2019	1352	SR 400	KATHLEEN RD	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
217	88162136	7/20/2019	1353	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	3	0	0
218	88141232	7/21/2019	1614	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
219	87289633	7/23/2019	2147	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
220	88056153	7/24/2019	1910	SR 400	US 98	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
221	88070864	7/24/2019	13	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
222	88168904	7/26/2019	1344	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
223	89346903	8/5/2019	1634	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
224	88070868	8/6/2019	2210	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
225	89346973	8/6/2019	2150	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
226	88130232	8/19/2019	1335	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	3	0	0
227	88101232	8/21/2019	345	I 4	MILE MARKER #30	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
228	89347106	8/23/2019	200	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
229	88166294	9/3/2019	1450	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
230	88003653	9/7/2019	1320	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
231	88168921	9/7/2019	1812	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
232	88173782	9/8/2019	1851	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	3	0	0	0	0
233	88071195	9/30/2019	700	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
234	89370099	10/1/2019	154	I 4	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
235	88166304	10/5/2019	1210	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
236	89347608	10/6/2019	1715	SR 539	FAIRBANKS ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
237	89347813	10/22/2019	1041	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
238	88107627	10/26/2019	1100	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
239	88220048	10/26/2019	1710	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
240	88226387	10/26/2019	30	I 4	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
241	88184243	10/31/2019	1830	SR 400	KATHLEEN RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
242	89348638	12/29/2019	2007	SR 539	KENDRICK LN	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0

Mainline Segment: I-4 from SR 539/Kathleen Road to US 98 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84558677	1/24/2015	700	SR 400	CR 582	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
2	84865541	2/23/2015	1840	SR 400	SR 700	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
3	84558691	2/24/2015	1423	SR 400	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
4	84569146	2/27/2015	1900	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	3	0	0
5	84501390	3/24/2015	2320	I 4	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
6	84879731	4/19/2015	1740	SR 400	CR 582	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
7	85154049	10/15/2015	1430	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
8	85154060	11/9/2015	59	SR 400	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
9	85154068	12/12/2015	1631	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
10	85154075	1/5/2016	1515	SR 400	CR 582	20 BRIDGE OVERHEAD STRUCTURE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
11	85230057	1/20/2016	1245	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
12	85226922	1/22/2016	940	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
13	85254514	1/26/2016	1410	I 4	SR 539	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
14	85223343	3/22/2016	1105	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	1	0
15	85180713	4/26/2016	600	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	3	0	2	0	0
16	85226969	6/9/2016	1128	SR 400	CR 582	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
17	85356826	10/1/2016	1452	I 4	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
18	85411892	12/19/2016	525	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
19	83785242	2/21/2017	2245	I 4	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
20	85370298	4/6/2017	450	SR 400	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
21	85371271	7/15/2017	2050	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	2	0	0
22	87139781	2/11/2018	1145	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
23	87108818	4/19/2018	1330	SR 400	CR 582	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
24	87139818	5/2/2018	115	SR 400	SR 539	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	1	0	1	0
25	87208561	8/5/2018	1630	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
26	87276788	8/28/2018	1440	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
27	87235552	11/10/2018	1650	SR 400	GRIFFIN RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	1	1	0	0
28	88036071	5/1/2019	2230	SR 400	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
29	87246879	5/16/2019	2340	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
30	87276747	5/25/2019	1605	SR 400	GRIFFIN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
31	88141218	6/8/2019	1955	I 4	SOCRUM LOOP RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
32	88056144	6/28/2019	1210	SR 400	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
33	87283712	7/20/2019	1351	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0

Interchange: I-4 at US 98 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	83742388	1/3/2015	1422	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
2	84952021	1/12/2015	2010	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
3	83834003	1/17/2015	1445	SR 400	SR 700	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
4	84951632	1/18/2015	1635	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
5	84678353	1/24/2015	700	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
6	85728732	1/25/2015	2209	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
7	85728925	1/25/2015	1419	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
8	85728986	1/28/2015	819	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
9	85728772	1/30/2015	1619	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
10	83741182	2/1/2015	1430	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
11	83771096	2/8/2015	1920	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
12	84545382	2/8/2015	2145	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
13	84545383	2/8/2015	2146	SR 400	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
14	84951762	2/9/2015	154	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
15	85729219	2/18/2015	1210	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
16	84951426	2/22/2015	2115	US 98	TUCKER ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
17	85729177	2/23/2015	1913	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
18	85729193	2/26/2015	1317	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
19	85729494	3/5/2015	1457	US 98 N	LAKELAND SQUARE MALL ENT	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
20	85729119	3/7/2015	2115	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
21	85729533	3/9/2015	749	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
22	85729382	3/11/2015	2009	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
23	85729552	3/16/2015	2057	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	06 REAR TO SIDE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
24	85729383	3/24/2015	1723	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	1	0	0
25	85729741	3/26/2015	2039	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
26	85729761	3/29/2015	2231	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
27	85729806	3/30/2015	1537	FLORIDA AVE N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
28	85729827	4/2/2015	846	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
29	85729678	4/5/2015	1728	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
30	85729886	4/8/2015	1809	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
31	85729771	4/13/2015	1128	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
32	84551365	4/22/2015	2230	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
33	85730000	4/26/2015	1550	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
34	85730027	5/10/2015	1527	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
35	85730228	5/11/2015	2045	US 98	PYRAMID PKWY	11 PEDALCYCLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	1
36	85729978	5/12/2015	1850	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
37	83790301	5/15/2015	2335	SR 700	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
38	85729745	5/18/2015	2247	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
39	84889114	5/20/2015	1405	I 4	SR 539	05 CARGO/EQUIPMENT LOSS OR SHIFT	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
40	85729113	5/23/2015	2108	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	5	0	0	0	0
41	85730040	5/24/2015	1410	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
42	85730506	5/28/2015	2217	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	2	0	0
43	84676865	6/2/2015	2005	US 98 N	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
44	83742403	6/7/2015	820	SR 400	SR 700	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
45	85729858	6/7/2015	1153	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
46	84545411	6/8/2015	1850	SR 400	MILE MARKER #33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
47	84952163	6/9/2015	1945	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
48	86126314	6/18/2015	837	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
49	86126331	6/22/2015	1040	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
50	84894690	6/23/2015	1702	US 98	I 4	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
51	84889770	6/29/2015	335	I 4	KATHLEEN RD	18 OTHER NON-FIXED OBJECT	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
52	84892585	7/5/2015	1840	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
53	84871684	7/9/2015	920	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	86126579	7/9/2015	243	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
55	85728952	7/10/2015	1521	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
56	86082426	7/16/2015	2120	PROVIDENCE RD	GRIFFIN RD	23 CULVERT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
57	85729924	7/17/2015	1327	SR 700	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	1	0	0
58	84892591	7/28/2015	725	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
59	84856588	8/2/2015	810	I 4	US 98	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
60	86126294	8/11/2015	48	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
61	86126942	8/12/2015	1550	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
62	86126295	8/15/2015	2151	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	4	0	1	0	0
63	85730594	8/18/2015	340	US 98	CREVASSE ST	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	01 CLEAR	1	0	1	1	0
64	86126600	9/5/2015	2200	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
65	85138981	9/12/2015	1345	SR 400	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
66	86126997	9/23/2015	1940	US 98 N	BREEZEWOOD DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	2	0	0
67	86127448	9/28/2015	728	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	03 DAWN	03 RAIN	2	0	1	0	0
68	84564654	10/8/2015	1304	I 4	MILE MARKER#31	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
69	86126724	10/11/2015	1020	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
70	86127798	10/12/2015	1605	US 98	SHOPPES OF LAKELAND	11 PEDALCYCLE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	1
71	84531335	10/23/2015	945	I 4	US 98	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
72	86127270	10/24/2015	1505	SR 700	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
73	84531336	10/27/2015	1335	SR 400	MM 32	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
74	86127720	11/8/2015	1747	US 98	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
75	86127476	11/11/2015	700	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
76	86127633	11/14/2015	1041	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
77	86127755	11/16/2015	2039	US 98	WOODLAND DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
78	86127872	11/17/2015	801	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
79	86127874	11/17/2015	1145	US 98 N	GRIFFIN RD	01 OVERTURN/ROLLOVER	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
80	86128134	11/17/2015	825	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
81	86128157	11/18/2015	1412	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
82	86128182	11/19/2015	1504	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
83	86127190	11/20/2015	1143	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
84	86127964	11/21/2015	1810	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
85	86128146	11/22/2015	1322	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	1	0	0

Interchange: I-4 at US 98 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85111003	11/23/2015	1115	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
87	86127822	11/23/2015	2019	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
88	86128300	12/1/2015	1146	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	4	0	1	0	0
89	86127974	12/4/2015	2211	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	4	0	3	0	0
90	86128266	12/8/2015	2038	US 98	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	4	0	3	0	0
91	86127700	12/10/2015	1427	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
92	86127433	12/11/2015	736	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
93	86127905	12/11/2015	1617	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
94	86127000	12/12/2015	1920	CREVASSE ST	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
95	86127001	12/15/2015	1835	US 98	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
96	86128099	12/15/2015	1516	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
97	86127726	12/21/2015	1824	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
98	86128591	12/25/2015	1718	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
99	86128524	1/3/2016	1650	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
100	86128757	1/4/2016	2009	US 98	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
101	86128495	1/5/2016	1655	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
102	83741202	1/7/2016	640	SR 700	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	03 DAWN	03 RAIN	2	0	2	0	0
103	86128760	1/8/2016	1814	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
104	86128683	1/11/2016	1517	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
105	86128828	1/13/2016	631	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
106	85254854	1/15/2016	1620	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
107	86128911	1/19/2016	1314	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
108	86128818	1/20/2016	1232	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
109	84881120	1/22/2016	1415	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
110	85151262	1/26/2016	2100	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
111	85226928	1/27/2016	1310	SR 400	SR 700	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
112	86313251	1/31/2016	1015	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
113	86129188	2/5/2016	1644	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
114	85254597	2/15/2016	1745	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
115	86129116	2/15/2016	1540	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
116	86345519	2/15/2016	1032	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
117	86345567	2/16/2016	931	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
118	85274093	2/18/2016	1725	SR 400	MM32	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
119	86345548	2/18/2016	1944	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	1	0	0
120	86127494	2/19/2016	334	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
121	85274096	2/23/2016	1000	SR 400	MILE MARKER #32	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
122	86129176	2/25/2016	2114	CREVASSE ST	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
123	86129100	2/26/2016	1655	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	5	0	1	0	0
124	86345769	3/2/2016	202	US 98	CREVASSE ST	36 OTHER POST, POLE, OR SUPPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
125	86345852	3/3/2016	1305	US 98 N	BREEZEWOOD DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
126	86129104	3/6/2016	1120	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
127	85148530	3/7/2016	855	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
128	85246897	3/7/2016	1720	US 98	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
129	86128481	3/13/2016	1740	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
130	86346041	3/15/2016	827	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	2	0	1	0	0
131	86313144	3/20/2016	1353	US 98	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
132	85254876	3/22/2016	1100	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
133	86346031	3/23/2016	1915	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	03 RAIN	2	0	1	0	0
134	85246903	3/24/2016	1230	SR 400	MM 32	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
135	86129200	3/27/2016	830	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
136	85274102	3/28/2016	1500	SR 400	US 98	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
137	86129261	3/28/2016	2111	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
138	86345709	3/30/2016	38	GRIFFIN RD	PROVIDENCE RD	24 CURB	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
139	86346096	4/1/2016	2024	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
140	86346468	4/14/2016	1052	GRIFFIN RD	FLORIDA AVE N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
141	86346352	4/22/2016	1125	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
142	86346472	4/22/2016	1225	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
143	86346586	4/26/2016	2040	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
144	86128893	4/28/2016	811	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
145	86345960	4/30/2016	1426	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
146	86346047	4/30/2016	429	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
147	86346005	5/2/2016	1542	US 98	I 4	10 PEDESTRIAN	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	1
148	86346297	5/4/2016	1237	GRIFFIN RD	PROVIDENCE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
149	86128949	5/11/2016	2340	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	1	0	0
150	86128894	5/13/2016	1344	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
151	86128950	5/21/2016	2135	US 98 N	WOODLAND DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
152	86346973	5/29/2016	1630	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
153	85263329	5/31/2016	755	I 4	MM32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
154	86347137	6/1/2016	1440	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
155	86347191	6/5/2016	2135	US 98 N	GRIFFIN RD	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
156	85290621	6/6/2016	29	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
157	86347015	6/12/2016	1620	US 98	ROBSON ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
158	86347254	6/12/2016	1656	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
159	86346761	6/14/2016	2348	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
160	86347416	6/17/2016	1510	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
161	86347370	6/20/2016	1504	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
162	86347402	6/20/2016	1215	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
163	86347029	7/19/2016	1945	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
164	86347440	7/20/2016	1713	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
165	86347726	7/21/2016	2119	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	5	0	0
166	86444954	7/28/2016	425	SR 35	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
167	86347862	8/2/2016	1339	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
168	86347920	8/3/2016	933	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
169	86347638	8/7/2016	1055	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
170	85243953	8/8/2016	40	I 4	MILE MARKER #32	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0

Interchange: I-4 at US 98 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	85243956	8/8/2016	1630	I 4	MILE MARKER #32	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
172	86347970	8/14/2016	1305	US 98	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
173	86347168	8/16/2016	1715	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
174	85152874	8/17/2016	1325	SR 400	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
175	85308886	8/22/2016	1900	SR 400	MM 32	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
176	85308888	8/27/2016	1430	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
177	85336085	8/30/2016	2045	I 4	SR 700	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	3	0	0
178	85356812	8/30/2016	23	I 4	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
179	85341101	9/4/2016	1745	I 4	MM 32	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
180	86128936	9/4/2016	2017	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
181	86347319	9/9/2016	1535	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
182	86347950	9/10/2016	1857	US 98	PYRAMID PKWY	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
183	86348186	9/11/2016	442	US 98	I 4	24 CURB	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
184	85341106	9/13/2016	1437	I 4	MM 32	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
185	86632608	9/14/2016	1551	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
186	85351944	9/16/2016	540	US 98	SR 400	24 CURB	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
187	85386972	9/18/2016	2049	I 4	MILE MARKER #32	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
188	84881124	10/5/2016	1430	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	4	0	2	0	0
189	85341114	10/8/2016	1015	SR 400	MM 32	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
190	85341115	10/8/2016	1430	SR 400	MM 32	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
191	85274150	10/9/2016	659	SR 400	MILE MARKER #32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
192	85346706	10/16/2016	1225	SR 400	US 92	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
193	85346707	10/16/2016	1605	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
194	85370259	10/29/2016	23	SR 400	US 98	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
195	86776714	11/9/2016	1448	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
196	85356838	11/11/2016	2000	I 4	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
197	86776730	11/14/2016	1204	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
198	86632828	11/18/2016	1130	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	1
199	86633000	11/24/2016	2110	US 98	CREVASSE ST	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
200	86818457	11/24/2016	1333	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
201	85420013	11/26/2016	730	SR 400	US 98	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
202	86818401	11/29/2016	1827	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
203	86633347	12/8/2016	1700	SR 35	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
204	86633362	12/10/2016	22	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
205	86818523	12/14/2016	1619	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
206	86818533	12/16/2016	1759	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
207	86818549	12/18/2016	1532	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
208	86633512	12/19/2016	1520	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
209	86635026	12/20/2016	1845	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
210	86633468	12/21/2016	1840	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	6	0	0
211	86633537	12/22/2016	1935	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
212	86633492	12/23/2016	1034	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
213	86635046	12/26/2016	1212	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
214	86632981	1/1/2017	2135	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
215	86633411	1/3/2017	650	US 98 N	LAKELAND MALL	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
216	86635099	1/4/2017	1700	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
217	86635118	1/4/2017	1114	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
218	86635104	1/5/2017	804	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
219	86633530	1/8/2017	1600	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
220	86635238	1/17/2017	1117	CR 582	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
221	86635225	1/19/2017	1013	FLORIDA AVE N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
222	86635232	1/21/2017	250	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
223	86633557	1/22/2017	600	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
224	86635257	1/23/2017	1345	GRIFFIN RD	FLORIDA AVE N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
225	85286081	1/29/2017	1037	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
226	85263346	2/4/2017	1545	SR 400	MM 32	09 OTHER NON-COLLISION	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
227	85336127	2/7/2017	115	SR 400	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
228	86633837	2/9/2017	1300	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
229	86633885	2/13/2017	1406	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
230	85263350	2/21/2017	1735	I 4	MILE MARKER #32	09 OTHER NON-COLLISION	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
231	85425522	2/22/2017	915	SR 400	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
232	85420029	2/26/2017	1305	SR 400	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
233	86634197	2/28/2017	2050	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
234	85473425	3/5/2017	1308	SR 400	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
235	85473869	3/8/2017	636	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
236	86634186	3/9/2017	1032	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
237	86634301	3/17/2017	2216	US 98	LAKELAND SQUARE MALL	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
238	85370294	3/18/2017	249	SR 400	US 98	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
239	86634354	3/19/2017	1251	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
240	86634367	3/19/2017	1820	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
241	86634468	3/23/2017	26	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
242	86634494	3/31/2017	1104	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
243	86634496	4/2/2017	1846	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
244	85501088	4/7/2017	1353	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
245	85501089	4/7/2017	1511	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
246	86634620	4/11/2017	733	FLORIDA AVE N	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
247	85501707	4/14/2017	1653	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
248	86634771	4/15/2017	2050	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
249	85391725	4/16/2017	1315	SR 400	MM 32	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
250	86634672	4/16/2017	1243	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
251	86634733	4/21/2017	1502	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
252	86634905	4/28/2017	1625	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	5	0	1	0	0
253	85409159	4/29/2017	252	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
254	85371258	5/1/2017	250	I 4	US 98	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
255	85506744	5/4/2017	1120	SR 400	MM 32	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Interchange: I-4 at US 98 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
256	86994725	5/9/2017	1139	SR 35	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
257	86635416	5/12/2017	1235	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
258	86635498	5/14/2017	1930	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
259	87342221	5/19/2017	910	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
260	87342033	5/21/2017	805	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
261	87342046	5/23/2017	806	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
262	87342108	6/1/2017	1737	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
263	87342245	6/5/2017	2216	US 98 N	WOODLAND DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
264	87342179	6/7/2017	1802	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
265	87342238	6/7/2017	1302	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
266	87342297	6/9/2017	2124	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
267	87342379	6/9/2017	1618	US 98	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	4	0	5	0	0
268	85501118	6/12/2017	1942	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	3	0	0	0	0
269	85474718	6/13/2017	2355	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
270	85474719	6/13/2017	2355	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
271	85501731	6/14/2017	2210	SR 400	MILE MARKER #31	26 EMBANKMENT	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
272	87342256	6/14/2017	2040	US 98	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
273	85151367	6/27/2017	50	I 4	MM 32	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
274	87342499	7/7/2017	2005	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	03 RAIN	2	0	0	0	0
275	85524887	7/8/2017	1700	SR 400	MILE MARKER #32	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
276	85534294	7/10/2017	1450	SR 400	MM 32	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
277	85553019	7/11/2017	805	I 4	MILE MARKER #32	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
278	87342556	7/11/2017	1835	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
279	85442368	7/13/2017	1232	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
280	85516088	7/16/2017	1859	SR 400	MM 32	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
281	87342716	7/24/2017	1320	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
282	87342780	7/24/2017	1426	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
283	87342781	7/25/2017	1620	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
284	87342806	7/27/2017	1742	US 98	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
285	87342785	7/31/2017	1920	CR 582	US 98 N	03 IMMERSION	00 NOT CODED	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
286	87342984	8/18/2017	250	US 98 N	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
287	85534313	8/20/2017	530	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
288	85474742	8/24/2017	800	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
289	85568616	8/25/2017	1750	SR 400	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
290	85474745	8/26/2017	855	SR 400	MILE MARKER #32	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
291	85528136	8/26/2017	815	I 4	GRIFFIN RD	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
292	87343216	8/26/2017	1644	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	4	0	4	0	0
293	87343163	8/31/2017	2003	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
294	87343166	9/2/2017	58	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
295	85513221	9/7/2017	2100	SR 400	MM 32	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
296	85568621	9/10/2017	1700	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
297	87343417	9/26/2017	1316	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
298	85568631	9/27/2017	910	SR 700	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
299	87343430	9/27/2017	1430	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
300	87343448	9/29/2017	2025	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
301	87343492	10/1/2017	1700	GRIFFIN RD	US 98	11 PEDALCYCLE	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	1
302	87343518	10/4/2017	1330	US 98	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
303	87343533	10/5/2017	1600	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
304	87343707	10/18/2017	1741	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	1
305	87343731	10/20/2017	2124	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	8	0	0
306	87343757	10/22/2017	1905	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	3	0	3	0	0
307	87343788	10/24/2017	2106	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
308	87343789	10/24/2017	1545	US 98	MALL ACCESS RD 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
309	87343810	10/26/2017	1412	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
310	87343820	10/27/2017	2004	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
311	85568653	11/9/2017	838	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
312	87343975	11/9/2017	1356	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
313	87332879	11/13/2017	1941	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
314	87344035	11/15/2017	1627	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
315	87344084	11/19/2017	1830	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
316	87344208	11/29/2017	1544	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
317	87344216	11/30/2017	2110	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
318	85605703	12/3/2017	2125	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
319	87344251	12/3/2017	1455	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
320	87344267	12/5/2017	1324	US 98 N	BREEZEWOOD DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
321	85574385	12/9/2017	1125	I 4	US 98	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
322	87333381	12/20/2017	2243	FLORIDA AVE N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
323	87344533	12/24/2017	2024	GRIFFIN RD	PROVIDENCE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
324	87344557	12/25/2017	1310	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
325	87344600	1/1/2018	2115	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
326	85579492	1/2/2018	900	US 98	SR 400	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	05 SLEET, HAIL, FREEZING RAIN	1	0	0	0	0
327	87344615	1/3/2018	1231	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
328	87344687	1/9/2018	1320	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
329	87114611	1/12/2018	553	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
330	87344815	1/18/2018	1630	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	0	0	0
331	87344856	1/24/2018	215	US 98	I 4	24 CURB	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
332	85528175	1/26/2018	1850	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
333	85568672	1/26/2018	1705	SR 400	SR 700	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
334	87344893	1/28/2018	854	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
335	87794943	2/10/2018	1658	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
336	87794960	2/13/2018	1949	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
337	87795008	2/18/2018	1257	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	0	0	0
338	87333056	2/20/2018	1606	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
339	87795048	2/21/2018	1050	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
340	87795063	2/21/2018	2317	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0

Interchange: I-4 at US 98 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
341	87795081	2/23/2018	1325	US 98 N	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
342	87795091	2/24/2018	2200	GRIFFIN RD	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
343	87795122	2/26/2018	1519	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
344	87795123	2/26/2018	1425	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
345	87795124	2/26/2018	705	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
346	87795152	2/28/2018	1308	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
347	87795206	3/1/2018	1339	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
348	87139793	3/2/2018	1157	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
349	85573906	3/7/2018	432	I 4	US 98	18 OTHER NON-FIXED OBJECT	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
350	87795257	3/9/2018	1230	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
351	87108809	3/10/2018	400	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
352	87795297	3/12/2018	736	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
353	87123165	3/19/2018	745	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
354	87196483	3/19/2018	1555	SR 400	MM 32	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
355	87795453	3/23/2018	1635	LAKELAND PK CNTR DR	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
356	87795535	3/25/2018	1620	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
357	87796010	3/27/2018	1706	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
358	87795544	4/2/2018	736	ROBSON ST	FLORIDA AVE N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
359	85603205	4/5/2018	1950	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
360	87795644	4/8/2018	1450	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
361	87795665	4/9/2018	2316	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
362	87795684	4/12/2018	1114	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	1	0	0	0
363	87795708	4/14/2018	1432	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
364	87795715	4/15/2018	1641	FLORIDA AVE N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
365	87795914	4/27/2018	847	SR 35	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
366	87158146	5/2/2018	1145	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
367	87795934	5/2/2018	1234	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
368	87795983	5/2/2018	1629	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
369	87795972	5/5/2018	1350	US 98 N	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	1	0	0
370	87796150	5/14/2018	829	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
371	87216958	5/16/2018	47	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
372	87796185	5/20/2018	1740	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	2	0	0
373	87796232	5/25/2018	1314	LAKELAND MALL	US 98	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
374	87796299	5/31/2018	1330	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
375	87796322	6/4/2018	259	US 98 N	CR 582	11 PEDALCYCLE	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	1	0	0	1
376	87796508	6/14/2018	1551	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
377	87196894	6/18/2018	1613	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
378	85595351	6/26/2018	1505	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
379	87796613	6/28/2018	1945	US 98 N	GRIFFIN RD	36 OTHER POST, POLE, OR SUPPORT	00 NOT CODED	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
380	87179206	7/1/2018	2200	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
381	87796586	7/1/2018	1108	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
382	87196510	7/2/2018	1644	SR 400	SR 539	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	1	0	0
383	87796641	7/6/2018	332	US 98 N	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
384	87796764	7/17/2018	1240	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	4	0	5	0	0
385	87208555	7/19/2018	1645	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
386	87796808	7/21/2018	1457	LAKELAND PK CNTR DR	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
387	87235522	7/25/2018	1248	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
388	87796877	7/26/2018	1725	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
389	87796926	7/31/2018	1307	US 98 N	I 4 W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
390	87797000	7/31/2018	1718	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
391	87796933	8/1/2018	323	GRIFFIN RD	PROVIDENCE RD	25 DITCH	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
392	87796969	8/2/2018	2134	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	4	0	1	0	0
393	87796963	8/3/2018	245	US 98 N	PYRAMID PKWY	39 OTHER FIXED OBJECT (WALL, BUIL	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
394	87796966	8/3/2018	1342	US 98 N	I 4 W	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
395	87195920	8/4/2018	710	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
396	87796990	8/6/2018	846	US 98 N	I 4 W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
397	87796992	8/6/2018	1148	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
398	87796996	8/6/2018	1245	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
399	87797003	8/7/2018	1144	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
400	87216978	8/8/2018	1644	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
401	87797092	8/14/2018	1839	FLORIDA AVE N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
402	87797129	8/17/2018	1812	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
403	87797141	8/17/2018	1935	BREEZEWOOD DR	US 98 N	10 PEDESTRIAN	00 NOT CODED	01 DRY	02 DUSK	01 CLEAR	1	0	1	0	1
404	87797240	8/26/2018	1915	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
405	87276943	8/27/2018	1659	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
406	87195929	8/28/2018	1700	SR 400	KATHLEEN RD	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
407	87797507	8/29/2018	1933	US 98 N	WOODLAND DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
408	87235533	9/5/2018	1901	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	02 CLOUDY	2	0	1	0	0
409	87235536	9/6/2018	251	SR 400	SR 35	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
410	87196618	9/14/2018	0	SR 400	SR 35	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
411	87196619	9/21/2018	2300	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
412	87797540	9/23/2018	1518	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
413	87797562	9/25/2018	1536	US 98 N	I 4	24 CURB	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
414	87196523	9/26/2018	448	SR 400	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
415	87797581	9/26/2018	2139	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
416	87797718	10/7/2018	1023	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
417	87797795	10/9/2018	1625	PROVIDENCE RD	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
418	87797865	10/17/2018	1743	US 98	LAKELAND MALL	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
419	88842836	10/25/2018	930	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
420	88842863	10/26/2018	1734	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
421	87186923	10/27/2018	1650	SR 400	SR 700	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
422	88842918	10/31/2018	2000	US 98 N	GRIFFIN RD	10 PEDESTRIAN	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	1	0
423	88843009	11/8/2018	1315	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
424	87112633	11/10/2018	1320	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
425	88843047	11/12/2018	1825	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0

Interchange: I-4 at US 98 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
426	88843058	11/12/2018	2110	US 98 N	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	4	0	0
427	85158007	11/13/2018	1035	SR 400	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
428	88843093	11/15/2018	1847	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
429	88843102	11/17/2018	1816	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
430	88843143	11/21/2018	950	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
431	88843200	11/23/2018	1730	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
432	88843178	11/26/2018	820	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
433	88843376	12/7/2018	1114	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
434	88843384	12/8/2018	1828	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
435	88843353	12/9/2018	1231	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
436	88843357	12/10/2018	614	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
437	88843369	12/10/2018	1510	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
438	88843459	12/17/2018	2328	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
439	88843463	12/17/2018	1722	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
440	88056098	12/26/2018	1355	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
441	87210807	12/28/2018	2325	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
442	87235562	12/29/2018	1705	SR 400	SR 35	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	05 OIL	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
443	88036031	12/29/2018	1905	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
444	88843620	1/1/2019	1345	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
445	88843622	1/1/2019	1232	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
446	88843623	1/1/2019	1558	LAKELAND PK CNTR DR	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
447	88843677	1/2/2019	1016	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
448	88843651	1/3/2019	2109	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
449	88843652	1/3/2019	1936	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
450	87210810	1/4/2019	125	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
451	88843658	1/4/2019	1600	LAKELAND PK CNTR DR	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
452	88843674	1/6/2019	349	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
453	88843675	1/6/2019	452	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
454	88843834	1/6/2019	452	US 98	I 4	09 OTHER NON-COLLISION	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
455	88843731	1/7/2019	1535	SR 35	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
456	88843789	1/14/2019	1211	GRIFFIN RD	US 98 N	10 PEDESTRIAN	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	1
457	88843799	1/15/2019	1306	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
458	88843802	1/15/2019	2021	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
459	88056106	1/16/2019	1520	SR 400	US 98	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
460	88844048	1/17/2019	5	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
461	88843841	1/18/2019	1945	US 98 N	WOODLAND DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	4	0	2	0	0
462	87252017	1/19/2019	2040	I 4	US 98	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
463	88843847	1/20/2019	1026	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	6	1	11	0	0
464	88843871	1/22/2019	1500	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
465	88843921	1/23/2019	850	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
466	88843900	1/24/2019	1558	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
467	88752421	1/27/2019	1550	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
468	88843970	1/30/2019	1645	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
469	87217014	2/2/2019	315	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	1	0	1	0	0
470	88844078	2/7/2019	1846	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
471	88844146	2/7/2019	942	US 98	SLEEPYHILL RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
472	88844253	2/15/2019	1910	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	3	0	0
473	87276975	2/18/2019	2032	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
474	88036048	2/20/2019	1240	SR 400	SR 700	24 CURB	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
475	87217022	2/26/2019	1725	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
476	88844469	3/7/2019	47	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
477	88070828	3/9/2019	1645	SR 400	SR 35	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
478	88032040	3/10/2019	1035	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
479	88844565	3/10/2019	1720	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
480	87288506	3/12/2019	1520	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
481	88844535	3/13/2019	1833	SR 700	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
482	88844562	3/15/2019	1414	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
483	88844699	3/24/2019	1340	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
484	87208694	3/25/2019	1826	SR 400	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	1	5	0	0
485	88844776	3/29/2019	540	FLORIDA AVE N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
486	87276995	4/4/2019	2054	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
487	88844829	4/4/2019	1926	PYRAMID PKWY	US 98	33 UTILITY POLE/LIGHT SUPPORT	00 NOT CODED	02 WET	03 DAWN	03 RAIN	1	0	1	0	0
488	88844888	4/5/2019	1336	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
489	88035713	4/6/2019	1347	SR 400	US 98	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
490	88844858	4/7/2019	1734	FLORIDA AVE N	ROBSON ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
491	88844952	4/10/2019	1037	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
492	88844949	4/14/2019	747	FLORIDA AVE N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
493	88845020	4/18/2019	1333	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
494	87288515	4/19/2019	1025	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
495	88845123	4/28/2019	1423	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
496	88845186	5/2/2019	2100	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
497	87277005	5/6/2019	2106	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
498	88845262	5/8/2019	720	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
499	88048676	5/12/2019	1652	I 4	US 98	29 CABLE BARRIER	88 UNKNOWN	88 UNKNOWN	88 UNKNOWN	77 OTHER (SEE NARRATIVE)	1	0	1	0	0
500	88845314	5/14/2019	718	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
501	88845432	5/26/2019	1931	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
502	88053055	5/27/2019	1640	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
503	87283703	5/31/2019	201	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
504	88845487	6/1/2019	1912	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
505	88032066	6/2/2019	1620	SR 400	US 98	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
506	88845523	6/4/2019	1511	US 98 N	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	0	0	0
507	88048682	6/7/2019	1109	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	02 CLOUDY	2	0	4	0	0
508	88845608	6/14/2019	1408	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
509	88845610	6/14/2019	1437	GRIFFIN RD	PROVIDENCE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
510	88845622	6/15/2019	1320	LAKELAND SQUARE MA	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0

Interchange: I-4 at US 98 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
511	87276752	6/18/2019	625	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	6	0	0
512	88845684	6/21/2019	457	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
513	88845789	7/1/2019	1724	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
514	88141224	7/4/2019	645	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
515	89346617	7/5/2019	1207	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
516	88048696	7/10/2019	1151	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
517	89346643	7/13/2019	1520	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
518	89346715	7/15/2019	1835	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
519	89346677	7/16/2019	1445	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
520	89346714	7/18/2019	2233	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	3	0	0
521	88070863	7/23/2019	2215	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
522	88111938	7/25/2019	923	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	3	0	0
523	89346869	7/25/2019	1544	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	2	0	0
524	88056156	8/9/2019	835	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
525	89346981	8/12/2019	1514	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	2	0	0
526	89347048	8/15/2019	1320	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
527	89347065	8/20/2019	652	US 98 N	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
528	89347109	8/23/2019	858	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
529	88130236	8/25/2019	1805	SR 400	US 98	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
530	89347224	9/3/2019	1756	US 98 N	PYRAMID PKWY	10 PEDESTRIAN	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	1	0
531	89347258	9/6/2019	35	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
532	89347412	9/20/2019	843	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
533	89347460	9/21/2019	1313	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
534	89347440	9/22/2019	1812	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
535	88162149	9/23/2019	1945	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
536	89347490	9/26/2019	1443	US 98	SLEEPYHILL RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
537	89347498	9/26/2019	2114	PYRAMID PKWY	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
538	89347554	9/26/2019	1432	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
539	89347496	9/27/2019	825	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
540	88130246	9/30/2019	600	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
541	89347524	9/30/2019	1046	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
542	89347534	9/30/2019	1702	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
543	89347542	9/30/2019	1028	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
544	89347552	10/2/2019	1146	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	5	0	0	0	0
545	89347572	10/3/2019	1945	FLORIDA AVE N	ROBSON ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
546	89347714	10/6/2019	1705	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
547	88173789	10/9/2019	1638	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
548	89347685	10/12/2019	1500	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
549	89347687	10/12/2019	1135	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
550	89347693	10/13/2019	1441	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
551	88154436	10/14/2019	1625	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
552	89347802	10/23/2019	1155	CR 582	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
553	88226767	10/29/2019	632	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
554	88166316	11/2/2019	1240	I 4	US 98	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
555	88220053	11/6/2019	400	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
556	89348035	11/6/2019	1720	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
557	89348133	11/9/2019	1158	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
558	88162159	11/10/2019	1425	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
559	89348226	11/11/2019	1712	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
560	88154445	11/14/2019	840	SR 400	MM 32	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
561	88173803	11/16/2019	2105	I 4	US 98	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
562	89348253	11/18/2019	1539	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
563	89348146	11/20/2019	1554	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
564	89348223	11/23/2019	1810	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
565	89348393	11/25/2019	1830	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
566	89348201	11/26/2019	725	US 98	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
567	89348260	12/1/2019	1627	US 98 N	CR 582	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
568	88262329	12/3/2019	1816	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
569	88162166	12/17/2019	640	US 98	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	04 FOG, SMOG, SMOKE	2	0	2	0	0
570	89348456	12/18/2019	815	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
571	89348589	12/25/2019	648	US 98	I 4	11 PEDALCYCLE	00 NOT CODED	01 DRY	03 DAWN	01 CLEAR	1	0	1	0	1
572	88140511	12/26/2019	348	SR 400	CR 582	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0

Mainline Segment: I-4 from US 98 to N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84484279	1/11/2015	1955	SR 400	MILE MARKER #33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
2	84501375	2/10/2015	1500	SR 400	US 98	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
3	84525657	2/27/2015	1445	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
4	83790290	3/18/2015	1640	SR 400	SR 700	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
5	81962663	4/22/2015	1800	SR 400	SOCRUM LOOP RD N	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
6	84516881	6/8/2015	1915	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
7	84871685	7/23/2015	1950	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	1	0	2	0	0
8	85138958	7/27/2015	1550	SR 400	SR 700	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
9	84894981	8/8/2015	1825	I 4	MILE MARKER #36	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
10	84886751	9/24/2015	2240	SR 400	MILE MARKER #33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
11	85150395	1/16/2016	13	I 4	MILE MARKER #33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
12	85274090	2/1/2016	1228	I 4	MILE MARKER #33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
13	83741204	2/23/2016	1005	SR 400	SR 700	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
14	85152952	2/24/2016	1414	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
15	85254534	3/28/2016	1657	I 4	CARPENTERS HOME RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
16	85246907	3/30/2016	1030	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
17	85254885	4/10/2016	330	I 4	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
18	85180712	4/22/2016	1550	SR 400	US 98	13 ANIMAL	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
19	85197201	4/29/2016	741	I 4	MM33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
20	85226961	5/31/2016	605	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	2	0	0
21	85290619	5/31/2016	2218	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
22	85226964	6/1/2016	1130	SR 400	MILE MARKER #33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
23	85254913	6/15/2016	2149	I 4	US 98	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
24	85356791	7/7/2016	2250	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
25	85356809	8/18/2016	1915	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
26	85286050	8/28/2016	1310	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
27	85356818	9/3/2016	2045	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
28	85306999	9/7/2016	1240	SR 400	US 98	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
29	85371217	9/10/2016	230	I 4	SOCRUM LOOP	36 OTHER POST, POLE, OR SUPPORT	88 UNKNOWN	01 DRY	02 DUSK	01 CLEAR	1	0	1	0	0
30	85386973	9/18/2016	2145	I 4	MILE MARKER #33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
31	85308902	9/27/2016	1640	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
32	85371223	9/28/2016	240	I 4	SOCRUM LOOP RD N	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	1	0	0
33	84881125	10/9/2016	700	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
34	83685094	11/27/2016	818	SR 400	MM 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
35	85390366	1/13/2017	311	I 4	CARPENTERS HOME RD	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	1	1	0	0
36	85370280	1/13/2017	311	SR 400	CARPENTERS HOME RD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
37	85263351	2/21/2017	2045	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
38	85409155	4/20/2017	2144	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
39	85442346	5/23/2017	1635	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
40	85442347	5/23/2017	1640	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
41	85503709	5/30/2017	2100	I 4	CARPENTERS HOME RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
42	85503710	6/8/2017	2250	SR 400	CARPENTERS HOME RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
43	84877545	6/23/2017	630	I 4	CR 582	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	1	0	0	0
44	85534288	6/29/2017	630	SR 400	MM 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
45	85474729	7/9/2017	1830	SR 400	MM 33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
46	85409184	7/11/2017	1840	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
47	85534300	7/23/2017	1135	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
48	85534308	7/29/2017	1425	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
49	85543341	8/13/2017	944	SR 400	US 98	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
50	86939130	8/24/2017	655	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	5	0	2	0	0
51	85579447	8/25/2017	1800	SR 400	CARPENTERS WAY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
52	82069680	10/16/2017	930	SR 400	MILE MARKER #33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
53	85532620	11/20/2017	744	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	83741224	12/22/2017	1515	SR 400	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
55	85595310	12/23/2017	255	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
56	85531316	12/31/2017	1640	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
57	87139770	1/4/2018	1234	SR 400	SR 35	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
58	85579903	1/14/2018	655	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
59	85573908	3/10/2018	646	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
60	87123160	3/11/2018	1145	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
61	85603208	4/14/2018	1640	SR 400	MM 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
62	87195893	4/25/2018	1615	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
63	87162252	5/4/2018	33	I 4	SOCRUM LOOP N	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	1	1	1	0
64	87170434	5/12/2018	1722	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
65	87162256	5/14/2018	2130	I 4	CARPENTERS WAY	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
66	87195904	5/23/2018	1530	SR 400	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
67	87162271	6/6/2018	10	I 4	US 98	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	2	0	0
68	87170452	6/29/2018	1530	SR 400	SOCRUM LOOP	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
69	87158165	7/6/2018	115	SR 400	MM 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
70	83741233	7/8/2018	1215	I 4	SR 700	19 IMPACT ATTENUATOR/CRASH CUSION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
71	87162281	7/18/2018	1509	I 4	CARPENTERS WAY	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
72	87235518	7/21/2018	2340	SR 400	MM 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
73	87235516	7/21/2018	1838	SR 400	MM 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
74	87198628	8/7/2018	1950	SR 400	US 98	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	0	0	0
75	87235535	9/6/2018	113	SR 400	MM 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
76	87223322	9/27/2018	1130	I 4	MM 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
77	87223328	10/12/2018	208	SR 400	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
78	88751601	10/29/2018	845	I 4	CARPENTERS WAY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
79	87276702	11/14/2018	345	SR 400	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
80	87276809	12/13/2018	1050	SR 400	US 98	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
81	88070824	2/25/2019	1645	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
82	87252023	2/26/2019	1626	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
83	87295078	3/18/2019	1036	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	4	0	3	0	0
84	87300473	3/18/2019	1030	SR 400	SOCRUM LOOP RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
85	87289608	4/18/2019	1446	I 4	SOCRUM LOOP RD	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0

Mainline Segment: I-4 from US 98 to N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	88089761	4/23/2019	1406	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
87	88011329	5/2/2019	653	I 4	US 98	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
88	88048674	5/8/2019	149	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
89	87246880	5/17/2019	438	SR 400	US 98	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
90	88111927	6/12/2019	1331	SR 400	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
91	87289619	6/21/2019	1710	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
92	88070856	7/7/2019	2000	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
93	88035311	7/21/2019	8	SR 400	SOCRUM LOOP	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
94	88111937	7/24/2019	800	SR 400	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
95	88070867	8/6/2019	2200	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
96	88173776	8/12/2019	1232	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	4	0	0
97	88203143	9/24/2019	135	I 4	MILE MARKER #33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
98	88130264	10/26/2019	1455	SR 400	SR 700	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
99	88089799	10/26/2019	1005	I 4	SOCRUM LOOP RD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
100	88111970	10/26/2019	2201	SR 400	SOCRUM LOOP	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
101	88220055	11/11/2019	2000	SR 400	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
102	88262331	12/12/2019	650	I 4	US 98	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
103	88122273	12/13/2019	1000	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
104	88215610	12/17/2019	941	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
105	88166326	12/17/2019	35	I 4	MILE MARKER #33	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	2	0	0

Interchange: I-4 at N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84951920	1/1/2015	437	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
2	84484416	1/11/2015	1345	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
3	85728979	1/27/2015	1554	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
4	85729158	2/11/2015	934	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
5	85729069	2/14/2015	1926	LAKELAND HILLS BLVD	MELODY RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
6	84525659	2/28/2015	1645	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
7	85729147	3/5/2015	2002	SR 33	ARBOR GLEN	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
8	85729471	3/5/2015	1523	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
9	84890332	3/22/2015	310	I 4	SOCRUM LOOP RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
10	84501392	3/26/2015	2225	SR 400	MM 34	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
11	84564608	3/26/2015	1110	I 4	MILE MARKER #34	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
12	85728814	3/27/2015	311	SR 33	SOCRUM LOOP RD	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
13	84879716	3/29/2015	1745	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
14	84551362	4/13/2015	620	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
15	84951984	4/22/2015	743	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
16	84482300	4/27/2015	830	I 4	SOCRUM LOOP RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
17	85730003	4/28/2015	1052	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	84545393	5/4/2015	32	I 4	MILE MARKER #34	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	1	0	0	0
19	84527393	5/20/2015	1620	SR 400	MM 34	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
20	85730413	5/20/2015	1552	OLD COMBEE RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
21	84516879	6/5/2015	1830	LAKELAND HILLS BLVD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	02 CLOUDY	2	0	2	0	0
22	85729597	6/8/2015	1842	SR 33	SOCRUM LOOP RD	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	1	0	0
23	84564619	6/9/2015	1351	I 4	MILE MAKER#33	01 OVERTURN/ROLLOVER	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
24	84952164	6/15/2015	535	SR 33	OLD COMBEE RD	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
25	84564622	6/24/2015	2206	I 4	MILE MARKER #34	39 OTHER FIXED OBJECT (WALL, BUIL	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
26	85688370	6/26/2015	726	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
27	84564625	7/3/2015	235	I 4	LAKELAND HILLS BLVD	01 OVERTURN/ROLLOVER	88 UNKNOWN	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
28	83742408	7/4/2015	1910	I 4	SOCRUM LOOP RD	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
29	85730624	7/9/2015	1227	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
30	80289642	7/13/2015	1258	I 4	SOCRUM LOOP RD N	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
31	86126274	7/14/2015	610	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	02 DUSK	01 CLEAR	2	0	2	0	0
32	85730659	7/17/2015	1330	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
33	84531293	7/24/2015	815	SR 400	MM 34	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
34	86082605	7/26/2015	2215	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
35	86126745	7/30/2015	1000	SR 33	SOCRUM LOOP RD	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
36	84545435	8/9/2015	1850	SR 400	MILE MARKER #34	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
37	84564634	8/11/2015	1553	I 4	MILE MARKER #33	05 CARGO/EQUIPMENT LOSS OR SHIFT	88 UNKNOWN	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
38	84564638	8/12/2015	1900	I 4	MILE MARKER#33	09 OTHER NON-COLLISION	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
39	86126925	8/13/2015	1157	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
40	85730290	8/18/2015	2043	N SOCRUM LOOP RD	0	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
41	83783646	9/7/2015	1900	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
42	84865594	9/10/2015	1945	SR 400	SOCRUM LOOP RD	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
43	85138978	9/10/2015	1910	SR 400	OLD COMBEE RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	2	0	0	0	0
44	85144977	9/14/2015	715	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
45	84894992	9/20/2015	1705	SR 400	SR 700	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
46	84541373	10/12/2015	1509	I 4	MILE MARKER #36	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
47	85139009	10/27/2015	1128	SR 400	OLD COMBEE RD	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
48	84531339	11/6/2015	2250	I 4	SOCRUM LOOP RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
49	86127226	11/9/2015	1649	LAKELAND HILLS BLVD	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
50	82254423	11/21/2015	1114	I 4	SOCRUM LOOP RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
51	85226914	12/21/2015	2317	I 4	US 98	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
52	84877536	12/22/2015	700	I 4	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
53	86128667	12/29/2015	1232	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
54	86128537	12/30/2015	2319	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
55	86128196	1/1/2016	935	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
56	86128279	1/7/2016	1656	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
57	85154081	1/30/2016	1625	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
58	85254593	2/1/2016	15	SR 400	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	88 UNKNOWN	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
59	86345937	3/9/2016	2216	N SOCRUM LOOP RD	0	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
60	86345640	3/23/2016	1913	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	1	0	0
61	85180709	3/28/2016	1511	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
62	85180139	4/3/2016	1810	I 4	OLD COMBEE RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	3	0	0
63	85286021	4/6/2016	932	SR 400	SOCRUM LOOP RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
64	86346443	4/12/2016	1427	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
65	85246916	4/13/2016	620	SR 400	MILE MARKER #34	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
66	86346786	5/5/2016	1	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	1	0	0	0
67	85180714	5/7/2016	645	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
68	85243925	5/15/2016	1952	I 4	MILE MARKER #34	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	02 CLOUDY	3	0	0	0	0
69	86347016	5/30/2016	1528	LAKELAND HILLS BLVD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
70	85256695	6/8/2016	1510	SR 400	MM 34	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
71	86347193	6/14/2016	1846	N SOCRUM LOOP RD	33	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
72	85254571	7/7/2016	1525	SR 400	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
73	86346680	7/26/2016	1521	CR-582	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
74	86347881	7/27/2016	1219	N SOCRUM LOOP RD	0	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
75	86347170	8/16/2016	2106	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
76	86348127	8/17/2016	1205	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
77	86348317	8/30/2016	1550	SR 400	SOCRUM LOOP RD N	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
78	85356817	9/2/2016	2025	I 4	US 98	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
79	86348355	9/6/2016	820	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
80	86347835	9/7/2016	614	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
81	86346860	9/9/2016	1753	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
82	86632572	9/11/2016	2238	N SOCRUM LOOP RD	OLD COMBEE RD	24 CURB	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
83	86632594	9/13/2016	1556	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
84	85274149	10/9/2016	658	I 4	MM34	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
85	85396940	10/27/2016	2050	I 4	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	3	0	0

Interchange: I-4 at N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	86818393	11/28/2016	1429	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
87	86632979	12/10/2016	1818	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
88	85411895	12/23/2016	520	SR 400	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
89	86635205	1/18/2017	905	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
90	86633955	2/16/2017	1205	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
91	86633981	2/19/2017	42	SR 33	LAKELAND HARBOR R	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
92	85409143	2/21/2017	1445	SR 400	MM 34	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
93	85371247	3/2/2017	400	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
94	85420037	3/13/2017	630	SR 400	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
95	86634366	3/17/2017	1725	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
96	85442333	3/25/2017	455	N SOCRUM LOOP RD	33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
97	85370295	3/31/2017	1834	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
98	85501090	4/8/2017	1756	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
99	86634758	4/13/2017	1637	N SOCRUM LOOP RD	POST LN	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
100	86634814	4/27/2017	2355	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
101	85501098	5/1/2017	1025	I 4	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
102	86634855	5/1/2017	1739	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
103	85503535	5/12/2017	1425	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	5	0	0
104	85442348	5/23/2017	1830	I 4	SR 33	01 OVERTURN/ROLLOVER	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
105	87342211	6/10/2017	1543	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
106	87342255	6/14/2017	2332	LAKELAND HILLS BLVD	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
107	85534286	6/26/2017	1510	SR 400	MM 34	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
108	81953856	7/9/2017	2000	SR 400	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
109	87342529	7/10/2017	435	N SOCRUM LOOP RD	33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
110	87342663	7/20/2017	1517	SR 33	I 4	27 GUARDRAIL FACE	00 NOT CODED	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
111	87342676	7/22/2017	1341	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	06 REAR TO SIDE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
112	87342678	7/22/2017	1345	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
113	85503568	7/30/2017	1130	SR 400	OLD COMBEE RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
114	87343046	8/23/2017	1749	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
115	85574355	8/25/2017	2152	I 4	OLD COMBEE RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
116	87343077	8/26/2017	1140	SR 33	MELODY RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
117	87343086	8/26/2017	1648	SR 33	MELODY LANE	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
118	85568617	8/27/2017	1530	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
119	85501756	8/30/2017	1620	SR 400	MM 34	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
120	87343191	9/1/2017	1715	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
121	85568620	9/8/2017	1250	SR 400	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
122	87343239	9/11/2017	543	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
123	87343338	9/17/2017	2005	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
124	87343439	9/28/2017	1625	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
125	87343514	10/4/2017	830	CR-582	POST LN	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	1	0	0
126	87343551	10/5/2017	634	SR 33	MELODY RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
127	87343571	10/9/2017	631	N SOCRUM LOOP RD	FERNERY RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
128	87343644	10/14/2017	2120	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
129	87343655	10/15/2017	1213	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
130	87343714	10/19/2017	635	N SOCRUM LOOP RD	33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
131	87343831	10/29/2017	242	SR 33	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
132	87343893	10/31/2017	1655	N SOCRUM LOOP RD	POST LN	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
133	87344031	11/15/2017	1850	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
134	87344167	11/20/2017	1839	SR 33	MELODY LANE	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	3	0	1	0	0
135	85532621	11/22/2017	1012	SR 400	SR 33	25 DITCH	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
136	85568657	11/22/2017	800	SR 400	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
137	87344178	11/27/2017	1043	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
138	85499057	12/7/2017	554	SR 400	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
139	87344362	12/12/2017	808	CR-582	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
140	87344465	12/17/2017	1829	N SOCRUM LOOP RD	33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
141	87344569	12/28/2017	1921	N SOCRUM LOOP RD	33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
142	87344586	12/31/2017	1445	N SOCRUM LOOP RD	0	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
143	87795177	1/1/2018	1858	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
144	85595313	1/6/2018	1155	SR 400	MM 34	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
145	87344656	1/7/2018	1500	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
146	87344734	1/14/2018	647	SR 33	MELODY LANE	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
147	87665870	1/14/2018	2310	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
148	87344801	1/19/2018	2110	N SOCRUM LOOP RD	0	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
149	85568668	1/20/2018	2220	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
150	87123146	2/1/2018	1805	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
151	87333086	2/15/2018	2207	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
152	87794987	2/15/2018	1349	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
153	87795014	2/18/2018	944	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
154	87666165	2/22/2018	2304	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
155	87795088	2/24/2018	1809	SR 33	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	6	0	0
156	87795113	2/26/2018	529	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	1	0	0	0
157	85595318	2/28/2018	1255	SR 400	SOCRUM LOOP RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
158	87795188	3/1/2018	1938	N SOCRUM LOOP RD	POST LN	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
159	87795191	3/2/2018	2028	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
160	87123161	3/11/2018	1320	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
161	85605731	4/15/2018	11	I 4	SOCRUM LOOP RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	2	0	0
162	87795974	5/4/2018	2219	N SOCRUM LOOP RD	LAKELAND PARK BLVD	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
163	87170432	5/5/2018	1556	I 4	LAKELAND HILLS BLVD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
164	87196880	5/14/2018	1443	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
165	87139824	5/29/2018	1109	SR 400	MM 34	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
166	87157591	6/1/2018	240	I 4	SOCRUM LOOP RD N	30 CONCRETE TRAFFIC BARRIER	88 UNKNOWN	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
167	87170441	6/5/2018	751	SR 400	SOCRUM LOOP	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
168	87186892	6/16/2018	2300	SR 400	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
169	87796466	6/19/2018	2130	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
170	87796583	6/30/2018	2105	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0

Interchange: I-4 at N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	87796590	7/1/2018	1449	SR 33	MELODY LANE	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
172	87796757	7/17/2018	910	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
173	87196513	7/18/2018	1143	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
174	83741235	7/23/2018	1250	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
175	87196908	7/23/2018	619	SR 400	US 98	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	1	0	0
176	87235524	7/29/2018	1651	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
177	87796908	7/30/2018	1126	CR-582	ARTEVA DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
178	87196916	8/9/2018	1819	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
179	87797182	8/22/2018	2124	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
180	87797255	8/28/2018	2118	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
181	87797301	8/31/2018	2332	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
182	87797297	9/1/2018	1824	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
183	87276877	9/19/2018	2130	I 4	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
184	87797589	9/26/2018	745	OLD COMBEE RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
185	87797666	10/4/2018	1034	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
186	87797697	10/6/2018	2218	SR 33	MELODY RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
187	87797699	10/7/2018	1017	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
188	87797703	10/7/2018	1301	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
189	87220290	10/10/2018	720	SR 400	SOCRUM LOOP	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
190	88750647	10/10/2018	1424	OLD COMBEE RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
191	88842870	10/24/2018	1517	OLD COMBEE RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
192	87223331	10/27/2018	1726	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
193	87208588	11/1/2018	1700	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
194	88842992	11/6/2018	1522	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
195	88843105	11/16/2018	1903	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
196	88843112	11/18/2018	1700	SR 33	CR 582	15 PARKED MOTOR VEHICLE	00 NOT CODED	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
197	88843139	11/19/2018	1020	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
198	88843273	12/2/2018	1936	N SOCRUM LOOP RD	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	3	0	0
199	88843388	12/10/2018	1713	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
200	88843911	1/23/2019	1018	LAKELAND HILLS BLVD	MELODY LANE	01 OVERTURN/ROLLOVER	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
201	88056111	2/2/2019	1230	SR 400	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
202	88844088	2/8/2019	2249	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	2	0	0
203	88056112	2/12/2019	1345	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
204	88844452	3/1/2019	744	OLD COMBEE RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
205	89009120	3/6/2019	645	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
206	88844492	3/8/2019	537	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
207	88844568	3/15/2019	1950	SR 33	MELODY LANE	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
208	87276991	3/18/2019	1307	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
209	87276992	4/4/2019	1008	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	1	0	0
210	87276994	4/4/2019	2012	I 4	SOCRUM LOOP RD N	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
211	88844847	4/4/2019	1430	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
212	87252411	4/24/2019	1740	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
213	88845506	5/29/2019	2200	SR 33	ARBOR GLEN	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
214	87276855	6/1/2019	327	SR 400	US 98	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	1	0	1	0
215	88048685	6/8/2019	1437	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	0	0	0
216	88044668	6/26/2019	1820	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
217	88168902	7/22/2019	1458	I 4	SOCRUM LOOP RD N	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
218	88111942	8/5/2019	815	SR 400	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
219	89346905	8/5/2019	1723	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
220	89346964	8/10/2019	9	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
221	88111951	9/10/2019	608	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
222	89347441	9/18/2019	1200	SR 33	OLD COMBEE RD	24 CURB	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
223	88101241	9/21/2019	734	I 4	SOCRUM LOOP RD N	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	88 UNKNOWN	88 UNKNOWN	77 OTHER (SEE NARRATIVE)	1	0	1	0	0
224	89347519	9/29/2019	1733	SR 33	ARBOR GLEN	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
225	88154428	10/3/2019	1845	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
226	88173788	10/8/2019	1220	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
227	88076423	10/11/2019	2330	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
228	88130257	10/17/2019	1950	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
229	88102907	10/20/2019	1617	I 4	SOCRUM LOOP RD N	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
230	89347785	10/21/2019	2105	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
231	85591165	10/23/2019	1842	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
232	89347838	10/25/2019	1408	OLD COMBEE RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
233	89347913	10/31/2019	2027	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
234	88166315	11/2/2019	840	I 4	SOCRUM LOOP RD	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
235	88166318	11/8/2019	815	I 4	SOCRUM LOOP RD N	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
236	88076435	11/19/2019	1730	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
237	89348158	11/22/2019	1730	SR 33	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	06 DARK-UNKNOWN LIGHTING	01 CLEAR	2	0	1	0	0
238	89348224	11/22/2019	221	SR 33	OLD COMBEE RD	34 TRAFFIC SIGN SUPPORT	00 NOT CODED	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
239	88220057	11/24/2019	30	I 4	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	2	0	0
240	89372183	12/2/2019	1708	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
241	88262334	12/19/2019	640	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	0	0	0

Mainline Segment: I-4 from N Socrum Loop Road & SR 33/Lakeland Hills Boulevard to SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84527504	1/3/2015	2300	I 4	SR 33	09 OTHER NON-COLLISION	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
2	83789646	1/11/2015	1610	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
3	83787128	2/12/2015	1424	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
4	83771097	2/12/2015	1200	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	1	0	0	0
5	84535799	2/15/2015	701	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	4	0	0
6	84545385	2/20/2015	302	SR 400	MILE MARKER #36	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
7	84569142	2/23/2015	1250	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
8	83834010	2/24/2015	440	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	2	1	1	0	0
9	83776159	4/3/2015	705	I 4	MILE MARKER #35	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
10	83784864	4/4/2015	300	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
11	84890346	4/17/2015	1355	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
12	84558718	4/18/2015	1238	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
13	84879729	4/19/2015	1400	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
14	84890349	4/26/2015	915	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
15	84545404	5/18/2015	2334	SR 400	MILE MARKER #37	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
16	84545410	5/31/2015	2000	SR 400	MM 37	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
17	84569174	5/31/2015	1300	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
18	83469265	6/5/2015	1715	SR 400	MILE MARKER #35	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
19	84516880	6/6/2015	1415	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
20	84894686	6/18/2015	937	I 4	SOCRUM LOOP RD N	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
21	84889766	6/22/2015	12	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
22	84856581	7/20/2015	1230	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
23	84886740	8/13/2015	725	SR 400	MM 36	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
24	83742414	8/20/2015	1545	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
25	84886754	10/3/2015	410	SR 400	MM 36	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
26	84889785	10/10/2015	425	I 4	SR 33	37 FENCE	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
27	83741198	10/27/2015	930	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
28	85149887	11/6/2015	1930	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
29	85152924	11/21/2015	1912	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
30	84895005	12/13/2015	30	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
31	85154072	12/19/2015	1410	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
32	84899187	12/23/2015	1845	I 4	MILE MARKER #36	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
33	84871694	12/29/2015	642	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
34	84871696	1/3/2016	1050	I 4	SOCRUM LOOP RD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
35	85149943	1/3/2016	1028	SR 400	MM35	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
36	85149945	1/7/2016	1305	SR 400	MM35	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	88 UNKNOWN	88 UNKNOWN	77 OTHER (SEE NARRATIVE)	1	0	0	0	0
37	85246870	1/14/2016	640	SR 400	MILE MARKER #35	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
38	85155128	1/19/2016	1050	I 4	SR 33	18 OTHER NON-FIXED OBJECT	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
39	85152938	1/22/2016	1008	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
40	85226924	1/26/2016	540	SR 400	OLD COMBEE RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
41	84899922	1/30/2016	1400	SR 400	MILE MARKER #37	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
42	85254862	2/7/2016	1715	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
43	85154082	2/16/2016	735	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	2	0	0	0	0
44	85226939	3/5/2016	645	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
45	85180703	3/10/2016	1215	SR 400	MM 34	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
46	85180705	3/15/2016	1605	SR 400	SOCRUM LOOP RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
47	85151275	3/18/2016	441	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
48	85254886	4/13/2016	1826	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
49	86442974	5/23/2016	1957	I 4	MILE MARKER #37	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
50	85254906	5/27/2016	2207	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
51	84498291	5/30/2016	542	I 4	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
52	85254559	6/5/2016	2348	SR 400	OLD COMBEE RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
53	85286040	6/6/2016	607	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	1	0	0
54	85254912	6/15/2016	445	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
55	85341066	6/17/2016	1435	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
56	85346670	6/17/2016	1525	SR 400	MILE MARKER #34	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
57	85356794	7/13/2016	150	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
58	85254581	7/23/2016	2132	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
59	85154157	8/2/2016	600	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	02 CLOUDY	1	0	0	0	0
60	85341088	8/2/2016	650	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	3	0	0	0	0
61	85194227	8/12/2016	305	I 4	OLD COMBEE RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	1	2	0	0
62	85308885	8/21/2016	1625	SR 400	MM 37	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
63	85342736	8/27/2016	630	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
64	85351936	8/29/2016	1340	SR 400	OLD COMBEE RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
65	85341097	8/30/2016	1610	I 4	MM 36	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
66	85336084	8/30/2016	1710	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
67	85356816	9/2/2016	254	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
68	85342738	9/10/2016	1204	SR 400	MM 34	01 OVERTURN/ROLLOVER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
69	85336092	9/18/2016	1900	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
70	85308898	9/18/2016	1840	SR 400	MM35	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
71	85396933	9/30/2016	2335	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
72	85307017	10/10/2016	1600	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
73	85370257	10/19/2016	2320	SR 400	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
74	85356844	11/21/2016	248	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
75	85346729	12/15/2016	601	SR 400	MILE MARKER #34	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
76	85342769	12/26/2016	2033	I 4	MILE MARKER #37	18 OTHER NON-FIXED OBJECT	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
77	85342771	1/3/2017	1555	I 4	SR 33	01 OVERTURN/ROLLOVER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
78	85356854	1/3/2017	45	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
79	85426545	1/6/2017	700	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
80	85409145	2/21/2017	1749	SR 400	MM 35	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
81	85420034	3/8/2017	1633	SR 400	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
82	85154685	3/25/2017	1045	I 4	OLD COMBEE RD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
83	85383725	4/2/2017	1635	SR 400	MM 35	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
84	85478655	5/4/2017	621	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
85	85478654	5/4/2017	621	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0

Mainline Segment: I-4 from N Socrum Loop Road & SR 33/Lakeland Hills Boulevard to SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85506743	5/4/2017	650	SR 400	MM 35	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	01 CLEAR	1	0	1	0	0
87	85409162	5/16/2017	326	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
88	85473451	5/29/2017	1545	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
89	85409166	5/30/2017	1702	SR 400	MM 37	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
90	85452052	6/2/2017	1038	I 4	SR 33	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
91	85501736	6/26/2017	405	SR 400	MM 35	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
92	85442365	6/30/2017	53	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
93	85409180	7/6/2017	1559	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
94	85503555	7/8/2017	1530	SR 400	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
95	85540036	7/10/2017	1120	I 4	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
96	85558529	7/25/2017	822	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
97	85501744	7/30/2017	923	SR 400	MM 35	25 DITCH	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
98	85501143	8/7/2017	1737	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
99	85501144	8/9/2017	2322	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
100	85503575	8/19/2017	1745	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
101	85534316	8/22/2017	830	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
102	85474744	8/26/2017	755	SR 400	MM 37	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
103	85513223	9/8/2017	300	SR 400	MM 35	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
104	85601590	9/29/2017	1845	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	3	0	2	0	0
105	85532608	10/16/2017	208	SR 400	MILE MARKER #35	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
106	85579883	10/27/2017	2350	SR 400	MM 36	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
107	85579884	10/28/2017	225	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
108	85574367	11/7/2017	1817	I 4	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
109	85573885	12/8/2017	400	I 4	SR 33	29 CABLE BARRIER	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
110	85573884	12/8/2017	525	I 4	SR 33	37 FENCE	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
111	85499067	12/30/2017	1426	SR 400	OLD COMBEE RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
112	87332118	12/31/2017	1632	I 4	MILE MARKER #35	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
113	85499071	1/6/2018	1844	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
114	85605721	1/20/2018	1952	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	2	0	0
115	85579907	1/25/2018	1855	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
116	87123144	1/27/2018	1845	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
117	85520450	2/6/2018	757	SR 400	OLD COMBEE RD	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
118	85605726	3/17/2018	2049	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
119	87195888	3/30/2018	720	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
120	85603209	4/14/2018	1850	SR 400	MM 37	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
121	85595337	4/25/2018	1510	SR 400	MM 37	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
122	87196881	5/14/2018	1740	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
123	87195902	5/17/2018	610	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
124	87123186	5/18/2018	1745	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
125	87162259	5/19/2018	500	I 4	OLD COMBEE RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
126	87162264	5/20/2018	0	I 4	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
127	87158151	5/20/2018	1920	SR 400	MM 36	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
128	87162263	5/20/2018	0	I 4	MM 37	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	1	0	0
129	87216963	5/31/2018	1210	I 4	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
130	87158155	6/3/2018	1640	SR 400	MM 35	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
131	87157592	6/6/2018	1816	I 4	SR 33	01 OVERTURN/ROLLOVER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
132	87156004	6/13/2018	425	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	1	0	0
133	87156006	6/13/2018	441	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
134	85531336	6/13/2018	427	SR 400	SR 33 N	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	04 FOG, SMOG, SMOKE	3	0	0	0	0
135	87156012	6/26/2018	1410	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
136	87158163	7/4/2018	100	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	1	0	0
137	87196902	7/8/2018	1621	SR 400	SR 33	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
138	87196903	7/17/2018	1216	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
139	87186898	7/18/2018	1917	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
140	87158168	7/27/2018	1455	SR 400	MM 36	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
141	87235526	7/31/2018	1118	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
142	87235527	8/1/2018	1144	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
143	87198625	8/2/2018	1935	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	1	2	0	0
144	87208565	8/15/2018	2300	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
145	87276682	8/24/2018	1635	SR 400	MM 37	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
146	87216985	8/28/2018	1809	I 4	OLD COMBEE RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
147	87196923	9/2/2018	1646	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
148	87171768	9/14/2018	1730	SR 400	MM 36	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
149	87273097	9/14/2018	1755	I 4	MILE MARKER #36	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
150	87220288	10/7/2018	1030	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
151	87196021	11/3/2018	1825	SR 400	MILE MARKER #36	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
152	87276805	11/13/2018	2139	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
153	87276806	11/20/2018	2329	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
154	88032030	11/20/2018	740	SR 400	MILE MARKER #35	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
155	87235558	11/24/2018	1328	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	5	0	0
156	87276900	12/7/2018	1100	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
157	87276902	12/8/2018	1215	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
158	88036026	12/20/2018	520	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
159	88070809	1/5/2019	345	SR 400	MM 36	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
160	87277135	1/7/2019	945	SR 400	SR 33	06 FELL/JUMPED FROM MOTOR VEHICLE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
161	87276968	1/7/2019	1010	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
162	88070811	1/10/2019	10	SR 400	MM 35	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
163	87157638	2/12/2019	1440	SR 400	MM 35	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
164	87235573	2/12/2019	453	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	3	0	0	0	0
165	87276920	2/21/2019	610	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
166	87277156	3/3/2019	651	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	03 DAWN	03 RAIN	2	0	1	0	0
167	88035275	3/10/2019	1100	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
168	88036056	3/15/2019	1810	SR 400	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
169	87300475	3/20/2019	709	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
170	87276729	3/25/2019	1530	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	4	0	0

Mainline Segment: I-4 from N Socrum Loop Road & SR 33/Lakeland Hills Boulevard to SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	87276996	4/13/2019	1532	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
172	87277000	4/22/2019	2332	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
173	88056129	5/1/2019	2000	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
174	88111914	5/5/2019	1511	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
175	88044184	5/9/2019	1718	SR 400	MILE MARKER #37	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
176	88036080	5/20/2019	1130	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
177	88141210	5/30/2019	1958	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
178	88141209	5/30/2019	1749	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
179	88141219	6/8/2019	2025	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
180	88102880	6/15/2019	241	I 4	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
181	88141234	7/22/2019	1621	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
182	88111936	7/23/2019	1159	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
183	88173777	8/12/2019	1153	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
184	88003651	8/21/2019	1700	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
185	88166293	8/28/2019	1545	I 4	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
186	88056159	9/9/2019	2230	SR 400	OLD GRADE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
187	88056160	9/10/2019	345	SR 400	OLD COMBEE RD	16 WORK ZONE/MAINTENANCE EQUIPMEN	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
188	88166299	9/21/2019	550	I 4	OLD COMBEE RD	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
189	88089793	10/18/2019	558	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
190	88111967	10/20/2019	109	I 4	OLD COMBEE RD	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
191	88111968	10/24/2019	2345	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
192	88168936	11/8/2019	513	SR 400	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
193	88076428	11/9/2019	1237	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
194	88226776	11/23/2019	220	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
195	87233528	12/19/2019	655	SR 400	MM 36	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0

Interchange: I-4 at SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84484277	1/11/2015	1615	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
2	84484278	1/11/2015	1650	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
3	83834006	1/22/2015	1820	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
4	83814372	1/23/2015	1115	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
5	84558693	2/27/2015	1040	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
6	83834017	3/2/2015	1755	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
7	84545390	3/9/2015	850	SR 400	LAKELAND HILLS BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
8	84543329	3/22/2015	1045	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
9	84501391	3/26/2015	350	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
10	85729775	4/17/2015	1802	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	02 DUSK	01 CLEAR	2	0	2	0	0
11	84551366	4/23/2015	2143	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	2	0	0
12	84894666	5/11/2015	1714	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
13	84551378	6/2/2015	800	I 4	SR 33	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
14	83742404	6/14/2015	1320	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
15	84892577	6/19/2015	1955	SR 400	SR 33	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
16	84899169	6/23/2015	1950	I 4	MILE MARKER #38	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
17	84516886	7/5/2015	1040	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	83819878	7/12/2015	1718	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
19	84894970	7/19/2015	1640	SR 400	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
20	84879765	7/24/2015	405	SR 400	SR 33	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
21	85138959	7/27/2015	1720	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
22	85138961	7/31/2015	1358	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
23	84892600	8/20/2015	1510	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	3	0	1	0	0
24	84889771	8/29/2015	438	I 4	SR 33	01 OVERTURN/ROLLOVER	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
25	86126495	8/29/2015	202	SR 33	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	06 DARK-UNKNOWN LIGHTING	01 CLEAR	1	0	0	0	0
26	84889774	9/5/2015	2205	I 4	SR 33	22 BRIDGE RAIL	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
27	84889777	9/22/2015	830	I 4	SR 33	22 BRIDGE RAIL	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
28	84876280	9/24/2015	0	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
29	84864758	9/28/2015	705	I 4	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	2	0	0
30	85139006	10/26/2015	1034	SR 33	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
31	85154052	10/26/2015	1540	SR 400	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
32	85149881	10/27/2015	1050	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
33	85139011	11/4/2015	717	SR 400	SR 33	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
34	85111000	11/9/2015	1055	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
35	84871693	11/20/2015	2120	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
36	85226904	11/20/2015	1957	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
37	85155471	12/15/2015	1659	I 4	MILE MARKER #38	22 BRIDGE RAIL	88 UNKNOWN	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
38	85150396	1/16/2016	300	I 4	MILE MARKER #38	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
39	85163082	1/17/2016	1350	I 4	MM38	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
40	86128797	1/26/2016	1638	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
41	85254521	2/9/2016	1622	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
42	85180702	3/7/2016	725	SR 33	SR 400	13 ANIMAL	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
43	85254531	3/19/2016	2024	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	4	0	0
44	86346024	3/21/2016	1205	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
45	85226945	4/6/2016	725	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
46	86129007	4/7/2016	1642	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
47	85230079	4/12/2016	1011	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
48	85254615	4/25/2016	215	I 4	SR 33	28 GUARDRAIL END	02 FRONT TO FRONT	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	3	0	0
49	85246927	5/6/2016	700	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
50	85286025	5/8/2016	931	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
51	85197205	5/12/2016	1429	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
52	85254901	5/12/2016	2249	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
53	85226968	6/6/2016	955	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
54	85230096	6/8/2016	1450	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
55	86346820	6/12/2016	1035	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
56	86347332	6/19/2016	2140	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
57	85256701	6/27/2016	1710	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
58	85254642	7/1/2016	1745	I 4	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
59	85306977	7/4/2016	1515	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
60	85256706	7/11/2016	1145	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
61	86347710	7/19/2016	922	TOMKOW RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
62	86347669	7/21/2016	1800	SR 33	UNIVERSITY BLVD	24 CURB	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
63	85356799	7/22/2016	240	I 4	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
64	86347827	7/26/2016	1740	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
65	86347933	8/4/2016	636	I 4	SR 33	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
66	85263070	8/8/2016	820	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
67	85370230	8/9/2016	2328	SR 400	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
68	86347984	8/10/2016	1617	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
69	85336078	8/16/2016	2250	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
70	85346689	8/27/2016	645	SR 400	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
71	85371213	8/30/2016	1740	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
72	85308890	8/31/2016	855	SR 400	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
73	85341100	9/4/2016	1630	I 4	MM 38	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
74	85341102	9/5/2016	900	I 4	MM 38	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
75	85371215	9/5/2016	1845	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
76	85263077	9/14/2016	1530	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
77	85386981	10/2/2016	1834	I 4	MILE MARKER #38	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	1	0	0	0	0
78	86632714	10/3/2016	2253	SR 33	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
79	85307027	11/2/2016	1625	SR 400	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
80	85371225	11/4/2016	1535	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
81	85420892	11/17/2016	620	I 4	MM 38	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
82	85370268	11/20/2016	1709	SR 33	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
83	83468732	11/27/2016	322	SR 400	SR 33	29 CABLE BARRIER	02 FRONT TO FRONT	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
84	85383692	12/11/2016	1600	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
85	85426549	1/27/2017	2240	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0

Interchange: I-4 at SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	86633787	1/27/2017	138	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
87	85371241	1/28/2017	400	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
88	85383713	2/6/2017	1700	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
89	85411903	2/13/2017	910	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
90	85161095	2/17/2017	1524	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
91	85420030	2/27/2017	1549	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
92	85478632	3/14/2017	801	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
93	86634349	3/17/2017	1530	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
94	85151363	3/28/2017	2357	I 4	MM 38	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
95	85478641	3/28/2017	718	I 4	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
96	85478643	3/28/2017	1718	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
97	85447315	4/11/2017	610	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
98	85478650	4/20/2017	701	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
99	85409158	4/28/2017	2324	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
100	83780757	4/30/2017	1055	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
101	86634914	5/5/2017	2329	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	4	0	0
102	85473881	5/7/2017	1115	SR 400	SR 33	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
103	85520430	5/17/2017	550	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
104	85371260	5/18/2017	2240	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
105	85520437	6/5/2017	1600	SR 33	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
106	83839210	6/7/2017	905	I 4	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
107	85473453	6/7/2017	1300	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
108	85409169	6/13/2017	1700	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
109	85524875	6/22/2017	1430	SR 400	MILE MARKER #38	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
110	85503552	7/2/2017	805	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
111	87342520	7/10/2017	1103	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
112	87342590	7/15/2017	16	SR 33	I 4	28 GUARDRAIL END	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
113	85473463	7/21/2017	2207	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
114	85501138	7/24/2017	1759	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
115	87342875	8/8/2017	2040	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
116	85534315	8/21/2017	1025	SR 400	MM 38	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
117	85403900	8/22/2017	1717	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
118	85403901	8/22/2017	1742	I 4	SR 33	22 BRIDGE RAIL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
119	85525860	8/22/2017	1730	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
120	85573847	8/22/2017	1740	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
121	87343111	8/28/2017	949	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
122	85494957	9/14/2017	1440	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
123	87343318	9/17/2017	1816	SR 33	I 4	39 OTHER FIXED OBJECT (WALL, BUIL	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
124	87343364	9/21/2017	604	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
125	87343554	10/7/2017	1409	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
126	87343579	10/8/2017	1520	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
127	85532610	10/19/2017	143	SR 400	MILE MARKER #38	29 CABLE BARRIER	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
128	85579885	10/28/2017	340	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
129	85543374	11/13/2017	2209	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
130	87344112	11/13/2017	1550	I 4	SR 33	39 OTHER FIXED OBJECT (WALL, BUIL	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
131	85568656	11/21/2017	645	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	1	0	0	0	0
132	85568660	11/30/2017	1350	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
133	87344235	12/2/2017	1818	SR 33	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
134	85517637	12/8/2017	210	SR 400	MM 38	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
135	85579488	12/21/2017	1635	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	02 CLOUDY	2	0	0	0	0
136	85573892	12/28/2017	1200	I 4	SR 33	27 GUARDRAIL FACE	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
137	87344625	1/3/2018	1440	SR 33 N	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
138	85579899	1/8/2018	605	SR 400	MM 38	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	2	0	0	0	0
139	87114613	1/27/2018	759	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
140	87344992	2/5/2018	1735	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
141	85528185	2/22/2018	1500	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
142	87139797	3/4/2018	600	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
143	87795268	3/10/2018	655	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
144	87186871	3/27/2018	30	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
145	87195887	3/27/2018	1745	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
146	87196557	3/30/2018	1800	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
147	87170423	4/2/2018	644	SR 400	SR 33	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
148	85605727	4/5/2018	140	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
149	87139815	4/8/2018	656	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
150	87186874	4/13/2018	335	SR 400	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
151	87195974	4/14/2018	1706	SR 400	MM 38	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
152	87795916	5/1/2018	651	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
153	87795968	5/5/2018	1330	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
154	87149549	5/12/2018	231	SR 33	SR 400	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
155	87796146	5/17/2018	2012	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
156	87123187	5/20/2018	1720	SR 400	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
157	87796262	5/28/2018	1358	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
158	87162270	5/29/2018	2215	I 4	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	1	0	1	0	0
159	87158156	5/31/2018	2036	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
160	87156001	6/8/2018	1944	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	02 CLOUDY	2	0	0	0	0
161	87156005	6/17/2018	2000	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
162	87123193	6/20/2018	745	SR 400	SR 33	22 BRIDGE RAIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
163	85595350	6/23/2018	1035	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
164	87156009	6/23/2018	1022	SR 33	I 4	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
165	87196594	7/2/2018	800	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
166	87796684	7/4/2018	2115	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
167	87796794	7/19/2018	1306	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
168	87235517	7/21/2018	2239	SR 400	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
169	87796824	7/22/2018	1420	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
170	85161120	7/24/2018	813	I 4	SR 33	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0

Interchange: I-4 at SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	87179213	7/25/2018	520	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
172	87195918	7/27/2018	735	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
173	87796914	7/30/2018	1812	SR 33	SR 400	20 BRIDGE OVERHEAD STRUCTURE	00 NOT CODED	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
174	87186905	8/1/2018	0	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	3	0	4	1	0
175	87196518	8/1/2018	1025	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
176	83786943	8/2/2018	1253	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
177	87797004	8/3/2018	857	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
178	87277083	8/5/2018	1155	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
179	87158169	8/6/2018	1915	SR 400	MM 38	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
180	87162285	8/11/2018	2105	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	02 CLOUDY	2	0	1	0	0
181	87162286	8/11/2018	2137	I 4	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
182	87196520	8/12/2018	1549	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
183	87797082	8/13/2018	2019	SR 33	I 4	24 CURB	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
184	87196609	8/15/2018	845	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
185	87208569	8/21/2018	1305	SR 400	SR 33	23 CULVERT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
186	87797186	8/23/2018	1540	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
187	87235531	9/1/2018	1817	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
188	87276791	9/5/2018	1438	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
189	87797354	9/7/2018	1154	SR 33	TOMKOW RD	37 FENCE	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
190	87112624	9/12/2018	1650	SR 400	MM 38	09 OTHER NON-COLLISION	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
191	87208572	9/14/2018	1740	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
192	87276878	9/26/2018	2105	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
193	87208582	10/16/2018	930	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
194	87208590	11/1/2018	2025	SR 400	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
195	87273111	11/5/2018	139	I 4	MM 38	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	1	0	0
196	87235553	11/12/2018	1550	SR 400	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
197	87273113	11/25/2018	2218	I 4	MILE MARKER #38	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
198	87276808	11/28/2018	1850	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
199	87276956	12/1/2018	1851	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
200	88843446	12/10/2018	1013	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
201	87157625	12/14/2018	637	I 4	MILE MARKER #38	09 OTHER NON-COLLISION	88 UNKNOWN	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
202	88843714	1/8/2019	1319	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
203	87270581	1/28/2019	1805	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
204	87235572	1/29/2019	2315	SR 400	MILE MARKER #38	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
205	87270582	2/1/2019	1614	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
206	87270583	2/1/2019	1849	I 4	SR 33	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
207	88844057	2/6/2019	1051	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
208	87276973	2/15/2019	2054	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
209	87276978	2/21/2019	1104	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
210	87270588	2/24/2019	754	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
211	87300465	2/27/2019	1205	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
212	88844347	2/27/2019	745	TOMKOW RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
213	88036054	3/9/2019	2030	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
214	87276986	3/10/2019	916	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
215	87276931	3/12/2019	1915	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
216	87300470	3/17/2019	1339	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
217	88844772	3/30/2019	1548	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
218	88036061	4/2/2019	735	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
219	87215418	4/5/2019	1533	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
220	88844895	4/9/2019	2240	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
221	88056126	4/13/2019	1230	SR 400	MILE MARKER #38	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
222	88089759	4/17/2019	1652	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
223	88007033	4/18/2019	2335	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
224	88845100	4/22/2019	1728	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
225	87289615	5/4/2019	2155	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
226	88007038	5/4/2019	50	I 4	SR 33	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
227	87292301	5/5/2019	1515	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
228	87276850	5/16/2019	2325	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
229	88845457	5/21/2019	1723	SR 33	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
230	88048678	6/3/2019	1721	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
231	88845536	6/6/2019	1224	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
232	87221114	6/12/2019	1910	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	02 CLOUDY	2	0	0	0	0
233	88044665	6/15/2019	1130	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
234	88089770	6/15/2019	1130	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
235	88845779	6/30/2019	747	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
236	88011515	7/2/2019	1631	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
237	89346581	7/4/2019	300	SR 33	I 4	25 DITCH	00 NOT CODED	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
238	87288534	7/23/2019	1720	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
239	87289634	7/24/2019	725	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
240	88130222	7/24/2019	650	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
241	89346772	7/24/2019	1147	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
242	88173767	7/25/2019	1528	I 4	SR 570	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
243	89346782	7/25/2019	903	SR 33	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	3	1	3	0	0
244	88070866	8/3/2019	2210	SR 400	MM 38	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
245	88154410	8/25/2019	1825	SR 400	MM 38	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
246	88162143	8/28/2019	410	SR 400	MM 38	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	1	0	0
247	88003655	9/3/2019	1455	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
248	88203139	9/7/2019	2321	SR 400	MILE MARKER #38	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
249	89347423	9/17/2019	56	I 4	SR 33	33 UTILITY POLE/LIGHT SUPPORT	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
250	89347415	9/19/2019	1705	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
251	89347453	9/22/2019	2038	SR 33	TOMKOW RD	33 UTILITY POLE/LIGHT SUPPORT	00 NOT CODED	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
252	88214317	9/27/2019	2227	I 4	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
253	88102904	10/6/2019	1511	I 4	MILE MARKER #38	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
254	88107620	10/8/2019	1725	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
255	88101246	10/18/2019	630	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0

Interchange: I-4 at SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
256	88101247	10/18/2019	805	I 4	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
257	88215595	10/20/2019	1102	SR 400	MM 38	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
258	88173795	10/28/2019	730	I 4	MM 38	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	04 FOG, SMOG, SMOKE	1	0	0	0	0
259	89347929	11/2/2019	403	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
260	88173801	11/7/2019	2339	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
261	88226772	11/8/2019	426	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
262	88230891	12/2/2019	1650	SR 400	MILE MARKER #39	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
263	88173805	12/7/2019	2224	I 4	MILE MARKER #38	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
264	88253837	12/16/2019	2020	I 4	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
265	88262333	12/18/2019	1705	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
266	88262337	12/19/2019	640	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
267	88173810	12/23/2019	2208	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
268	88226789	12/25/2019	1211	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
269	88122278	12/28/2019	555	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0

Mainline Segment: I-4 from SR 33/Lakeland Hills Boulevard/Commonwealth Avenue to SR 570/Polk Parkway (East) (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84498119	1/2/2015	1355	I 4	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
2	84535784	1/2/2015	10	I 4	MM39	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	1	0
3	84545375	1/4/2015	750	SR 400	MM 40	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
4	83833999	1/11/2015	1840	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	2	0	0
5	83787122	1/15/2015	13	SR 400	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
6	84535786	1/24/2015	353	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
7	84543292	1/25/2015	1118	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
8	84564596	2/14/2015	557	I 4	MILE MARKER #40	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
9	84543310	2/15/2015	1535	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
10	83771106	3/1/2015	1300	I 4	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
11	83784049	3/6/2015	2345	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
12	84484294	3/12/2015	37	SR 400	MM 40	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
13	84535817	3/22/2015	1550	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
14	84535826	4/1/2015	605	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	2	0	0
15	84892557	4/25/2015	1420	SR 400	MM 36	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
16	84892560	4/30/2015	1730	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
17	83685085	5/12/2015	1255	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
18	84527392	5/12/2015	1520	SR 400	MILE MARKER #39	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
19	84886711	5/20/2015	1750	SR 400	MM 40	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
20	84516878	6/4/2015	1830	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
21	84894680	6/7/2015	728	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
22	84516884	6/14/2015	1910	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	1	0	0
23	84894968	6/23/2015	445	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
24	84894700	7/29/2015	517	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	4	0	0
25	83819883	7/29/2015	848	I 4	SR 33	09 OTHER NON-COLLISION	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
26	85149940	12/21/2015	420	SR 400	MILE MARKER #40	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
27	85149904	12/30/2015	605	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
28	85152934	1/3/2016	642	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
29	84871697	1/12/2016	620	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
30	85151263	1/27/2016	2019	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	4	0	0	0	0
31	85246880	2/3/2016	1430	SR 400	MM 39	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
32	85252547	2/4/2016	1040	SR 400	MM 40	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
33	85152951	2/23/2016	638	SR 400	SR 570	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
34	85150929	2/26/2016	2230	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
35	85286013	3/27/2016	828	SR 400	SR 33	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
36	85286015	3/28/2016	700	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	04 FOG, SMOG, SMOKE	1	0	0	0	0
37	85180140	4/4/2016	400	I 4	MILE MARKER #40	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
38	85150939	4/22/2016	1830	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
39	85230085	4/26/2016	1045	I 4	SR 570	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	4	0	0
40	85274112	6/5/2016	1330	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
41	85243934	6/8/2016	1405	I 4	MILE MARKER #40	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	3	0	0
42	85254562	6/10/2016	458	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
43	85256704	7/10/2016	1330	SR 400	MM 40	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
44	85286045	7/26/2016	849	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
45	85356804	8/5/2016	1655	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
46	85356807	8/9/2016	1956	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
47	85336086	8/31/2016	1910	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
48	85336087	8/31/2016	2010	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
49	85302774	9/2/2016	1229	SR 400	MM 40	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	4	0	0
50	85425508	12/23/2016	1354	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
51	85425510	1/2/2017	1505	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	3	1	0
52	85442323	2/23/2017	1525	I 4	SR 33	37 FENCE	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
53	85263353	2/27/2017	1719	SR 400	MM39	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
54	85478627	3/9/2017	1149	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
55	85506712	4/3/2017	1405	SR 400	MILE MARKER #39	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
56	85420045	4/5/2017	1730	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
57	85503702	5/12/2017	1835	SR 400	SR 570	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
58	83741214	6/4/2017	700	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
59	85442361	6/12/2017	1606	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
60	85425552	6/23/2017	855	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
61	85501136	7/10/2017	1516	I 4	SR 33	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	1	0	0	0
62	85473458	7/16/2017	2210	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
63	85516095	7/25/2017	1408	SR 400	MILE MARKER #39	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
64	85473468	8/9/2017	2215	SR 400	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
65	85151370	8/22/2017	1925	I 4	SR 33	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
66	85579445	8/24/2017	1925	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
67	85524905	10/8/2017	2018	SR 400	MILE MARKER #40	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
68	85532609	10/16/2017	531	SR 400	MILE MARKER #40	25 DITCH	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
69	85532611	10/20/2017	216	SR 400	MM39	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
70	85528163	10/25/2017	628	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
71	85601617	11/16/2017	2110	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
72	85532618	11/17/2017	1058	I 4	MILE MARKER #39	29 CABLE BARRIER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
73	83741223	12/9/2017	1435	I 4	SR 33	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
74	85601629	12/26/2017	1320	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
75	87139768	12/31/2017	1640	SR 400	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
76	85528172	1/25/2018	500	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
77	85494974	2/28/2018	1541	I 4	SR 33	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
78	85574405	3/1/2018	1035	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
79	87665647	3/4/2018	1525	I 4	MILE MARKER #40	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
80	85531324	3/4/2018	1555	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
81	87139814	4/3/2018	2309	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
82	85605730	4/13/2018	440	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
83	87196499	5/5/2018	1640	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
84	87170433	5/11/2018	1331	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	4	0	0
85	87170436	5/14/2018	1501	SR 400	SR 33	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0

Mainline Segment: I-4 from SR 33/Lakeland Hills Boulevard/Commonwealth Avenue to SR 570/Polk Parkway (East) (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	87196883	5/31/2018	927	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
87	87196885	6/4/2018	1242	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
88	87196886	6/5/2018	915	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
89	87196893	6/14/2018	1704	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	4	0	1	0	0
90	85531338	6/21/2018	1750	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
91	87208548	6/27/2018	1305	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
92	85595352	6/27/2018	1650	SR 400	MM 40	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
93	87196899	6/29/2018	1751	SR 400	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
94	87157603	7/3/2018	1420	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
95	87195912	7/4/2018	1650	SR 400	SR 33	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
96	87195914	7/14/2018	400	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
97	87195915	7/18/2018	1917	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
98	87186899	7/26/2018	2210	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
99	87208559	8/2/2018	1305	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	3	0	0
100	87198631	8/13/2018	1112	SR 400	MM 38	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
101	87195924	8/14/2018	1735	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
102	87186908	8/14/2018	1320	SR 400	MILE MARKER #39	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
103	87196920	8/18/2018	1820	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
104	87186910	8/19/2018	1435	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
105	87195926	8/22/2018	1900	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
106	87112622	8/28/2018	2335	SR 400	MILE MARKER #39	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
107	87277096	9/2/2018	2116	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	2	0	0	0	0
108	87276945	9/11/2018	2021	SR 400	SR 570	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
109	87276793	9/13/2018	915	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
110	87196013	9/14/2018	1812	SR 400	MILE MARKER #39	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
111	87196927	9/20/2018	747	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
112	83784320	9/28/2018	1105	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
113	87265145	10/7/2018	530	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	3	0	0
114	87171769	10/9/2018	1720	SR 400	MM 40	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
115	87273103	10/10/2018	1340	I 4	MILE MARKER #40	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
116	87180513	10/28/2018	635	SR 400	MM 40	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	02 CLOUDY	4	0	2	0	0
117	87195955	11/14/2018	1810	SR 400	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
118	87235555	11/16/2018	1419	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
119	87196626	12/10/2018	340	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
120	87157624	12/13/2018	1150	I 4	SR 33	09 OTHER NON-COLLISION	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
121	87277129	12/13/2018	2120	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
122	87248866	12/20/2018	2206	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
123	87248865	12/20/2018	2206	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	05 DARK-NOT LIGHTED	03 RAIN	4	0	4	0	0
124	87234408	12/26/2018	26	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
125	88056109	1/26/2019	535	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
126	87276972	2/14/2019	1419	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
127	88044174	3/17/2019	212	SR 400	MILE MARKER #40	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	3	0	0
128	88035712	4/5/2019	1419	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	4	0	0
129	87252299	4/18/2019	2305	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
130	88035290	4/24/2019	1001	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
131	88036072	5/3/2019	1420	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
132	88141215	6/6/2019	1636	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
133	88111931	6/27/2019	1629	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	3	0	2	0	0
134	88089782	8/6/2019	2253	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
135	88130228	8/9/2019	1730	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
136	88154421	9/17/2019	1200	SR 400	MM 40	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
137	88076154	9/18/2019	1623	SR 400	SR 570	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
138	88076156	9/26/2019	824	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
139	88226773	11/10/2019	258	SR 400	SR 570	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
140	88226775	11/23/2019	306	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
141	89372307	11/23/2019	1912	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	4	0	0	0	0
142	88230888	11/24/2019	602	SR 400	MM 39	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
143	88226778	12/2/2019	830	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
144	88251150	12/8/2019	1450	SR 400	MM 39	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
145	88226782	12/9/2019	729	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0

Interchange: I-4 at SR 570/Polk Parkway (East) (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84545376	1/4/2015	1115	SR 400	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
2	84498121	1/8/2015	1610	I 4	SR 570	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
3	84535785	1/23/2015	449	I 4	SR 570	28 GUARDRAIL END	88 UNKNOWN	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
4	84558676	1/23/2015	715	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	2	0	0
5	84535805	2/25/2015	528	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
6	84865543	3/8/2015	954	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
7	84477478	3/12/2015	1900	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
8	84558700	3/13/2015	650	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
9	83790293	4/1/2015	1425	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
10	84545395	4/3/2015	1414	SR 400	MM 41	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
11	84879732	4/20/2015	1710	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
12	83786243	4/23/2015	1950	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	02 CLOUDY	2	0	0	0	0
13	84879734	4/27/2015	905	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
14	84488851	5/24/2015	1948	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
15	84545407	5/24/2015	2115	SR 400	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
16	84516873	5/25/2015	1920	I 4	SR 570	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
17	84892582	7/3/2015	2000	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
18	84899174	7/17/2015	1342	I 4	MILE MARKER #41	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
19	82254416	7/24/2015	900	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
20	86083402	8/15/2015	225	I 4	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
21	84886753	10/1/2015	105	SR 400	MM 41	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
22	84541371	10/5/2015	2155	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
23	85149878	10/25/2015	715	SR 400	SR 570	21 BRIDGE PIER OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
24	85226900	11/16/2015	1830	I 4	CR 655	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
25	85152402	11/25/2015	1335	SR 400	MM 41	06 FELL/JUMPED FROM MOTOR VEHICLE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
26	85149932	11/27/2015	1630	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
27	86312301	12/11/2015	1508	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
28	85226913	12/17/2015	924	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	3	0	0
29	85226916	12/25/2015	440	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
30	85254845	12/31/2015	1450	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	5	0	0
31	83785218	1/2/2016	1610	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
32	85254853	1/15/2016	318	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
33	85149953	1/27/2016	720	SR 400	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
34	85254516	2/1/2016	2113	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	1	0	0	0
35	85252546	2/4/2016	805	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
36	85254596	2/10/2016	2030	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
37	83788387	2/13/2016	1900	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
38	84870188	2/20/2016	1709	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
39	85246891	2/26/2016	650	SR 400	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
40	85226936	2/28/2016	1028	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
41	84870193	3/26/2016	355	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	4	0	0
42	85180137	3/26/2016	540	I 4	MILE MARKER #41	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
43	85246905	3/29/2016	1525	SR 400	MM 41	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
44	85254537	4/1/2016	1806	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
45	85224671	4/6/2016	336	I 4	MILE MARKER #41	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
46	85254884	4/9/2016	220	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
47	85180711	4/13/2016	1505	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
48	85254613	4/14/2016	2215	I 4	SR 570	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
49	84870194	4/15/2016	351	I 4	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
50	85226955	5/3/2016	810	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	03 DAWN	03 RAIN	3	0	0	0	0
51	85290611	5/3/2016	2147	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
52	85254545	5/5/2016	2346	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
53	85254898	5/8/2016	1803	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	85254567	6/26/2016	315	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
55	85254639	6/26/2016	2320	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
56	85351914	7/4/2016	1715	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
57	85254573	7/8/2016	2228	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
58	85252587	7/17/2016	805	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
59	85356797	7/18/2016	2253	I 4	SR 570	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
60	85356798	7/19/2016	205	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
61	85230105	7/20/2016	1518	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
62	85356803	8/4/2016	1539	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
63	85370227	8/5/2016	2005	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
64	85154661	8/21/2016	800	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
65	85306992	8/24/2016	615	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
66	85356813	8/30/2016	16	I 4	SR 570	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
67	85306995	9/1/2016	515	SR 400	SR 570	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
68	85351941	9/6/2016	1215	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
69	85307002	9/12/2016	1310	SR 400	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
70	85370245	9/25/2016	2000	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	4	0	5	0	0
71	85346710	10/21/2016	1650	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
72	85307022	10/29/2016	400	SR 400	SR 570	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
73	85356835	10/29/2016	355	I 4	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
74	85370262	11/2/2016	2319	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
75	85420888	11/3/2016	730	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
76	85386988	11/18/2016	1925	SR 400	MILE MARKER #41	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
77	85342758	11/19/2016	1830	I 4	SR 570	29 CABLE BARRIER	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
78	85370279	1/8/2017	2132	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
79	85346736	1/12/2017	1029	SR 400	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
80	85387003	1/14/2017	1454	I 4	MILE MARKER #41	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
81	83666849	1/26/2017	30	I 4	POLK PKWY	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
82	83780751	2/14/2017	905	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
83	84870210	2/15/2017	25	SR 400	MILE MARKER #41	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
84	85383724	3/29/2017	1935	SR 400	MM 41	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
85	85370296	4/1/2017	2045	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	3	0	0	0	0

Interchange: I-4 at SR 570/Polk Parkway (East) (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85420044	4/5/2017	922	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
87	85425528	4/15/2017	430	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	88 UNKNOWN	77 OTHER (SEE NARRATIVE)	1	0	2	0	0
88	85409157	4/21/2017	2151	SR 400	MM 41	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
89	85478652	4/25/2017	1018	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	3	0	0
90	85501102	5/10/2017	1600	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
91	85425539	5/11/2017	1723	SR 400	SR 570	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
92	85409165	5/27/2017	2103	SR 400	MM 41	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	3	0	0
93	85501730	6/13/2017	1936	SR 400	MM 41	25 DITCH	88 UNKNOWN	02 WET	02 DUSK	02 CLOUDY	1	0	0	0	0
94	85524882	6/27/2017	1545	SR 400	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
95	85409181	7/6/2017	1825	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
96	85503569	7/31/2017	620	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
97	85256233	8/15/2017	1305	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
98	85524894	8/19/2017	2040	I 4	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	5	0	0
99	85579442	8/19/2017	2000	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
100	85516109	8/26/2017	1845	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
101	85501761	9/4/2017	2217	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
102	83789907	9/12/2017	2300	SR 400	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
103	85541330	9/20/2017	1010	SR 400	MM 41	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
104	85541333	10/6/2017	420	SR 400	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
105	84870221	10/14/2017	1644	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
106	85579886	11/7/2017	1215	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
107	85605701	11/9/2017	1135	I 4	SR 570	09 OTHER NON-COLLISION	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
108	85532619	11/17/2017	1613	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
109	87344137	11/25/2017	254	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
110	85161104	12/8/2017	632	POLK PKWY	SR 400	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
111	85605709	12/22/2017	2125	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	04 FOG, SMOG, SMOKE	1	0	1	0	0
112	85595311	12/28/2017	545	SR 400	MM 41	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	0	0
113	87114610	1/8/2018	831	SR 400	MILE MARKER #41	01 OVERTURN/ROLLOVER	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
114	85605714	1/13/2018	2034	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
115	85574403	2/28/2018	1424	SR 570	I 4	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
116	87186870	3/23/2018	2250	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
117	85605728	4/10/2018	445	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
118	87666796	4/23/2018	1330	SR 570	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
119	87195977	4/24/2018	928	SR 400	SR 570	27 GUARDRAIL FACE	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
120	85148559	5/5/2018	1400	SR 570	SR 570 EB; MP 24.380	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
121	87174297	5/29/2018	1025	I 4	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
122	87196579	6/1/2018	1740	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
123	87216964	6/1/2018	1151	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	8	0	0
124	85531334	6/5/2018	2200	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	4	0	0
125	85150802	6/9/2018	815	SR 400	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
126	87869991	6/13/2018	1630	SR 570	I 4	05 CARGO/EQUIPMENT LOSS OR SHIFT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
127	87162278	7/3/2018	1438	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
128	87174301	7/8/2018	1830	I 4	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
129	85163026	7/20/2018	1507	I 4	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
130	87196600	7/28/2018	1855	SR 570	SR 400	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
131	87198630	8/12/2018	1655	I 4	MM 41	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
132	87276680	8/12/2018	1620	SR 400	MM 41	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
133	87276935	8/14/2018	1816	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
134	85148567	8/15/2018	600	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
135	87276861	8/15/2018	2110	I 4	SR 570	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
136	81985963	8/28/2018	555	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
137	85163029	8/28/2018	1820	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
138	87265148	10/10/2018	0	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
139	87223333	10/29/2018	1755	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
140	81985967	11/4/2018	520	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
141	87196026	11/9/2018	1518	SR 400	MILE MARKER #41	27 GUARDRAIL FACE	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
142	87265151	11/15/2018	1720	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	06 REAR TO SIDE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
143	87195956	11/16/2018	1205	SR 400	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
144	87235560	12/3/2018	700	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	04 FOG, SMOG, SMOKE	1	0	0	0	0
145	87277134	12/24/2018	2045	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
146	87235564	1/3/2019	1938	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	1	0
147	87277138	1/14/2019	1232	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
148	87252018	1/21/2019	2050	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
149	87235571	1/27/2019	238	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
150	87217015	2/7/2019	2222	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
151	87276720	2/18/2019	1900	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
152	88056118	3/12/2019	2310	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
153	85556148	3/13/2019	7	I 4	SR 570	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
154	87276832	3/15/2019	946	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	1	0	0	0	0
155	88056119	3/16/2019	10	SR 400	SR 570	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
156	85531349	3/22/2019	1820	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
157	87276732	4/6/2019	1620	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
158	88105770	4/18/2019	1555	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
159	87276840	4/26/2019	805	SR 570	MILE MARKER #24	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
160	88105779	4/28/2019	1525	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
161	88036074	5/6/2019	1405	SR 400	SR 570	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
162	88044187	5/13/2019	1558	SR 400	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
163	87276746	5/25/2019	1355	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
164	87288524	5/28/2019	1945	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
165	87292309	6/3/2019	845	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
166	88070848	6/5/2019	1000	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
167	87221113	6/12/2019	1720	SR 570	I 4	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
168	88111925	6/12/2019	1125	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
169	88111926	6/12/2019	1155	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
170	88070853	6/27/2019	1635	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0

Interchange: I-4 at SR 570/Polk Parkway (East) (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	87288529	7/5/2019	400	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
172	88011518	7/16/2019	350	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
173	88070859	7/16/2019	355	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
174	88070860	7/16/2019	355	SR 400	MM 41	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
175	88141229	7/18/2019	2106	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
176	88173765	7/19/2019	1628	I 4	SR 570	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	1	0	0
177	88141231	7/20/2019	1938	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
178	88141233	7/21/2019	1830	SR 400	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
179	87188771	7/24/2019	2105	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
180	88171543	7/24/2019	1830	I 4	SR 570	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
181	88141244	8/1/2019	2050	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	03 RAIN	2	0	1	0	0
182	88044213	8/9/2019	1444	SR 400	MILE MARKER #41	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
183	88067763	8/9/2019	1600	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
184	88111947	8/25/2019	248	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
185	88154412	8/29/2019	1705	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
186	88048447	8/30/2019	1750	I 4	MILE MARKER #41	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
187	89013311	9/17/2019	1708	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
188	88141271	9/22/2019	1409	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
189	88076155	9/25/2019	1608	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
190	88130245	9/29/2019	950	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
191	88020366	10/9/2019	2030	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
192	88076424	10/17/2019	2302	SR 400	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	07 SEVERE CROSSWINDS	4	0	0	0	0
193	88130269	11/6/2019	1030	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
194	81985992	11/17/2019	540	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
195	88230893	12/9/2019	1907	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
196	88168950	12/12/2019	629	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
197	88226786	12/16/2019	524	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	2	0	3	0	0

Mainline Segment: I-4 from SR 570/Polk Parkway (East) to SR 559 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	83787121	1/6/2015	228	SR 400	SR 559	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
2	84520156	1/27/2015	730	SR 400	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
3	83834014	2/27/2015	1415	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
4	83742396	3/23/2015	1505	SR 400	SR 559	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	5	0	0	0	0
5	84865549	3/24/2015	841	SR 400	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
6	84890334	3/26/2015	1823	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
7	84894655	4/14/2015	931	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
8	84879733	4/27/2015	740	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
9	84894963	5/22/2015	315	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
10	84894965	5/31/2015	50	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
11	84894966	6/7/2015	350	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	4	0	0
12	84879755	6/8/2015	1925	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
13	84865570	6/21/2015	956	SR 400	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
14	83742406	6/28/2015	1545	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
15	84569193	6/28/2015	2030	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	1	0	0
16	84886724	6/30/2015	1649	SR 400	MM 44	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	3	0	0
17	84886733	7/29/2015	1849	SR 400	MM 42	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	84894982	8/10/2015	1945	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
19	84886738	8/12/2015	1700	SR 400	MM 43	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	4	0	1	0	0
20	84886736	8/12/2015	1540	SR 400	MM 43	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	3	0	1	0	0
21	84886743	8/21/2015	1235	SR 400	MM 43	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
22	84489393	8/27/2015	1450	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
23	85138984	9/19/2015	1940	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
24	84892611	9/21/2015	1020	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
25	85152919	11/6/2015	1744	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
26	85154057	11/7/2015	2310	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	3	0	0	0	0
27	85154058	11/8/2015	50	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
28	85154059	11/8/2015	0	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	3	0	1	0	0
29	84895001	11/18/2015	2350	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
30	85152403	11/25/2015	2025	SR 400	MM 42	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
31	85150393	1/5/2016	2228	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
32	85152937	1/21/2016	1234	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
33	85154079	1/30/2016	1248	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
34	85150401	1/30/2016	2035	I 4	MILE MARKER #43	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
35	85152846	2/12/2016	925	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
36	85209213	2/15/2016	241	I 4	MM 42	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	1	1	0	0
37	86313569	2/15/2016	2318	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
38	85254865	2/26/2016	312	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	4	0	0
39	85254868	3/6/2016	2254	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
40	83786258	3/15/2016	1425	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	2	0	0
41	85254873	3/15/2016	1405	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	2	0	0
42	86313704	3/24/2016	1435	I 4	SR 559	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
43	85226953	4/30/2016	736	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
44	85286034	5/26/2016	1456	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
45	85254558	6/5/2016	2157	SR 400	SR 570	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
46	85226967	6/6/2016	814	SR 400	CR 655	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
47	85254635	6/17/2016	1825	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
48	85254634	6/17/2016	1820	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
49	85254915	6/19/2016	2250	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
50	85254563	6/20/2016	50	SR 400	CR 655	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
51	86314774	6/24/2016	1345	I 4	MILE MARKER #43	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
52	86444320	7/16/2016	541	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
53	85290644	7/23/2016	2036	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	7	0	0
54	85341092	8/11/2016	1350	SR 400	MM 43	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
55	85371207	8/11/2016	2100	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	02 CLOUDY	2	0	0	0	0
56	85336079	8/17/2016	1930	I 4	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
57	85351930	8/19/2016	825	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
58	85154161	8/31/2016	1310	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
59	85341104	9/8/2016	1445	SR 400	MM 42	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
60	85336090	9/9/2016	1650	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
61	85351942	9/12/2016	550	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	3	0	0	0	0
62	85346696	9/19/2016	828	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
63	86445959	9/22/2016	1510	I 4	MILE MARKER #42	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
64	85371221	9/24/2016	2015	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	02 CLOUDY	2	0	0	0	0
65	85286061	10/5/2016	1557	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
66	85336100	10/20/2016	1900	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
67	85420009	11/15/2016	710	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
68	83785317	11/19/2016	508	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
69	85411889	12/10/2016	1030	SR 400	SR 559	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
70	85390362	12/14/2016	1505	I 4	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
71	83785238	1/6/2017	800	SR 400	SR 559	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
72	85161096	3/6/2017	813	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
73	85386314	3/20/2017	1133	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	1	1	0	0
74	85420049	4/13/2017	1750	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
75	85154698	5/9/2017	1030	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
76	85409167	5/31/2017	1310	SR 400	MM 43	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
77	85503545	6/11/2017	40	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
78	85520441	6/14/2017	1700	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
79	85425558	7/6/2017	720	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
80	85443872	7/30/2017	1200	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
81	83741218	7/30/2017	1120	SR 400	SR 559	29 CABLE BARRIER	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
82	85503567	7/30/2017	1030	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
83	85528129	8/11/2017	700	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	4	0	0
84	86995754	8/14/2017	518	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
85	85151375	8/26/2017	1013	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0

Mainline Segment: I-4 from SR 570/Polk Parkway (East) to SR 559 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85543347	8/28/2017	1300	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
87	85579452	9/3/2017	2040	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
88	85531308	9/23/2017	1900	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
89	85543360	10/12/2017	1334	SR 400	MILE MARKER #42	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
90	85601599	10/25/2017	710	SR 400	SR 570	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
91	85601619	11/17/2017	1540	SR 400	SR 570	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
92	87113143	11/18/2017	2240	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
93	85499073	1/12/2018	2044	SR 400	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
94	85574391	1/30/2018	1652	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
95	85161107	2/2/2018	906	I 4	SR 570	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
96	87162233	2/28/2018	1210	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
97	87162240	3/22/2018	1420	I 4	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
98	85492279	3/29/2018	1300	I 4	SR 559	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
99	87195896	5/4/2018	400	SR 400	SR 570	37 FENCE	77 OTHER (SEE NARRATIVE)	88 UNKNOWN	88 UNKNOWN	77 OTHER (SEE NARRATIVE)	1	0	0	0	0
100	85531332	5/22/2018	200	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	3	0	1	0	0
101	87196585	6/11/2018	1430	SR 400	SR 570	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
102	87196586	6/19/2018	610	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
103	87179217	7/28/2018	2150	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
104	87198629	8/8/2018	135	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
105	87276858	8/10/2018	710	I 4	MILE MARKER #42	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
106	87276862	8/22/2018	1929	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
107	87171766	8/29/2018	625	SR 400	MM 42	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
108	87276795	9/22/2018	815	SR 400	MM 42	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
109	87276689	9/26/2018	645	SR 400	MT OLIVE RD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
110	87277109	10/8/2018	1541	SR 400	MM 43	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
111	87265147	10/8/2018	758	I 4	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
112	87223327	10/10/2018	100	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
113	87186917	10/14/2018	1430	SR 400	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
114	87276882	10/19/2018	455	I 4	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	2	0	0
115	87196621	11/23/2018	1630	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
116	87277125	11/27/2018	755	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
117	87196624	12/3/2018	620	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	03 DAWN	02 CLOUDY	2	0	0	0	0
118	87276959	12/13/2018	1655	SR 400	SR 570	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
119	87276960	12/13/2018	1932	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
120	87234404	12/15/2018	2118	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	1	0	0	0
121	87288489	12/22/2018	200	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
122	87234409	12/24/2018	2140	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
123	88035258	1/12/2019	255	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
124	87289593	1/28/2019	920	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
125	88056114	2/14/2019	550	SR 400	SR 570	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
126	88019233	3/30/2019	1341	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
127	88056128	5/1/2019	1420	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
128	87276743	5/7/2019	905	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
129	88111916	5/9/2019	1718	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
130	88056136	5/29/2019	1615	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
131	89011738	6/6/2019	115	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
132	88162130	6/30/2019	845	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
133	88036083	7/7/2019	1655	SR 400	SR 570	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	1	2	0	0
134	87283709	7/9/2019	925	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
135	88070861	7/22/2019	200	SR 400	MM 43	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
136	88141235	7/25/2019	1844	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
137	88141239	7/29/2019	1442	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
138	88173773	8/1/2019	1856	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	1	0	0
139	88076143	8/16/2019	635	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
140	88111946	8/16/2019	105	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
141	88130233	8/19/2019	1630	SR 400	SR 570	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
142	88166290	8/21/2019	1731	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
143	88168917	8/22/2019	609	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
144	85591159	8/23/2019	1244	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
145	88168920	9/3/2019	608	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	01 CLEAR	2	0	0	0	0
146	88130249	10/6/2019	1420	SR 400	SR 570	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
147	88101244	10/8/2019	1745	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
148	88107633	11/2/2019	612	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
149	88220051	11/3/2019	2235	I 4	SR 559	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
150	88203699	11/20/2019	438	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
151	88041738	11/23/2019	1120	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
152	88140506	12/13/2019	624	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
153	88262228	12/20/2019	1112	I 4	CR 655	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
154	88173808	12/22/2019	326	I 4	SR 570	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
155	88216637	12/22/2019	1148	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0

Interchange: I-4 at SR 559 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	83786876	1/2/2015	911	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
2	84569133	1/18/2015	1945	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
3	85687204	2/6/2015	1940	BROADWAY BLVD	CAMP GILEAD DR	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
4	84625923	2/19/2015	2110	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
5	81962693	3/1/2015	1520	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
6	84889736	3/23/2015	1440	I 4	SR 559	09 OTHER NON-COLLISION	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
7	85688357	3/30/2015	1826	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
8	84551360	4/6/2015	800	I 4	SR 559	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
9	84569161	4/12/2015	2235	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	1	0	0
10	83921981	4/20/2015	630	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	03 DAWN	02 CLOUDY	2	0	1	0	0
11	85688134	4/28/2015	1740	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
12	84894953	5/4/2015	725	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
13	84488846	5/12/2015	825	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
14	84865563	5/31/2015	2000	SR 400	SR 559	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
15	84892583	7/4/2015	1755	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
16	84545424	7/8/2015	1138	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	4	0	0
17	84531288	7/18/2015	1210	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	84886731	7/18/2015	1150	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
19	84558745	7/19/2015	1315	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	1	3	0	0
20	84865585	7/19/2015	1624	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
21	83819881	7/20/2015	733	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
22	84569196	7/20/2015	625	I 4	SR 559	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
23	84625299	7/21/2015	1550	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
24	85620112	8/25/2015	1217	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
25	85620160	9/28/2015	1201	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
26	85149872	10/4/2015	1820	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
27	84886756	10/10/2015	1025	SR 400	MM 44	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
28	86084712	10/18/2015	1020	SR 559	BAY LAKE RESORT DR	19 IMPACT ATTENUATOR/CRASH CUSION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
29	83685090	10/25/2015	1400	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
30	85139007	10/27/2015	547	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
31	85212525	10/28/2015	250	I 4	MM 44	15 PARKED MOTOR VEHICLE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
32	83785307	10/29/2015	115	I 4	SR 559	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
33	85151235	11/4/2015	1912	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
34	86084845	11/7/2015	2320	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
35	84889788	11/9/2015	550	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
36	85110999	11/9/2015	542	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
37	86312395	11/13/2015	340	I 4	SR 559	30 CONCRETE TRAFFIC BARRIER	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
38	85111005	12/6/2015	525	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
39	85152838	12/12/2015	30	SR 400	SR 559	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
40	85151255	12/31/2015	401	SR 559	I 4	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
41	85150392	1/2/2016	1925	I 4	SR 559	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
42	86312419	1/19/2016	140	SR 400	SR 559	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
43	86084899	1/28/2016	509	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
44	85254857	1/29/2016	2120	I 4	SR 559	27 GUARDRAIL FACE	88 UNKNOWN	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
45	85209211	1/31/2016	240	SR 400	MM 44	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
46	85152845	2/8/2016	1430	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
47	85246885	2/12/2016	1240	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
48	85155488	2/14/2016	1600	I 4	MILE MARKER #44	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
49	85155492	2/15/2016	1646	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
50	85209214	2/15/2016	2249	I 4	MM 44	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	4	0	0
51	86313982	2/19/2016	530	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
52	85246889	2/22/2016	900	SR 400	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
53	85150928	2/26/2016	300	SR 400	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
54	85252556	3/4/2016	1005	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
55	85620398	3/5/2016	1532	SR-559	BAY LAKE RESORT RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
56	86442134	3/7/2016	1805	BAY LAKE RESORT DR	SR 559	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
57	86314821	3/22/2016	1740	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
58	86314883	3/22/2016	405	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
59	85286014	3/27/2016	1047	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
60	81977418	3/28/2016	1332	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
61	84624032	3/28/2016	2030	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
62	85254535	3/28/2016	1923	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
63	85230074	4/3/2016	1155	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
64	86314847	4/3/2016	740	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	02 CLOUDY	1	0	1	0	0
65	86313584	4/10/2016	744	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
66	86442574	4/15/2016	1212	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
67	85230091	5/20/2016	920	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
68	85286033	5/26/2016	1021	SR 559	SR 400	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	1	0
69	85152866	6/2/2016	1135	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
70	85230093	6/2/2016	930	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
71	85286039	6/2/2016	1405	SR 400	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
72	85254633	6/12/2016	1750	I 4	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
73	86313492	6/12/2016	1827	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
74	86443521	6/12/2016	1215	BAY LAKE RESORT DR	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
75	85254564	6/22/2016	1218	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
76	85620608	6/24/2016	900	SR-559	BAY LAKE RESORT RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
77	85351912	6/28/2016	1425	SR 400	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
78	85254644	7/5/2016	2350	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
79	85252584	7/7/2016	1559	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
80	86444082	7/12/2016	1600	I 4	MILE MARKER #44	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
81	86444363	7/16/2016	2141	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
82	85256711	7/25/2016	1140	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
83	85230111	8/3/2016	1220	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
84	85230112	8/3/2016	1225	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
85	85370228	8/6/2016	22	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0

Interchange: I-4 at SR 559 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85336081	8/26/2016	1610	SR 400	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
87	85371212	8/28/2016	450	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
88	85290656	8/30/2016	29	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	3	0	0
89	86444737	9/11/2016	1725	SR-559	BAY LAKE RESORT RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
90	85286055	9/12/2016	1248	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
91	85351946	9/30/2016	620	SR 400	SR 559	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	02 CLOUDY	1	0	0	0	0
92	85370254	10/14/2016	2035	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
93	85342748	10/17/2016	1310	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
94	85363522	10/25/2016	1225	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
95	85336101	10/26/2016	2035	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
96	85370266	11/15/2016	2130	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
97	86442772	11/18/2016	1818	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
98	85386991	12/7/2016	1120	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
99	85346734	1/8/2017	607	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
100	85390367	1/19/2017	418	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
101	85686707	1/19/2017	2001	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
102	85383711	1/29/2017	1840	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
103	85370285	2/9/2017	50	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
104	86937393	2/9/2017	1	SR 400	MILE MARKER #44	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
105	85409144	2/21/2017	1602	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
106	86937616	2/26/2017	1542	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
107	85154680	3/10/2017	1130	SR 400	SR 559	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
108	85473429	3/29/2017	1800	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
109	86939738	4/13/2017	150	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
110	85425535	5/2/2017	1715	SR 400	SR 559	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	4	0	0	0	0
111	85447327	5/10/2017	650	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
112	86939586	5/10/2017	1521	SR 559	FRED JONES BLVD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
113	85621275	6/9/2017	724	BAY LAKE RESORT DR	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
114	85409183	7/8/2017	1739	SR 400	MILE MARKER #44	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
115	85425565	7/16/2017	1317	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
116	85442372	7/19/2017	921	I 4	CR 655	05 CARGO/EQUIPMENT LOSS OR SHIFT	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
117	85516097	7/30/2017	1240	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
118	86938614	7/30/2017	610	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
119	85621383	8/15/2017	915	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
120	85579450	8/31/2017	930	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
121	86995048	8/31/2017	1813	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
122	85520449	9/13/2017	1635	SR 400	SR 559	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
123	86938062	10/5/2017	740	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
124	85543361	10/12/2017	1625	SR 400	MILE MARKER #44	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
125	87332699	12/16/2017	220	I 4	MILE MARKER #44	27 GUARDRAIL FACE	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
126	87665540	12/17/2017	840	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
127	85601635	1/18/2018	1945	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
128	85601636	1/18/2018	2010	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
129	87666564	2/11/2018	2153	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
130	85601652	2/24/2018	1537	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
131	83466866	3/6/2018	1754	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
132	87666245	3/9/2018	2044	SR 559	I 4	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
133	85603195	3/14/2018	740	SR 559	SR 400	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
134	87108816	4/2/2018	2200	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
135	85894784	4/3/2018	730	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
136	87196863	4/3/2018	900	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
137	87667464	4/13/2018	715	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
138	87196877	5/12/2018	2043	SR 400	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	3	0	0	0	0
139	87196878	5/12/2018	2127	SR 400	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
140	87667533	5/12/2018	1719	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	2	0	0
141	87196587	6/19/2018	1140	SR 559	SR 400	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
142	85531337	6/21/2018	1525	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
143	87869945	6/23/2018	1213	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
144	87179209	7/15/2018	620	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
145	87235523	7/29/2018	511	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
146	87196604	8/5/2018	1520	SR 400	SR 559	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
147	87665440	8/5/2018	335	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
148	87276941	8/26/2018	1731	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
149	87276875	9/15/2018	1100	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
150	87871196	9/20/2018	830	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
151	87223323	10/3/2018	658	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
152	85161128	11/1/2018	924	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
153	88751414	11/7/2018	1645	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
154	87288484	11/15/2018	925	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
155	87236029	11/22/2018	1209	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
156	87235559	11/25/2018	1848	SR 400	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
157	87869849	12/1/2018	1110	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
158	88753042	12/28/2018	1414	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
159	87248871	1/13/2019	1231	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
160	88753312	1/26/2019	1115	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
161	87245386	1/27/2019	750	SR 400	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
162	87245394	2/21/2019	1520	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
163	87288501	3/1/2019	855	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
164	89009572	3/4/2019	1225	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
165	87300468	3/6/2019	1300	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
166	88056117	3/6/2019	59	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
167	87869880	3/16/2019	1145	SR 559	FRED JONES BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
168	87871399	3/20/2019	1021	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
169	87300478	3/22/2019	1405	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
170	89009424	3/22/2019	1647	SR 559	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Interchange: I-4 at SR 559 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	85895366	3/24/2019	2050	BAY LAKE RESORT DR	SR 559	32 TREE (STANDING)	00 NOT CODED	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
172	87190180	3/29/2019	535	SR 559	I 4	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
173	88032048	3/29/2019	1510	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
174	89009796	4/1/2019	645	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	03 DAWN	04 FOG, SMOG, SMOKE	2	0	0	0	0
175	89010434	4/4/2019	2322	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
176	88035289	4/6/2019	1517	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
177	87291679	4/9/2019	1355	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
178	87252298	4/13/2019	315	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
179	89010910	5/12/2019	1746	SR 559	I 4	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
180	88053050	5/13/2019	1219	SR 400	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
181	87278577	6/13/2019	728	I 4	SR 559	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
182	89011995	6/19/2019	2100	SR 559	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
183	89011880	6/30/2019	1743	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
184	87289623	7/5/2019	1737	I 4	SR 559	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
185	88076141	7/6/2019	1650	SR 400	MILE MARKER #44	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
186	89012573	7/15/2019	2110	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
187	87283713	7/20/2019	2007	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
188	88173766	7/22/2019	1853	I 4	SR 559	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	2	0	0
189	88056151	7/23/2019	1810	SR 400	SR 559	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
190	88019714	7/25/2019	815	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
191	88111940	7/31/2019	740	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
192	88168909	8/4/2019	1854	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
193	89369966	8/30/2019	1837	I 4	SR 559	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	01 CLEAR	2	0	0	0	0
194	89370423	9/19/2019	2028	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
195	89371000	10/15/2019	1908	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
196	89371630	10/21/2019	1542	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
197	88166317	11/5/2019	1820	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	2	0	0	0	0
198	88168935	11/8/2019	57	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	1	0	0
199	89372025	11/16/2019	203	SR 559	I 4	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
200	88168944	11/22/2019	2005	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
201	88235024	12/19/2019	1555	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
202	88141132	12/21/2019	1405	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	1	5	0	0
203	88215611	12/24/2019	608	SR 400	MILE MARKER #44	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0

Mainline Segment: I-4 from SR 559 to SR 557 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84865530	2/12/2015	1842	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
2	83776148	2/17/2015	230	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
3	83700924	2/24/2015	1510	SR 400	SR 559	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
4	84527514	2/25/2015	938	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
5	84890337	4/3/2015	1551	SR 400	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	4	0	0
6	83790296	4/17/2015	1010	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
7	84894943	4/17/2015	1810	SR 400	CR 557	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
8	83790299	5/11/2015	2250	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
9	84865557	5/19/2015	1025	SR 400	SR 559	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
10	84569180	6/5/2015	1230	I 4	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
11	84889764	6/7/2015	523	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
12	84865568	6/13/2015	1702	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
13	84889768	6/28/2015	1255	I 4	CR 557	27 GUARDRAIL FACE	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
14	84894694	7/1/2015	1643	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
15	84894969	7/1/2015	10	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
16	84569195	7/4/2015	2135	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	3	0	0
17	84879760	7/8/2015	1300	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
18	83790309	8/1/2015	820	SR 400	SR 559	29 CABLE BARRIER	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
19	83790310	8/5/2015	1520	SR 400	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
20	84489378	8/10/2015	131	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
21	84886739	8/12/2015	1845	SR 400	MM 47	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
22	83742412	8/13/2015	1125	I 4	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
23	84489395	8/28/2015	2000	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
24	84489403	9/19/2015	2210	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	2	0	0
25	85139000	10/18/2015	610	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
26	85151236	11/5/2015	608	I 4	CR 557A	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
27	85151237	11/9/2015	1317	I 4	CR 557A	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
28	84889789	11/9/2015	1300	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
29	85152400	11/14/2015	1010	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
30	84541393	11/16/2015	600	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
31	85152835	11/18/2015	2115	SR 400	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
32	85152837	11/21/2015	1320	SR 400	CR 557A	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
33	84895006	12/13/2015	510	SR 400	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
34	85209210	1/21/2016	258	SR 400	MILE MARKER #45	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
35	85152942	2/1/2016	1003	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
36	83741203	2/5/2016	1350	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
37	86312653	2/11/2016	2234	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
38	84498284	2/22/2016	730	I 4	CR 557	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
39	85151267	2/24/2016	2058	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
40	85209220	3/6/2016	29	I 4	MILE MARKER #45	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
41	85254526	3/6/2016	14	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	4	0	0	0	0
42	85152852	3/15/2016	1635	SR 400	CR 557	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
43	85290601	3/23/2016	2030	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	2	0	0
44	85152858	3/26/2016	1620	SR 400	SR 559	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
45	85230076	4/8/2016	810	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
46	85286031	5/24/2016	918	SR 400	SR 559	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
47	84881122	5/27/2016	1250	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
48	85263328	5/27/2016	1631	I 4	MM 46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
49	85341056	6/2/2016	1250	SR 400	MM 47	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
50	85152867	6/2/2016	1320	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	2	0	0
51	85254631	6/7/2016	2130	I 4	CR 557	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
52	85336062	6/12/2016	2100	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
53	85254637	6/18/2016	0	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	04 ICE/FROST	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
54	85223364	6/23/2016	1120	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
55	85336064	6/30/2016	1920	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
56	84498298	6/30/2016	1735	I 4	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
57	85243946	7/17/2016	48	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
58	86442435	7/17/2016	1230	SR 400	CR 557	29 CABLE BARRIER	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
59	85346682	8/11/2016	620	I 4	MILE MARKER #48	13 ANIMAL	03 ANGLE	02 WET	03 DAWN	02 CLOUDY	2	0	1	0	0
60	85336080	8/22/2016	400	SR 400	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
61	85351935	8/28/2016	1235	SR 400	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
62	85351938	9/1/2016	625	SR 400	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
63	85290658	9/3/2016	1927	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
64	85370242	9/20/2016	1424	SR 400	CR 557A	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
65	85386977	9/24/2016	2117	I 4	MILE MARKER #48	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	2	0	0
66	85302787	10/1/2016	911	SR 400	MM 46	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
67	85286062	10/7/2016	1626	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
68	85336097	10/7/2016	1850	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
69	85263085	10/7/2016	1330	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
70	85302789	10/8/2016	307	SR 400	MM 45	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
71	85390335	10/15/2016	511	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
72	85363520	10/20/2016	1345	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
73	85286067	11/2/2016	702	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
74	85425505	12/19/2016	1226	I 4	MILE MARKER #45	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
75	85409146	2/22/2017	1505	SR 400	MM 45	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
76	85426556	3/9/2017	1300	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
77	85425523	3/26/2017	2358	SR 400	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
78	85154689	4/6/2017	1200	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
79	85473432	4/12/2017	1700	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
80	86939047	5/4/2017	540	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
81	85531289	5/29/2017	1340	SR 400	SR 559	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
82	85501126	6/26/2017	1850	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
83	85501129	6/30/2017	1219	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
84	85501738	7/1/2017	2249	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
85	85501132	7/1/2017	1902	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0

Mainline Segment: I-4 from SR 559 to SR 557 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85501131	7/1/2017	1219	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
87	86995058	7/1/2017	1807	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
88	83741219	7/31/2017	615	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
89	86995418	8/15/2017	1434	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
90	85573844	8/15/2017	1640	I 4	CR 557	29 CABLE BARRIER	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
91	85473472	8/20/2017	700	SR 400	MILE MARKER #47	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
92	85516107	8/26/2017	1415	SR 400	MM 45	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
93	85151373	8/26/2017	838	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
94	85543344	8/27/2017	849	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
95	85524896	9/2/2017	36	SR 400	MILE MARKER #47	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
96	85596596	9/16/2017	50	SR 400	MM 45	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
97	85596598	9/19/2017	2350	SR 400	MM 46	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
98	86995589	9/19/2017	2117	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
99	85559338	9/28/2017	115	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
100	85531310	9/29/2017	1835	SR 400	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
101	85568634	10/3/2017	605	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
102	85574362	10/3/2017	1805	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
103	85574363	10/7/2017	1313	I 4	SR 559	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	5	0	0
104	85524912	10/17/2017	2158	SR 400	MILE MARKER #46	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
105	85573889	12/26/2017	1405	I 4	CR 557	18 OTHER NON-FIXED OBJECT	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
106	85579904	1/15/2018	730	SR 400	MM 47	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
107	85601642	2/4/2018	720	SR 400	MM 45	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
108	85579912	2/4/2018	1630	SR 400	MM 47	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
109	85531320	2/23/2018	1530	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
110	85573910	3/17/2018	635	I 4	CR 557	27 GUARDRAIL FACE	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	1	0	0	0	0
111	87108811	3/19/2018	140	SR 400	MM 47	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
112	87196862	4/3/2018	555	SR 400	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	4	0	1	0	0
113	87196492	4/9/2018	1152	SR 400	SR 559	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
114	87162247	4/21/2018	2040	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	03 RAIN	2	0	1	0	0
115	85573915	4/21/2018	835	I 4	MM 47	09 OTHER NON-COLLISION	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
116	87667534	5/12/2018	2229	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
117	87668234	5/12/2018	1700	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	3	0	0	0	0
118	87667903	5/15/2018	220	I 4	MM 45	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
119	87195899	5/16/2018	1340	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
120	85531333	5/25/2018	200	SR 400	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
121	87235509	5/29/2018	1330	I 4	REST AREA ENT	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
122	87132590	5/31/2018	315	SR 400	MM 46	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
123	87196578	6/1/2018	1330	SR 400	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
124	87186888	6/5/2018	13	I 4	MM 47	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
125	87132593	6/8/2018	520	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	1	0	0
126	87196590	6/24/2018	700	SR 400	MM 47	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
127	87179205	6/28/2018	1700	I 4	SR 559	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
128	87186897	7/4/2018	430	I 4	MM 46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	4	0	0
129	87196511	7/16/2018	1155	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
130	87208556	7/20/2018	1340	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
131	87196597	7/21/2018	1900	SR 400	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	03 DAWN	03 RAIN	2	0	0	0	0
132	87196911	7/25/2018	756	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
133	87216984	8/24/2018	913	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
134	87276865	8/28/2018	1455	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
135	87235532	9/1/2018	2239	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	3	0	0
136	87196925	9/12/2018	1300	SR 400	MM 46	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
137	87196012	9/13/2018	1855	SR 400	MILE MARKER #45	01 OVERTURN/ROLLOVER	88 UNKNOWN	01 DRY	02 DUSK	01 CLEAR	1	0	1	0	0
138	87277106	9/27/2018	1237	SR 400	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
139	87276797	10/3/2018	1640	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
140	87208577	10/7/2018	1020	SR 400	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
141	87216987	10/11/2018	847	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
142	88750866	11/4/2018	615	I 4	MILE MARKER #47	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	03 DAWN	01 CLEAR	2	0	1	0	0
143	85531344	11/4/2018	718	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
144	87208598	11/8/2018	1905	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
145	87276804	11/10/2018	458	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
146	87276897	11/24/2018	920	I 4	MILE MARKER #47	33 UTILITY POLE/LIGHT SUPPORT	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
147	87234405	11/25/2018	2000	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
148	88035252	11/25/2018	737	SR 400	CR 557	33 UTILITY POLE/LIGHT SUPPORT	88 UNKNOWN	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
149	87288486	11/30/2018	130	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
150	87196538	12/3/2018	1610	SR 400	CR 557A	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
151	87288487	12/8/2018	320	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
152	83786945	12/9/2018	1605	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
153	87210805	12/19/2018	835	SR 400	MM 45	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
154	87277136	1/7/2019	1419	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
155	87248869	1/9/2019	609	SR 400	MM 46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
156	87289591	1/18/2019	2010	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
157	88070813	1/19/2019	250	SR 400	MM 46	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
158	87270580	1/26/2019	2032	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
159	88089748	3/9/2019	537	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	3	0	0
160	87286823	3/19/2019	1400	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
161	89010059	3/20/2019	1620	I 4	MILE MARKER #47	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
162	88036063	4/3/2019	1240	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
163	89010325	4/7/2019	1609	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
164	88036067	4/15/2019	715	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
165	87292297	4/26/2019	410	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	3	0	0	0	0
166	88011328	5/1/2019	1208	I 4	SR 559	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
167	87230187	5/13/2019	1333	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
168	88053051	5/13/2019	1335	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
169	88105805	5/13/2019	1330	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
170	88102873	5/19/2019	749	I 4	MM 51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Mainline Segment: I-4 from SR 559 to SR 557 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	88056138	5/31/2019	810	SR 400	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
172	88141217	6/8/2019	1600	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
173	88089768	6/11/2019	1448	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
174	88056143	6/22/2019	945	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
175	88070855	6/30/2019	1515	SR 400	MM 46	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
176	88141225	7/4/2019	1238	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
177	89012312	7/12/2019	356	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
178	88141227	7/14/2019	1614	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
179	88141236	7/25/2019	2136	SR 400	CR 557	06 FELL/JUMPED FROM MOTOR VEHICLE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	2	0	0
180	89013119	8/8/2019	2151	I 4	MM 47	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	4	1	0
181	89013031	8/8/2019	2040	I 4	MILE MARKER #47	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
182	88056722	8/20/2019	2352	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
183	88056721	8/20/2019	2200	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
184	88130234	8/22/2019	1230	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	2	0	0
185	88130237	8/26/2019	1435	SR 400	SR 559	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
186	88168918	8/27/2019	1230	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
187	88203134	8/29/2019	1859	SR 400	MILE MARKER #45	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	03 RAIN	2	0	4	0	0
188	88166297	9/10/2019	1815	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
189	88101240	9/18/2019	2005	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
190	88076421	9/18/2019	2220	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
191	88089791	10/8/2019	1415	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	4	0	5	0	0
192	88100844	10/14/2019	1428	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
193	89371383	10/21/2019	255	I 4	MM 47	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
194	88168939	11/11/2019	1551	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
195	88041739	11/26/2019	1928	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
196	88230892	12/7/2019	11	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
197	88253841	12/20/2019	2030	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
198	88235027	12/21/2019	1715	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
199	88262336	12/21/2019	720	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0

Interchange: I-4 at SR 557 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	84520149	1/18/2015	1103	SR 557	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
2	83784417	2/6/2015	1909	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
3	83784420	2/8/2015	2131	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
4	84484293	2/28/2015	514	SR 400	CR 557	18 OTHER NON-FIXED OBJECT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
5	84477468	3/22/2015	1035	CR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
6	85688442	3/24/2015	709	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	03 DAWN	04 FOG, SMOG, SMOKE	2	0	0	0	0
7	84879715	3/27/2015	1630	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
8	84890343	4/12/2015	1913	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
9	84569163	4/18/2015	2335	OLD GRADE RD	0	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	2	0	0
10	84569176	6/2/2015	750	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
11	84894681	6/7/2015	1111	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
12	84569190	6/22/2015	2100	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	1	0	0
13	86082711	7/8/2015	1450	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
14	84899173	7/14/2015	1733	I 4	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
15	83685089	7/15/2015	1000	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
16	86083466	9/6/2015	400	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
17	85149856	9/8/2015	1235	SR 400	CR 557	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	3	0	0
18	84865598	9/17/2015	1823	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
19	85138983	9/17/2015	1620	SR 400	CR 557	19 IMPACT ATTENUATOR/CRASH CUSION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
20	86083479	9/23/2015	647	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
21	84876283	10/4/2015	2310	SR 400	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
22	84878173	10/26/2015	1410	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
23	83783653	11/1/2015	1840	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	1	0	0	0
24	85154065	11/17/2015	0	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
25	85152405	11/28/2015	645	SR 557	SR 400	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
26	85111006	12/13/2015	230	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
27	83783655	12/18/2015	2050	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
28	85151261	1/14/2016	509	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
29	85152944	2/6/2016	1335	SR 400	CR 557	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
30	85152948	2/18/2016	1051	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
31	83786933	2/23/2016	1508	SR 400	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
32	85151271	3/5/2016	2343	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
33	86313908	3/9/2016	1430	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
34	85254532	3/22/2016	2159	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	4	0	3	0	0
35	85150405	3/24/2016	2152	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
36	85254609	3/27/2016	2030	SR 400	CR 557	35 TRAFFIC SIGNAL SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
37	85246913	4/8/2016	1725	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
38	85254612	4/11/2016	2055	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
39	85290606	4/15/2016	2134	SR 557	320035	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
40	85226959	5/18/2016	550	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	02 CLOUDY	2	0	0	0	0
41	85286028	5/22/2016	1248	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
42	85286035	5/26/2016	1647	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	5	0	0
43	85254555	5/28/2016	2330	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
44	85290625	6/11/2016	2327	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
45	85341065	6/17/2016	1020	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
46	85230100	6/30/2016	648	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
47	85243943	7/11/2016	2135	I 4	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
48	85254648	7/12/2016	120	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
49	85336071	7/14/2016	2345	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
50	85342726	7/20/2016	1442	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
51	85290643	7/23/2016	1906	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
52	85243952	8/3/2016	338	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
53	85290649	8/5/2016	2038	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
54	85154158	8/11/2016	600	I 4	CR 557	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
55	85154656	8/11/2016	655	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
56	85152873	8/17/2016	650	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
57	85351929	8/19/2016	540	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
58	85302771	8/20/2016	1459	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
59	85243962	8/22/2016	507	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
60	85346687	8/25/2016	558	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
61	85152877	8/26/2016	1040	SR 400	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
62	85336083	8/26/2016	1740	SR 400	CR 557	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
63	85290657	9/1/2016	1859	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	5	0	0
64	85263078	9/19/2016	640	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
65	86141454	9/21/2016	1724	SR 557	I 4	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
66	86444463	9/21/2016	1640	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
67	85346697	9/23/2016	910	SR 400	CR 557	06 FELL/JUMPED FROM MOTOR VEHICLE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
68	85420005	10/27/2016	1557	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
69	86446490	11/11/2016	1632	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	1	0	0	0
70	83685101	12/11/2016	635	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	0	0
71	85409135	12/18/2016	1211	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
72	85363535	12/20/2016	620	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	0	0
73	85336116	12/26/2016	2110	SR 400	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
74	85356853	12/28/2016	520	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
75	85346732	1/3/2017	638	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	03 DAWN	03 RAIN	2	0	2	0	0
76	85356855	1/3/2017	440	I 4	CR 557	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
77	85286077	1/6/2017	637	SR 400	CR 557	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	02 CLOUDY	1	0	0	0	0
78	85688585	1/13/2017	1344	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	2	0	0
79	85363552	1/22/2017	840	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
80	85470715	1/24/2017	2215	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
81	86444787	1/24/2017	1828	CR 557	I 4	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	77 OTHER EXPLAIN IN NARRATIVE	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
82	85370287	2/26/2017	2050	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
83	83786937	3/14/2017	310	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
84	85409152	3/22/2017	1410	I 4	CR 557	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
85	86938038	3/27/2017	1840	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0

Interchange: I-4 at SR 557 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85371252	4/2/2017	2045	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
87	86937698	4/2/2017	1212	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
88	85501708	4/14/2017	1818	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
89	86938118	5/6/2017	1834	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
90	85520434	5/26/2017	640	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
91	85371264	5/29/2017	2100	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	2	0	0
92	85473888	6/5/2017	630	SR 400	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
93	85371268	6/12/2017	1905	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
94	85443869	7/22/2017	2119	SR 400	CR 557	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
95	85534303	7/24/2017	1150	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
96	85534304	7/27/2017	710	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
97	85501745	7/30/2017	1036	I 4	MILE MARKER #48	37 FENCE	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
98	86937662	7/31/2017	1812	I 4	SR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
99	85501747	8/10/2017	2200	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
100	85501749	8/11/2017	2134	I 4	CR 557	37 FENCE	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
101	86995417	8/15/2017	1615	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
102	85151371	8/22/2017	2051	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
103	85573851	8/25/2017	1034	I 4	CR 557	37 FENCE	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
104	85524901	9/16/2017	2135	SR 400	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
105	87331527	9/23/2017	400	I 4	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	4	0	1	0	0
106	85531313	10/23/2017	545	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
107	85601603	10/31/2017	800	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
108	85543369	11/1/2017	1156	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
109	85573872	11/11/2017	610	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	1	0	0	0	0
110	85573873	11/11/2017	910	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
111	85573878	11/29/2017	1620	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
112	87139755	12/7/2017	710	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	3	0	0	0	0
113	85579500	1/16/2018	640	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
114	85605722	2/12/2018	2330	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
115	87108814	3/23/2018	0	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
116	87186876	5/4/2018	1546	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
117	87186880	5/7/2018	2025	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
118	87667411	5/12/2018	2115	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
119	87665365	5/26/2018	2230	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	77 OTHER (SEE NARRATIVE)	1	0	0	0	0
120	87162267	5/28/2018	20	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
121	87132588	5/30/2018	2130	SR 400	MM 48	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
122	87870076	6/19/2018	1650	CR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
123	85595348	6/20/2018	1610	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
124	87157596	6/20/2018	1521	I 4	MM 48	01 OVERTURN/ROLLOVER	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
125	87158161	6/21/2018	235	SR 400	MM 48	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
126	87170448	6/23/2018	2025	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
127	87869999	6/29/2018	1945	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
128	87179207	7/10/2018	920	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
129	87870393	7/11/2018	700	CR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
130	87157608	7/18/2018	1720	I 4	CR 557	37 FENCE	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
131	87235519	7/22/2018	351	SR 400	CR 557	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
132	87179216	7/26/2018	100	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
133	87196605	8/6/2018	1830	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
134	87276786	8/17/2018	700	SR 400	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
135	87195925	8/22/2018	1520	SR 400	CR 557	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
136	87265140	8/28/2018	1126	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	2	1	0	0
137	87288468	8/29/2018	50	I 4	CR 557	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	1	0	1	0
138	87196921	8/30/2018	1836	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
139	87196616	9/6/2018	2300	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
140	87265141	9/6/2018	1430	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
141	87667509	9/23/2018	1610	CR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	4	0	0
142	87871447	9/26/2018	1815	CR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
143	87223326	10/8/2018	1545	SR 400	CR 557	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
144	87208580	10/10/2018	805	SR 400	CR 557	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
145	87157617	10/11/2018	1800	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
146	87170470	11/6/2018	635	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	04 FOG, SMOG, SMOKE	2	0	1	0	0
147	87196027	11/9/2018	2112	SR 400	MILE MARKER #48	09 OTHER NON-COLLISION	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
148	87217005	12/13/2018	1131	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
149	87234406	12/18/2018	2000	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
150	87276908	12/19/2018	1430	I 4	CR 557	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
151	87210812	1/5/2019	155	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
152	87273122	1/6/2019	1938	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
153	87196550	1/15/2019	1229	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
154	87276815	1/18/2019	651	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
155	87288494	1/25/2019	940	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
156	87276819	2/8/2019	1153	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	2	0	0
157	89008590	2/13/2019	2106	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
158	88035263	2/14/2019	1652	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
159	87276721	2/21/2019	1605	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
160	89009344	2/26/2019	900	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
161	88044171	3/1/2019	2339	SR 400	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
162	89009877	3/15/2019	1025	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	04 FOG, SMOG, SMOKE	1	0	1	0	0
163	87295079	3/18/2019	1357	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
164	87300474	3/19/2019	1207	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
165	89010314	3/30/2019	1122	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
166	88036066	4/15/2019	605	SR 400	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
167	89011053	4/29/2019	1651	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
168	88102872	5/6/2019	1338	I 4	MILE MARKER #48	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
169	87230185	5/7/2019	851	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
170	88035294	5/12/2019	713	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Interchange: I-4 at SR 557 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	88035297	5/16/2019	1409	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
172	88053053	5/18/2019	1350	SR 400	CR 557	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
173	87289618	5/21/2019	147	I 4	MILE MARKER #48	21 BRIDGE PIER OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
174	87276854	5/31/2019	2224	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
175	88168899	5/31/2019	1628	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
176	88011511	6/11/2019	1448	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
177	88044664	6/11/2019	1340	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
178	88102879	6/11/2019	238	I 4	MM 48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
179	88048689	6/19/2019	1147	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
180	89012514	6/29/2019	1352	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
181	88044202	7/1/2019	1719	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
182	88168893	7/2/2019	118	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
183	88070858	7/16/2019	30	SR 400	MM 48	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	1	0	0
184	88168900	7/21/2019	1422	SR 400	CR 557	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
185	89012929	7/23/2019	700	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	03 DAWN	02 CLOUDY	2	0	1	0	0
186	88011519	7/25/2019	2220	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
187	89013118	7/25/2019	2209	I 4	MILE MARKER #48	02 FIRE/EXPLOSION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
188	88044676	7/31/2019	1500	I 4	MILE MARKER #48	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
189	88076139	7/31/2019	254	SR 400	CR 557	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
190	88076140	7/31/2019	2317	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
191	88168910	8/4/2019	2032	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
192	89013558	8/14/2019	1357	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
193	89013302	8/18/2019	55	SR 557	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
194	88048445	8/19/2019	1830	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
195	88111948	8/30/2019	2214	I 4	MILE MARKER #48	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
196	88203135	8/30/2019	1748	SR 400	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	01 CLEAR	2	0	5	0	0
197	88215585	9/19/2019	2002	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
198	89013574	9/20/2019	1320	CR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
199	89371141	10/9/2019	247	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
200	88089792	10/17/2019	1016	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
201	88203151	10/18/2019	2045	SR 400	MILE MARKER #48	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	1	0	1	0	0
202	88141029	10/26/2019	2000	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
203	88226769	11/3/2019	442	SR 400	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
204	88101249	11/5/2019	10	I 4	SR 559	04 JACKKNIFE	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
205	88140502	11/5/2019	0	SR 400	MILE MARKER #48	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
206	88076436	11/27/2019	1600	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
207	89372614	11/27/2019	1550	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	8	0	0
208	89372341	11/28/2019	610	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
209	88230894	12/12/2019	1505	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
210	89372589	12/18/2019	2300	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
211	88173809	12/22/2019	2245	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
212	88235029	12/26/2019	1301	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
213	88173812	12/27/2019	1358	I 4	MM 48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
214	88226793	12/27/2019	1419	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
215	89372783	12/27/2019	834	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	83787120	1/4/2015	2208	SR 400	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
2	83784408	1/4/2015	1120	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
3	84484419	1/11/2015	1655	I 4	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
4	83700916	1/16/2015	520	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
5	84527505	1/18/2015	245	I 4	MILE MARKER #56	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	0	0
6	83742389	1/21/2015	1055	SR 400	SR 25	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
7	84535787	1/27/2015	2133	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
8	83785197	1/28/2015	2205	I 4	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
9	83784411	1/31/2015	1951	SR 400	SR 25	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
10	84543302	2/4/2015	300	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
11	84569136	2/4/2015	408	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
12	83776146	2/6/2015	242	I 4	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
13	83784419	2/8/2015	1726	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
14	84865531	2/13/2015	1627	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
15	84545384	2/14/2015	435	SR 400	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
16	84527513	2/18/2015	920	I 4	CR 557	01 OVERTURN/ROLLOVER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
17	84564598	2/18/2015	1738	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	84527515	2/25/2015	1155	I 4	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
19	84569144	2/27/2015	1445	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
20	84569145	2/27/2015	1445	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	2	0	0
21	83700926	2/27/2015	1225	SR 400	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
22	84527521	3/8/2015	1730	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
23	84626927	3/13/2015	155	I 4	MILE MARKER #52	01 OVERTURN/ROLLOVER	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
24	85687838	3/14/2015	2355	SR 400	MILE MARKER #52	15 PARKED MOTOR VEHICLE	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
25	84535815	3/15/2015	1524	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
26	84477467	3/22/2015	755	I 4	US 27	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
27	84865547	3/22/2015	732	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
28	83741188	3/27/2015	1540	I 4	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
29	84535825	3/31/2015	1228	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	6	0	0
30	84501393	4/1/2015	30	SR 400	MM 49	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
31	84477476	4/10/2015	1455	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
32	84477477	4/10/2015	1430	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
33	83790295	4/10/2015	1045	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
34	84894652	4/12/2015	857	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
35	84558716	4/15/2015	2030	SR 400	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
36	84894945	4/19/2015	1455	SR 400	SR 25	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
37	84894659	4/20/2015	1100	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
38	85687188	4/22/2015	238	SR 400	SR 25	15 PARKED MOTOR VEHICLE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	1	1	0
39	85687000	4/22/2015	235	SR 400	MM 52	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
40	84894947	4/27/2015	850	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
41	84894948	4/27/2015	1015	SR 400	SR 25	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
42	84894951	4/29/2015	1120	I 4	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
43	85688170	5/4/2015	505	I 4	CR 557	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	88 UNKNOWN	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
44	84551373	5/15/2015	2313	I 4	MILE MARKER #49	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
45	84894959	5/17/2015	815	I 4	SR 25	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
46	85688235	5/18/2015	1946	SR 400	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
47	84894964	5/30/2015	515	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
48	84625758	6/5/2015	1425	I 4	MILE MARKER #52	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
49	80289206	6/5/2015	1447	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
50	83784058	6/7/2015	800	SR 400	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
51	84886719	6/13/2015	1100	SR 400	MM 49	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
52	84865571	6/22/2015	926	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
53	84558740	7/5/2015	1255	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	83810869	7/8/2015	2153	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
55	83784064	7/10/2015	1520	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
56	84865580	7/13/2015	720	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
57	83819880	7/19/2015	200	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
58	84865586	7/23/2015	1855	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
59	84894698	7/24/2015	347	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	4	0	0
60	84531296	7/24/2015	1215	SR 400	MM 50	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
61	83819882	7/28/2015	705	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
62	83784067	7/29/2015	250	SR 400	SR 25	23 CULVERT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
63	84894977	8/1/2015	1310	SR 400	SR 25	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
64	84892593	8/2/2015	639	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	02 CLOUDY	2	0	1	0	0
65	85144955	8/2/2015	630	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	02 CLOUDY	2	0	2	0	0
66	85138969	8/10/2015	1700	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
67	83810877	8/13/2015	306	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
68	86083140	8/14/2015	2000	I 4	MILE MARKER #51	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
69	83742415	8/22/2015	2045	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
70	86082183	8/24/2015	1355	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
71	83742416	8/24/2015	1415	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	4	0	2	0	0
72	84894703	8/25/2015	1639	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
73	84489394	8/27/2015	1910	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
74	86082105	8/30/2015	1715	SR 400	SR 25	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
75	84889773	9/4/2015	120	I 4	US 27	27 GUARDRAIL FACE	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
76	84894710	9/9/2015	2110	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
77	85149860	9/11/2015	1545	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
78	84865597	9/12/2015	1610	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
79	84489402	9/15/2015	3	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
80	84886748	9/18/2015	2150	SR 400	MM 49	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
81	84886750	9/24/2015	40	SR 400	MM 51	06 FELL/JUMPED FROM MOTOR VEHICLE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
82	85152911	10/4/2015	1630	SR 400	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	7	0	0
83	86084826	10/16/2015	1515	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
84	84878170	10/17/2015	1943	I 4	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
85	84541376	10/22/2015	1345	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
86	85144990	10/23/2015	1615	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
87	83741199	10/27/2015	1145	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
88	83785308	11/5/2015	1845	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
89	84894999	11/7/2015	425	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
90	84895000	11/13/2015	25	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
91	84889793	11/19/2015	635	I 4	US 27	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
92	85111004	11/24/2015	618	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
93	84541399	11/25/2015	627	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
94	84541401	12/1/2015	1140	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
95	86312898	12/11/2015	1500	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
96	85155108	12/14/2015	1724	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
97	85155109	12/17/2015	2100	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
98	85111008	12/20/2015	2200	I 4	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	4	0	0
99	85155113	12/25/2015	1504	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
100	84871695	12/30/2015	950	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
101	85254846	1/1/2016	1430	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	10	0	0
102	85209206	1/2/2016	405	SR 400	MM 50	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
103	86313472	1/11/2016	1440	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
104	85152421	1/22/2016	1220	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
105	85254858	1/30/2016	1630	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
106	85155487	2/10/2016	1248	I 4	MM 51	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
107	85151266	2/10/2016	215	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
108	85150923	2/12/2016	0	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
109	86312871	2/12/2016	1726	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
110	86312654	2/12/2016	1719	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
111	85152949	2/18/2016	1619	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	5	0	0	0	0
112	85155675	2/22/2016	1532	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
113	85209217	2/25/2016	319	I 4	MM 52	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
114	85151268	3/3/2016	2301	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
115	85148532	3/7/2016	1710	SR 400	MM 52	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
116	85230070	3/20/2016	1005	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
117	85254878	3/24/2016	2245	I 4	CR 557	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
118	85197196	3/28/2016	951	I 4	MILE MARKER #54	25 DITCH	88 UNKNOWN	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
119	85252564	4/1/2016	1310	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
120	85252565	4/6/2016	815	SR 400	MM 50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
121	85148542	4/7/2016	1710	SR 400	MM 53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
122	85148540	4/7/2016	1515	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
123	85180144	4/8/2016	1915	I 4	MILE MARKER #51	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
124	84498287	4/17/2016	830	I 4	SR 25	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
125	84498288	4/17/2016	1105	I 4	SR 25	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	3	0	0
126	85150938	4/19/2016	40	SR 400	SR 25	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
127	85230086	5/1/2016	1110	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
128	85290610	5/3/2016	1933	I 4	CR 557	09 OTHER NON-COLLISION	03 ANGLE	02 WET	77 OTHER (EXPLAIN IN NARRATIVE)	03 RAIN	2	0	0	0	0
129	85290615	5/12/2016	1820	I 4	CR 557	09 OTHER NON-COLLISION	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
130	85252572	5/13/2016	700	SR 400	MM 53	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
131	85290617	5/13/2016	1737	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
132	85263330	5/31/2016	1527	I 4	MILE MARKER #54	01 OVERTURN/ROLLOVER	88 UNKNOWN	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
133	85336061	6/3/2016	1850	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
134	85341057	6/3/2016	645	SR 400	MM 49	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
135	85254911	6/10/2016	2246	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
136	85290626	6/14/2016	1803	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
137	85290631	6/21/2016	228	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	5	0	0
138	85341068	6/22/2016	615	SR 400	MM 51	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
139	85252581	6/23/2016	1159	SR 400	MM 53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
140	86444411	6/27/2016	1625	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
141	85243944	7/14/2016	1441	I 4	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
142	85254649	7/14/2016	2345	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
143	85351918	7/17/2016	530	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
144	85290640	7/17/2016	2158	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	5	0	0
145	86083959	7/28/2016	1815	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
146	81977423	8/2/2016	1334	SR 400 MM 49	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
147	85302765	8/6/2016	1307	SR 400	MM 53	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
148	85286049	8/6/2016	1241	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	3	0	0
149	85302767	8/10/2016	1356	SR 400	MM 53	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
150	86445320	8/11/2016	122	SR 400	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
151	86443960	8/11/2016	100	SR 400	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
152	86443961	8/11/2016	117	SR 400	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
153	85290652	8/16/2016	149	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	2	0	0
154	85243960	8/18/2016	319	I 4	MILE MARKER #54	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
155	85290653	8/19/2016	1805	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
156	85243961	8/21/2016	1846	I 4	MILE MARKER #54	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
157	85290655	8/25/2016	143	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	4	0	0
158	85243964	8/28/2016	22	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	4	0	7	0	0
159	85263072	8/30/2016	1625	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
160	85386969	8/31/2016	2132	I 4	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
161	85286053	9/1/2016	734	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
162	85342737	9/4/2016	1400	I 4	US 92	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
163	85290659	9/6/2016	2229	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
164	85274136	9/6/2016	1235	SR 400	MILE MARKER #53	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
165	85274135	9/6/2016	1015	SR 400	MILE MARKER #50	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
166	85386971	9/10/2016	159	I 4	MILE MARKER #50	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
167	85302777	9/11/2016	1424	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
168	85390331	9/18/2016	228	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
169	85336093	9/18/2016	2015	SR 400	MILE MARKER #53	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
170	85386976	9/23/2016	1743	I 4	MILE MARKER #54	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
171	85356824	9/25/2016	2150	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
172	85286058	9/25/2016	1046	SR 400	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0	
173	85336095	9/28/2016	340	I 4	MILE MARKER #51	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
174	85286063	10/9/2016	1018	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
175	85154166	10/12/2016	830	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
176	85302790	10/13/2016	1600	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
177	85396937	10/13/2016	2110	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	3	0	0	0	0
178	85396939	10/16/2016	430	I 4	CR 557	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
179	83785313	10/27/2016	1601	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
180	85390340	10/29/2016	314	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
181	85370264	11/7/2016	1900	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
182	85390344	11/10/2016	1208	I 4	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
183	83785315	11/11/2016	2330	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
184	85286068	11/11/2016	845	SR 400	CR 557	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
185	85336105	11/18/2016	1600	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
186	83685093	11/18/2016	1645	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
187	85286072	11/24/2016	1522	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
188	85390351	11/25/2016	2019	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
189	83467431	12/5/2016	30	I 4	MILE MARKER #52	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
190	85409132	12/9/2016	1542	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
191	85409133	12/10/2016	1710	SR 400	MM 50	18 OTHER NON-FIXED OBJECT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
192	85363534	12/16/2016	1645	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
193	85363533	12/16/2016	1410	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
194	85286076	12/19/2016	551	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
195	85356851	12/23/2016	58	I 4	US 27	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
196	86084817	12/24/2016	2020	I 4	MILE MARKER #51	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
197	85363537	12/25/2016	1448	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
198	85342767	12/25/2016	1503	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
199	85363540	12/26/2016	1325	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
200	85409138	12/28/2016	1400	SR 400	MM 51	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
201	86314951	12/29/2016	1052	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
202	85420907	1/3/2017	107	SR 400	MM 52	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
203	86312359	1/7/2017	502	I 4	MILE MARKER #53	10 PEDESTRIAN	02 FRONT TO FRONT	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	1	0	1	0
204	86312358	1/7/2017	502	I 4	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	3	0	2	0	0
205	85688174	1/12/2017	1625	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
206	85425514	1/16/2017	1457	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
207	85470714	1/21/2017	1937	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
208	86445860	1/25/2017	2005	SR 400	SR 25	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
209	85363557	1/27/2017	1515	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
210	85371242	1/29/2017	145	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
211	85473861	2/8/2017	755	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
212	85363560	2/10/2017	600	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
213	85473421	2/24/2017	1350	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
214	86937674	3/10/2017	1423	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
215	85420944	3/15/2017	1315	SR 400	MM 51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
216	85426560	3/16/2017	1250	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
217	85473873	3/16/2017	1404	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
218	85390390	3/16/2017	1832	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
219	85473427	3/29/2017	1207	SR 400	SR 25	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
220	86938655	4/1/2017	1340	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
221	85473430	4/6/2017	1805	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
222	85447316	4/16/2017	1515	I 4	US 27	27 GUARDRAIL FACE	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
223	84623649	4/18/2017	900	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
224	85425529	4/19/2017	2040	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
225	85473878	4/27/2017	703	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
226	85473879	4/28/2017	1055	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
227	85442338	5/1/2017	330	I 4	CR 557	37 FENCE	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
228	85447324	5/5/2017	1420	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
229	85520428	5/13/2017	930	SR 400	CR 557	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
230	85154701	5/15/2017	940	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
231	85447329	5/15/2017	825	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
232	85154700	5/15/2017	1005	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	4	3	0
233	85473884	5/17/2017	915	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
234	85478663	5/18/2017	1504	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
235	83741212	5/26/2017	645	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
236	85442349	5/28/2017	1707	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
237	85442351	5/29/2017	1828	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
238	85151366	5/31/2017	1502	SR 400	MM 51	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
239	86995692	6/2/2017	2125	SR 400	SR 25	27 GUARDRAIL FACE	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
240	85473454	6/6/2017	1630	SR 400	SR 25	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
241	85501115	6/11/2017	2138	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
242	85501130	6/30/2017	1524	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
243	85503554	7/7/2017	1225	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
244	85425561	7/7/2017	1510	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
245	85185760	7/7/2017	1630	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	1	0	0	0
246	85540035	7/10/2017	930	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
247	85503557	7/16/2017	1345	SR 400	SR 25	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
248	85473460	7/17/2017	0	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
249	85473459	7/17/2017	1909	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
250	85503558	7/17/2017	800	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
251	85503561	7/20/2017	1650	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	3	0	0
252	85443866	7/20/2017	1746	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
253	85473462	7/21/2017	120	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
254	85443870	7/25/2017	1520	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
255	85474731	7/27/2017	1500	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
256	85442373	7/27/2017	700	I 4	US 27	09 OTHER NON-COLLISION	88 UNKNOWN	02 WET	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
257	85531302	8/1/2017	800	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
258	85534309	8/6/2017	710	SR 400	MM 49	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
259	85501748	8/11/2017	121	I 4	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
260	85579440	8/14/2017	1215	I 4	CR 557	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
261	85516103	8/17/2017	1432	SR 400	MM 51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
262	85579446	8/25/2017	1605	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
263	85573854	8/26/2017	900	I 4	US 27	37 FENCE	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
264	85573855	8/26/2017	850	I 4	US 27	29 CABLE BARRIER	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
265	85516111	9/1/2017	1410	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
266	85543349	9/1/2017	1320	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
267	85513220	9/1/2017	1200	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
268	86995719	9/3/2017	2122	I 4	MILE MARKER 52	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
269	85528142	9/4/2017	1145	I 4	CR 557	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
270	85574358	9/5/2017	35	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
271	85543352	9/11/2017	1348	SR 400	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
272	85541327	9/13/2017	1520	SR 400	MM 50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
273	85543354	9/24/2017	830	SR 400	CR 557	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
274	85473489	9/28/2017	1735	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
275	85531309	9/28/2017	1900	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
276	85524904	9/30/2017	1935	SR 400	MILE MARKER #53	25 DITCH	77 OTHER (SEE NARRATIVE)	88 UNKNOWN	88 UNKNOWN	77 OTHER (SEE NARRATIVE)	1	0	0	0	0
277	85524908	10/13/2017	2318	SR 400	MILE MARKER #54	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
278	85568642	10/19/2017	2115	SR 400	SR 25	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
279	85528160	10/20/2017	1530	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
280	85574364	10/20/2017	1219	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
281	85579471	10/27/2017	1620	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	4	0	0	0	0
282	86994408	11/2/2017	1730	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
283	85579887	11/8/2017	1035	SR 400	MM 50	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
284	85543370	11/9/2017	2316	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
285	85483723	11/9/2017	1653	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
286	85483726	11/16/2017	1642	SR 400	SR 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
287	85483727	11/16/2017	1753	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
288	85601615	11/16/2017	1520	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
289	85601622	11/18/2017	1720	SR 400	MILE MARKER #49	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
290	85543377	11/24/2017	56	SR 400	US HWY 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
291	85568658	11/26/2017	920	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
292	85579895	12/8/2017	1620	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
293	85528167	12/19/2017	1335	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
294	87333048	12/26/2017	1415	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
295	85573890	12/27/2017	1847	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
296	85148556	1/7/2018	1515	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
297	85579498	1/11/2018	1215	SR 400	US 27	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
298	85528177	2/5/2018	1850	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
299	85579913	2/5/2018	1740	SR 400	MM 49	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
300	85603191	2/10/2018	2015	SR 400	MM 51	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
301	85601645	2/15/2018	1350	SR 400	CR 557	19 IMPACT ATTENUATOR/CRASH CUSION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
302	85573901	2/15/2018	1242	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
303	87139784	2/15/2018	1357	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
304	87139785	2/16/2018	1319	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
305	85605723	2/17/2018	2109	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
306	85574395	2/17/2018	959	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	1	6	0	0
307	85579510	2/19/2018	1209	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
308	87666847	2/22/2018	325	I 4	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
309	85574398	2/23/2018	535	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
310	85531319	2/23/2018	1435	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
311	85528187	2/24/2018	1920	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
312	87139789	2/25/2018	840	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
313	87186863	3/2/2018	1535	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
314	85531322	3/2/2018	1817	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
315	87139795	3/3/2018	826	SR 400	MM 52	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
316	85574406	3/6/2018	1815	I 4	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	3	0	0
317	87196853	3/15/2018	1638	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
318	87666046	3/16/2018	400	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
319	87162238	3/22/2018	715	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
320	87195962	3/22/2018	2022	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
321	87195961	3/22/2018	1713	SR 400	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
322	87195960	3/22/2018	1419	SR 400	MM 53	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
323	87195964	3/24/2018	1442	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
324	87170422	3/26/2018	1212	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
325	87139810	3/29/2018	1318	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
326	87139811	3/30/2018	1240	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
327	87196559	4/12/2018	1800	SR 400	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
328	85605729	4/12/2018	2113	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
329	87196867	4/16/2018	856	SR 400	MM 52	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
330	85161110	4/21/2018	1428	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
331	85574416	4/24/2018	8	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
332	87196563	4/24/2018	715	SR 400	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
333	87196564	4/24/2018	1307	SR 400	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
334	85573916	4/28/2018	610	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
335	87195894	5/1/2018	1355	SR 400	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
336	87196873	5/4/2018	1055	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
337	87108827	5/4/2018	600	SR 400	MM 52	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	0	0	0
338	87132577	5/4/2018	1308	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
339	87196874	5/4/2018	1145	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
340	87196568	5/7/2018	835	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
341	87157585	5/11/2018	1124	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
342	87157586	5/15/2018	1600	I 4	MM 52	37 FENCE	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
343	87123183	5/15/2018	615	SR 400	SR 25	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
344	87195901	5/16/2018	1730	SR 400	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
345	87186884	5/22/2018	1155	SR 400	SR 25	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
346	87668226	5/25/2018	530	I 4	MILE MARKER #54	15 PARKED MOTOR VEHICLE	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
347	87195906	5/26/2018	1230	SR 400	US 92	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
348	87132586	5/28/2018	530	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
349	85595343	6/1/2018	1300	SR 400	MM 50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
350	87196888	6/6/2018	940	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
351	87869909	6/7/2018	1500	I 4	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
352	87667877	6/10/2018	2111	I 4	MILE MARKER #51	01 OVERTURN/ROLLOVER	00 NOT CODED	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
353	87162272	6/11/2018	25	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	1	0	0
354	87156003	6/12/2018	2145	SR 400	US 27	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
355	87196890	6/13/2018	717	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
356	87157595	6/13/2018	1844	I 4	CR 557	29 CABLE BARRIER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
357	87186893	6/17/2018	0	SR 400	SR 25	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
358	87170444	6/17/2018	1756	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
359	87195994	6/18/2018	653	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
360	87196895	6/21/2018	1314	SR 400	MM 51	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
361	87196897	6/22/2018	1520	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
362	85531339	6/22/2018	1600	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
363	87170447	6/23/2018	1514	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
364	87157599	6/26/2018	1758	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
365	87179204	6/28/2018	1500	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	3	0	1	0	0
366	87158162	6/28/2018	50	SR 400	MM 51	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
367	87196592	6/28/2018	1420	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
368	85595353	6/30/2018	620	SR 400	MM 52	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	04 FOG, SMOG, SMOKE	2	0	1	0	0
369	85595356	7/6/2018	1310	SR 400	MM 50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
370	87195913	7/6/2018	1220	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
371	87332467	7/6/2018	410	I 4	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
372	87195997	7/13/2018	1529	SR 400	MM 52	09 OTHER NON-COLLISION	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	3	0	0
373	87157607	7/18/2018	1608	I 4	CR 557	01 OVERTURN/ROLLOVER	88 UNKNOWN	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
374	87216973	7/24/2018	1342	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
375	87196515	7/24/2018	641	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
376	87196910	7/24/2018	1013	SR 400	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
377	87216975	8/3/2018	1249	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
378	81953844	8/6/2018	1915	I 4	SR 25	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
379	87276782	8/7/2018	1444	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
380	87277084	8/8/2018	708	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
381	87276859	8/11/2018	1340	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
382	87196003	8/15/2018	651	SR 400	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
383	87216983	8/17/2018	1128	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
384	87288465	8/20/2018	1925	I 4	US 27	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
385	87288466	8/20/2018	1925	I 4	MM 52	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
386	87277092	8/27/2018	1503	SR 400	CR 557	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
387	87871101	8/27/2018	1725	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
388	87196611	8/28/2018	700	I 4	MM 53	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
389	87196007	8/28/2018	749	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	5	0	0
390	87276864	8/28/2018	1345	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
391	87276868	8/29/2018	1555	I 4	MM 50	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
392	87170461	8/30/2018	1830	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
393	87170462	8/31/2018	1442	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
394	87276789	8/31/2018	1100	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
395	85531341	8/31/2018	1630	I 4	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
396	87196615	9/5/2018	910	SR 400	MILE MARKER #53	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
397	87276688	9/6/2018	730	SR 400	CR 557	24 CURB	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
398	87196011	9/7/2018	1424	SR 400	MILE MARKER #51	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
399	87196015	9/16/2018	1816	SR 400	MILE MARKER #53	25 DITCH	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
400	87277103	9/26/2018	708	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
401	87196620	9/26/2018	2050	SR 400	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
402	87196524	9/30/2018	2324	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
403	85134991	10/1/2018	634	I 4	MM 53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	03 DAWN	02 CLOUDY	2	0	0	0	0
404	87276691	10/2/2018	1015	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
405	87288474	10/3/2018	1825	I 4	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	1	0	0	0
406	87196526	10/7/2018	2038	SR 400	US 27	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
407	87223325	10/7/2018	2042	SR 400	US 27	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
408	87871414	10/7/2018	2034	I 4	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
409	88751047	10/11/2018	1735	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
410	87276799	10/12/2018	1044	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
411	87180512	10/17/2018	1050	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
412	87208586	10/22/2018	2250	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
413	87196017	10/26/2018	39	SR 400	MILE MARKER #49	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	3	0	0
414	87235549	11/1/2018	1717	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
415	87235551	11/1/2018	2021	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
416	87224169	11/3/2018	1935	I 4	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
417	87208592	11/3/2018	2055	SR 400	SR 25	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
418	87276701	11/4/2018	250	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
419	87223335	11/5/2018	651	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
420	87196025	11/8/2018	1421	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	4	0	0
421	88032026	11/14/2018	635	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
422	87196030	11/15/2018	1543	SR 400	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
423	87196031	11/16/2018	1524	SR 400	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
424	88044148	11/22/2018	1541	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
425	87180518	11/22/2018	1552	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
426	87276807	11/24/2018	319	I 4	MILE MARKER #49	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	4	0	3	0	0
427	87277126	12/2/2018	1503	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
428	87276957	12/6/2018	1831	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
429	87217002	12/7/2018	756	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
430	87236034	12/14/2018	23	SR 400	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
431	87210804	12/18/2018	945	SR 400	MM 50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
432	87157626	12/19/2018	1600	I 4	US 27	29 CABLE BARRIER	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
433	88752894	12/20/2018	1153	I 4	MILE MARKER #49	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
434	87248867	12/22/2018	350	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
435	88035255	12/26/2018	43	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
436	87276810	12/27/2018	915	SR 400	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
437	88044157	12/27/2018	1507	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
438	88044158	12/28/2018	1827	SR 400	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	4	0	0	0	0
439	87210808	12/30/2018	15	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
440	88753065	1/2/2019	214	I 4	MILE MARKER #54	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
441	87210811	1/4/2019	535	SR 400	MM 52	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
442	88070810	1/6/2019	2245	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
443	88044160	1/7/2019	1540	SR 400	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
444	87276914	1/11/2019	1325	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
445	87196546	1/13/2019	945	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
446	87196549	1/15/2019	732	SR 400	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
447	87248872	1/21/2019	804	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
448	89008763	1/27/2019	1030	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
449	87270585	2/7/2019	454	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
450	87217016	2/9/2019	9	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	1	0	0
451	87273129	2/12/2019	953	I 4	US 27	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
452	87217018	2/15/2019	301	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
453	88032036	2/16/2019	2315	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
454	89008933	2/17/2019	1500	I 4	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
455	87276921	2/22/2019	945	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
456	88102855	3/3/2019	2051	I 4	US 27	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
457	87288504	3/6/2019	1400	I 4	MM 53	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
458	87245398	3/9/2019	1515	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
459	88753305	3/10/2019	1804	I 4	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
460	87295076	3/10/2019	1249	I 4	MM 52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
461	88035278	3/11/2019	1003	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
462	88032044	3/13/2019	1230	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
463	87276831	3/14/2019	1139	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
464	88089749	3/16/2019	1100	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	5	0	0
465	87276725	3/18/2019	1510	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
466	87276835	3/20/2019	1500	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
467	88032045	3/21/2019	1515	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
468	88032046	3/23/2019	1615	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
469	88035285	3/29/2019	1545	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	6	0	0
470	87245406	4/5/2019	315	I 4	CR 557	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
471	87295083	4/7/2019	134	SR 400	CR 557	13 ANIMAL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
472	87295084	4/8/2019	2327	SR 400	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
473	87252296	4/11/2019	115	SR 400	US 27	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
474	89010120	4/12/2019	2335	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
475	88035715	4/13/2019	1705	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
476	87215420	4/13/2019	1654	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
477	87289607	4/15/2019	1110	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
478	88044180	4/18/2019	1533	SR 400	MILE MARKER #52	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	07 SEVERE CROSSWINDS	1	0	0	0	0
479	88100541	4/25/2019	2005	I 4	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	3	0	0
480	87277003	4/29/2019	647	I 4	MM 51	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
481	88044181	5/2/2019	1824	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
482	88025117	5/9/2019	130	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
483	88048675	5/9/2019	127	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
484	89010998	5/10/2019	1730	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
485	88044185	5/11/2019	1654	SR 400	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
486	87276848	5/11/2019	703	SR 400	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
487	89011189	5/12/2019	2005	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
488	88141207	5/13/2019	1322	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
489	88141206	5/13/2019	1155	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
490	88025120	5/17/2019	1015	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
491	88056133	5/22/2019	1450	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
492	87246881	5/22/2019	2328	SR 400	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
493	88056135	5/25/2019	1120	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
494	87292307	5/27/2019	650	SR 400	US 27	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
495	87283701	5/29/2019	2337	I 4	US 27	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
496	88035301	5/31/2019	1357	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
497	89010876	6/3/2019	1858	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
498	87292310	6/4/2019	845	SR 400	US 27	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
499	87292312	6/5/2019	545	SR 400	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
500	88141213	6/6/2019	1452	SR 400	CR 557	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
501	88048681	6/6/2019	1707	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
502	88048684	6/7/2019	1928	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
503	88044663	6/8/2019	1020	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
504	87283705	6/8/2019	2311	I 4	US 27	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
505	88102878	6/9/2019	513	I 4	MILE MARKER #55	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	1	0	0
506	88044192	6/9/2019	629	SR 400	MILE MARKER #49	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
507	89012010	6/12/2019	1623	I 4	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
508	88089769	6/12/2019	1624	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
509	87292315	6/15/2019	1735	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
510	88035305	6/19/2019	625	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2015 - December 2019)

#	HSMV Report Number	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
511	88048692	6/23/2019	855	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
512	88166352	6/24/2019	2202	SR 400	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
513	89012265	6/25/2019	1749	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
514	88011514	6/28/2019	736	I 4	MILE MARKER #49	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
515	88166354	7/1/2019	2316	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	4	0	0
516	88009731	7/5/2019	1515	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
517	88009733	7/6/2019	1800	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
518	88009734	7/7/2019	1850	I 4	US 27	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
519	88089771	7/11/2019	1223	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
520	88162135	7/19/2019	1530	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
521	88032079	7/20/2019	1945	I 4	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	1	0	0	0	0
522	88044674	7/24/2019	2015	I 4	MILE MARKER #52	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
523	88102882	7/24/2019	1315	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
524	88070865	7/28/2019	25	SR 400	MM 54	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
525	88141241	8/1/2019	1405	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
526	88173772	8/1/2019	1431	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
527	87288536	8/2/2019	1015	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
528	88141245	8/3/2019	1447	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
529	88141247	8/5/2019	1421	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
530	88089781	8/6/2019	124	I 4	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	2	0	0
531	87278579	8/7/2019	2055	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
532	88162141	8/11/2019	2350	SR 400	MM 53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
533	87188775	8/16/2019	1322	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
534	88089786	8/23/2019	1247	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
535	88067766	8/25/2019	1850	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
536	88101233	8/27/2019	2225	I 4	US 27	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
537	88141259	8/28/2019	840	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
538	89013415	8/30/2019	2320	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
539	88154413	9/1/2019	1535	SR 400	MM 52	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
540	88203137	9/1/2019	1531	SR 400	MM 52	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
541	88089787	9/3/2019	2002	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
542	89370369	9/13/2019	15	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
543	88173785	9/14/2019	2105	I 4	US 27	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
544	89012760	9/14/2019	1725	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
545	88141268	9/15/2019	1904	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	02 CLOUDY	4	0	1	0	0
546	88168922	9/16/2019	1546	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
547	88166298	9/18/2019	1855	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
548	88141272	9/22/2019	2056	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
549	89370756	10/1/2019	752	I 4	MILE MARKER #50	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
550	88099406	10/3/2019	1805	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
551	88203144	10/4/2019	1451	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
552	88076158	10/5/2019	1042	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
553	88166303	10/5/2019	645	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
554	88111963	10/6/2019	102	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
555	88203150	10/17/2019	1707	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	02 CLOUDY	2	0	0	0	0
556	88041734	10/18/2019	858	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
557	89370963	10/18/2019	2300	I 4	MILE MARKER #53	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
558	88041733	10/18/2019	745	I 4	US 27	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
559	88162153	10/23/2019	300	SR 400	MM 53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
560	89371371	10/25/2019	2313	SR 400	MILE MARKER #49	21 BRIDGE PIER OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
561	88107625	10/25/2019	1200	I 4	SR 25	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
562	89371616	10/26/2019	151	SR 400	MILE MARKER #49	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	3	0	0
563	88173794	10/27/2019	538	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
564	88142644	11/2/2019	1833	I 4	MILE MARKER #54	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
565	88226770	11/7/2019	1906	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
566	88215600	11/7/2019	1408	SR 400	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
567	88142647	11/8/2019	1926	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
568	88101250	11/8/2019	315	I 4	MILE MARKER #52	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
569	85531358	11/11/2019	1650	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
570	88089805	11/20/2019	325	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
571	88215603	11/22/2019	1628	SR 400	MM 49	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
572	89371767	11/22/2019	1418	I 4	MILE MARKER #50	08 RAN INTO WATER/CANAL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
573	88142654	11/22/2019	1739	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
574	88142656	11/24/2019	1411	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
575	88041740	11/28/2019	1055	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
576	88215607	12/1/2019	649	SR 400	MM 49	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
577	88130277	12/6/2019	1805	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	1	0	0
578	88226783	12/11/2019	631	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	02 CLOUDY	2	0	1	0	0
579	88251151	12/12/2019	1830	SR 400	MM 50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
580	88235023	12/16/2019	2135	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
581	88141130	12/16/2019	920	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
582	88262335	12/19/2019	1625	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
583	88251155	12/21/2019	1735	SR 400	MM 50	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	1	0	0
584	88220068	12/22/2019	20	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
585	88162168	12/22/2019	945	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
586	88162169	12/22/2019	1115	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	6	0	0
587	88122277	12/27/2019	1248	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
588	88184247	12/28/2019	205	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

2020 – May 2022

Uncertified Signal Four Analytics + SSOGIS (Certified Fatal + Incapacitating Injuries)

Interchange: I-4 at SR 570/Polk Parkway (West) (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88251159	SSOGIS	1/1/2020	1000	SR 400	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
2	87285683	SSOGIS	1/8/2020	1955	SR 400	MM 27	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
3	87174327	Signal Four Analytics	1/9/2020	4:00:00 PM	I-4	SR-570	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
4	88251164	SSOGIS	1/13/2020	1020	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
5	88253847	Signal Four Analytics	1/16/2020	12:10:00 AM	SR 400 (I-4)	SR 25 (US HWY 27 EXIT 55)	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	1	0	0
6	88235039	SSOGIS	1/31/2020	1502	SR 400	POLK PKWY	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
7	88220080	Signal Four Analytics	1/31/2020	9:45:00 PM	I-4 (SR 400) EB	SR 570	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
8	88275139	Signal Four Analytics	2/8/2020	9:50:00 AM	STATE 4 (STATE ROAD	US HIGHWAY 27	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	1	0	0	0	0
9	88262232	Signal Four Analytics	2/13/2020	11:50:00 PM	NTERSTATE 4(SR 400)	U.S. HIGHWAY 27(SR 25)	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
10	88170908	Signal Four Analytics	2/14/2020	10:44:00 AM	SR-400	SR-570	Guardrail Face	Other	Wet	Daylight	Rain	1	0	0	0	0
11	88162182	SSOGIS	2/24/2020	1115	SR 400	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
12	88166351	SSOGIS	2/28/2020	1310	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
13	88275156	SSOGIS	2/29/2020	1135	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
14	88253862	SSOGIS	3/4/2020	1105	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	2	0	0
15	88233566	Signal Four Analytics	3/15/2020	2:18:00 PM	SR-400 (I-4) WB MM5	US-27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
16	88308368	SSOGIS	4/14/2020	1615	I 4	MILE MARKER #26	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
17	88033096	SSOGIS	4/15/2020	733	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	03 DAWN	02 CLOUDY	2	0	0	0	0
18	88171484	SSOGIS	5/16/2020	149	SR 570	SR 400	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
19	88262702	Signal Four Analytics	5/20/2020	9:16:00 PM	SR400	COUNTY LINE ROAD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
20	88251185	SSOGIS	5/24/2020	1715	SR 400	MM 27	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
21	88194419	SSOGIS	6/2/2020	1721	SR 400	COUNTY LINE RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
22	88184265	SSOGIS	6/3/2020	645	SR 400	COUNTY LINE RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
23	88233581	SSOGIS	6/5/2020	642	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
24	88327833	Signal Four Analytics	6/6/2020	4:15:00 PM	B EXIT RAMP TO SR-57	STATE ROAD 400 (INTERSTATE 4)	Other Fixed Object	Other	Wet	Daylight	Rain	1	1	1	0	0
25	88215644	SSOGIS	6/13/2020	415	SR 400	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
26	88215645	SSOGIS	6/15/2020	246	SR 400	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
27	88322510	SSOGIS	6/21/2020	2139	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
28	88294641	Signal Four Analytics	6/25/2020	5:52:00 AM	R-400(INTERSTATE 4)N	US HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	2	0	0
29	88258548	SSOGIS	7/2/2020	1731	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
30	89842613	SSOGIS	7/5/2020	2000	I 4	MILE MARKER #27	07 THROWN OR FALLING OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
31	88294645	Signal Four Analytics	7/12/2020	4:44:00 PM	R-400(INTERSTATE 4)N	US HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
32	88314318	SSOGIS	7/23/2020	910	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
33	88175102	SSOGIS	7/28/2020	1600	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
34	88194425	SSOGIS	7/30/2020	1245	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
35	88306956	SSOGIS	8/3/2020	1450	SR 570	US 92	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	3	0	0
36	88175105	SSOGIS	8/6/2020	1200	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
37	88046281	SSOGIS	8/7/2020	1830	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
38	88233597	SSOGIS	8/8/2020	1429	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
39	88308399	SSOGIS	8/22/2020	1245	I 4	COUNTY LINE RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
40	88262261	Signal Four Analytics	8/28/2020	10:57:00 PM	NTERSTATE 4(SR 400)	U.S. HIGHWAY 27(SR 25)	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	1	0	1	0	0
41	88262262	Signal Four Analytics	8/28/2020	11:02:00 PM	NTERSTATE 4(SR 400)	U.S. HIGHWAY 27(SR 27)	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	2	0	0
42	88361456	SSOGIS	9/1/2020	604	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	02 CLOUDY	2	0	1	0	0
43	88306756	SSOGIS	9/9/2020	1944	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
44	88361468	SSOGIS	9/14/2020	1504	I 4	MM 26	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
45	88319037	SSOGIS	9/21/2020	1525	SR 400	MM 27	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
46	88319039	SSOGIS	9/26/2020	1935	SR 400	MM 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	1	0	0
47	88272791	SSOGIS	10/6/2020	645	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
48	88310659	SSOGIS	10/10/2020	2015	SR 400	COUNTY LINE RD	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	4	0	7	0	0
49	88288842	SSOGIS	10/13/2020	1340	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
50	88349886	SSOGIS	10/24/2020	2335	SR 400	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
51	88349890	SSOGIS	11/5/2020	1126	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
52	88310664	SSOGIS	11/8/2020	1130	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
53	24137058	Signal Four Analytics	11/11/2020	10:12:00 PM	SR-400 WB (I4)	SR-25 (HWY 27)	Motor Vehicle in Transport	Other	Wet	Dark - Not Lighted	Rain	2	0	0	0	0
54	88390076	Signal Four Analytics	11/27/2020	1:30:00 AM	SR 400 (I-4)	SR-25 (US-27)	Cable Barrier	Other	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
55	88390078	Signal Four Analytics	12/1/2020	8:14:00 AM	SR-400 (I-4)	SR-25 (US-27)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
56	88383398	SSOGIS	12/3/2020	1035	SR 400	MM 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
57	24137985	SSOGIS	12/3/2020	2030	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
58	88322559	SSOGIS	12/3/2020	1757	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	0	0	0
59	88445445	Signal Four Analytics	12/29/2020	5:20:00 PM	R-400(INTERSTATE 4)N	US HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dawn	Clear	2	0	0	0	0
60	24138462	SSOGIS	12/30/2020	1308	I 4	MILE MARKER #27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
61	88318923	Signal Four Analytics	1/5/2021	2:45:00 AM	SR-400 (I-4) WB MM5	US-27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
62	88468332	Signal Four Analytics	2/23/2021	2:50:00 PM	SR 400 (I-4)	SR-25 (US-27)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
63	88404078	Signal Four Analytics	3/5/2021	11:37:00 AM	-400 (INTERSTATE-4) N	US-27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
64	88404079	Signal Four Analytics	3/11/2021	6:20:00 AM	-400 (INTERSTATE-4)	US-27	Motor Vehicle in Transport	Front to Rear	Dry	Dawn	Clear	2	0	0	0	0
65	88398997	Signal Four Analytics	3/19/2021	6:01:00 AM	STATE 4 (STATE ROAD	US-HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
66	88374006	SSOGIS	4/8/2021	1650	SR 400	MILE MARKER #26	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
67	88306780	Signal Four Analytics	4/9/2021	7:52:00 AM	NTERSTATE 4(SR 400)	U.S. HIGHWAY 27(SR 25)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
68	88365082	Signal Four Analytics	4/11/2021	4:26:00 AM	TBOUND STATE ROAD	STATE ROAD 570	Guardrail Face	Other	Dry	Dark - Lighted	Clear	1	0	0	0	0
69	88310803	SSOGIS	4/16/2021	1518	SR 400	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
70	88399007	Signal Four Analytics	4/16/2021	10:32:00 PM	STATE 4 (STATE ROAD	US-HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
71	24288813	Signal Four Analytics	5/3/2021	7:35:00 PM	INTERSTATE 4	US HIGHWAY 27	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	1	0	2	0	0
72	88365092	Signal Four Analytics	5/12/2021	11:14:00 PM	TBOUND STATE ROAD	STATE ROAD 570	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	2	0	1	0	0
73	88399013	Signal Four Analytics	5/28/2021	9:04:00 AM	STATE 4 (STATE ROAD	US-HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
74	88399016	Signal Four Analytics	6/3/2021	2:02:00 PM	STATE 4 (STATE ROAD	US-HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	3	0	0
75	88374024	SSOGIS	6/6/2021	1733	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
76	88365096	Signal Four Analytics	6/6/2021	4:12:00 AM	TBOUND STATE ROAD	STATE ROAD 570	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
77	85155943	SSOGIS	6/7/2021	1920	SR 570	SR 400	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	1	0	1	0	0
78	88493990	Signal Four Analytics	6/11/2021	1:05:00 PM	NTERSTATE 4(SR 400)	U.S HIGHWAY 27(SR 25)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	5	0	0
79	24289484	Signal Four Analytics	6/13/2021	2:15:00 PM	INTERSTATE 4	US HWY 27	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
80	88408516	Signal Four Analytics	6/15/2021	8:18:00 AM	0 (I-4) EB ENTRANCE	US-27	Overturn/Rollover	Other	Wet	Daylight	Rain	1	0	1	0	0
81	88493995	Signal Four Analytics	6/17/2021	6:20:00 PM	E 4(SR 400) WB ENTRA	U.S. HIGHWAY 27(SR 25)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
82	88487196	SSOGIS	6/21/2021	720	I 4	POLK PKWY	16 WORK ZONE/MAINTENANCE EQUIPMEN	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	2	0	0
83	88492819	Signal Four Analytics	6/25/2021	3:24:00 PM	-400(INTERSTATE 4)M	US HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
84	88449330	Signal Four Analytics	6/30/2021	3:05:00 PM	STATE 4 (STATE ROAD	U.S. HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
85	88468652	Signal Four Analytics	7/1/2021	9:55:00 AM	SR 400 (I-4) EB 55MM	SR 25 (US HWY 27)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
86	88492823	Signal Four Analytics	7/2/2021	4:07:00 PM	-400(INTERSTATE 4)M	US HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
87	85155947	SSOGIS	7/28/2021	2145	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
88	88549593	Signal Four Analytics	8/2/2021	7:43:00 AM	NTERSTATE 4 EXIT RAM	US 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
89	88453037	Signal Four Analytics	8/2/2021	4:26:00 PM	-400 (INTERSTATE-4) N	US-27	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	3	0	0	0	0

Interchange: I-4 at SR 570/Polk Parkway (West) (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
90	24290965	Signal Four Analytics	8/11/2021	2:30:00 AM	SR-400 (I4)	U.S. HWY 27	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	1	0	0	0	0
91	88468660	Signal Four Analytics	8/13/2021	12:45:00 PM	SR 400 (I-4) EB 55MM	SR 25 (US HWY 27)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	3	0	0	0	0
92	85155948	SSOGIS	8/18/2021	1000	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
93	88266934	SSOGIS	8/26/2021	1805	SR 570	I 4	27 GUARDRAIL FACE	88 UNKNOWN	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
94	88471791	SSOGIS	8/26/2021	1347	I 4	COUNTY LINE RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
95	88453230	Signal Four Analytics	8/29/2021	12:10:00 AM	STATE 4 EXIT RAMP TO	US 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
96	88468662	Signal Four Analytics	9/1/2021	7:20:00 AM	SR 400 (I-4) EB 55	SR 25 (US HWY 27)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
97	88472073	Signal Four Analytics	9/10/2021	6:10:00 PM	STATE 4 (STATE ROAD	U.S. HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	3	0	0	0	0
98	88453054	Signal Four Analytics	9/19/2021	1:07:00 PM	-400 (INTERSTATE-4) I	US-27	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	3	0	0	0	0
99	24680714	Signal Four Analytics	10/18/2021	4:50:00 PM	I-4 WB EXIT RAMP	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
100	24680852	Signal Four Analytics	10/25/2021	11:52:00 PM	STBOUND ENTRANCE	HWY 27 EAST OFF RAMP	Traffic Sign Support	Other	Wet	Dark - Lighted	Rain	1	0	1	0	0
101	24681100	Signal Four Analytics	10/28/2021	7:09:00 AM	INTERSTATE 4	HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	1	0	0
102	88483626	Signal Four Analytics	11/2/2021	7:25:00 AM	INTERSTATE 4	U.S. HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Opposite Direction	Dry	Daylight	Clear	2	0	0	0	0
103	88572745	Signal Four Analytics	11/2/2021	2:45:00 PM	TERSTATE 4 EXIT RAM	US 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	2	0	0
104	24680853	Signal Four Analytics	11/5/2021	7:00:00 PM	I-4 WESTBOUND	HWY 27	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Not Lighted	Rain	2	0	2	0	0
105	88588482	Signal Four Analytics	11/12/2021	7:39:00 AM	ROAD 400 (INTERSTAT	STATE ROAD 25(US 27)	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
106	24681187	Signal Four Analytics	11/12/2021	6:06:00 PM	INTERSTATE 4	HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
107	88572750	Signal Four Analytics	11/16/2021	2:41:00 PM	ERSTATE 4 EB EXIT RA	US 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
108	88493552	Signal Four Analytics	11/17/2021	7:00:00 AM	STATE 4 (STATE ROAD	U.S. HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
109	88527596	SSOGIS	12/4/2021	530	I 4	POLK PKWY	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
110	24680451	Signal Four Analytics	12/12/2021	10:43:00 PM	I-4	HWY 27	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	1	0	0	0	0
111	24682471	Signal Four Analytics	12/21/2021	8:30:00 AM	INTERSTATE 4	HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Dark - Lighted	Rain	2	0	1	0	0
112	24881602	Signal Four Analytics	12/23/2021	3:23:00 PM	INTERSTATE 4(SR400)	US27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
113	24683028	SSOGIS	12/24/2021	1612	I 4	MILE MARKER #26	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
114	24682721	Signal Four Analytics	12/26/2021	9:40:00 PM	INTERSTATE 4	US HIGHWAY 27	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	1	0	0	0	0
115	24681515	Signal Four Analytics	1/3/2022	7:56:00 PM	I4 WESTBOUND	HWY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
116	88507232	Signal Four Analytics	1/17/2022	2:56:00 PM	STATE 4 (STATE ROAD	U.S. HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
117	88507233	Signal Four Analytics	1/17/2022	6:11:00 PM	STATE 4 (STATE ROAD	U.S. HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
118	24684072	Signal Four Analytics	2/10/2022	2:09:00 PM	EASTBOUND I-4	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
119	25108160	Signal Four Analytics	2/16/2022	11:55:00 AM	SR 400 EB (I4)	US HWY 27	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
120	24910013	SSOGIS	2/23/2022	1506	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
121	24683411	Signal Four Analytics	2/24/2022	10:48:00 PM	INTERSTATE-4	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
122	25108499	Signal Four Analytics	3/2/2022	9:37:00 AM	I4 E	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	4	0	0	0	0
123	25108778	Signal Four Analytics	3/2/2022	10:46:00 AM	I4 E	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
124	25109060	Signal Four Analytics	3/9/2022	2:15:00 PM	INTERSTATE 4	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
125	24884823	Signal Four Analytics	3/19/2022	2:47:00 PM	ROAD 400(INTERSTAT	STATE ROAD 25(US 27)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
126	88574850	Signal Four Analytics	3/22/2022	11:36:00 AM	-400 (INTERSTATE-4) I	US-27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
127	25109137	Signal Four Analytics	3/23/2022	10:17:00 PM	I-4	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	2	0	0
128	24910023	Signal Four Analytics	3/25/2022	12:00:00 PM	TATE 4 (STATE ROAD	US HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
129	25109309	Signal Four Analytics	3/27/2022	2:05:00 PM	SR 400 (I4) EB	US HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
130	25109290	Signal Four Analytics	3/31/2022	8:00:00 AM	I 4 E	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
131	25109106	Signal Four Analytics	4/1/2022	4:00:00 PM	EASTBOUND I-4	HWY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	1	0	0	0	0
132	88227864	Signal Four Analytics	4/9/2022	7:40:00 AM	SR-400	SR-570	Traffic Sign Support	Other	Dry	Daylight	Clear	1	0	0	0	0
133	25109027	Signal Four Analytics	4/14/2022	9:42:00 AM	I4 WB	HWY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
134	24910028	Signal Four Analytics	4/18/2022	6:22:00 AM	TATE 4 (STATE ROAD 4	COUNTY LINE ROAD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Unknown Lighting	Clear	2	0	0	0	0
135	25110590	Signal Four Analytics	5/1/2022	1:05:00 PM	I-4 EASTBOUND	HWY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
136	24912141	SSOGIS	5/15/2022	1510	I 4	SR 570	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
137	25110833	SSOGIS	5/18/2022	635	SR 570	US 92	27 GUARDRAIL FACE	03 ANGLE	01 DRY	03 DAWN	01 CLEAR	1	0	1	0	0
138	88227866	SSOGIS	5/25/2022	1425	SR 570	SR 400	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
139	24914827	Signal Four Analytics	5/25/2022	5:00:00 PM	4 EB EXIT RAMP MM5	US 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0

Mainline Segment: I-4 from SR 570/Polk Parkway (West) to SR 546/W Memorial Boulevard (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88262230	SSOGIS	1/30/2020	2223	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	5	0	0
2	88166346	SSOGIS	2/22/2020	1210	I 4	POLK PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
3	88184260	SSOGIS	4/6/2020	710	SR 400	SR 546	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
4	88327824	SSOGIS	5/16/2020	529	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	0	0	0
5	88267810	SSOGIS	7/6/2020	1240	SR 400	MM 27	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
6	88327844	SSOGIS	7/17/2020	2053	SR 400	MEMORIAL BLVD	09 OTHER NON-COLLISION	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
7	88378020	SSOGIS	8/6/2020	1107	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	3	0	0
8	88361448	Signal Four Analytics	8/11/2020	9:46:00 AM	ATE ROAD 400) ENTRA	STATE ROAD 546 (W MEMORIAL BLVD)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
9	88349888	SSOGIS	10/25/2020	2346	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
10	88378052	SSOGIS	11/16/2020	906	SR 400	MEMORIAL BLVD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
11	88404042	SSOGIS	12/7/2020	1939	I 4	MEMORIAL BLVD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
12	88392892	Signal Four Analytics	3/18/2021	3:30:00 AM	SR400	SR570	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
13	88518791	Signal Four Analytics	6/12/2021	1:22:00 PM	I-4 E	US HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
14	24289832	Signal Four Analytics	6/14/2021	10:50:00 PM	SR-400 (I4)	US HWY 27	Motor Vehicle in Transport	Other	Wet	Dark - Not Lighted	Rain	1	0	0	0	0
15	88468651	Signal Four Analytics	7/1/2021	9:15:00 AM	SR 400 (I-4) EB 56MM	SR 25 (US HWY 27)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
16	88457654	Signal Four Analytics	7/21/2021	10:29:00 PM	STATE 4 (STATE ROAD	U.S. HIGHWAY 27	Overturn/Rollover	Other	Wet	Dark - Lighted	Clear	1	0	0	0	0
17	88457656	Signal Four Analytics	7/24/2021	1:18:00 AM	STATE 4 (STATE ROAD	U.S. HIGHWAY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
18	88494023	Signal Four Analytics	8/14/2021	10:24:00 AM	NSTATE 4(STATE ROAD	U.S. 27 (STATE ROAD 25)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	2	0	0
19	24291773	Signal Four Analytics	8/20/2021	7:30:00 PM	INTERSTATE 4	HWY 27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
20	89846531	Signal Four Analytics	9/6/2021	1:50:00 PM	TERSTATE-4 WESTBOU	MEMORIAL BOULEVARD	Other Non-Collision	Other	Dry	Daylight	Clear	1	0	1	0	0
21	88475674	Signal Four Analytics	9/25/2021	5:06:00 PM	INTERSTATE 4(SR400)	SR570	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
22	88482371	Signal Four Analytics	9/29/2021	4:50:00 PM	INTERSTATE 4(SR400)	SR570	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
23	24400602	Signal Four Analytics	10/9/2021	11:00:00 PM	I-4	W MEMORIAL BLVD	Other Traffic Barrier	<Null>	Dry	Dark - Lighted	Clear	1	0	0	0	0
24	88588478	Signal Four Analytics	10/29/2021	1:09:00 PM	ROAD 400 (INTERSTAT	STATE ROAD 25 (US 27)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
25	24681157	Signal Four Analytics	11/12/2021	3:30:00 AM	SR-400 (I4)	U.S. HWY 27	Motor Vehicle in Transport	Other	Wet	Dark - Lighted	Cloudy	2	0	0	0	0
26	24681206	Signal Four Analytics	11/13/2021	9:30:00 PM	INTERSTATE 4	HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
27	88588499	Signal Four Analytics	12/24/2021	3:39:00 PM	OAD 400(INTERSTATE	STATE ROAD 25(US27)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
28	24887483	Signal Four Analytics	1/16/2022	11:50:00 AM	INTERSTATE 4(SR400)	US27	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
29	24884810	Signal Four Analytics	1/22/2022	12:11:00 PM	ROAD 400(INTERSTAT	STATE ROAD 25(US27)	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
30	88579427	Signal Four Analytics	1/22/2022	12:34:00 PM	R400 (I-4) WEST OF M	U.S. HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
31	89591056	Signal Four Analytics	2/4/2022	10:31:00 PM	TERSTATE 4 EXIT RAM	SR 546 (W MEMORIAL BLVD)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
32	24884819	Signal Four Analytics	3/15/2022	7:08:00 AM	ROAD 400(INTERSTAT	STATE ROAD 25(US27)	Motor Vehicle in Transport	Front to Rear	Dry	Dawn	Clear	2	0	0	0	0
33	24916743	Signal Four Analytics	3/24/2022	3:48:00 PM	TATE 4 WB ENTRANCE	SR 546 (MEMORIAL BLVD)	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Daylight	Cloudy	2	0	0	0	0
34	88574852	Signal Four Analytics	3/31/2022	8:10:00 AM	-400 (INTERSTATE-4) I	US-27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	1	0	0
35	88574853	Signal Four Analytics	4/5/2022	9:10:00 AM	-400 (INTERSTATE-4) I	US-27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
36	88551439	SSOGIS	5/14/2022	755	I 4	MILE MARKER #27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
37	24934801	Signal Four Analytics	5/18/2022	10:21:00 AM	SR-400 (I-4) NEAR MM	U.S. HIGHWAY 27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0

Interchange: I-4 at SR 546/W Memorial Boulevard (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	89348846	SSOGIS	1/21/2020	1756	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
2	89373636	Signal Four Analytics	1/21/2020	8:13:00 AM	MEMORIAL BLVD	GARY AVE N	Jackknife	Angle	Dry	Daylight	Clear	2	0	2	0	0
3	88226804	Signal Four Analytics	1/28/2020	10:18:00 AM	MEMORIAL BLVD	CHESTNUT RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
4	88253851	SSOGIS	2/6/2020	1615	SR 400	KATHLEEN RD	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
5	88166342	SSOGIS	2/15/2020	1130	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
6	89373648	Signal Four Analytics	2/15/2020	2:06:00 PM	MEMORIAL BLVD	CHESTUT RD	Pedalcycle	Other	Dry	Daylight	Clear	1	0	1	0	1
7	88220085	SSOGIS	2/23/2020	2320	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
8	88170917	SSOGIS	2/28/2020	1249	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
9	88175073	SSOGIS	2/29/2020	5	SR 400	MM 28	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
10	89349369	SSOGIS	3/9/2020	1430	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
11	89349453	SSOGIS	3/16/2020	850	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
12	88246102	SSOGIS	3/26/2020	1700	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
13	88246105	SSOGIS	4/2/2020	1345	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
14	88246105	Signal Four Analytics	4/3/2020	1:45:00 PM	I-4 (SR 400)	SR 546 (MEMORIAL BL)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
15	88233571	SSOGIS	4/19/2020	1437	SR 400	SWINDELL RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
16	88194098	SSOGIS	4/24/2020	1210	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
17	88233576	SSOGIS	5/17/2020	1104	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	88308377	SSOGIS	6/1/2020	1325	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
19	88275170	SSOGIS	6/2/2020	1453	I 4	GALLOWAY RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
20	88184270	SSOGIS	6/19/2020	1930	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
21	24006205	SSOGIS	6/23/2020	1445	SR 546	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	1	1	0	0
22	88327839	SSOGIS	6/28/2020	926	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
23	88308383	SSOGIS	6/29/2020	2220	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
24	88327848	SSOGIS	7/27/2020	1921	I 4	MEMORIAL BLVD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
25	24006590	SSOGIS	8/7/2020	2120	I 4	MEMORAIL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
26	88310646	SSOGIS	8/9/2020	25	SR 400	SR 546	19 IMPACT ATTENUATOR/CRASH CUSION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
27	88361448	SSOGIS	8/10/2020	946	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
28	88308396	Signal Four Analytics	8/13/2020	6:00:00 PM	W MEMORIAL BLVD	WABASH AVE	Motor Vehicle in Transport	Angle	Wet	Daylight	Rain	2	0	3	0	0
29	88194427	Signal Four Analytics	8/13/2020	8:59:00 PM	-546 (MEMORIAL BLV	CHESTNUT RD	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Cloudy	3	0	2	0	0
30	88262721	SSOGIS	8/21/2020	908	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
31	88206396	SSOGIS	8/25/2020	1335	I 4	SR 546	26 EMBANKMENT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	1	0	0	0
32	88206396	Signal Four Analytics	8/26/2020	1:35:00 PM	I-4 OR SR 400 WB	SR 546 OR MEMORIAL BLVD	Embankment	Other	Wet	Daylight	Cloudy	1	1	0	0	0
33	88322534	SSOGIS	8/29/2020	20	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	2	0	0
34	88306752	SSOGIS	9/5/2020	1204	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
35	88361464	SSOGIS	9/10/2020	1453	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
36	89846058	SSOGIS	9/10/2020	1730	I 4	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
37	88319027	SSOGIS	9/11/2020	1510	SR 400	MM 28	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
38	88369165	SSOGIS	9/20/2020	1646	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
39	24007541	SSOGIS	11/7/2020	2114	MEMORIAL BLVD	I 4	24 CURB	00 NOT CODED	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
40	88378050	Signal Four Analytics	11/14/2020	3:53:00 PM	EXIT RAMP FROM SR-	MEMORIAL BLVD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
41	24137630	SSOGIS	11/26/2020	1540	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
42	24007797	Signal Four Analytics	12/1/2020	3:32:00 PM	W MEMORIAL BLVD	CRUTCHFIELD RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
43	24007962	Signal Four Analytics	12/14/2020	6:00:00 AM	92	CRUTCHFIELD RD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
44	24008310	Signal Four Analytics	1/16/2021	6:59:00 AM	W MEMORIAL BLVD	MEMORIAL BLVD	Other Non-Fixed Object	0	Dry	Dawn	Clear	1	0	0	0	0
45	88383407	SSOGIS	1/31/2021	35	SR 400	SR 546	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
46	24398021	Signal Four Analytics	3/12/2021	8:21:00 PM	W MEMORIAL BLVD	MEMORIAL BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
47	88449308	SSOGIS	4/10/2021	1144	I 4	SR 546	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
48	88374012	SSOGIS	4/12/2021	1620	SR 400	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
49	88462009	SSOGIS	4/16/2021	326	I 4	SR 546	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	4	0	0
50	88462011	SSOGIS	4/21/2021	2208	I 4	MEMORIAL BLVD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
51	88430520	Signal Four Analytics	4/30/2021	3:18:00 PM	NTRANCE RAMP TO SR	MEMORIAL BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
52	24398941	SSOGIS	5/14/2021	2312	I 4	MEMORIAL BLVD	30 CONCRETE TRAFFIC BARRIER	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
53	88432446	SSOGIS	5/21/2021	1823	SR 400	MEMORIAL BLVD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
54	24399030	SSOGIS	5/30/2021	740	MEMORIAL BLVD	I 4	27 GUARDRAIL FACE	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
55	24399273	Signal Four Analytics	6/21/2021	7:11:00 AM	M I-4 W TO W MEMO	W MEMORIAL BLVD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
56	88454936	SSOGIS	6/27/2021	735	I 4	MEMORIAL BLVD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
57	88408518	SSOGIS	6/28/2021	1018	SR 400	SR 546	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
58	24290194	SSOGIS	7/2/2021	2150	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	01 CLEAR	1	0	2	0	0
59	24399498	Signal Four Analytics	7/10/2021	7:20:00 PM	SR-546	CRUTCHFIELD RD	Traffic Sign Support	0	Wet	Dusk	Rain	1	0	0	0	0
60	88510215	Signal Four Analytics	7/15/2021	12:39:00 PM	TE 4 (STATE ROAD 40	STATE ROAD 546 (MEMORIAL BLVD)	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	0	0	0
61	88432453	Signal Four Analytics	7/18/2021	3:11:00 PM	-400 (INTERSTATE-4) I	US-27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	2	0	0
62	88525160	SSOGIS	7/19/2021	541	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	03 DAWN	01 CLEAR	2	0	1	0	0
63	88525159	Signal Four Analytics	7/19/2021	9:06:00 AM	IT RAMP FROM I-4 (E	MEMORIAL BLVD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
64	24400042	Signal Four Analytics	8/27/2021	3:50:00 AM	SR-546	CRUTCHFIELD RD	Ditch	0	Dry	Dark - Lighted	Clear	1	0	0	0	0
65	24400153	Signal Four Analytics	9/4/2021	6:14:00 PM	SR-546	I 4	Concrete Traffic Barrier	0	Dry	Dark - Lighted	Clear	1	0	1	0	0
66	24400546	Signal Four Analytics	10/6/2021	1:55:00 PM	MEMORIAL BLVD W	I4 W ON RAMP	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
67	88513131	SSOGIS	10/22/2021	1101	I 4	SR 546	29 CABLE BARRIER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
68	88568629	SSOGIS	11/21/2021	1120	SR 400	MEMORIAL BLVD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
69	24681286	SSOGIS	11/23/2021	2047	I 4	MM 28	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	1	0	1	0
70	88513141	Signal Four Analytics	12/11/2021	3:48:00 PM	SR546	INTERSTATE 4(SR400)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
71	24682214	Signal Four Analytics	12/12/2021	12:25:00 AM	MEMORIAL BLVD W	I-4 W	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
72	24770325	Signal Four Analytics	12/18/2021	9:07:00 PM	M W MEMORIAL BLV	W MEMORIAL BLVD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
73	88579425	SSOGIS	1/6/2022	330	I 4	MEMORIAL BLVD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
74	24683090	Signal Four Analytics	1/20/2022	7:50:00 AM	I4 E	HWY 27	Struck by Falling, Shifting Cargo	Other	Dry	Daylight	Clear	2	0	0	0	0
75	24770793	Signal Four Analytics	2/1/2022	12:35:00 PM	SR-546	MEMORIAL BLVD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
76	24770796	Signal Four Analytics	2/2/2022	7:25:00 AM	VEST MEMORIAL BLV	OFF RAMP OF I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
77	88293258	Signal Four Analytics	2/6/2022	1:50:00 PM	WB I-4	MEMORIAL BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	4	0	0
78	88493531	Signal Four Analytics	2/11/2022	3:29:00 AM	-400 (INTERSTATE-4) I	COUNTY LINE RD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
79	24771112	Signal Four Analytics	2/24/2022	11:05:00 AM	SR-546	I 4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
80	88551430	Signal Four Analytics	2/28/2022	2:35:00 PM	R-400 WB EXIT 28 RAM	SR-546	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	4	0	0
81	24771181	Signal Four Analytics	3/3/2022	6:12:00 AM	W MEMORIAL BLVD	I 4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
82	24771318	Signal Four Analytics	3/14/2022	8:15:00 PM	SR-546	MEMORIAL BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
83	24771487	Signal Four Analytics	3/30/2022	3:54:00 AM	SR-546	MEMORIAL BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
84	24772085	Signal Four Analytics	5/18/2022	7:15:00 PM	SR-546	0	Embankment	0	Dry	Daylight	Clear	1	0	0	0	0
85	24906194	SSOGIS	5/19/2022	1016	SR 400	SR 546	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
86	24935835	SSOGIS	5/22/2022	2202	SR 400	MM 28	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	3	0	0

Mainline Segment: I-4 from SR 546/W Memorial Boulevard to SR 539/Kathleen Road (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88226807	SSOGIS	2/5/2020	727	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
2	88166338	SSOGIS	2/5/2020	1620	I 4	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
3	88230914	SSOGIS	2/16/2020	1418	SR 400	MEMORIAL BLVD W	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
4	88246108	SSOGIS	4/5/2020	2055	I 4	KATHLEEN RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
5	88327827	SSOGIS	5/29/2020	2150	SR 400	SR 546	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	2	0	0
6	88253870	SSOGIS	6/8/2020	1605	SR 400	SR 546	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
7	88310643	SSOGIS	7/27/2020	2005	SR 400	MM 30	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
8	88046282	SSOGIS	8/14/2020	1425	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
9	88312590	SSOGIS	8/17/2020	759	SR 400	MILE MARKER #30	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
10	88306965	SSOGIS	8/25/2020	1535	I 4	SR 539	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
11	88378027	SSOGIS	8/27/2020	1220	SR 400	MEMORIAL BLVD	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
12	88262394	SSOGIS	8/29/2020	1210	I 4	MM 28	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
13	88314321	SSOGIS	9/8/2020	2300	I 4	MEMORIAL BLVD W	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
14	24006923	SSOGIS	9/11/2020	2323	I 4	MILE MARKER #30	37 FENCE	00 NOT CODED	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
15	88390052	SSOGIS	9/19/2020	1730	SR 400	SR 539	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
16	88390060	SSOGIS	9/28/2020	1505	SR 400	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
17	88306764	SSOGIS	10/2/2020	2340	SR 400	MEMORIAL BLVD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
18	88314740	SSOGIS	10/28/2020	503	I 4	SR 546	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
19	88378053	SSOGIS	11/16/2020	907	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
20	88312116	SSOGIS	11/20/2020	1310	SR 400	MM 30	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
21	88355116	SSOGIS	11/20/2020	1305	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
22	88355118	SSOGIS	11/24/2020	1456	SR 400	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
23	88383402	SSOGIS	12/9/2020	1140	SR 400	MM 30	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
24	88404048	SSOGIS	12/14/2020	1847	I 4	MEMORIAL BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
25	88262292	Signal Four Analytics	3/13/2021	12:37:00 AM	INTERSTATE 4(SR 400)	KATHLEEN ROAD	Motor Vehicle in Transport	Other	Dry	Dark - Not Lighted	Clear	3	0	3	0	0
26	88449319	SSOGIS	6/5/2021	540	I 4	10TH ST W	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
27	88518800	Signal Four Analytics	7/2/2021	1:53:00 PM	I-4 W	KATHLEEN ROAD	Overturn/Rollover	Other	Wet	Daylight	Cloudy	1	0	0	0	0
28	24291340	SSOGIS	8/12/2021	1958	I 4	MILE MARKER #30	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	1	0	0	0	0
29	88457667	SSOGIS	9/3/2021	1546	SR 400	10TH ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
30	24884806	SSOGIS	1/18/2022	2232	I 4	SR 539	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
31	24683210	SSOGIS	2/14/2022	1947	I 4	MILE MARKER #30	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
32	24895350	Signal Four Analytics	2/16/2022	6:52:00 AM	INTERSTATE 4(SR400)	SR546	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
33	24910027	SSOGIS	4/10/2022	1957	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
34	24901961	SSOGIS	4/14/2022	1001	I 4	BELLE VISTA DR	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
35	25108101	SSOGIS	4/17/2022	1845	I 4	MILE MARKER #28	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
36	88574859	Signal Four Analytics	4/30/2022	4:01:00 PM	-400 (INTERSTATE-4) I	US-27	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
37	24902755	Signal Four Analytics	5/5/2022	9:30:00 AM	STATE ROAD 400	STATE ROAD 539	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0

Interchange: I-4 at SR 539/Kathleen Road (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88230898	Signal Four Analytics	1/6/2020	6:23:00 AM	T RAMP FROM SR-400	KATHLEEN ROAD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
2	89348697	SSOGIS	1/8/2020	1041	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
3	88253846	SSOGIS	1/14/2020	455	SR 400	KATHLEEN RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
4	88253846	Signal Four Analytics	1/15/2020	4:55:00 AM	SR 400 (I-4)	CR 35A (KATHLEEN RD)	Ditch	Other	Wet	Dark - Lighted	Rain	1	0	0	0	0
5	89348844	Signal Four Analytics	1/22/2020	1:05:00 PM	SR 539	I 4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
6	89348899	SSOGIS	1/27/2020	720	KATHLEEN RD	FAIRBANKS ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
7	89349149	Signal Four Analytics	1/27/2020	6:22:00 PM	SR 539	E I-4	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Cloudy	2	0	0	0	0
8	89348914	Signal Four Analytics	1/30/2020	2:58:00 AM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
9	88253850	SSOGIS	1/31/2020	1340	SR 400	KATHLEEN RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
10	88253850	Signal Four Analytics	2/1/2020	1:40:00 PM	) (I-4 WB ENTRANCE F	CR 35A	Ditch	Other	Wet	Daylight	Cloudy	1	0	0	0	0
11	89349147	Signal Four Analytics	2/5/2020	6:15:00 PM	CR 35A	MALL HILL DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
12	89349064	SSOGIS	2/10/2020	1501	KATHLEEN RD	LAVON ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
13	89349043	Signal Four Analytics	2/10/2020	8:30:00 AM	CR 35A	I 4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
14	89349224	SSOGIS	2/16/2020	1855	SR 539	FAIRBANKS ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	2	0	0
15	88215623	SSOGIS	2/18/2020	553	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
16	87285701	SSOGIS	2/22/2020	245	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
17	88226814	SSOGIS	2/23/2020	1423	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	88170912	SSOGIS	2/25/2020	1704	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
19	88262364	SSOGIS	3/6/2020	910	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
20	88162186	Signal Four Analytics	3/6/2020	10:25:00 AM	CR-35A	SR-400	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	2	0	0
21	88251175	SSOGIS	3/8/2020	2340	SR 400	MM 31	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
22	88162187	SSOGIS	3/9/2020	657	SR 400	MM 31	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
23	88308365	SSOGIS	3/11/2020	1705	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
24	88308366	SSOGIS	3/12/2020	1135	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
25	88308365	Signal Four Analytics	3/12/2020	5:05:00 PM	TATE 4 (SR 400) EXIT R	KATHLEEN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
26	89349477	SSOGIS	3/15/2020	1258	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
27	88253863	SSOGIS	4/21/2020	950	I 4	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
28	88308371	SSOGIS	5/2/2020	1120	I 4	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
29	24005940	SSOGIS	5/26/2020	1409	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
30	24006076	SSOGIS	6/11/2020	750	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
31	24006075	Signal Four Analytics	6/11/2020	1:35:00 PM	CR-35A	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
32	88262705	Signal Four Analytics	6/12/2020	12:03:00 PM	SR400	KATHLEEN RD	Other Non-Fixed Object	Other	Dry	Daylight	Clear	2	0	0	0	0
33	24006094	Signal Four Analytics	6/15/2020	4:23:00 PM	KATHLEEN RD	MALL HILL DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
34	88162198	SSOGIS	6/16/2020	1320	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
35	88162198	Signal Four Analytics	6/17/2020	1:20:00 PM	SR-400 EB MM31	MM31	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
36	88046280	Signal Four Analytics	6/20/2020	3:35:00 AM	SR400	KATHLEEN RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
37	88251200	SSOGIS	6/28/2020	925	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
38	88262709	SSOGIS	7/7/2020	2102	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
39	24006446	Signal Four Analytics	7/7/2020	10:15:00 PM	CR-35A	GRAND BAY CIR	Motor Vehicle in Transport	Front to Rear	Dry	Dawn	Clear	3	0	0	0	0
40	88267812	SSOGIS	7/10/2020	130	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
41	24006302	Signal Four Analytics	7/10/2020	11:54:00 AM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
42	24006422	SSOGIS	7/21/2020	1620	SR 539	KENDRICK LN	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
43	88310642	SSOGIS	7/26/2020	1650	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
44	88310642	Signal Four Analytics	7/27/2020	4:50:00 PM	-400 WB EXIT 31 RAN	CR-35A	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	1	0	0
45	88309194	SSOGIS	7/30/2020	1003	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	5	2	4	0	0
46	88327849	SSOGIS	7/30/2020	1010	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
47	88233596	SSOGIS	8/6/2020	1738	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
48	88322527	SSOGIS	8/8/2020	1952	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
49	88233598	SSOGIS	8/8/2020	1847	SR 400	US 98	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
50	88322528	SSOGIS	8/10/2020	1632	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
51	88285048	SSOGIS	8/16/2020	1606	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
52	88262722	SSOGIS	8/22/2020	1319	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
53	24006731	SSOGIS	8/23/2020	1606	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	88234413	SSOGIS	8/25/2020	1845	SR 400	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
55	88175113	SSOGIS	8/25/2020	1516	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
56	88262723	SSOGIS	8/25/2020	1506	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	1	0	0
57	88319025	SSOGIS	8/26/2020	1150	SR 400	MM 31	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
58	88322535	SSOGIS	8/29/2020	2319	I 4	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
59	88361455	SSOGIS	8/30/2020	731	I 4	SR 539	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
60	88390046	Signal Four Analytics	9/13/2020	4:55:00 PM	SR 400 (I-4)	SR 539 (KATHLEEN RD)	Embankment	Other	Wet	Daylight	Cloudy	1	0	0	0	0
61	88319034	SSOGIS	9/19/2020	1555	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
62	24007016	Signal Four Analytics	9/23/2020	9:43:00 AM	4 EB OFF RAMP EXIT 3	KATHLEEN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
63	88369167	SSOGIS	9/25/2020	2038	I 4	KATHLEEN RD	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
64	24007197	Signal Four Analytics	10/8/2020	9:48:00 AM	CR 35 A	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
65	88288840	Signal Four Analytics	10/10/2020	10:40:00 AM	TATE 4 EB EXIT RAMP	KATHLEEN RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
66	88322548	SSOGIS	10/18/2020	1629	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
67	88369177	SSOGIS	10/21/2020	603	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
68	88306767	SSOGIS	10/23/2020	445	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
69	24007475	SSOGIS	10/25/2020	1533	SR 539	I 4	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
70	24007486	Signal Four Analytics	11/4/2020	10:48:00 AM	SR 539	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
71	88328373	SSOGIS	11/5/2020	820	SR 400	SR 539	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
72	87188795	SSOGIS	11/10/2020	2356	SR 400	CR 582	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
73	88310667	SSOGIS	11/15/2020	605	SR 400	MM 31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
74	24007704	Signal Four Analytics	11/17/2020	6:55:00 PM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
75	24007687	Signal Four Analytics	11/20/2020	7:37:00 AM	SR-539	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
76	24008123	SSOGIS	12/1/2020	535	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
77	88396609	SSOGIS	12/7/2020	21	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
78	24007870	Signal Four Analytics	12/7/2020	8:40:00 AM	CR-35A	MALL HILL DR	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
79	24007938	SSOGIS	12/10/2020	1147	KATHLEEN RD	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
80	88355130	SSOGIS	12/11/2020	1300	SR 400	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
81	88404045	SSOGIS	12/13/2020	1620	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
82	88309310	SSOGIS	12/19/2020	117	I 4	KATHLEEN RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
83	24008095	SSOGIS	12/20/2020	1819	SR 539	LAVON ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	0	0	0
84	24138266	SSOGIS	12/22/2020	402	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
85	24008182	Signal Four Analytics	1/5/2021	7:11:00 AM	FROM I-4 W TO KATHL	CR-35A	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
86	88355138	Signal Four Analytics	1/10/2021	12:30:00 PM	R-400 ENTRANCE RAM	CR-35A	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
87	88390090	Signal Four Analytics	1/10/2021	11:30:00 PM	00 (I-4 - EXIT 31 EXIT R	SR 539 (KATHLEEN RD)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
88	24008257	Signal Four Analytics	1/12/2021	3:03:00 PM	SR 563	KENDRICK LN	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
89	24008315	Signal Four Analytics	1/16/2021	3:20:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0

Interchange: I-4 at SR 539/Kathleen Road (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
90	24008321	Signal Four Analytics	1/17/2021	11:42:00 AM	SR 539	SR 400	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	0	0	0
91	24008348	Signal Four Analytics	1/19/2021	6:51:00 PM	SR-539	BELLGROVE ST	Other Post, Pole or Support	0	Dry	Dark - Lighted	Clear	1	0	2	0	0
92	24008429	Signal Four Analytics	1/27/2021	10:19:00 AM	SR-539	KENDRICK LN	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
93	88328394	SSOGIS	1/30/2021	1610	SR 400	SR 539	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
94	24008494	Signal Four Analytics	2/2/2021	5:32:00 PM	FROM I-4 W TO KATHL	KATHLEEN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
95	88392883	Signal Four Analytics	2/4/2021	4:00:00 PM	SR400 EXIT RAMP	CR35A	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
96	88390102	SSOGIS	2/7/2021	1320	I 4	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
97	24398223	Signal Four Analytics	2/9/2021	7:40:00 AM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
98	88449290	SSOGIS	2/19/2021	1004	I 4	BELLA VISTA ST W	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
99	88449291	Signal Four Analytics	2/25/2021	7:31:00 PM	STATE 4 (STATE ROAD	STATE ROAD 539 (COUNTY ROAD 35A)	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
100	24397931	Signal Four Analytics	3/6/2021	10:17:00 PM	CR-35A	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	2	0	0
101	24397942	Signal Four Analytics	3/8/2021	7:43:00 AM	SR-539	W ELLIOTT ST	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
102	88474540	SSOGIS	3/10/2021	1731	I 4	KATHLEEN RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	1	0	0
103	88468341	Signal Four Analytics	3/15/2021	3:28:00 PM	WB ENTRANCE RAMP	SR-700 (US-98)	Tree (standing)	Other	Dry	Daylight	Cloudy	1	0	1	0	0
104	24398035	Signal Four Analytics	3/15/2021	9:38:00 PM	FLORIDA 539	LAVON ST	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	1	0	0
105	88399000	SSOGIS	3/23/2021	1915	I 4	KATHLEEN RD	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
106	24398201	Signal Four Analytics	3/25/2021	10:31:00 PM	CR-35A	MALL HILL DR	Motor Vehicle in Transport	Angle	Dry	Dark - Not Lighted	Clear	2	0	2	0	0
107	88392896	Signal Four Analytics	3/31/2021	5:10:00 AM	SR400	KATHLEEN RD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
108	87251619	Signal Four Analytics	4/1/2021	8:28:00 AM	SR 400	U.S. HIGHWAY 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
109	24398267	Signal Four Analytics	4/5/2021	10:22:00 AM	SR 539	I 4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
110	24398309	Signal Four Analytics	4/8/2021	9:24:00 AM	CR-35A	MALL HILL DR	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
111	24398403	Signal Four Analytics	4/15/2021	6:49:00 AM	SR-539	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
112	24140098	SSOGIS	4/22/2021	1446	I 4	KATHLEEN RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
113	24398573	Signal Four Analytics	4/26/2021	8:14:00 AM	CR-35A	W I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
114	24398683	Signal Four Analytics	5/4/2021	7:59:00 AM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
115	24398747	Signal Four Analytics	5/8/2021	12:27:00 PM	CR-35A	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
116	24399171	Signal Four Analytics	6/12/2021	12:00:00 PM	KATHLEEN RD	KENDRICK LN	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	0	0	0
117	24399219	Signal Four Analytics	6/16/2021	2:11:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
118	24399278	Signal Four Analytics	6/21/2021	12:43:00 PM	35A	W ELLIOTT ST	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
119	88471770	SSOGIS	6/30/2021	1929	SR 400	US 98	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
120	88449333	Signal Four Analytics	7/3/2021	7:45:00 AM	STATE 4 (STATE ROAD	U.S. HIGHWAY 98	Cable Barrier	Other	Wet	Daylight	Clear	1	0	0	0	0
121	24399523	Signal Four Analytics	7/13/2021	7:46:00 AM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
122	24399544	Signal Four Analytics	7/14/2021	10:08:00 AM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
123	24399653	Signal Four Analytics	7/25/2021	1:45:00 PM	CR-35A	MALL HILL DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
124	24399701	Signal Four Analytics	7/28/2021	1:37:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
125	24399718	Signal Four Analytics	7/30/2021	9:50:00 AM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
126	24399761	Signal Four Analytics	8/3/2021	10:43:00 AM	SR 539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
127	24399869	Signal Four Analytics	8/12/2021	7:40:00 AM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
128	24399908	Signal Four Analytics	8/16/2021	7:43:00 AM	CR-35A	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
129	88471790	Signal Four Analytics	8/20/2021	12:03:00 PM	TBOUND STATE ROAD	KATHLEEN ROAD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	4	0	3	0	0
130	24400114	SSOGIS	8/28/2021	322	SR 539	LAVON ST	36 OTHER POST, POLE, OR SUPPORT	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
131	24400146	Signal Four Analytics	9/2/2021	9:55:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Dark - Lighted	Clear	2	0	0	0	0
132	24400256	Signal Four Analytics	9/10/2021	10:13:00 PM	CR-35A	W I-4	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	3	0	1	0	0
133	24400287	Signal Four Analytics	9/15/2021	10:45:00 AM	SR 539	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
134	24400400	Signal Four Analytics	9/23/2021	3:32:00 PM	CR 35A	MALL HILL DR	Pedestrian	0	Dry	Daylight	Clear	1	1	0	1	0
135	88454959	SSOGIS	9/25/2021	120	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
136	88510239	SSOGIS	9/27/2021	831	I 4	SR 539	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
137	24400456	Signal Four Analytics	9/29/2021	1:21:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
138	88529168	SSOGIS	10/4/2021	1418	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
139	88465728	Signal Four Analytics	10/7/2021	11:15:00 AM	-400 (INTERSTATE-4) M	US-27	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
140	24400620	Signal Four Analytics	10/11/2021	7:54:00 AM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
141	88497943	SSOGIS	10/15/2021	0	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
142	24769638	Signal Four Analytics	10/18/2021	2:45:00 PM	CR-35A	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
143	24769535	Signal Four Analytics	10/18/2021	4:03:00 PM	CR-35A	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	4	0	0	0	0
144	24769571	Signal Four Analytics	10/21/2021	5:13:00 AM	SR 539 (KATHLEEN RD	W I-4	Motor Vehicle in Transport	Rear to Rear	Dry	Dark - Lighted	Rain	3	0	0	0	0
145	24769685	Signal Four Analytics	10/26/2021	3:41:00 PM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
146	24769710	Signal Four Analytics	11/2/2021	7:57:00 AM	SR 539	KENDRICK LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
147	24769750	Signal Four Analytics	11/4/2021	10:50:00 PM	KATHLEEN RD	MALL HILL DR	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	2	0	0	0	0
148	88568628	Signal Four Analytics	11/16/2021	2:10:00 PM	SR 400 EXIT RAMP	US HIGHWAY 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
149	24770190	Signal Four Analytics	12/3/2021	10:44:00 AM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
150	24770260	Signal Four Analytics	12/9/2021	3:13:00 PM	SR-539	KENDRICK LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
151	24770307	Signal Four Analytics	12/14/2021	5:46:00 PM	CR-35A	W I-4	Pedestrian	0	Wet	Dusk	Cloudy	1	0	1	1	0
152	24770286	Signal Four Analytics	12/15/2021	5:41:00 PM	KATHLEEN RD	E I-4	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Cloudy	2	0	0	0	0
153	88568632	SSOGIS	12/20/2021	904	SR 400	KATHLEEN RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
154	24770349	Signal Four Analytics	12/20/2021	3:20:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
155	88561239	Signal Four Analytics	12/21/2021	7:35:00 AM	KATHLEEN RD	STATE ROAD 400	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
156	24770394	Signal Four Analytics	12/24/2021	1:45:00 PM	SR-539	KENDRICK LN	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
157	24770436	Signal Four Analytics	12/30/2021	10:02:00 AM	CR-35A	MALL HILL DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	2	0	0
158	24770604	Signal Four Analytics	1/15/2022	2:21:00 PM	FROM I-4 E TO KATHL	SR-539	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
159	24770722	Signal Four Analytics	1/20/2022	11:59:00 AM	SR-539	KENDRICK LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
160	24770690	Signal Four Analytics	1/24/2022	5:39:00 PM	SR-539	E I-4	Curb	0	Dry	Daylight	Clear	1	0	1	0	0
161	24770809	Signal Four Analytics	1/28/2022	7:04:00 PM	SR-539	KENDRICK LN	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Unknown Lighting	Clear	2	0	0	0	0
162	24683896	SSOGIS	1/29/2022	419	I 4	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
163	24894757	SSOGIS	1/30/2022	1042	I 4	SR 539	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	1	0	1	0
164	24770964	Signal Four Analytics	2/4/2022	7:07:00 PM	SR-539	KENDRICK LN	Motor Vehicle in Transport	Front to Front	Dry	Dark - Lighted	Clear	3	0	1	0	0
165	24895949	SSOGIS	2/5/2022	1640	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
166	24770875	Signal Four Analytics	2/7/2022	3:55:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
167	24770876	Signal Four Analytics	2/7/2022	4:44:00 PM	CR-35A	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
168	25108102	SSOGIS	2/9/2022	2330	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
169	24770951	Signal Four Analytics	2/9/2022	7:21:00 PM	CR-35A	GRAND BAY CIR	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
170	24772228	Signal Four Analytics	3/8/2022	7:15:00 AM	SR-539	KENDRICK LN	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	0	0	0
171	24771273	Signal Four Analytics	3/10/2022	7:44:00 AM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Clear	3	0	0	0	0
172	24771274	Signal Four Analytics	3/10/2022	8:00:00 AM	SR-539	FAIRBANKS ST	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
173	24771335	Signal Four Analytics	3/10/2022	2:15:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
174	24901835	SSOGIS	3/21/2022	1445	I 4	KATHLEEN RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
175	24934792	Signal Four Analytics	4/2/2022	2:18:00 PM	RAMP FROM SR-400	KATHLEEN ROAD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
176	24771776	Signal Four Analytics	4/17/2022	12:19:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	3	0	0	0	0
177	24771854	Signal Four Analytics	4/28/2022	7:35:00 AM	SR-539	BELLGROVE ST	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
178	24885031	Signal Four Analytics	5/3/2022	11:18:00 AM	STATE ROAD 400	KATHLEEN RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0

Interchange: I-4 at SR 539/Kathleen Road (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
179	24771972	Signal Four Analytics	5/9/2022	1:38:00 PM	CR-35A	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
180	24772020	Signal Four Analytics	5/12/2022	5:18:00 PM	SR-539	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	2	0	0
181	24772044	Signal Four Analytics	5/16/2022	10:27:00 AM	CR-35A	MALL HILL DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0

Mainline Segment: I-4 from SR 539/Kathleen Road to US 98 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88170904	SSOGIS	1/30/2020	1205	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
2	88253855	Signal Four Analytics	2/15/2020	4:20:00 PM	400 (EB ENTRANCE RA	SR 700 (US HWY 98)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
3	88166344	Signal Four Analytics	2/21/2020	7:30:00 AM	: 4 (SR 400) EB EXIT RA	U.S HWY 98 (SR 700)	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
4	88250793	Signal Four Analytics	3/10/2020	7:46:00 AM	I-4 EXIT RAMP	US 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
5	88262708	Signal Four Analytics	6/25/2020	7:47:00 PM	SR-400 EXIT RAMP	US-98	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
6	88310644	Signal Four Analytics	8/2/2020	3:28:00 PM	400 EB ENTRANCE RA	US-98	Pedalcycle	Angle	Dry	Daylight	Clear	1	0	0	0	1
7	88285046	Signal Four Analytics	8/14/2020	9:23:00 PM	-400 (I-4) EB EXIT RAN	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
8	88309209	SSOGIS	8/17/2020	1738	I 4	SR 539	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
9	88322538	Signal Four Analytics	9/15/2020	7:55:00 AM	EB I-4 EXIT RAMP	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
10	88262267	SSOGIS	9/23/2020	1620	I 4	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
11	88328372	Signal Four Analytics	11/2/2020	11:25:00 AM	400 (I-4) EB EXIT RAN	SR 700 (US HWY 98) EXIT 32	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
12	88285066	Signal Four Analytics	11/26/2020	11:21:00 AM	SR-400	US-98	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
13	88425406	Signal Four Analytics	1/16/2021	6:35:00 PM	I-4 (SR 400)	US 98 (SR 700)	Ditch	Other	Dry	Dark - Not Lighted	Clear	1	0	1	0	0
14	87251593	Signal Four Analytics	1/21/2021	2:00:00 PM	I-4 E	KATHLEEN ROAD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
15	88390097	Signal Four Analytics	2/5/2021	6:50:00 AM	SR 400 (I-4)	SR 539 (KATHLEEN RD)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	3	0	0	0	0
16	88359468	Signal Four Analytics	2/10/2021	3:02:00 PM	STATE 4 (STATE ROAD	STATE ROAD 35	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
17	88430513	Signal Four Analytics	3/12/2021	10:21:00 AM	0 (INTERSTATE 4) NEA	GRIFFIN ROAD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
18	88449297	Signal Four Analytics	3/18/2021	3:50:00 PM	STATE 4 (STATE ROAD	U.S. HIGHWAY 98 (STATE ROAD 700)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dawn	Clear	2	0	1	0	0
19	88416513	SSOGIS	4/22/2021	1500	I 4	SR 539	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
20	88500839	Signal Four Analytics	5/9/2021	1:15:00 AM	WB (SR 400) ENT RAM	US 98 (SR 700)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
21	88471772	Signal Four Analytics	7/8/2021	6:03:00 PM	400 EASTBOUND EXIT	US 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
22	88462790	Signal Four Analytics	8/4/2021	4:42:00 PM	INTERSTATE 4(SR400)	SR700(US98)	Motor Vehicle in Transport	Unknown	Wet	Daylight	Rain	2	0	0	0	0
23	88457662	Signal Four Analytics	8/18/2021	3:44:00 PM	STATE 4 (STATE ROAD	U.S. HIGHWAY 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
24	88549607	Signal Four Analytics	8/24/2021	3:05:00 PM	ERSTATE 4 WB EXIT RA	US 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
25	88525178	SSOGIS	8/29/2021	345	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	88 UNKNOWN	04 DARK-LIGHTED	02 CLOUDY	1	0	1	0	0
26	88518819	Signal Four Analytics	8/29/2021	1:40:00 PM	STATE ROAD 400	STATE ROAD 700	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
27	88518820	Signal Four Analytics	8/29/2021	2:20:00 PM	TE ROAD 400 EXIT RA	STATE ROAD 700	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
28	88472401	Signal Four Analytics	9/8/2021	5:53:00 PM	INTERSTATE 4(SR400)	US98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
29	88475673	Signal Four Analytics	9/24/2021	8:55:00 PM	INTERSTATE 4(SR400)	US98	Motor Vehicle in Transport	Unknown	Dry	Dusk	Cloudy	2	0	0	0	0
30	88483628	Signal Four Analytics	11/9/2021	9:00:00 AM	STATE 4 (STATE ROAD	US HIGHWAY 98 (STATE ROAD 700)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	1	0	0
31	24882190	Signal Four Analytics	12/25/2021	10:25:00 PM	4 WB EXIT RAMP TO U	US 98	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
32	88551426	Signal Four Analytics	1/22/2022	1:10:00 PM	R-400 EB EXIT 32 RAM	US-98	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
33	24885010	Signal Four Analytics	1/31/2022	12:11:00 PM	OAD 400 EXIT RAMP T	US 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
34	24902120	Signal Four Analytics	3/3/2022	8:40:00 PM	INTERSTATE 4(SR400)	US98	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
35	88568645	Signal Four Analytics	5/7/2022	2:58:00 AM	SR 400 EXIT RAMP	U.S. HIGHWAY 98	Curb	Other	Dry	Dark - Lighted	Clear	1	0	0	0	0

Interchange: I-4 at US 98 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	89348706	SSOGIS	1/5/2020	1850	LAKELAND PK CNTR DR	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
2	89348713	Signal Four Analytics	1/5/2020	10:37:00 AM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
3	89348741	Signal Four Analytics	1/5/2020	4:18:00 PM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
4	89348715	SSOGIS	1/7/2020	1645	US 98	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
5	89348692	Signal Four Analytics	1/9/2020	7:45:00 AM	US-98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
6	89348798	Signal Four Analytics	1/9/2020	2:52:00 PM	US-98	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
7	89348711	Signal Four Analytics	1/10/2020	4:07:00 PM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
8	89348727	SSOGIS	1/11/2020	1856	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
9	89348782	SSOGIS	1/16/2020	1948	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
10	88184250	SSOGIS	1/16/2020	1940	SR 400	SR 700	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
11	89348951	SSOGIS	1/17/2020	1138	US 98	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
12	88168958	SSOGIS	1/18/2020	1616	SR 400	US 98	29 CABLE BARRIER	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
13	88162175	SSOGIS	1/21/2020	1035	SR 400	MM 32	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
14	90103383	SSOGIS	1/24/2020	1424	US 98	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
15	89348873	Signal Four Analytics	1/25/2020	6:46:00 PM	US HIGHWAY 98 N	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
16	89348923	SSOGIS	1/29/2020	1753	US 98 N	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
17	88235040	Signal Four Analytics	2/1/2020	5:16:00 PM	SR400(EXIT RAMP)MM	US HIGHWAY 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
18	89349072	SSOGIS	2/7/2020	1005	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
19	89349032	SSOGIS	2/8/2020	1200	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
20	89349039	SSOGIS	2/8/2020	300	US 98	ROBSON ST	39 OTHER FIXED OBJECT (WALL, BUIL	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
21	88262233	SSOGIS	2/14/2020	50	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
22	88250787	SSOGIS	2/15/2020	1504	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
23	88184254	SSOGIS	2/17/2020	920	SR 700	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
24	89349168	Signal Four Analytics	2/17/2020	12:12:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
25	89349177	Signal Four Analytics	2/22/2020	12:50:00 PM	US-98	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
26	89349199	Signal Four Analytics	2/25/2020	8:48:00 AM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
27	89349253	SSOGIS	2/27/2020	1520	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
28	89349262	SSOGIS	2/28/2020	2113	US 98	LAKELAND PK CNTR DR	10 PEDESTRIAN	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	1	0
29	88253859	SSOGIS	3/2/2020	1210	SR 700	SR 400	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
30	89349295	Signal Four Analytics	3/4/2020	1:12:00 PM	US 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
31	89349332	SSOGIS	3/6/2020	1358	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
32	89349337	SSOGIS	3/7/2020	620	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
33	89349381	SSOGIS	3/10/2020	1453	US 98 N	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
34	90103349	SSOGIS	3/10/2020	1629	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
35	89349377	Signal Four Analytics	3/11/2020	7:15:00 AM	I-4 EB EXIT 32 RAMP	US 98 N	Motor Vehicle in Transport	Front to Rear	Dry	Dawn	Clear	2	0	0	0	0
36	89349481	SSOGIS	3/17/2020	1423	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
37	89349482	SSOGIS	3/19/2020	1702	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
38	90103363	Signal Four Analytics	4/1/2020	11:15:00 AM	US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
39	88175075	SSOGIS	4/7/2020	415	SR 400	MM 32	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
40	24005637	SSOGIS	4/14/2020	1419	US 98 N	CREVASSE ST	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
41	24005619	Signal Four Analytics	4/15/2020	2:10:00 PM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
42	24005659	SSOGIS	4/17/2020	1130	US 98 N	LAKELAND PK CNTR DR	15 PARKED MOTOR VEHICLE	00 NOT CODED	02 WET	01 DAYLIGHT	03 RAIN	4	0	2	0	0
43	24005679	Signal Four Analytics	4/18/2020	12:13:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
44	24005703	SSOGIS	4/20/2020	1335	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
45	24005690	Signal Four Analytics	4/25/2020	1:50:00 AM	US 98 N	US-98	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Dark - Lighted	Clear	2	0	0	0	0
46	88175079	SSOGIS	4/29/2020	355	SR 400	MM 32	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
47	88175080	SSOGIS	5/2/2020	230	SR 400	MM 32	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
48	24005752	Signal Four Analytics	5/6/2020	12:20:00 PM	US 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	4	0	0	0	0
49	24005903	SSOGIS	5/7/2020	1615	US 98	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	2	0	0
50	24005770	Signal Four Analytics	5/9/2020	7:30:00 PM	US-98 N	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	0	0	0
51	24005828	SSOGIS	5/10/2020	1713	PYRAMID PKWY	US 98 N	39 OTHER FIXED OBJECT (WALL, BUIL	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
52	88184263	Signal Four Analytics	5/11/2020	6:30:00 PM	US HWY 98	GRIFFEN RD	Motor Vehicle in Transport	Rear to Side	Dry	Daylight	Clear	2	0	0	0	0
53	24005813	SSOGIS	5/13/2020	1024	CR 582	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	88295674	SSOGIS	5/13/2020	1345	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
55	24005812	Signal Four Analytics	5/13/2020	1:10:00 PM	US-98	MALL ACCESS ROAD 3	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
56	24005808	Signal Four Analytics	5/14/2020	6:50:00 AM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
57	24005835	SSOGIS	5/16/2020	1636	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
58	24005836	SSOGIS	5/16/2020	2004	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	1	0	0
59	24005832	Signal Four Analytics	5/16/2020	5:09:00 PM	US-98	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
60	24005846	SSOGIS	5/17/2020	1118	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
61	24005907	SSOGIS	5/22/2020	1757	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
62	88251183	SSOGIS	5/22/2020	1635	SR 400	MM 32	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
63	88251184	SSOGIS	5/23/2020	1740	SR 400	MM 32	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
64	24005920	Signal Four Analytics	5/25/2020	9:27:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Rain	2	0	0	0	0
65	24005933	SSOGIS	5/26/2020	1229	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
66	88184266	SSOGIS	6/3/2020	1035	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
67	24006029	SSOGIS	6/6/2020	352	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
68	24006026	Signal Four Analytics	6/7/2020	2:05:00 PM	US 98	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
69	24006039	Signal Four Analytics	6/8/2020	3:58:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
70	24006069	SSOGIS	6/10/2020	1315	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
71	88262382	Signal Four Analytics	6/11/2020	4:20:00 PM	I-4 W	US 98	Other Non-Collision	Other	Wet	Daylight	Rain	1	0	0	0	0
72	24006139	SSOGIS	6/17/2020	825	US 98	I 4	10 PEDESTRIAN	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	1	0
73	24006100	Signal Four Analytics	6/17/2020	8:49:00 AM	EAST EXIT RAMP EXIT	US-98	Overturn/Rollover	0	Dry	Daylight	Clear	1	0	0	0	0
74	24006149	Signal Four Analytics	6/19/2020	1:53:00 PM	US-98	WOODLAND DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
75	24006135	Signal Four Analytics	6/21/2020	12:50:00 PM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
76	88251197	SSOGIS	6/23/2020	740	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
77	24006183	Signal Four Analytics	6/23/2020	11:50:00 AM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
78	24006177	SSOGIS	6/25/2020	1411	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
79	24006174	Signal Four Analytics	6/26/2020	11:24:00 AM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
80	88327840	SSOGIS	6/30/2020	608	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	02 CLOUDY	2	0	0	0	0
81	24006360	SSOGIS	7/1/2020	1900	US 98 N	GRIFFIN RD	10 PEDESTRIAN	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	1
82	24006221	Signal Four Analytics	7/1/2020	7:46:00 AM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
83	88262386	Signal Four Analytics	7/1/2020	4:00:00 PM	4 W EXIT RAMP MM 3	US HWY 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
84	24006246	SSOGIS	7/2/2020	800	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
85	24006288	SSOGIS	7/2/2020	1015	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
86	24006267	SSOGIS	7/3/2020	2330	US 98	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
87	24006289	Signal Four Analytics	7/3/2020	1:25:00 PM	US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
88	24006330	Signal Four Analytics	7/3/2020	4:20:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
89	24006296	SSOGIS	7/8/2020	1124	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Interchange: I-4 at US 98 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
90	24006351	SSOGIS	7/8/2020	624	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
91	24006311	SSOGIS	7/9/2020	1930	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
92	88361438	SSOGIS	7/10/2020	2015	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
93	24006300	Signal Four Analytics	7/10/2020	10:29:00 AM	US 98 N	I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
94	24006378	SSOGIS	7/13/2020	1328	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
95	88327842	Signal Four Analytics	7/13/2020	4:58:00 PM	TO WB ENTRANCE RA	U.S. HIGHWAY 98	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
96	24006403	SSOGIS	7/14/2020	1230	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
97	24006374	SSOGIS	7/15/2020	1847	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
98	24006364	Signal Four Analytics	7/15/2020	8:51:00 PM	N US-98	CR-582	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Rain	2	0	0	0	0
99	88308390	SSOGIS	7/16/2020	1555	I 4	US 98	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
100	24006394	SSOGIS	7/18/2020	1659	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
101	24006478	SSOGIS	7/18/2020	1614	US 98 N	PYRAMID PKWY	09 OTHER NON-COLLISION	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
102	24006419	SSOGIS	7/21/2020	1151	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
103	24006412	Signal Four Analytics	7/21/2020	9:22:00 AM	US-98	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
104	88309190	SSOGIS	7/23/2020	635	SR 400	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
105	24006459	Signal Four Analytics	7/23/2020	2:30:00 PM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
106	88309192	SSOGIS	7/28/2020	1211	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
107	24006518	SSOGIS	7/30/2020	1137	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
108	24006529	SSOGIS	7/30/2020	1105	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	3	0	0
109	24006508	Signal Four Analytics	7/30/2020	1:18:00 PM	US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
110	88310644	SSOGIS	8/1/2020	1528	SR 400	US 98	11 PEDALCYCLE	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	1
111	24006552	Signal Four Analytics	8/1/2020	1:05:00 PM	US 98	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	2	0	0
112	24006574	Signal Four Analytics	8/6/2020	4:18:00 PM	US-98	PYRAMID PKWY	Motor Vehicle in Transport	Other	Wet	Daylight	Clear	3	0	0	0	0
113	88262257	SSOGIS	8/7/2020	2328	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	7	0	0
114	88309201	SSOGIS	8/8/2020	1952	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
115	24006589	Signal Four Analytics	8/8/2020	10:39:00 PM	US-98	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Dark - Lighted	Rain	2	0	0	0	0
116	24006596	Signal Four Analytics	8/9/2020	2:50:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
117	24006774	Signal Four Analytics	8/11/2020	4:30:00 PM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Daylight	Cloudy	2	0	0	0	0
118	24006646	SSOGIS	8/12/2020	1530	US 98 N	WOODLAND DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
119	88322529	SSOGIS	8/14/2020	1340	I 4	MILE MARKER #32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
120	24006683	Signal Four Analytics	8/17/2020	1:15:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Angle	Wet	Daylight	Rain	2	0	0	0	0
121	88312590	Signal Four Analytics	8/18/2020	7:59:00 AM	R 400 ENTRANCE RAM	MILE MARKER 30	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
122	24006718	SSOGIS	8/21/2020	2208	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
123	24006748	SSOGIS	8/25/2020	1833	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
124	88175114	SSOGIS	8/25/2020	1650	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
125	24006779	SSOGIS	8/27/2020	1743	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
126	24006759	Signal Four Analytics	8/27/2020	7:11:00 PM	N US-98	CR-582	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	3	0	0	0	0
127	24006773	Signal Four Analytics	8/28/2020	5:56:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
128	88322537	SSOGIS	8/31/2020	1936	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
129	88162816	SSOGIS	8/31/2020	1713	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
130	24006869	Signal Four Analytics	9/2/2020	5:30:00 PM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
131	88361462	SSOGIS	9/6/2020	1521	US 98	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
132	24006857	Signal Four Analytics	9/7/2020	6:40:00 PM	SR-700	GRIFFIN RD	Motor Vehicle in Transport	Angle	Wet	Daylight	Cloudy	2	0	0	0	0
133	24006955	SSOGIS	9/8/2020	1747	US 98 N	GRIFFIN RD	06 FELL/JUMPED FROM MOTOR VEHICLE	00 NOT CODED	02 WET	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
134	88319026	SSOGIS	9/10/2020	1945	SR 400	MM 32	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	02 CLOUDY	1	0	0	0	0
135	88319028	SSOGIS	9/11/2020	1930	SR 400	MM 32	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
136	24006969	SSOGIS	9/16/2020	923	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
137	24006958	Signal Four Analytics	9/16/2020	3:52:00 PM	US HIGHWAY 98 N	GRIFFIN RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
138	24006963	Signal Four Analytics	9/17/2020	11:32:00 AM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
139	24006984	SSOGIS	9/18/2020	2239	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
140	24007081	SSOGIS	9/19/2020	1603	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
141	24007084	Signal Four Analytics	9/19/2020	12:19:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
142	88390051	Signal Four Analytics	9/19/2020	6:10:00 PM	SR-700 (US-98)	SR-400 (I-4) EXIT RAMP	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
143	24007074	Signal Four Analytics	9/19/2020	11:50:00 PM	SR-700	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Rain	2	0	0	0	0
144	24007038	Signal Four Analytics	9/23/2020	8:14:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
145	24007056	SSOGIS	9/25/2020	2021	US 98 N	GRIFFIN RD	10 PEDESTRIAN	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	1	0
146	24007266	SSOGIS	9/28/2020	1027	US 98 N	BREEZEWOOD DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
147	24007066	Signal Four Analytics	9/28/2020	8:10:00 AM	US-98	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
148	24007097	Signal Four Analytics	9/29/2020	7:48:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Rain	2	0	0	0	0
149	24007184	SSOGIS	10/2/2020	1159	FLORIDA AVE N	ROBSON ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
150	88306763	SSOGIS	10/2/2020	2156	SR 400	US 98	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
151	24007160	SSOGIS	10/3/2020	2003	FLORIDA AVE N	ROBSON ST	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
152	88272788	SSOGIS	10/3/2020	830	SR 400	MM 32	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
153	88272789	SSOGIS	10/3/2020	940	SR 400	MM 32	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
154	88378041	Signal Four Analytics	10/7/2020	10:31:00 AM	RAMP FROM SR-400 T	U.S. HIGHWAY 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
155	24007186	Signal Four Analytics	10/7/2020	10:58:00 AM	US-98 N	GRIFFIN RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
156	24007215	Signal Four Analytics	10/9/2020	4:43:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
157	24007247	SSOGIS	10/11/2020	1650	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
158	88322544	SSOGIS	10/15/2020	1350	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
159	24007287	Signal Four Analytics	10/17/2020	7:20:00 PM	US-98	SHARON DR	Pedestrian	0	Dry	Dark - Lighted	Clear	1	0	1	1	0
160	24007369	SSOGIS	10/18/2020	2016	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
161	24007332	Signal Four Analytics	10/21/2020	4:40:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
162	24007353	SSOGIS	10/22/2020	1448	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
163	88369179	SSOGIS	10/22/2020	1250	I 4	US 98	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
164	24007364	SSOGIS	10/23/2020	2258	US 98	LAKELAND PK CNTR DR	39 OTHER FIXED OBJECT (WALL, BUIL	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
165	88369183	SSOGIS	10/29/2020	1711	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
166	24007436	SSOGIS	10/30/2020	1300	US 98	LAKELAND PK CNTR DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
167	24007439	SSOGIS	10/30/2020	1929	US 98 N	SLEEPYHILL RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
168	24007556	SSOGIS	10/30/2020	7	US 98 N	CR 582	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
169	24007468	SSOGIS	11/1/2020	1520	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
170	24007467	SSOGIS	11/2/2020	1115	FLORIDA AVE N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
171	88306770	SSOGIS	11/3/2020	1539	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
172	24007469	Signal Four Analytics	11/3/2020	2:45:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
173	24007512	Signal Four Analytics	11/3/2020	4:14:00 PM	N US-98	CR-582	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
174	24007616	SSOGIS	11/13/2020	1332	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
175	24007626	SSOGIS	11/13/2020	1805	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
176	24007615	Signal Four Analytics	11/14/2020	3:00:00 PM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
177	24007621	Signal Four Analytics	11/14/2020	6:50:00 PM	US HIGHWAY 98 N	WOODLAND DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
178	24007638	Signal Four Analytics	11/16/2020	9:10:00 AM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0

Interchange: I-4 at US 98 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
179	24007640	Signal Four Analytics	11/16/2020	9:16:00 AM	US-98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
180	24007658	Signal Four Analytics	11/17/2020	2:29:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
181	24007698	Signal Four Analytics	11/19/2020	11:00:00 PM	I-4	N US-98	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
182	24007711	SSOGIS	11/21/2020	1104	FLORIDA AVE N	ROBSON ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
183	24007855	SSOGIS	11/21/2020	1053	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
184	24007859	SSOGIS	11/28/2020	1910	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
185	24007779	Signal Four Analytics	11/30/2020	9:17:00 AM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
186	24007820	Signal Four Analytics	12/1/2020	7:53:00 AM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
187	24007959	SSOGIS	12/2/2020	2009	CREVASSE ST	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
188	88396608	SSOGIS	12/2/2020	343	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
189	24007814	Signal Four Analytics	12/2/2020	6:07:00 PM	US HIGHWAY 98 N	CR-582	Motor Vehicle in Transport	Other	Dry	Dawn	Clear	2	0	0	0	0
190	24007826	Signal Four Analytics	12/3/2020	10:22:00 AM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
191	24007828	Signal Four Analytics	12/3/2020	12:47:00 PM	N US-98	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
192	24007850	SSOGIS	12/4/2020	1153	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
193	24007865	Signal Four Analytics	12/4/2020	6:25:00 PM	US-98 N	GRIFFIN RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
194	88285063	SSOGIS	12/5/2020	1807	US 98	ROBSON ST	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
195	88318918	SSOGIS	12/7/2020	1822	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	5	0	1	0	0
196	24007866	Signal Four Analytics	12/7/2020	7:01:00 AM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
197	24007927	SSOGIS	12/10/2020	1246	US 98	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
198	24007954	SSOGIS	12/12/2020	1346	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
199	24008049	Signal Four Analytics	12/12/2020	10:40:00 AM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
200	24007973	SSOGIS	12/13/2020	1239	FLORIDA AVE N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
201	24007955	Signal Four Analytics	12/13/2020	6:29:00 PM	N US-98	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
202	88310670	SSOGIS	12/14/2020	2100	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
203	88390084	Signal Four Analytics	12/14/2020	9:10:00 AM	SR 700 (US-98)	SR-400 (I-4)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
204	24007995	SSOGIS	12/15/2020	2221	US 98 N	SHARON DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
205	24008001	SSOGIS	12/16/2020	1411	GRIFFIN RD	US 98 N	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
206	88355133	SSOGIS	12/16/2020	1520	SR 400	US 98	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
207	24008116	SSOGIS	12/19/2020	1210	CR 582	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
208	24008071	SSOGIS	12/21/2020	1834	US 98 N	GRIFFIN RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
209	24008097	Signal Four Analytics	12/26/2020	5:42:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
210	24008173	SSOGIS	12/29/2020	1605	US 98 N	PYRAMID PKWY	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
211	24008214	Signal Four Analytics	12/31/2020	2:18:00 PM	US HIGHWAY 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
212	88430500	SSOGIS	1/2/2021	1528	SR 400	MILE MARKER #32	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
213	24008193	Signal Four Analytics	1/6/2021	10:26:00 AM	US 98 N	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
214	88383403	Signal Four Analytics	1/8/2021	6:40:00 PM	TATE ROAD 700 (US-9	STATE ROAD 400	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
215	24008246	Signal Four Analytics	1/11/2021	12:50:00 PM	US 98	PYRAMID PARKWAY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
216	24398400	Signal Four Analytics	1/15/2021	7:55:00 AM	I4 OFF RAMP	US 98 N	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
217	24008410	Signal Four Analytics	1/15/2021	10:50:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Wet	Dark - Lighted	Clear	2	0	0	0	0
218	24008329	Signal Four Analytics	1/16/2021	6:33:00 PM	SR-700	PYRAMID PKWY	Pedestrian	0	Dry	Daylight	Clear	1	0	0	1	0
219	24008339	Signal Four Analytics	1/18/2021	4:28:00 PM	SR-700	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
220	24008336	Signal Four Analytics	1/18/2021	7:40:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	3	0	0
221	24008337	Signal Four Analytics	1/18/2021	7:58:00 PM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	2	0	1	0	0
222	88318926	SSOGIS	1/19/2021	50	SR 400	CR 582	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
223	24008375	Signal Four Analytics	1/22/2021	9:00:00 AM	SR-700	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
224	24008392	Signal Four Analytics	1/23/2021	7:24:00 AM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Other	Wet	Dusk	Rain	2	0	0	0	0
225	24008428	Signal Four Analytics	1/23/2021	10:20:00 AM	SR-700	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
226	24008419	Signal Four Analytics	1/26/2021	4:04:00 PM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
227	24008529	Signal Four Analytics	1/30/2021	11:10:00 AM	US 98	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
228	24008469	Signal Four Analytics	1/31/2021	10:22:00 AM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Rear to Side	Dry	Daylight	Clear	2	0	0	0	0
229	24008496	Signal Four Analytics	1/31/2021	4:49:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	1	0	0
230	24008528	Signal Four Analytics	2/5/2021	2:23:00 PM	US 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	3	0	0	0	0
231	24008530	Signal Four Analytics	2/5/2021	3:06:00 PM	US 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
232	88162824	Signal Four Analytics	2/6/2021	2:15:00 PM	ND I-4(STATE ROAD 4	US 98	Embankment	Other	Wet	Daylight	Rain	1	0	0	0	0
233	24008581	Signal Four Analytics	2/7/2021	3:58:00 AM	SR-700	BREEZEWOOD DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Rain	2	0	0	0	0
234	24008586	Signal Four Analytics	2/7/2021	11:20:00 AM	SR-700	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
235	24008580	Signal Four Analytics	2/7/2021	12:30:00 PM	98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
236	24397746	Signal Four Analytics	2/10/2021	3:00:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	5	0	4	0	0
237	24008605	Signal Four Analytics	2/11/2021	4:58:00 PM	US-98	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
238	24397707	Signal Four Analytics	2/12/2021	12:24:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	0	0	0
239	24397727	Signal Four Analytics	2/17/2021	12:39:00 PM	US 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Wet	Daylight	Clear	2	0	0	0	0
240	88396626	Signal Four Analytics	2/18/2021	9:45:00 AM	TATE 4 (STATE ROAD	STATE ROAD 539 (KATHLEEN ROAD)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	2	0	0
241	24397733	Signal Four Analytics	2/18/2021	10:23:00 AM	US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
242	24397760	SSOGIS	2/19/2021	228	US 98	I 4	31 OTHER TRAFFIC BARRIER	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
243	88430508	SSOGIS	2/20/2021	427	SR 400	US 98	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
244	24397805	Signal Four Analytics	2/20/2021	11:37:00 AM	US-98 N	CR-582	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
245	24397796	Signal Four Analytics	2/24/2021	1:07:00 PM	98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
246	24397854	Signal Four Analytics	2/25/2021	4:50:00 PM	3230 US 98 N	0	Other Post, Pole or Support	0	Dry	Daylight	Clear	1	0	0	0	0
247	24397861	Signal Four Analytics	3/1/2021	1:33:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
248	24397913	Signal Four Analytics	3/5/2021	9:45:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
249	24397948	Signal Four Analytics	3/9/2021	7:22:00 AM	MP FROM I-4 E TO US-	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
250	24397961	Signal Four Analytics	3/10/2021	1:53:00 AM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	3	0	0	0	0
251	24397965	Signal Four Analytics	3/10/2021	8:00:00 AM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
252	24397990	Signal Four Analytics	3/12/2021	12:59:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
253	24398010	Signal Four Analytics	3/13/2021	4:45:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
254	88468341	SSOGIS	3/14/2021	1528	SR 400	SR 700	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
255	24398012	Signal Four Analytics	3/14/2021	12:25:00 PM	US 98	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
256	24398020	Signal Four Analytics	3/14/2021	5:39:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
257	24398109	Signal Four Analytics	3/20/2021	9:54:00 AM	N US-98	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
258	24398600	Signal Four Analytics	3/27/2021	2:17:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
259	24398989	Signal Four Analytics	3/27/2021	5:01:00 PM	US HIGHWAY 98 N	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
260	24398169	Signal Four Analytics	3/28/2021	7:28:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	0	0	0
261	24398285	Signal Four Analytics	3/30/2021	1:24:00 PM	N US-98	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
262	24398287	Signal Four Analytics	4/1/2021	2:45:00 PM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
263	24398232	Signal Four Analytics	4/1/2021	6:12:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
264	24398247	Signal Four Analytics	4/1/2021	7:25:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
265	24398255	Signal Four Analytics	4/3/2021	7:25:00 PM	US-98	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	1	0	0
266	24398261	Signal Four Analytics	4/4/2021	4:23:00 PM	98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
267	24398271	Signal Four Analytics	4/5/2021	10:14:00 AM	US HIGHWAY 98 N	CR-582	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0

Interchange: I-4 at US 98 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
268	24398281	Signal Four Analytics	4/5/2021	10:10:00 PM	N US-98	CR 582	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
269	88449303	SSOGIS	4/6/2021	1657	I 4	US 98	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
270	24398399	Signal Four Analytics	4/6/2021	4:15:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
271	88310795	SSOGIS	4/7/2021	530	SR 400	CR 582	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
272	24398516	SSOGIS	4/9/2021	2210	US 98	PYRAMID PKWY	39 OTHER FIXED OBJECT (WALL, BUIL	00 NOT CODED	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
273	24398330	Signal Four Analytics	4/9/2021	8:40:00 PM	SR-700	GRIFFIN RD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
274	24398337	Signal Four Analytics	4/11/2021	10:08:00 AM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
275	24398375	Signal Four Analytics	4/13/2021	4:51:00 PM	P FROM I-4 W TO US-	US HIGHWAY 98 N	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
276	24398382	Signal Four Analytics	4/14/2021	8:30:00 AM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
277	24398452	Signal Four Analytics	4/15/2021	2:40:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
278	24398416	Signal Four Analytics	4/15/2021	2:45:00 PM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
279	24398437	SSOGIS	4/16/2021	2235	US 98	I 4	10 PEDESTRIAN	00 NOT CODED	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	1	0	1	0
280	24398424	Signal Four Analytics	4/16/2021	7:11:00 PM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
281	24398443	Signal Four Analytics	4/17/2021	1:22:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	1	0	0
282	24288299	SSOGIS	4/18/2021	900	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
283	24398495	Signal Four Analytics	4/22/2021	5:20:00 PM	US HIGHWAY 98 N	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
284	24398532	SSOGIS	4/23/2021	1540	US 98 N	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
285	24398517	Signal Four Analytics	4/23/2021	3:40:00 PM	US-98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
286	24398518	Signal Four Analytics	4/23/2021	3:48:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
287	24398545	Signal Four Analytics	4/23/2021	4:34:00 PM	I-4	N US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
288	24398541	Signal Four Analytics	4/25/2021	4:08:00 AM	US-98 N	PYRAMID PKWY	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
289	88431605	Signal Four Analytics	4/25/2021	7:56:00 AM	SR400	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
290	24398638	Signal Four Analytics	4/30/2021	10:37:00 AM	US-98	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
291	24398649	Signal Four Analytics	4/30/2021	2:57:00 PM	US HIGHWAY 98 N	E I-4	Thrown or Falling Object	0	Dry	Daylight	Clear	1	0	0	0	0
292	24398757	SSOGIS	5/7/2021	2346	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
293	24398771	Signal Four Analytics	5/10/2021	7:55:00 AM	US-98	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
294	24398822	Signal Four Analytics	5/13/2021	9:05:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
295	88499884	SSOGIS	5/15/2021	1743	SR 400	MILE MARKER #32	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	4	0	0
296	24398842	Signal Four Analytics	5/16/2021	12:07:00 AM	US-98	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
297	24398907	Signal Four Analytics	5/21/2021	12:12:00 PM	US HIGHWAY 98 N	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
298	88431617	SSOGIS	5/22/2021	500	SR 400	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
299	24398995	Signal Four Analytics	5/23/2021	4:28:00 AM	P FROM I-4 W TO US-	US HIGHWAY 98 N	Other Non-Collision	0	Dry	Dark - Lighted	Clear	1	0	0	0	0
300	24399104	Signal Four Analytics	5/23/2021	12:40:00 PM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
301	24399011	Signal Four Analytics	5/28/2021	8:28:00 PM	US-98	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
302	24399044	Signal Four Analytics	6/1/2021	12:51:00 PM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
303	24399103	Signal Four Analytics	6/5/2021	3:41:00 PM	US-98	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
304	24399244	Signal Four Analytics	6/10/2021	1:08:00 PM	US-98	E I-4	Other Non-Fixed Object	0	Dry	Daylight	Clear	1	0	0	0	0
305	24399167	Signal Four Analytics	6/11/2021	2:15:00 PM	US HIGHWAY 98 N	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
306	24399270	Signal Four Analytics	6/13/2021	12:08:00 PM	US HIGHWAY 98 N	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
307	88525147	Signal Four Analytics	6/14/2021	3:54:00 PM	T RAMP FROM I-4 (EX	KATHLEEN ROAD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
308	24399258	Signal Four Analytics	6/19/2021	2:33:00 PM	880 US HIGHWAY 98	0	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
309	24399263	Signal Four Analytics	6/20/2021	10:55:00 AM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
310	24399331	Signal Four Analytics	6/23/2021	12:00:00 PM	UNNAMED RD	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
311	24399347	Signal Four Analytics	6/27/2021	9:53:00 AM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
312	24399356	Signal Four Analytics	6/28/2021	10:20:00 AM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
313	24399491	Signal Four Analytics	6/30/2021	5:45:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
314	24399403	Signal Four Analytics	7/1/2021	5:29:00 PM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
315	24399404	Signal Four Analytics	7/1/2021	6:40:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Angle	Wet	Daylight	Rain	2	0	0	0	0
316	24399420	Signal Four Analytics	7/2/2021	11:39:00 PM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
317	88518802	Signal Four Analytics	7/4/2021	5:00:00 PM	U.S. HIGHWAY 98	I4 ENT RAMP	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	6	0	0
318	24399441	Signal Four Analytics	7/5/2021	11:52:00 AM	98 N	SHARON DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
319	24399440	Signal Four Analytics	7/5/2021	3:38:00 PM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
320	88449334	Signal Four Analytics	7/7/2021	12:35:00 AM	STATE 4 (STATE ROAD	U.S. HIGHWAY 98	Tree (standing)	Other	Wet	Dark - Not Lighted	Rain	1	0	0	0	0
321	24399483	Signal Four Analytics	7/8/2021	1:20:00 PM	US HIGHWAY 98 N	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Daylight	Cloudy	2	0	0	0	0
322	88455803	SSOGIS	7/10/2021	1037	I 4	SR 35	30 CONCRETE TRAFFIC BARRIER	88 UNKNOWN	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
323	24399576	Signal Four Analytics	7/10/2021	11:44:00 AM	US98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
324	24399604	Signal Four Analytics	7/10/2021	4:08:00 PM	98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
325	24399607	Signal Four Analytics	7/20/2021	12:40:00 PM	US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
326	24399652	Signal Four Analytics	7/25/2021	12:10:00 PM	HWY 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
327	24399681	Signal Four Analytics	7/26/2021	9:50:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
328	24291341	SSOGIS	7/31/2021	550	I 4	MILE MARKER #32	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
329	24399730	Signal Four Analytics	7/31/2021	3:58:00 PM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
330	24399778	Signal Four Analytics	8/1/2021	1:16:00 AM	US-98	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	3	0	0	0	0
331	24399745	Signal Four Analytics	8/2/2021	6:50:00 AM	98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Front	Dry	Daylight	Clear	2	0	1	0	0
332	24399935	Signal Four Analytics	8/3/2021	7:25:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Angle	Dry	Dusk	Clear	2	0	0	0	0
333	88457659	Signal Four Analytics	8/4/2021	5:36:00 PM	STATE 4 (STATE ROAD	U.S. HIGHWAY 98	Motor Vehicle in Transport	Front to Front	Wet	Daylight	Rain	2	0	0	0	0
334	24399858	Signal Four Analytics	8/11/2021	2:57:00 PM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
335	24399892	Signal Four Analytics	8/13/2021	10:50:00 AM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
336	24399894	Signal Four Analytics	8/13/2021	2:50:00 PM	US HIGHWAY 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	3	0	0
337	24399919	Signal Four Analytics	8/16/2021	4:39:00 PM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
338	24399928	Signal Four Analytics	8/17/2021	2:07:00 PM	US HIGHWAY 98 N	GRIFFIN RD	Pedestrian	0	Dry	Daylight	Cloudy	1	0	1	1	0
339	24400031	Signal Four Analytics	8/22/2021	5:00:00 PM	SR-700	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
340	24400039	Signal Four Analytics	8/22/2021	10:16:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
341	24400002	Signal Four Analytics	8/24/2021	4:35:00 PM	US 98 N	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
342	88454952	SSOGIS	8/29/2021	2318	I 4	US 98	11 PEDALCYCLE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	1
343	24400106	Signal Four Analytics	8/29/2021	9:28:00 PM	N US-98	US-98	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Rain	2	0	2	0	0
344	24400189	Signal Four Analytics	9/4/2021	8:07:00 PM	HIGHWAY 98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
345	24400159	Signal Four Analytics	9/5/2021	1:48:00 PM	US-98 N	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
346	24400169	Signal Four Analytics	9/7/2021	6:00:00 AM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dawn	Clear	2	0	0	0	0
347	24400168	Signal Four Analytics	9/7/2021	7:10:00 AM	US-98	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
348	24400188	Signal Four Analytics	9/7/2021	8:51:00 PM	US-98 N	PYRAMID PKWY	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	5	0	0	0	0
349	24400370	Signal Four Analytics	9/15/2021	4:30:00 PM	US 98	I4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
350	88472765	Signal Four Analytics	9/15/2021	5:41:00 PM	INTERSTATE 4(SR400)	US98	Cable Barrier	Unknown	Wet	Daylight	Rain	1	0	0	0	0
351	88475670	Signal Four Analytics	9/16/2021	3:02:00 PM	INTERSTATE 4(SR400)	US98	Cable Barrier	Unknown	Wet	Daylight	Rain	1	0	0	0	0
352	88475672	Signal Four Analytics	9/17/2021	3:02:00 PM	INTERSTATE 4(SR400)	US98	Cable Barrier	Unknown	Wet	Daylight	Rain	1	0	0	0	0
353	24400330	Signal Four Analytics	9/17/2021	3:30:00 PM	US 98 N	I 4	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	4	0	1	0	0
354	24400347	Signal Four Analytics	9/19/2021	12:59:00 PM	98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
355	24400355	Signal Four Analytics	9/19/2021	6:42:00 PM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
356	24400362	Signal Four Analytics	9/20/2021	10:03:00 AM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0

Interchange: I-4 at US 98 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
357	24400401	Signal Four Analytics	9/23/2021	8:20:00 PM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
358	24400424	Signal Four Analytics	9/25/2021	8:00:00 PM	US-98	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
359	88454961	SSOGIS	9/27/2021	150	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
360	88510240	SSOGIS	9/28/2021	708	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
361	24400511	Signal Four Analytics	10/3/2021	1:14:00 AM	SR-700	0	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
362	24400531	Signal Four Analytics	10/4/2021	5:03:00 PM	N US-98	US-98	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
363	24400525	Signal Four Analytics	10/5/2021	1:59:00 AM	3300 BLK US-98 N	0	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
364	24400558	Signal Four Analytics	10/7/2021	11:35:00 AM	US 98 N	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
365	24400610	Signal Four Analytics	10/8/2021	10:24:00 AM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
366	24400598	Signal Four Analytics	10/8/2021	11:15:00 AM	US 98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
367	24400631	Signal Four Analytics	10/11/2021	5:33:00 PM	US-98 N	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
368	24400639	Signal Four Analytics	10/12/2021	7:15:00 AM	US HIGHWAY 98 N	MALL ACCESS 3	Motor Vehicle in Transport	Front to Front	Dry	Daylight	Clear	2	0	0	0	0
369	24400661	Signal Four Analytics	10/14/2021	4:04:00 PM	US HIGHWAY 98 N	CR-582	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	2	0	0
370	24769484	Signal Four Analytics	10/15/2021	9:41:00 AM	US 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	4	0	2	0	0
371	24769493	Signal Four Analytics	10/15/2021	7:38:00 PM	US-98 N	GRIFFIN RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
372	24769492	Signal Four Analytics	10/15/2021	8:00:00 PM	SR-35	WOODLAND DR	Pedestrian	0	Dry	Dark - Lighted	Clear	1	0	1	1	0
373	24769520	Signal Four Analytics	10/15/2021	10:43:00 PM	P FROM I-4 W TO US-	SR-35	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	0	0	0
374	24769607	Signal Four Analytics	10/16/2021	11:02:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	2	0	0
375	24769553	Signal Four Analytics	10/17/2021	4:41:00 PM	98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
376	24769532	Signal Four Analytics	10/18/2021	12:23:00 PM	N US-98	CR-582	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
377	24769608	Signal Four Analytics	10/18/2021	3:56:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
378	24769621	Signal Four Analytics	10/21/2021	9:21:00 PM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
379	88579408	Signal Four Analytics	10/27/2021	2:05:00 PM	RAMP FROM SR-400 (	U.S. HIGHWAY 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	1	0	0
380	24769689	Signal Four Analytics	10/30/2021	4:34:00 PM	US 98 N	MALL ACCESS 3	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	0	0	0
381	88588477	Signal Four Analytics	10/31/2021	6:45:00 AM	ROAD 400 (INTERSTAT	STATE ROAD 33 (MEMORIAL BLVD)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dawn	Clear	2	0	1	0	0
382	24769703	Signal Four Analytics	11/1/2021	8:48:00 AM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
383	24769706	Signal Four Analytics	11/1/2021	1:55:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
384	24769711	Signal Four Analytics	11/1/2021	1:57:00 PM	US-98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
385	88588479	Signal Four Analytics	11/1/2021	4:14:00 PM	ROAD 400 (INTERSTAT	US 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
386	24769900	Signal Four Analytics	11/6/2021	5:30:00 AM	US 98	I-4 EAST EXIT RAMP	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Dark - Lighted	Rain	2	0	0	0	0
387	24769877	Signal Four Analytics	11/6/2021	11:22:00 AM	US-98	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	3	0	1	0	0
388	24769891	Signal Four Analytics	11/10/2021	6:10:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Cloudy	2	0	0	0	0
389	24769854	SSOGIS	11/11/2021	1649	US 98	PYRAMID PKWY	27 GUARDRAIL FACE	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
390	24769964	Signal Four Analytics	11/12/2021	8:09:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
391	24769869	Signal Four Analytics	11/14/2021	12:21:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
392	24770005	Signal Four Analytics	11/17/2021	6:52:00 PM	US HIGHWAY 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
393	24769954	Signal Four Analytics	11/19/2021	7:55:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	1	0	0
394	24770039	SSOGIS	11/20/2021	2252	US 98	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	4	0	0
395	24769956	Signal Four Analytics	11/20/2021	6:35:00 AM	US 98	0	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	3	0	2	0	0
396	24769960	Signal Four Analytics	11/20/2021	5:38:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
397	24770013	Signal Four Analytics	11/24/2021	2:32:00 PM	US-98	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
398	24770073	Signal Four Analytics	11/27/2021	12:37:00 AM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
399	24770050	Signal Four Analytics	11/28/2021	7:18:00 AM	US HIGHWAY 98 N	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
400	24770116	Signal Four Analytics	11/30/2021	6:35:00 PM	US-98	GRIFFIN RD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
401	24770091	Signal Four Analytics	12/1/2021	8:00:00 AM	N US-98	I-4 E OFF RAMP	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
402	88493555	SSOGIS	12/3/2021	356	I 4	US 98	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	2	0	0
403	24770161	Signal Four Analytics	12/3/2021	3:00:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
404	24770124	Signal Four Analytics	12/4/2021	1:06:00 PM	US-98	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
405	24770208	Signal Four Analytics	12/9/2021	3:50:00 PM	US 98	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
406	24770344	Signal Four Analytics	12/10/2021	2:07:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	1	0	0
407	24770354	Signal Four Analytics	12/10/2021	3:13:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
408	24770222	Signal Four Analytics	12/10/2021	7:45:00 PM	US-98 N	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
409	24770282	Signal Four Analytics	12/11/2021	2:22:00 PM	HWY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
410	24770281	Signal Four Analytics	12/11/2021	6:39:00 PM	N 98	GRIFFIN RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dusk	Clear	2	0	0	0	0
411	24770290	Signal Four Analytics	12/15/2021	9:52:00 PM	N US-98	PYRAMID PKWY	Pedalcycle	0	Dry	Dark - Lighted	Clear	1	0	1	0	1
412	24770332	Signal Four Analytics	12/19/2021	4:50:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	4	0	0	0	0
413	24770401	Signal Four Analytics	12/21/2021	6:02:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
414	24882189	SSOGIS	12/24/2021	130	I 4	US 98	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
415	24770427	Signal Four Analytics	12/24/2021	4:13:00 PM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
416	24770502	Signal Four Analytics	12/27/2021	7:25:00 PM	US-98	SLEEPY HILL RD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	1	0	0
417	24770447	Signal Four Analytics	12/30/2021	5:45:00 PM	US-98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dusk	Clear	2	0	0	0	0
418	24770457	Signal Four Analytics	1/1/2022	4:39:00 AM	US HIGHWAY 98 N	0	Tree (standing)	0	Dry	Dark - Lighted	Clear	1	0	0	0	0
419	24770473	Signal Four Analytics	1/2/2022	6:30:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
420	24770481	Signal Four Analytics	1/3/2022	4:08:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
421	24770482	Signal Four Analytics	1/3/2022	4:49:00 PM	US HIGHWAY 98 N	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
422	24770496	Signal Four Analytics	1/3/2022	8:03:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
423	24770717	Signal Four Analytics	1/15/2022	1:00:00 PM	US 98	SLEEPY HILL RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
424	24770634	Signal Four Analytics	1/17/2022	10:38:00 AM	N US-98	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
425	24770720	Signal Four Analytics	1/17/2022	11:26:00 AM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
426	24770721	Signal Four Analytics	1/17/2022	1:08:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
427	24770671	Signal Four Analytics	1/21/2022	10:25:00 PM	US-98 N	WOODLAND DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
428	88545370	Signal Four Analytics	1/23/2022	12:12:00 AM	(SR-400) MM32 EXIT	US HIGHWAY 98 (STATE ROAD 35)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	2	0	0
429	88551427	Signal Four Analytics	1/23/2022	7:25:00 PM	00 EB MM 32 EXIT RA	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	3	0	0	0	0
430	24770710	Signal Four Analytics	1/24/2022	10:20:00 AM	US-98	PYRAMID PKWY	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
431	24770834	Signal Four Analytics	1/25/2022	1:03:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Daylight	Rain	2	0	0	0	0
432	24770783	Signal Four Analytics	1/28/2022	12:32:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	2	0	0
433	24770864	Signal Four Analytics	1/28/2022	4:35:00 PM	US-98	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
434	24770758	Signal Four Analytics	1/28/2022	6:10:00 PM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
435	24683882	SSOGIS	1/29/2022	1956	I 4	SR 33	31 OTHER TRAFFIC BARRIER	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
436	24770800	Signal Four Analytics	1/30/2022	3:15:00 PM	US 98	US-98	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
437	24770795	Signal Four Analytics	1/31/2022	6:32:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
438	24770812	Signal Four Analytics	2/1/2022	4:30:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
439	24770815	Signal Four Analytics	2/3/2022	8:36:00 AM	US-98	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
440	24770848	Signal Four Analytics	2/4/2022	1:54:00 PM	US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
441	24770898	Signal Four Analytics	2/4/2022	3:45:00 PM	US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
442	24770900	Signal Four Analytics	2/6/2022	10:40:00 AM	N US-98	GRIFFIN RD	Struck by Falling, Shifting Cargo	0	Dry	Daylight	Cloudy	2	0	0	0	0
443	24770911	Signal Four Analytics	2/9/2022	10:14:00 AM	US HIGHWAY 98 N	CR-582	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
444	24770986	Signal Four Analytics	2/10/2022	10:37:00 AM	US-98	W I-4	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	0	0	0
445	24770944	Signal Four Analytics	2/11/2022	7:14:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0

Interchange: I-4 at US 98 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
446	24771009	Signal Four Analytics	2/19/2022	4:15:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	3	0	0	0	0
447	24901949	Signal Four Analytics	2/20/2022	10:28:00 PM	TATE 4 (STATE ROAD	STATE ROAD 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
448	24771040	Signal Four Analytics	2/21/2022	1:37:00 PM	US-98	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	2	0	0
449	24771094	Signal Four Analytics	2/23/2022	1:30:00 PM	US-98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
450	24771108	Signal Four Analytics	2/24/2022	12:45:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	0	0	0
451	24771120	Signal Four Analytics	2/26/2022	12:13:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
452	24771135	Signal Four Analytics	2/28/2022	7:37:00 AM	US 98 N	I 4	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	0	0	0
453	24771153	Signal Four Analytics	3/1/2022	2:55:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
454	24771188	Signal Four Analytics	3/3/2022	5:56:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
455	24910017	Signal Four Analytics	3/4/2022	5:38:00 PM	TATE 4 (STATE ROAD	US HIGHWAY 98	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dusk	Clear	2	0	0	0	0
456	24771266	Signal Four Analytics	3/8/2022	2:04:00 PM	N US-98	PYRAMID PKWY	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	1	0	0
457	24771269	Signal Four Analytics	3/9/2022	6:09:00 AM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Other Post, Pole or Support	0	Dry	Dawn	Clear	1	0	0	0	0
458	24771315	Signal Four Analytics	3/9/2022	5:13:00 PM	US-98	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
459	24771312	Signal Four Analytics	3/14/2022	12:45:00 AM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
460	24771363	Signal Four Analytics	3/16/2022	6:05:00 AM	US-98 N	CR-582	Motor Vehicle in Transport	Front to Rear	Dry	Dawn	Clear	2	0	0	0	0
461	24771420	Signal Four Analytics	3/18/2022	3:45:00 PM	US-98	SHARON DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
462	24771419	Signal Four Analytics	3/20/2022	2:03:00 PM	SR-700	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
463	24771423	Signal Four Analytics	3/20/2022	4:05:00 PM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
464	24771435	Signal Four Analytics	3/24/2022	10:21:00 AM	US 98 N	I 4 EAST ON RAMP	Motor Vehicle in Transport	Angle	Wet	Daylight	Cloudy	2	0	0	0	0
465	24771436	Signal Four Analytics	3/24/2022	5:16:00 PM	US-98 N	CR-582	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	3	0	0	0	0
466	24771462	Signal Four Analytics	3/27/2022	5:25:00 PM	US-98	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
467	24771481	Signal Four Analytics	3/29/2022	10:52:00 AM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
468	24771526	Signal Four Analytics	3/29/2022	3:50:00 PM	98 N	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
469	24771498	Signal Four Analytics	3/30/2022	2:30:00 PM	N US-98	GRIFFIN RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
470	24771511	Signal Four Analytics	3/30/2022	4:25:00 PM	US-98	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
471	24771592	Signal Four Analytics	4/2/2022	3:48:00 PM	US-98	GRIFFIN RD	Motor Vehicle in Transport	Angle	Wet	Daylight	Rain	2	0	0	0	0
472	24771636	Signal Four Analytics	4/4/2022	10:55:00 AM	US 98	US 98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
473	24771632	Signal Four Analytics	4/6/2022	4:46:00 PM	US-98	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
474	24901957	Signal Four Analytics	4/6/2022	5:29:00 PM	RANCE RAMP FROM U	US HIGHWAY 98	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
475	24771682	Signal Four Analytics	4/8/2022	8:53:00 PM	US HIGHWAY 98 N	SHARON DR	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
476	24771774	Signal Four Analytics	4/17/2022	10:25:00 AM	US-98	BREEZEWOOD DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
477	24910029	Signal Four Analytics	4/18/2022	10:39:00 AM	TATE 4 (STATE ROAD	US HIGHWAY 98	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
478	24771770	Signal Four Analytics	4/22/2022	1:40:00 PM	US HIGHWAY 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
479	24771785	Signal Four Analytics	4/23/2022	1:35:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
480	24771801	Signal Four Analytics	4/23/2022	2:01:00 PM	US 98	I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
481	24771886	Signal Four Analytics	4/29/2022	7:17:00 PM	US HIGHWAY 98 N	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
482	24771927	Signal Four Analytics	5/3/2022	12:10:00 PM	US HIGHWAY 98 N	CR-582	Parked Motor Vehicle	0	Dry	Daylight	Clear	2	0	2	1	0
483	24771919	Signal Four Analytics	5/3/2022	3:40:00 PM	US HIGHWAY 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
484	24771945	Signal Four Analytics	5/4/2022	4:39:00 PM	US 98 N	GRIFFIN RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
485	24934799	Signal Four Analytics	5/7/2022	8:39:00 AM	R-400 (I-4) EAST OF M	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
486	24772062	Signal Four Analytics	5/17/2022	1:55:00 AM	I-4	N US-98	Curb	0	Dry	Dark - Lighted	Clear	1	0	0	0	0
487	24772057	Signal Four Analytics	5/17/2022	1:17:00 PM	US HIGHWAY 98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
488	24772091	Signal Four Analytics	5/19/2022	1:42:00 PM	US HIGHWAY 98 N	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
489	24772101	Signal Four Analytics	5/20/2022	11:45:00 AM	US HIGHWAY 98 N	CR-582	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
490	24772114	Signal Four Analytics	5/20/2022	8:20:00 PM	US-98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Wet	Dark - Lighted	Rain	2	0	0	0	0
491	24772117	Signal Four Analytics	5/21/2022	2:18:00 PM	US-98 N	PYRAMID PKWY	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
492	24772127	Signal Four Analytics	5/22/2022	12:20:00 PM	US 98	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
493	24772149	Signal Four Analytics	5/24/2022	1:10:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
494	24910036	Signal Four Analytics	5/26/2022	3:38:00 PM	TATE 4 (STATE ROAD 4	US HIGHWAY 98	Other Non-Fixed Object	Other	Dry	Daylight	Clear	1	0	0	0	0
495	24772176	Signal Four Analytics	5/27/2022	7:52:00 AM	US-98	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
496	24772184	Signal Four Analytics	5/27/2022	4:01:00 PM	MP FROM I-4 E TO US-	US-98	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Clear	2	0	1	0	0
497	24772201	Signal Four Analytics	5/29/2022	1:23:00 PM	US HIGHWAY 98 N	LAKELAND PARK CENTER DR	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
498	24772222	Signal Four Analytics	5/31/2022	4:44:00 PM	MP FROM I-4 E TO US-	US-98	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0

Mainline Segment: I-4 from US 98 to N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88251161	SSOGIS	1/7/2020	1145	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
2	88226809	SSOGIS	2/13/2020	1037	SR 400	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
3	88215628	SSOGIS	3/1/2020	1430	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
4	88262362	Signal Four Analytics	3/5/2020	4:00:00 PM	I-4 E	SR 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
5	88327820	SSOGIS	4/9/2020	2123	SR 400	SOCRUM LOOP	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
6	88253867	SSOGIS	5/16/2020	1850	SR 400	SR 700	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
7	85343530	SSOGIS	5/24/2020	1119	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	6	0	0	0	0
8	88262379	SSOGIS	6/3/2020	645	SR 400	MM 32	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	5	1	6	0	0
9	88314314	SSOGIS	6/3/2020	1016	I 4	US 98	23 CULVERT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
10	88258545	SSOGIS	6/4/2020	908	I 4	KATHLEEN RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
11	88184267	SSOGIS	6/9/2020	1320	SR 400	SR 700	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
12	88322508	SSOGIS	6/15/2020	1932	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
13	88310638	SSOGIS	7/6/2020	1140	SR 400	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
14	88327841	SSOGIS	7/10/2020	1436	SR 400	US 98	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	3	0	2	0	0
15	88262251	SSOGIS	7/14/2020	1702	I 4	US 98	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	6	0	0
16	87188790	SSOGIS	7/30/2020	1020	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
17	88314719	Signal Four Analytics	8/20/2020	3:29:00 PM	STATE 4 (STATE ROAD	STATE ROAD 33	Cable Barrier	Other	Wet	Daylight	Rain	1	0	0	0	0
18	88308401	SSOGIS	8/29/2020	1240	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
19	88312597	SSOGIS	9/5/2020	2110	SR 400	MM 34	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
20	88175115	SSOGIS	9/8/2020	20	SR 400	MM 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
21	88378039	SSOGIS	9/20/2020	435	SR 400	MILE MARKER #33	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
22	88319042	SSOGIS	9/28/2020	1735	SR 400	MM 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
23	88288837	SSOGIS	10/3/2020	943	I 4	MILE MARKER #33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
24	88285058	SSOGIS	10/11/2020	1644	SR 400	US 98	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
25	88349881	Signal Four Analytics	10/11/2020	4:37:00 AM	I-4 E	SR-33	Other Non-Collision	Other	Dry	Dark - Lighted	Clear	1	0	0	0	0
26	88383397	SSOGIS	11/29/2020	805	SR 400	MM 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
27	85152042	SSOGIS	12/6/2020	745	I 4	SR 700	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
28	88390093	SSOGIS	1/31/2021	745	SR 400	SR 700	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
29	88390103	Signal Four Analytics	2/10/2021	7:38:00 AM	SR 400 (I-4)	SR 33 (COMMONWEALTH AVE)	Struck by Falling, Shifting Cargo	Other	Dry	Daylight	Fog, Smog, Smoke	1	0	0	0	0
30	88468342	SSOGIS	3/14/2021	1550	SR 400	SR 700	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
31	88416510	SSOGIS	4/9/2021	2243	SR 400	MILE MARKER #33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
32	88430524	Signal Four Analytics	5/4/2021	5:20:00 PM	00 (INTERSTATE 4) NEA	STATE ROAD 33 (EXIT 38)	Overturn/Rollover	Other	Dry	Daylight	Cloudy	1	0	0	0	0
33	88487448	SSOGIS	6/1/2021	1910	I 4	US 98	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	02 CLOUDY	2	0	6	0	0
34	88449324	SSOGIS	6/22/2021	2012	I 4	SOCRUM LOOP RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
35	88479720	SSOGIS	7/12/2021	1957	SR 400	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
36	88518808	Signal Four Analytics	7/19/2021	10:00:00 PM	STATE ROAD 400	STATE ROAD 33	Motor Vehicle in Transport	Angle	Wet	Dark - Not Lighted	Rain	2	0	0	0	0
37	88518809	Signal Four Analytics	7/19/2021	10:30:00 PM	I-4 E	SR 33	Ran into Water/Canal	Other	Wet	Dark - Not Lighted	Rain	1	0	0	0	0
38	88510229	SSOGIS	8/20/2021	1914	I 4	US 98	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
39	88579411	SSOGIS	11/4/2021	900	SR 400	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
40	89586706	SSOGIS	1/21/2022	1325	SR 400	MM 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	3	0	0
41	24884816	Signal Four Analytics	2/14/2022	8:10:00 PM	ROAD 400(INTERSTAT	STATE ROAD 33 N	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
42	88579431	Signal Four Analytics	2/23/2022	12:18:00 PM	R-400 (I-4) WEST OF N	STATE ROAD 33 (EXIT 38)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
43	24885022	Signal Four Analytics	3/15/2022	11:54:00 PM	STATE ROAD 400	STATE ROAD 33	Motor Vehicle in Transport	Other	Wet	Dark - Lighted	Rain	1	0	0	0	0
44	24910030	Signal Four Analytics	4/20/2022	9:15:00 AM	TATE 4 (STATE ROAD 4	US HIGHWAY 98	Other Non-Fixed Object	Other	Dry	Daylight	Clear	1	0	0	0	0

Interchange: I-4 at N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88230902	SSOGIS	1/10/2020	1523	SR 400	SOCRUM LOOP RD	05 CARGO/EQUIPMENT LOSS OR SHIFT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
2	89348803	Signal Four Analytics	1/19/2020	8:25:00 PM	N SOCRUM LOOP RD	LAKELAND PARK BLVD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	2	0	0
3	89374099	Signal Four Analytics	1/22/2020	7:45:00 AM	SOCRUM LOOP RD N	SR 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
4	89348858	Signal Four Analytics	1/23/2020	6:00:00 PM	CR 582	SR 33	Motor Vehicle in Transport	Angle	Dry	Dusk	Clear	2	0	0	0	0
5	89348955	SSOGIS	1/27/2020	556	I 4	SOCRUM LOOP RD	27 GUARDRAIL FACE	00 NOT CODED	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
6	88230909	SSOGIS	2/1/2020	1304	SR 400	OLD COMBEE RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
7	89348947	Signal Four Analytics	2/1/2020	9:50:00 AM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
8	88230908	Signal Four Analytics	2/1/2020	1:39:00 PM	IT RAMP TO SR-33 (EX	STATE ROAD 33	Traffic Sign Support	Other	Wet	Daylight	Cloudy	1	0	0	0	0
9	89348964	Signal Four Analytics	2/2/2020	12:41:00 PM	N SOCRUM LOOP RD	LAKELAND PARK BLVD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	3	0	0
10	88230909	Signal Four Analytics	2/2/2020	1:04:00 PM	-400 (INTERSTATE 4) I	OLD COMBEE ROAD	Overturn/Rollover	Other	Dry	Daylight	Clear	1	0	1	0	0
11	88215619	SSOGIS	2/3/2020	1253	SR 400	MM 34	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
12	89349027	SSOGIS	2/7/2020	10	I 4	SOCRUM LOOP RD N	27 GUARDRAIL FACE	00 NOT CODED	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
13	88184252	Signal Four Analytics	2/10/2020	7:45:00 AM	SR 400 (I-4)	SR 33 (EXIT 38)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
14	88173820	SSOGIS	2/13/2020	1007	I 4	MILE MARKER #31	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
15	88170907	Signal Four Analytics	2/14/2020	6:20:00 AM	R-400 ENTRANCE RAM	SR-33	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Fog, Smog, Smoke	2	0	0	0	0
16	87285696	Signal Four Analytics	2/15/2020	8:50:00 AM	00 EB EXIT RAMP (38	SR 33	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
17	88220084	SSOGIS	2/17/2020	210	I 4	SOCRUM LOOP RD	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
18	89349130	Signal Four Analytics	2/17/2020	1:29:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Sideswipe, Opposite Direction	Dry	Daylight	Clear	2	0	0	0	0
19	89349155	SSOGIS	2/18/2020	1117	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
20	89349126	Signal Four Analytics	2/18/2020	8:55:00 AM	SR-33	MELODY LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
21	87285700	Signal Four Analytics	2/21/2020	9:40:00 PM	00 WB EXIT RAMP (EX	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
22	88226815	SSOGIS	2/23/2020	1737	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	7	0	0
23	89349181	Signal Four Analytics	2/23/2020	6:30:00 AM	SR-33	N SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Dry	Dawn	Clear	2	0	2	0	0
24	89349284	Signal Four Analytics	2/27/2020	11:44:00 AM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
25	88308361	SSOGIS	3/3/2020	1730	I 4	OLD COMBEE RD	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
26	89349276	Signal Four Analytics	3/3/2020	7:10:00 AM	CR-582	I 4	Motor Vehicle in Transport	Front to Rear	Dry	Dawn	Clear	3	0	5	0	0
27	88233565	SSOGIS	3/13/2020	1656	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
28	88327815	Signal Four Analytics	3/17/2020	8:25:00 AM	-400 (INTERSTATE 4)	STATE ROAD 33	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
29	88226824	Signal Four Analytics	4/1/2020	11:25:00 AM	400 (INTERSTATE-4)	SR-33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
30	88194091	Signal Four Analytics	4/1/2020	3:25:00 PM	SR-33	FIRSTPARK BLVD	Other Non-Fixed Object	Other	Dry	Daylight	Clear	1	0	0	0	0
31	88253864	SSOGIS	4/26/2020	1025	SR 400	CR 582	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
32	89842327	SSOGIS	5/4/2020	1730	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
33	88327823	SSOGIS	5/15/2020	2310	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	4	0	0
34	24005842	Signal Four Analytics	5/15/2020	1:56:00 PM	CR-582	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
35	24005867	SSOGIS	5/19/2020	958	I 4	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
36	24005911	SSOGIS	5/22/2020	1550	SR 33	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
37	88327826	SSOGIS	5/28/2020	29	I 4	SOCRUM LOOP RD	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
38	24005960	SSOGIS	5/29/2020	1923	I 4	CR 582	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
39	87188783	SSOGIS	5/30/2020	1600	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
40	87188783	Signal Four Analytics	5/31/2020	4:00:00 PM	R-400 EB EXIT RAMP T	SR-33	Motor Vehicle in Transport	Other	Dry	Daylight	Cloudy	2	0	0	0	0
41	88251189	SSOGIS	6/2/2020	2200	SR 400	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
42	88215641	SSOGIS	6/3/2020	743	SR 400	SOCRUM LOOP RD	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
43	24006002	Signal Four Analytics	6/4/2020	11:53:00 PM	I-4 OFF RAMP EXIT 3	SR 33	Motor Vehicle in Transport	Angle	Wet	Dark - Not Lighted	Cloudy	2	0	0	0	0
44	88233580	SSOGIS	6/5/2020	503	SR 400	SOCRUM LOOP RD	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
45	24006056	SSOGIS	6/8/2020	1624	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
46	24006073	Signal Four Analytics	6/11/2020	5:50:00 PM	CR-582	SR-33	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	1	0	0
47	88322513	SSOGIS	6/22/2020	2025	I 4	US 98	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	2	0	0
48	24006162	Signal Four Analytics	6/22/2020	10:44:00 AM	SR-33	E I-4	Other Fixed Object	0	Dry	Daylight	Clear	1	0	0	0	0
49	24006155	Signal Four Analytics	6/23/2020	8:18:00 PM	N SOCRUM LOOP RD	LAKELAND PARK BLVD	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Not Lighted	Rain	2	0	0	0	0
50	88251198	SSOGIS	6/24/2020	1235	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
51	24006181	Signal Four Analytics	6/26/2020	10:17:00 PM	CR-582	POST LN	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	2	0	0
52	24006215	Signal Four Analytics	6/29/2020	4:05:00 PM	N SOCRUM LOOP RD	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
53	24006211	Signal Four Analytics	6/29/2020	5:37:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
54	24006280	Signal Four Analytics	7/1/2020	6:40:00 AM	4 EXIT 33 EB OFF RAM	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
55	24006304	Signal Four Analytics	7/10/2020	1:42:00 PM	SR 33	SOCRUM LOOP RD N	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
56	24006359	Signal Four Analytics	7/13/2020	3:31:00 PM	CR-582	SR-33	Concrete Traffic Barrier	0	Dry	Daylight	Clear	1	0	0	0	0
57	88275182	Signal Four Analytics	7/15/2020	4:39:00 PM	STATE 4 (STATE ROAD	STATE ROAD 33	Guardrail Face	Other	Wet	Daylight	Rain	1	0	0	0	0
58	88308392	Signal Four Analytics	7/22/2020	4:45:00 PM	STATE 4 (SR 400) EB E	STATE ROAD 33 (SR 33)	Overturn/Rollover	Other	Wet	Daylight	Cloudy	1	0	1	0	0
59	24006492	Signal Four Analytics	7/28/2020	6:25:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Wet	Daylight	Rain	2	0	0	0	0
60	24006521	Signal Four Analytics	8/1/2020	11:35:00 PM	CR-582	LAKELAND PARK BLVD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	1	0	0
61	24006534	SSOGIS	8/2/2020	1844	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
62	88308397	Signal Four Analytics	8/20/2020	5:35:00 PM	TE 4 (SR 400) WB EXIT	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	1	0	0
63	24006724	Signal Four Analytics	8/24/2020	10:33:00 AM	CR-582	LAKELAND PARK BLVD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
64	24006930	SSOGIS	9/2/2020	2150	SR 33	MELODY LANE	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
65	88378036	SSOGIS	9/12/2020	2155	SR 400	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	3	0	2	0	0
66	24006956	Signal Four Analytics	9/15/2020	7:10:00 PM	N SOCRUM LOOP RD	FERNERY RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
67	24006959	Signal Four Analytics	9/16/2020	3:59:00 PM	N SOCRUM LOOP RD	OLD COMBEE RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	1	0	0
68	88390058	SSOGIS	9/27/2020	1720	SR 400	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
69	88390058	Signal Four Analytics	9/28/2020	5:20:00 PM	) (I-4) EXIT RAMP TO C	CR 582 (SOCRUM LOOP RD)	Concrete Traffic Barrier	Other	Wet	Daylight	Cloudy	1	0	0	0	0
70	24007103	Signal Four Analytics	9/29/2020	7:58:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Front to Front	Wet	Dark - Lighted	Cloudy	2	0	1	0	0
71	88310656	SSOGIS	10/2/2020	1810	SR 400	MM 34	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	1	0	0
72	24007130	Signal Four Analytics	10/2/2020	7:44:00 AM	CR-582	ARTEVA DR	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
73	24007154	SSOGIS	10/3/2020	920	OLD COMBEE RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
74	88288836	SSOGIS	10/3/2020	826	I 4	US 98	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
75	24007211	SSOGIS	10/5/2020	1519	I 4	SOCRUM LOOP RD N	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
76	24007257	Signal Four Analytics	10/13/2020	7:57:00 AM	SR-33	N SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
77	24007307	Signal Four Analytics	10/19/2020	2:34:00 PM	CR-582	LAKELAND PARK BLVD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
78	24007337	SSOGIS	10/20/2020	1403	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
79	24007333	Signal Four Analytics	10/21/2020	2:52:00 PM	CR 582	SOCRUM LOOP RD/I4 ON RAMP	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
80	24007339	Signal Four Analytics	10/22/2020	4:00:00 PM	SR-33	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
81	88314742	SSOGIS	10/30/2020	124	I 4	SOCRUM LOOP RD	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
82	88314742	Signal Four Analytics	10/31/2020	1:24:00 AM	STATE 4 (STATE ROAD	STATE ROAD 33	Ditch	Other	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
83	88328371	Signal Four Analytics	11/2/2020	9:20:00 AM	SR 400 (I-4) EXIT RAM	SR 33 (EXIT 38)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
84	24007600	Signal Four Analytics	11/4/2020	5:28:00 PM	CR-582	POST LN	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
85	24007502	Signal Four Analytics	11/5/2020	2:14:00 PM	N SOCRUM LOOP RD	I 4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
86	24007521	Signal Four Analytics	11/5/2020	5:12:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
87	24007508	Signal Four Analytics	11/5/2020	11:00:00 PM	CR-582	LAKELAND PARK BLVD	Motor Vehicle in Transport	Front to Front	Dry	Dark - Lighted	Clear	2	0	1	0	0
88	24137214	SSOGIS	11/10/2020	830	OLD COMBEE RD	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
89	88312612	SSOGIS	11/11/2020	135	SR 400	MM 34	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0

Interchange: I-4 at N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
90	24007609	SSOGIS	11/12/2020	1823	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
91	24007682	Signal Four Analytics	11/19/2020	3:17:00 PM	N SOCRUM LOOP RD	LAKELAND PARK BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
92	24138101	SSOGIS	12/15/2020	2052	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
93	24008038	SSOGIS	12/19/2020	209	SR 33	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
94	88309313	SSOGIS	12/21/2020	351	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
95	24008162	SSOGIS	12/24/2020	1004	SR 33	LAKELAND HARBOR	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
96	88425395	SSOGIS	12/27/2020	2108	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
97	24008289	Signal Four Analytics	12/31/2020	4:51:00 PM	CR-582	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
98	88425396	Signal Four Analytics	1/4/2021	2:20:00 PM	I-4 (SR 400)	SR 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
99	83788094	Signal Four Analytics	1/6/2021	10:20:00 AM	N SOCRUM LOOP RD	WB SR 400	Other Fixed Object	Other	Dry	Daylight	Clear	1	0	2	0	0
100	24008198	Signal Four Analytics	1/6/2021	2:57:00 PM	CR-582	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
101	88404058	SSOGIS	1/13/2021	950	SR 33	I 4	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
102	24008296	Signal Four Analytics	1/14/2021	3:26:00 PM	CR-582	I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	2	0	0
103	88445448	Signal Four Analytics	1/19/2021	7:02:00 PM	N SOCRUM LOOP RD	INTERSTATE 4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dawn	Clear	2	0	0	0	0
104	24008380	Signal Four Analytics	1/22/2021	3:46:00 PM	N SOCRUM LOOP RD	FERNERY RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
105	88408470	Signal Four Analytics	1/23/2021	6:08:00 PM	SR-400 (I-4) WB MM3	SR-33	Motor Vehicle in Transport	Angle	Wet	Dark - Not Lighted	Rain	2	0	0	0	0
106	24008455	Signal Four Analytics	1/29/2021	2:53:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
107	88404070	Signal Four Analytics	1/30/2021	2:10:00 AM	NB SR-33	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	2	0	0
108	24008475	Signal Four Analytics	2/1/2021	2:13:00 PM	CR-582	LAKELAND PARK BLVD	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	0	0	0
109	24008512	Signal Four Analytics	2/1/2021	2:40:00 PM	CR-582	OLD COMBEE RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
110	24008503	Signal Four Analytics	2/3/2021	5:50:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	0	0	0
111	88404074	SSOGIS	2/5/2021	1817	I 4	SOCRUM LOOP RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
112	88335717	Signal Four Analytics	2/6/2021	12:00:00 AM	ERSTATE 4 EB EXIT RA	STATE ROAD 33	Guardrail Face	Other	Dry	Dark - Lighted	Clear	1	1	0	0	0
113	24008543	Signal Four Analytics	2/7/2021	1:42:00 AM	I-4	N SOCRUM LOOP RD	Other Non-Collision	<Null>	Wet	Dark - Unknown Lighting	Rain	1	0	0	0	0
114	24008584	Signal Four Analytics	2/10/2021	3:12:00 PM	SR-33	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
115	88392884	Signal Four Analytics	2/10/2021	5:25:00 PM	SR400	SR33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
116	88359469	Signal Four Analytics	2/10/2021	6:16:00 PM	STATE 4 (STATE ROAD	STATE ROAD 33	Motor Vehicle in Transport	Angle	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
117	24397687	Signal Four Analytics	2/14/2021	8:00:00 AM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Daylight	Cloudy	2	0	0	0	0
118	24397741	Signal Four Analytics	2/18/2021	4:44:00 PM	SR-33	N SOCRUM LOOP RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
119	88449292	Signal Four Analytics	2/27/2021	6:49:00 AM	STATE 4 (STATE ROAD	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
120	24397835	Signal Four Analytics	2/28/2021	2:44:00 AM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	2	0	0	0	0
121	24397883	SSOGIS	3/2/2021	659	SR 33	I 4	24 CURB	00 NOT CODED	06 MUD, DIRT, GRAVEL	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
122	88328401	SSOGIS	3/3/2021	110	SR 400	SOCRUM LOOP RD	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
123	88430514	Signal Four Analytics	3/13/2021	11:32:00 AM	-33 (LAKELAND HILLS	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
124	24398011	Signal Four Analytics	3/13/2021	12:10:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
125	24398052	Signal Four Analytics	3/16/2021	6:34:00 AM	N SOCRUM LOOP RD	POST LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
126	24398053	Signal Four Analytics	3/16/2021	6:34:00 PM	CR-582	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
127	87251616	Signal Four Analytics	3/24/2021	6:00:00 AM	SR400	STATE ROAD 33	Other	Concrete Traffic Barrier	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
128	88468624	SSOGIS	3/26/2021	2000	SR 400	SOCRUM LOOP RD	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
129	88468624	Signal Four Analytics	3/27/2021	8:00:00 PM	00 (EXIT RAMP) EXIT 3	SOCRUM LOOP RD	Concrete Traffic Barrier	Other	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
130	88404086	Signal Four Analytics	4/4/2021	2:00:00 AM	-400 (INTERSTATE-4) N	SR-33	Other Non-Collision	Other	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
131	88462001	Signal Four Analytics	4/6/2021	8:48:00 AM	ATE 4 (STATE ROAD 4	STATE ROAD 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
132	24398317	Signal Four Analytics	4/8/2021	10:25:00 PM	CR-582	ARTEVA DR	Tree (standing)	0	Dry	Dark - Lighted	Cloudy	1	0	1	0	0
133	24398319	Signal Four Analytics	4/8/2021	10:48:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
134	88374009	Signal Four Analytics	4/11/2021	6:00:00 PM	R-400 EB EXIT 38 RAM	SR-33	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	3	0	0
135	24398395	Signal Four Analytics	4/14/2021	3:21:00 PM	STATE ROAD 33 N	OLD COMBEE RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
136	24398446	Signal Four Analytics	4/18/2021	9:47:00 PM	SR-33	N SOCRUM LOOP RD	Traffic Sign Support	0	Dry	Dark - Lighted	Clear	1	0	0	0	0
137	24398584	Signal Four Analytics	4/21/2021	5:32:00 PM	SR-33	MELODY LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
138	24398594	Signal Four Analytics	4/22/2021	4:43:00 PM	SR-33	CR-582	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
139	24398525	Signal Four Analytics	4/23/2021	5:40:00 PM	N SOCRUM LOOP RD	POST LN	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
140	24398538	Signal Four Analytics	4/24/2021	7:29:00 PM	SR-33	DEEP FOREST CT	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
141	24398729	Signal Four Analytics	5/6/2021	9:30:00 PM	SR-33	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	1	0	0
142	88449316	Signal Four Analytics	5/7/2021	12:00:00 PM	INTERSTATE 4	STATE ROAD 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
143	88493707	Signal Four Analytics	5/9/2021	10:39:00 AM	INTERSTATE 4 WB	COUNTY ROAD 582	Concrete Traffic Barrier	Other	Dry	Daylight	Clear	1	0	1	0	0
144	24398766	Signal Four Analytics	5/9/2021	7:31:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
145	24398806	Signal Four Analytics	5/13/2021	7:40:00 AM	N SOCRUM LOOP RD	POST LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
146	88431613	Signal Four Analytics	5/15/2021	8:24:00 AM	SR400	SOCRUM LOOP RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	2	0	0
147	24398872	Signal Four Analytics	5/18/2021	5:00:00 PM	SR 33	I4 OFF RAMP	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
148	24398927	Signal Four Analytics	5/23/2021	12:00:00 PM	SR-33	N SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
149	24399115	Signal Four Analytics	6/3/2021	7:06:00 AM	SR-33	MELODY LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
150	88518790	Signal Four Analytics	6/9/2021	10:24:00 AM	I-4 W EXIT RAMP	SR 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
151	24399282	Signal Four Analytics	6/21/2021	9:57:00 PM	CR-582	SR-33	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Rain	2	0	0	0	0
152	24399298	Signal Four Analytics	6/23/2021	5:32:00 AM	N SOCRUM LOOP RD	SR-33	Concrete Traffic Barrier	0	Wet	Dawn	Cloudy	1	0	0	0	0
153	88525153	SSOGIS	6/24/2021	1714	I 4	SOCRUM LOOP RD	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
154	24399342	Signal Four Analytics	6/26/2021	12:15:00 PM	33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
155	88293244	Signal Four Analytics	7/2/2021	1:39:00 PM	EB I-4	SR 33	Cable Barrier	Other	Wet	Daylight	Rain	1	0	0	0	0
156	88462040	Signal Four Analytics	7/6/2021	6:43:00 PM	STATE ROAD 400) EXI	COUNTY ROAD 582 (SOCRUM LOOP RD)	Pedestrian	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
157	88499906	Signal Four Analytics	7/10/2021	8:40:00 PM	(INTERSTATE 4) EXIT 3	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Cloudy	2	0	0	0	0
158	24399560	Signal Four Analytics	7/15/2021	5:20:00 PM	SOCRUM LOOP RD N	POST LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
159	24399587	SSOGIS	7/17/2021	2037	I 4	SOCRUM LOOP RD N	27 GUARDRAIL FACE	00 NOT CODED	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
160	24399621	Signal Four Analytics	7/21/2021	8:00:00 PM	N SOCRUM LOOP RD	SR-33 N	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
161	24399721	Signal Four Analytics	7/30/2021	1:50:00 PM	CR-582	POST LN	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
162	24399738	Signal Four Analytics	7/31/2021	6:53:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
163	88412160	Signal Four Analytics	8/4/2021	5:58:00 AM	OCRUM LOOP RD (CR-	INTERSTATE 4 (STATE ROAD 400)	Motor Vehicle in Transport	Angle	Wet	Dark - Lighted	Cloudy	2	0	0	0	0
164	24399823	SSOGIS	8/5/2021	1545	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
165	88494020	Signal Four Analytics	8/8/2021	8:20:00 AM	INTERSTATE 4(SR 400	STATE ROAD 33(SR 33)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
166	24400354	Signal Four Analytics	8/23/2021	5:48:00 AM	STATE ROAD 33 N	E I-4	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	2	0	0
167	24400067	Signal Four Analytics	8/29/2021	9:30:00 AM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Mailbox	0	Dry	Daylight	Clear	1	0	0	0	0
168	24400079	Signal Four Analytics	8/30/2021	4:30:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
169	24400102	Signal Four Analytics	9/1/2021	10:45:00 AM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	2	0	0
170	24400105	Signal Four Analytics	9/1/2021	11:09:00 AM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Rain	2	0	0	0	0
171	24400115	Signal Four Analytics	9/2/2021	1:15:00 AM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
172	24400292	Signal Four Analytics	9/3/2021	9:20:00 PM	CR-582	SR-33	Other Traffic Barrier	0	Wet	Dark - Lighted	Rain	1	0	1	0	0
173	24400218	Signal Four Analytics	9/9/2021	3:30:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
174	24679538	Signal Four Analytics	9/9/2021	10:33:00 PM	I-4 E	HIGHWAY 33	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	3	0	4	0	0
175	24400328	Signal Four Analytics	9/17/2021	1:00:00 PM	RSTATE 4 WEST OFF R	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
176	24400335	Signal Four Analytics	9/17/2021	4:34:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	3	0	0	0	0
177	24400472	Signal Four Analytics	9/30/2021	12:14:00 PM	I4 EAST OFF RAMP	SR 33	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
178	24400483	Signal Four Analytics	9/30/2021	10:04:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0

Interchange: I-4 at N Socrum Loop Road & SR 33/Lakeland Hills Boulevard (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
179	24400490	Signal Four Analytics	10/1/2021	11:50:00 AM	SR-33	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
180	88510243	SSOGIS	10/2/2021	30	I 4	SOCRUM LOOP RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
181	88510243	Signal Four Analytics	10/3/2021	12:30:00 AM	TE 4 (STATE ROAD 40	COUNTY ROAD 582 (SOCRUM LOOP ROAD)	Other Non-Collision	Other	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
182	24400503	Signal Four Analytics	10/3/2021	10:48:00 AM	N SOCRUM LOOP RD	LAKELAND PARK BLVD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
183	24400624	Signal Four Analytics	10/8/2021	11:48:00 AM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
184	24400645	Signal Four Analytics	10/12/2021	3:34:00 PM	SR-33	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
185	24769603	Signal Four Analytics	10/15/2021	8:04:00 AM	CR-582	LAKELAND PARK BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
186	24769518	Signal Four Analytics	10/17/2021	6:22:00 PM	STATE ROAD 33 N	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
187	24769576	Signal Four Analytics	10/22/2021	12:50:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
188	89845339	SSOGIS	10/27/2021	20	SR 33	I 4	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
189	24769720	Signal Four Analytics	10/29/2021	5:28:00 PM	SR-33	DEEP FOREST CT	Curb	0	Dry	Daylight	Clear	1	0	1	0	0
190	24769754	Signal Four Analytics	11/5/2021	7:00:00 AM	N SOCRUM LOOP RD	LAKELAND PARK BLVD	Other Non-Fixed Object	0	Wet	Dawn	Rain	1	0	0	0	0
191	88465737	Signal Four Analytics	11/5/2021	4:18:00 PM	-400 (INTERSTATE-4) M	SR-33	Ran into Water/Canal	Other	Wet	Daylight	Rain	1	0	0	0	0
192	24769843	Signal Four Analytics	11/11/2021	6:15:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Wet	Dark - Lighted	Clear	2	0	0	0	0
193	24769924	Signal Four Analytics	11/15/2021	5:30:00 AM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
194	24769966	Signal Four Analytics	11/16/2021	5:35:00 PM	N SOCRUM LOOP RD	FERNERY RD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
195	24769980	Signal Four Analytics	11/19/2021	4:48:00 PM	CR-582	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
196	24769989	Signal Four Analytics	11/22/2021	5:22:00 PM	SR-33	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
197	88493524	Signal Four Analytics	11/24/2021	3:40:00 PM	-400 (INTERSTATE-4)	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
198	24770046	Signal Four Analytics	11/26/2021	4:01:00 PM	CR-582	OLD COMBEE RD	Curb	0	Dry	Daylight	Clear	1	0	0	0	0
199	88510251	Signal Four Analytics	12/1/2021	10:29:00 AM	ATE 4 (SR 400) MM33	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
200	88513139	SSOGIS	12/3/2021	1901	I 4	SOCRUM LOOP RD	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
201	24770164	Signal Four Analytics	12/3/2021	3:17:00 PM	CR-582	POST LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
202	24770253	Signal Four Analytics	12/3/2021	4:00:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
203	24770254	Signal Four Analytics	12/3/2021	4:17:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
204	88513139	Signal Four Analytics	12/4/2021	7:01:00 PM	INTERSTATE 4(SR400)	CR582	Motor Vehicle in Transport	Other	Dry	Dark - Lighted	Clear	1	0	0	0	0
205	24770134	Signal Four Analytics	12/5/2021	12:20:00 PM	SR-33	MELODY LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
206	24770169	Signal Four Analytics	12/7/2021	6:50:00 PM	STATE ROAD 33 N	HYDE PARKE BLVD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
207	24770219	Signal Four Analytics	12/10/2021	4:17:00 PM	CR-582	POST LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
208	24770301	Signal Four Analytics	12/16/2021	5:54:00 AM	N SOCRUM LOOP RD	SR-33	Curb	0	Dry	Dark - Lighted	Clear	1	0	1	0	0
209	24770316	Signal Four Analytics	12/17/2021	4:53:00 PM	CR-582	I-4 W	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
210	88511618	Signal Four Analytics	12/20/2021	4:12:00 PM	-400 (I-4) WB EXIT RA	SR-33 N	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
211	24770390	Signal Four Analytics	12/21/2021	6:45:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Wet	Dark - Lighted	Rain	3	0	0	0	0
212	24770374	Signal Four Analytics	12/22/2021	7:34:00 PM	CR-582	OLD COMBEE RD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
213	24770438	Signal Four Analytics	12/29/2021	12:39:00 PM	SOCRUM LOOP N	I - 4 WEST ENTRANCE AND EXIT RAMP	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	3	0	0
214	88587748	Signal Four Analytics	12/31/2021	11:56:00 AM	I4 EXIT RAMP MM 33	SR 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	2	0	0
215	24770462	Signal Four Analytics	12/31/2021	10:39:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
216	24770466	SSOGIS	1/1/2022	1026	SR 33	I 4 E	27 GUARDRAIL FACE	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
217	24770488	Signal Four Analytics	1/4/2022	6:50:00 PM	CR-582	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	1	0	0
218	24770497	Signal Four Analytics	1/5/2022	1:25:00 PM	CR-582	I 4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
219	24770537	Signal Four Analytics	1/7/2022	1:24:00 PM	CR-582	POST LN	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
220	24884802	Signal Four Analytics	1/13/2022	5:33:00 PM	TATE ROAD 400(I4) EX	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
221	24770606	Signal Four Analytics	1/15/2022	7:05:00 PM	CR-582	LAKELAND PARK BLVD	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	3	0	0
222	24770737	Signal Four Analytics	1/21/2022	1:21:00 PM	CR-582	FERNERY RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
223	24770814	Signal Four Analytics	1/31/2022	7:55:00 PM	N SOCRUM LOOP RD	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	1	0	0
224	24770789	Signal Four Analytics	2/1/2022	6:10:00 AM	SR 582	SR-33	Curb	0	Dry	Dawn	Clear	1	0	0	0	0
225	24770820	Signal Four Analytics	2/3/2022	1:30:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
226	24910010	Signal Four Analytics	2/19/2022	8:55:00 PM	TATE 4 (STATE ROAD 4	STATE ROAD 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
227	24771043	Signal Four Analytics	2/21/2022	7:00:00 PM	CR-582	SOCRUM LOOP RD N	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
228	24771068	Signal Four Analytics	2/22/2022	2:23:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
229	24771069	Signal Four Analytics	2/23/2022	6:38:00 AM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Dry	Dawn	Clear	2	0	0	0	0
230	24771079	Signal Four Analytics	2/23/2022	12:30:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
231	89586712	Signal Four Analytics	2/25/2022	9:42:00 AM	NTERSTATE 4) EB EXIT	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
232	24771224	Signal Four Analytics	3/5/2022	3:48:00 PM	N SOCRUM LOOP RD	FERNERY RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
233	24771401	Signal Four Analytics	3/10/2022	3:03:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	1	0	0
234	24913870	SSOGIS	3/11/2022	1858	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
235	24885020	Signal Four Analytics	3/11/2022	2:10:00 AM	STATE ROAD 400	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
236	24771395	Signal Four Analytics	3/13/2022	1:10:00 PM	N SOCRUM LOOP RD	POST LN	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
237	24771444	Signal Four Analytics	3/18/2022	5:14:00 PM	CR-582	POST LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	4	0	1	0	0
238	24771377	Signal Four Analytics	3/18/2022	5:31:00 PM	CR-582	POST LN	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
239	24771465	Signal Four Analytics	3/27/2022	7:30:00 PM	STATE ROAD 33 N	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
240	24771473	Signal Four Analytics	3/28/2022	4:18:00 PM	SR-33	DEEP FOREST CT	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
241	24771585	Signal Four Analytics	4/1/2022	4:45:00 PM	SR 33	LAKELAND HARBOR BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
242	88527611	SSOGIS	4/6/2022	635	I 4	SOCRUM LOOP RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
243	24771848	Signal Four Analytics	4/27/2022	4:18:00 PM	M I-4 W TO N SOCRUI	N SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
244	24771968	Signal Four Analytics	4/29/2022	3:38:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	2	0	0
245	24771982	Signal Four Analytics	5/10/2022	10:45:00 AM	N SOCRUM LOOP RD	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
246	24772082	Signal Four Analytics	5/15/2022	9:07:00 PM	CR-582	SOCRUM LOOP RD	Motor Vehicle in Transport	Angle	Wet	Dark - Lighted	Clear	2	0	4	0	0
247	24772067	Signal Four Analytics	5/17/2022	8:54:00 AM	N SOCRUM LOOP RD	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
248	24940658	Signal Four Analytics	5/21/2022	11:24:00 AM	STATE 4 (SR 400) EXIT	SOCRUM LOOP	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
249	88568650	Signal Four Analytics	5/25/2022	1:19:00 PM	I-4 E	SR33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
250	24772199	Signal Four Analytics	5/29/2022	11:11:00 AM	582	SOCRUM LOOP RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0

Mainline Segment: I-4 from N Socrum Loop Road & SR 33/Lakeland Hills Boulevard to SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88220077	SSOGIS	1/14/2020	520	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
2	88253845	SSOGIS	1/14/2020	225	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	0	0
3	88230913	SSOGIS	2/7/2020	1933	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
4	88308362	SSOGIS	3/4/2020	1600	I 4	MILE MARKER #39	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
5	88327817	SSOGIS	3/30/2020	1701	I 4	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	5	0	0
6	88233569	SSOGIS	4/16/2020	1824	SR 400	CR 582	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
7	88327822	SSOGIS	4/29/2020	435	SR 400	OLD COMBEE RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
8	88308375	SSOGIS	5/27/2020	1715	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
9	88215642	SSOGIS	6/3/2020	1402	SR 400	MM 37	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
10	88184272	SSOGIS	6/22/2020	2010	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	3	0	0	0	0
11	88215648	SSOGIS	7/4/2020	319	SR 400	MM 35	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
12	88184279	SSOGIS	7/13/2020	1115	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
13	88292596	SSOGIS	7/26/2020	1730	I 4	OLD COMBEE RD	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
14	88308394	SSOGIS	8/4/2020	1535	I 4	OLD COMBEE RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
15	88322530	SSOGIS	8/16/2020	1634	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
16	88314720	SSOGIS	8/19/2020	1610	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
17	88216646	SSOGIS	8/19/2020	1609	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	4	0	0
18	88306963	SSOGIS	8/19/2020	1530	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
19	88308398	SSOGIS	8/21/2020	725	I 4	OLD COMBEE RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
20	88309211	SSOGIS	8/22/2020	1921	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	02 CLOUDY	2	0	0	0	0
21	88312591	SSOGIS	8/26/2020	1208	SR 400	MM 37	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
22	88314319	SSOGIS	8/29/2020	1930	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	03 RAIN	3	0	0	0	0
23	88378029	Signal Four Analytics	9/2/2020	11:54:00 AM	00 (INTERSTATE 4) NEA	STATE ROAD 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Cloudy	2	0	0	0	0
24	88390040	SSOGIS	9/4/2020	2040	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
25	88390045	SSOGIS	9/11/2020	1220	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
26	88361467	SSOGIS	9/12/2020	1939	I 4	MILE MARKER #36	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
27	88087495	SSOGIS	9/12/2020	5	I 4	MM 37	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
28	88262269	SSOGIS	10/3/2020	820	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
29	88306765	SSOGIS	10/3/2020	10	SR 400	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
30	88262270	SSOGIS	10/3/2020	845	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
31	88322551	SSOGIS	10/31/2020	239	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
32	88306775	SSOGIS	11/10/2020	2029	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
33	84877580	SSOGIS	12/11/2020	1018	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
34	85156102	Signal Four Analytics	1/2/2021	1:43:00 AM	SR 400	SR 33	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
35	87251590	SSOGIS	1/5/2021	2300	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
36	24138580	SSOGIS	1/7/2021	612	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
37	88390094	Signal Four Analytics	2/1/2021	10:50:00 AM	SR 400 (I-4)	SR-33	Other Non-Collision	Other	Dry	Daylight	Cloudy	2	0	0	0	0
38	87251598	Signal Four Analytics	2/8/2021	10:06:00 AM	STATE ROAD 400	STATE ROAD 33	Other Non-Collision	Other	Dry	Daylight	Cloudy	1	0	1	0	0
39	88365052	SSOGIS	2/24/2021	1330	I 4	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
40	88328402	Signal Four Analytics	3/9/2021	4:00:00 AM	SR 400 (I-4) EB 35MM	SR 33 (EXIT 33)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
41	88408504	SSOGIS	4/11/2021	1711	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	3	0	0
42	88416512	Signal Four Analytics	4/20/2021	9:36:00 AM	-400 (INTERSTATE-4) N	SR-33	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Daylight	Rain	2	0	0	0	0
43	88525152	SSOGIS	6/21/2021	1928	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
44	88525154	Signal Four Analytics	6/26/2021	5:01:00 PM	0 (INTERSTATE 4) NEA	STATE ROAD 33	Overturn/Rollover	Other	Dry	Daylight	Cloudy	1	0	0	0	0
45	88494009	Signal Four Analytics	7/26/2021	11:05:00 PM	INTERSTATE 4(SR 400)	STATE ROAD 33(SR 33)	Motor Vehicle in Transport	Angle	Dry	Dark - Not Lighted	Clear	2	0	8	0	0
46	88518811	Signal Four Analytics	8/1/2021	11:45:00 PM	STATE ROAD 400	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	3	0	0	0	0
47	88494014	Signal Four Analytics	8/4/2021	5:01:00 PM	INTERSTATE 4(SR 400)	STATE ROAD 33(SR33)	Cable Barrier	Other	Wet	Daylight	Rain	1	0	0	0	0
48	88468661	Signal Four Analytics	8/23/2021	5:40:00 AM	SR 400 (I-4) EB 35MM	SR 33 (EXIT 33)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
49	88487217	SSOGIS	8/26/2021	1258	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
50	24291797	Signal Four Analytics	10/23/2021	3:48:00 AM	ERSTATE 4 (EASTBOU	<Null>	Overturn/Rollover	Other	Dry	Dark - Not Lighted	Clear	1	1	0	0	0
51	88588474	Signal Four Analytics	10/24/2021	8:05:00 PM	ROAD 400(INTERSTAT	STATE ROAD 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Wet	Dark - Lighted	Rain	2	0	0	0	0
52	88579422	SSOGIS	12/20/2021	913	I 4	OLD COMBEE RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
53	88579421	SSOGIS	12/20/2021	738	SR 400	OLD COMBEE RD	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
54	88568638	Signal Four Analytics	3/2/2022	5:05:00 AM	I-4 E	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
55	24901950	Signal Four Analytics	3/2/2022	9:58:00 PM	TATE 4 (STATE ROAD 4	STATE ROAD 33	Other Non-Collision	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	1	0	0
56	88574849	SSOGIS	3/7/2022	2116	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
57	24884829	SSOGIS	4/2/2022	1609	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
58	24927815	Signal Four Analytics	4/3/2022	12:44:00 PM	INTERSTATE 4(SR400)	SR33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
59	88551435	SSOGIS	4/5/2022	640	I 4	MILE MARKER #37	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
60	24934796	Signal Four Analytics	4/13/2022	5:48:00 PM	SR-400 (I-4) NEAR MM	STATE ROAD 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	1	0	0
61	88568641	Signal Four Analytics	4/16/2022	4:00:00 AM	SR 400	SR 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
62	24945431	Signal Four Analytics	5/21/2022	1:49:00 AM	INTERSTATE 4(SR400)	SR33	Thrown or Falling Object	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0

Interchange: I-4 at SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88173814	SSOGIS	1/2/2020	1147	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
2	88226800	SSOGIS	1/8/2020	1604	SR 400	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
3	88220076	SSOGIS	1/13/2020	2100	I 4	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
4	88230908	SSOGIS	1/31/2020	1339	SR 400	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
5	88235045	SSOGIS	2/6/2020	1747	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
6	89349070	SSOGIS	2/6/2020	1728	SR 33	TOMKOW RD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
7	89349021	Signal Four Analytics	2/7/2020	8:04:00 AM	SR-33	W I-4	Guardrail Face	0	Dry	Daylight	Clear	2	0	0	0	0
8	88275141	SSOGIS	2/8/2020	1150	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
9	88170907	SSOGIS	2/13/2020	620	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	0	0
10	87285696	SSOGIS	2/14/2020	850	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
11	85591177	SSOGIS	2/15/2020	1330	I 4	SR 33	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
12	88173822	SSOGIS	2/16/2020	1206	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
13	89349155	Signal Four Analytics	2/19/2020	11:17:00 AM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
14	89349268	SSOGIS	3/1/2020	708	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
15	88162190	SSOGIS	3/16/2020	848	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
16	88150862	SSOGIS	3/30/2020	1300	I 4	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
17	88194093	SSOGIS	4/17/2020	1121	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
18	88251181	SSOGIS	5/3/2020	645	SR 400	MM 38	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
19	88258537	SSOGIS	5/6/2020	2224	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
20	24005771	SSOGIS	5/8/2020	2007	SR 33	TOMKOW RD	01 OVERTURN/ROLLOVER	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
21	88262375	SSOGIS	5/12/2020	2025	I 4	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
22	88162192	SSOGIS	5/24/2020	2050	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	3	0	0
23	88175085	SSOGIS	5/28/2020	820	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
24	88171485	SSOGIS	6/3/2020	1605	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
25	24006056	Signal Four Analytics	6/9/2020	4:24:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
26	88308379	SSOGIS	6/13/2020	125	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	01 CLEAR	2	0	3	0	0
27	88308379	Signal Four Analytics	6/14/2020	1:25:00 AM	TATE 4 WB MM 38 EXI	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	3	0	0
28	88184275	SSOGIS	7/5/2020	1645	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
29	88184276	SSOGIS	7/5/2020	1745	SR 400	SR 33	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
30	88310637	SSOGIS	7/6/2020	1	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	1	0	0
31	88294644	SSOGIS	7/10/2020	1444	SR 400	MILE MARKER #38	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
32	88267815	SSOGIS	7/12/2020	430	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
33	88184280	SSOGIS	7/13/2020	1145	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
34	88308392	SSOGIS	7/21/2020	1645	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
35	88327847	SSOGIS	7/26/2020	1616	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
36	88262712	SSOGIS	7/30/2020	1836	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
37	88322517	SSOGIS	7/30/2020	1008	I 4	SR 33	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
38	88322518	SSOGIS	7/30/2020	1008	I 4	SR 33	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
39	88322519	SSOGIS	8/2/2020	1002	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
40	89844947	SSOGIS	8/2/2020	45	I 4	SR 33	29 CABLE BARRIER	00 NOT CODED	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
41	24006567	SSOGIS	8/6/2020	35	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
42	88378022	SSOGIS	8/12/2020	1237	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
43	24006641	SSOGIS	8/13/2020	23	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
44	88322531	SSOGIS	8/17/2020	1654	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
45	89845475	SSOGIS	8/17/2020	1643	SR 400	MILE MARKER #38	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
46	24006692	SSOGIS	8/18/2020	1549	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
47	88308397	SSOGIS	8/19/2020	1735	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
48	88310648	SSOGIS	8/23/2020	2245	SR 400	MILE MARKER #38	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
49	88361463	SSOGIS	9/6/2020	1748	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
50	24006870	SSOGIS	9/7/2020	1623	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	0	0
51	88184291	SSOGIS	9/8/2020	720	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
52	88390047	SSOGIS	9/13/2020	1810	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
53	88319029	SSOGIS	9/14/2020	1505	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	88361471	SSOGIS	9/19/2020	1517	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
55	88369163	SSOGIS	9/19/2020	2018	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	2	0	0
56	88390055	SSOGIS	9/25/2020	605	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
57	24007103	SSOGIS	9/28/2020	1958	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
58	88175117	SSOGIS	10/1/2020	720	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
59	88310662	SSOGIS	10/19/2020	1740	SR 33	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	4	0	0
60	88349887	SSOGIS	10/25/2020	206	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
61	24007413	SSOGIS	10/28/2020	1050	SR 33	TOMKOW RD	34 TRAFFIC SIGN SUPPORT	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
62	88319045	SSOGIS	10/29/2020	2050	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
63	88314743	SSOGIS	10/30/2020	445	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
64	24007489	Signal Four Analytics	11/4/2020	10:50:00 AM	P FROM I-4 W TO SR-	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
65	88349891	SSOGIS	11/8/2020	1300	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
66	88312610	SSOGIS	11/10/2020	231	SR 400	MM 39	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
67	88310666	SSOGIS	11/11/2020	610	SR 400	MM38	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
68	88369191	SSOGIS	11/15/2020	1820	I 4	SR 33	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
69	88390073	SSOGIS	11/16/2020	1455	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
70	24007734	SSOGIS	11/23/2020	1815	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	0	0	0
71	88312613	SSOGIS	11/25/2020	443	SR 400	MILE MARKER #37	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
72	88322558	SSOGIS	11/28/2020	2112	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
73	24007952	SSOGIS	12/12/2020	1107	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	1	0	0	0
74	88404047	SSOGIS	12/14/2020	1741	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
75	88253816	SSOGIS	12/19/2020	315	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
76	24008079	Signal Four Analytics	12/19/2020	12:52:00 AM	SR-33 N	UNIVERSITY BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
77	85156100	SSOGIS	12/22/2020	2140	SR 33	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
78	88404052	SSOGIS	12/28/2020	917	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
79	24008160	Signal Four Analytics	12/29/2020	7:55:00 AM	SR-33	UNIVERSITY BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
80	24008179	Signal Four Analytics	1/4/2021	5:09:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Front to Front	Dry	Daylight	Clear	2	0	3	0	0
81	24008400	Signal Four Analytics	1/23/2021	2:45:00 PM	SR-33	UNIVERSITY BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
82	24008547	SSOGIS	1/26/2021	1701	SR 33	I 4	34 TRAFFIC SIGN SUPPORT	00 NOT CODED	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
83	88335717	SSOGIS	2/5/2021	0	SR 400	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	1	0	0	0
84	87251597	SSOGIS	2/6/2021	750	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
85	88420883	SSOGIS	2/9/2021	1723	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	02 DUSK	01 CLEAR	3	0	1	0	0
86	24008592	Signal Four Analytics	2/11/2021	12:11:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
87	24008607	Signal Four Analytics	2/11/2021	12:16:00 PM	33	TOMKOW RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
88	88465269	SSOGIS	2/26/2021	1933	I 4	MILE MARKER #39	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
89	24397883	Signal Four Analytics	3/3/2021	6:59:00 AM	SR-33	W I-4	Curb	0	Mud, Dirt, Gravel	Dark - Lighted	Rain	1	0	0	0	0

Interchange: I-4 at SR 33/Lakeland Hills Boulevard/Commonwealth Avenue (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
90	24397884	Signal Four Analytics	3/3/2021	6:59:00 AM	SR-33	W I-4	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Rain	2	0	0	0	0
91	24397896	Signal Four Analytics	3/4/2021	10:37:00 AM	N SR-33	TOMKOW RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
92	24398071	Signal Four Analytics	3/14/2021	7:53:00 PM	SR-33	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
93	88411117	SSOGIS	4/4/2021	608	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	1	0	0
94	88374015	SSOGIS	4/22/2021	725	SR 400	MILE MARKER #38	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
95	24398569	Signal Four Analytics	4/26/2021	9:17:00 AM	SR-33	W I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
96	88310808	Signal Four Analytics	5/4/2021	6:57:00 PM	SR-33	TOMKOW ROAD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
97	24398731	Signal Four Analytics	5/6/2021	1:45:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
98	88445495	Signal Four Analytics	5/7/2021	5:24:00 PM	EXIT RAMP MM38	STATE ROAD 33	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
99	24398835	Signal Four Analytics	5/11/2021	11:45:00 AM	SR-33	E I-4	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	0	0	0
100	88408509	Signal Four Analytics	5/18/2021	1:47:00 AM	D (I-4) EB MM 38 EXIT	SR-33 S	Overturn/Rollover	Other	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
101	24399056	Signal Four Analytics	5/19/2021	3:40:00 PM	SR-33	TOMKOW RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
102	24398891	Signal Four Analytics	5/20/2021	3:51:00 AM	SR-33	UNIVERSITY BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	3	0	0
103	88408513	SSOGIS	6/5/2021	417	SR 400	SR 33	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
104	24399357	Signal Four Analytics	6/10/2021	10:25:00 AM	SR-33	TOMKOW RD	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
105	24399289	Signal Four Analytics	6/22/2021	10:54:00 AM	SR-33	I4 W OFFRAMP	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	0	0	0
106	24399325	Signal Four Analytics	6/24/2021	2:56:00 PM	STATE ROAD 33 N	TOMKOW RD	Parked Motor Vehicle	0	Dry	Daylight	Clear	2	0	0	0	0
107	88449326	SSOGIS	6/25/2021	540	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
108	88449328	SSOGIS	6/26/2021	505	I 4	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
109	88525155	SSOGIS	6/28/2021	1810	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
110	88529153	SSOGIS	7/2/2021	315	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	3	0	0	0	0
111	24399470	Signal Four Analytics	7/7/2021	2:30:00 PM	SR 33	UNIVERSITY BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
112	24399593	Signal Four Analytics	7/9/2021	12:00:00 PM	SR-33	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
113	24399569	Signal Four Analytics	7/16/2021	3:08:00 PM	SR 33	I4 WEST OFF RAMP	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
114	24399723	Signal Four Analytics	7/27/2021	6:30:00 PM	SR-33	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
115	24399713	Signal Four Analytics	7/28/2021	1:04:00 PM	N SR-33	TOMKOW RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Rain	2	0	0	0	0
116	24399823	Signal Four Analytics	8/6/2021	3:45:00 PM	SR-33	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
117	88529161	SSOGIS	8/7/2021	628	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	1	0	0
118	88471789	SSOGIS	8/11/2021	1715	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
119	88487213	SSOGIS	8/11/2021	600	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
120	88468663	SSOGIS	8/31/2021	1155	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
121	24400272	Signal Four Analytics	9/7/2021	1:57:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
122	24400201	Signal Four Analytics	9/8/2021	11:00:00 AM	SR-33	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
123	88579404	SSOGIS	10/7/2021	1515	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
124	24400669	Signal Four Analytics	10/13/2021	7:38:00 PM	SR-33 N	UNIVERSITY BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
125	24769583	Signal Four Analytics	10/23/2021	11:40:00 AM	SR-33	W I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
126	88519639	Signal Four Analytics	11/2/2021	11:06:00 AM	STATE ROAD 400	STATE ROAD 33	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
127	88484402	SSOGIS	11/4/2021	1951	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
128	88568626	SSOGIS	11/4/2021	817	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
129	24769794	Signal Four Analytics	11/8/2021	7:13:00 AM	SR-33	TOMKOW RD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
130	88527593	SSOGIS	11/10/2021	1810	I 4	SR 33	11 PEDALCYCLE	03 ANGLE	02 WET	01 DAYLIGHT	01 CLEAR	1	0	0	0	1
131	24769937	Signal Four Analytics	11/18/2021	4:40:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Angle	Wet	Daylight	Rain	2	0	0	0	0
132	24770136	Signal Four Analytics	11/27/2021	3:35:00 PM	SR-33	W I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
133	88493554	SSOGIS	11/30/2021	420	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
134	24770142	Signal Four Analytics	12/3/2021	9:43:00 AM	SR-33	TOMKOW RD	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
135	88493527	SSOGIS	12/5/2021	1543	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
136	24770314	Signal Four Analytics	12/17/2021	1:25:00 PM	SR-33	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	2	0	0
137	88527599	Signal Four Analytics	12/20/2021	6:45:00 PM	ATE 4 WESTBOUND O	STATE ROAD 33	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	0	0	0
138	24770466	Signal Four Analytics	1/2/2022	10:26:00 AM	SR-33	E I-4	Guardrail Face	0	Dry	Daylight	Clear	1	0	0	0	0
139	24770517	Signal Four Analytics	1/7/2022	12:18:00 AM	SR-33	E I-4	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
140	88510260	SSOGIS	1/11/2022	1337	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	4	0	1	0	0
141	24770565	Signal Four Analytics	1/11/2022	7:47:00 AM	SR-33	UNIVERSITY BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
142	24895957	SSOGIS	2/20/2022	1925	I 4	SR 33	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
143	24771044	Signal Four Analytics	2/21/2022	9:40:00 PM	SR-33	W I-4	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	4	0	2	0	0
144	24771215	Signal Four Analytics	3/5/2022	8:30:00 AM	SR-33	E I-4	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
145	24884817	SSOGIS	3/7/2022	803	SR 33	SR 400	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
146	24912905	SSOGIS	3/27/2022	1345	I 4	SR 33	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
147	24771560	Signal Four Analytics	4/2/2022	5:23:00 PM	AP FROM I-4 E TO SR-	SR-33	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
148	24771647	Signal Four Analytics	4/9/2022	7:43:00 PM	AP FROM I-4 E TO SR-	SR-33	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
149	24914823	SSOGIS	4/30/2022	2220	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
150	24772008	Signal Four Analytics	5/10/2022	4:55:00 PM	SR-33	UNIVERSITY BLVD	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0

Mainline Segment: I-4 from SR 33/Lakeland Hills Boulevard/Commonwealth Avenue to SR 570/Polk Parkway (East) (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88168959	SSOGIS	1/28/2020	6	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
2	88327813	SSOGIS	3/10/2020	1200	I 4	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
3	88173831	SSOGIS	4/16/2020	1810	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
4	88322503	SSOGIS	4/26/2020	2114	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
5	88194100	SSOGIS	4/28/2020	1556	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
6	88184264	SSOGIS	5/24/2020	930	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
7	88250812	SSOGIS	6/8/2020	1750	SR 400	MM 41	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
8	88327836	SSOGIS	6/14/2020	613	SR 400	SR 33	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
9	88215646	SSOGIS	6/18/2020	2235	I 4	MM39	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
10	83787239	SSOGIS	7/1/2020	1340	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
11	88258549	SSOGIS	7/3/2020	1857	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
12	88267811	SSOGIS	7/7/2020	1320	SR 400	MM 39	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
13	88310641	SSOGIS	7/26/2020	1455	SR 400	MM39	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
14	88285045	SSOGIS	8/9/2020	1440	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
15	88262720	SSOGIS	8/19/2020	1529	SR 400	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
16	88262719	SSOGIS	8/19/2020	1429	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
17	88184289	SSOGIS	8/22/2020	510	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
18	88306751	Signal Four Analytics	8/30/2020	12:44:00 PM	SR-400	SR-570	Motor Vehicle in Transport	Angle	Wet	Daylight	Rain	2	0	0	0	0
19	89845755	SSOGIS	9/4/2020	1058	I 4	SR 570	29 CABLE BARRIER	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
20	88378034	SSOGIS	9/11/2020	2309	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	3	0	0
21	88378035	SSOGIS	9/11/2020	2311	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	4	0	5	2	0
22	88306759	SSOGIS	9/12/2020	237	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
23	88314322	SSOGIS	9/14/2020	2230	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	08 WATER (STANDING/MOVING)	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
24	88184293	SSOGIS	9/16/2020	1210	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
25	88306761	SSOGIS	9/16/2020	0	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
26	88319035	SSOGIS	9/19/2020	2000	SR 400	MM 40	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	02 CLOUDY	3	0	0	0	0
27	88312603	SSOGIS	9/19/2020	1940	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
28	88349885	SSOGIS	10/18/2020	328	SR 400	MM 41	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
29	88309303	SSOGIS	10/19/2020	1705	SR 400	MM39	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
30	88390066	SSOGIS	10/25/2020	900	SR 400	SR 570	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	1	0	0	0	0
31	88288844	SSOGIS	10/28/2020	2110	I 4	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
32	88306768	SSOGIS	10/29/2020	610	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
33	88378047	SSOGIS	11/2/2020	1833	I 4	SR 33	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
34	88396610	SSOGIS	12/19/2020	2150	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
35	88322564	SSOGIS	12/28/2020	640	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
36	88392888	Signal Four Analytics	3/5/2021	11:39:00 AM	SR400	SR570	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
37	87251607	Signal Four Analytics	3/5/2021	7:37:00 PM	I-4 W	SR570	Other Non-Fixed Object	Other	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
38	24126458	Signal Four Analytics	3/14/2021	11:10:00 AM	I 4	<Null>	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
39	88408838	SSOGIS	3/29/2021	652	I 4	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	02 CLOUDY	1	1	0	0	0
40	88525151	SSOGIS	6/21/2021	1754	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
41	24289601	SSOGIS	7/1/2021	1317	I 4	SR 33	29 CABLE BARRIER	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
42	88412161	SSOGIS	8/11/2021	1630	I 4	SR 33	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
43	88454955	SSOGIS	9/12/2021	2249	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
44	88561222	SSOGIS	10/29/2021	210	SR 400	MM 39	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
45	88588497	SSOGIS	12/20/2021	932	SR 400	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
46	89586704	SSOGIS	1/18/2022	658	SR 400	MM 38	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
47	24889410	SSOGIS	2/3/2022	2321	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	3	0	0
48	24901955	SSOGIS	4/1/2022	1844	I 4	SR 33	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
49	24927816	Signal Four Analytics	4/8/2022	9:20:00 AM	INTERSTATE 4(SR400)	SR570	Struck by Falling, Shifting Cargo	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
50	24906190	SSOGIS	4/30/2022	2137	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0

Interchange: I-4 at SR 570/Polk Parkway (East) (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88173819	SSOGIS	1/26/2020	736	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
2	88275137	SSOGIS	1/31/2020	715	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
3	83787236	SSOGIS	2/10/2020	700	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
4	88253857	SSOGIS	2/24/2020	1315	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
5	87285702	SSOGIS	2/28/2020	305	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
6	88173827	SSOGIS	3/7/2020	1917	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	1	0	0
7	88226819	SSOGIS	3/7/2020	1429	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	5	0	0
8	88216642	SSOGIS	3/31/2020	1219	SR 570	SR 400	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
9	88308374	SSOGIS	5/21/2020	645	I 4	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
10	88194420	SSOGIS	6/3/2020	609	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
11	88216643	SSOGIS	6/3/2020	700	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
12	88327833	SSOGIS	6/5/2020	1615	SR 400	SR 570	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	1	1	0	0
13	88184271	SSOGIS	6/20/2020	2100	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
14	87174341	SSOGIS	7/5/2020	1450	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
15	88250814	SSOGIS	7/6/2020	22	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
16	88250814	Signal Four Analytics	7/7/2020	12:22:00 AM	SR 400 (I-4 EB)	MM 41	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
17	88267816	SSOGIS	7/19/2020	505	SR 570	I 4	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
18	85520468	SSOGIS	8/6/2020	610	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	1	0	0	0
19	88262258	SSOGIS	8/13/2020	235	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
20	88378026	SSOGIS	8/26/2020	623	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	01 CLEAR	1	0	0	0	0
21	88234418	SSOGIS	9/9/2020	1859	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	02 CLOUDY	2	0	0	0	0
22	88361465	SSOGIS	9/11/2020	1612	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	3	0	0
23	88378033	SSOGIS	9/11/2020	2154	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
24	88306758	SSOGIS	9/11/2020	2153	SR 400	SR 570	15 PARKED MOTOR VEHICLE	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	4	0	3	0	0
25	89844823	SSOGIS	9/12/2020	740	SR 570	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
26	88361466	SSOGIS	9/12/2020	1455	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
27	88390054	SSOGIS	9/24/2020	1840	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
28	88390057	SSOGIS	9/27/2020	1500	SR 400	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
29	88162819	SSOGIS	10/18/2020	1701	I 4	SR 570	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
30	88378045	SSOGIS	10/21/2020	1131	SR 400	EB EXIT TO SR 570 R	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
31	88378048	SSOGIS	11/6/2020	1754	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
32	88355115	Signal Four Analytics	11/21/2020	12:05:00 PM	SR-400	SR570	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
33	88396607	SSOGIS	11/30/2020	514	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
34	88404046	SSOGIS	12/14/2020	1704	SR 400	MM 41	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
35	88396611	SSOGIS	12/22/2020	8	I 4	SR 570	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
36	85156101	SSOGIS	12/26/2020	100	SR 400	SR 33	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
37	88318921	SSOGIS	12/29/2020	417	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
38	88310671	SSOGIS	12/29/2020	550	SR 400	MM 41	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
39	88390088	SSOGIS	1/1/2021	2200	SR 570	SR 400	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	02 CLOUDY	1	0	0	0	0
40	88404056	SSOGIS	1/12/2021	2307	I 4	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
41	88328393	SSOGIS	1/29/2021	1535	SR 400	SR 570	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
42	88127694	SSOGIS	2/4/2021	2335	I 4	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	1	0	0	0
43	88127694	Signal Four Analytics	2/5/2021	11:35:00 PM	INTERSTATE 4 WB	STATE ROAD 570	Tree (standing)	Other	Dry	Dark - Lighted	Clear	1	1	0	0	0
44	88404076	SSOGIS	3/2/2021	636	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
45	88392891	Signal Four Analytics	3/11/2021	1:50:00 PM	SR-400	SR-570	Struck by Falling, Shifting Cargo	Other	Dry	Daylight	Clear	2	0	0	0	0
46	88374008	SSOGIS	4/9/2021	1855	SR 400	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	02 DUSK	03 RAIN	2	0	7	0	0
47	88408515	SSOGIS	6/6/2021	229	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
48	88445515	SSOGIS	6/9/2021	1036	I 4	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
49	24288758	SSOGIS	6/11/2021	1053	SR 570	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
50	88449322	Signal Four Analytics	6/17/2021	8:51:00 PM	STATE 4 (STATE ROAD	STATE ROAD 570	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
51	24289961	SSOGIS	6/19/2021	535	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	1	0	0
52	24289600	SSOGIS	6/26/2021	2011	I 4	SR 570	28 GUARDRAIL END	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
53	88457653	SSOGIS	7/16/2021	59	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
54	88529162	SSOGIS	8/11/2021	1448	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
55	88510227	SSOGIS	8/19/2021	1817	I 4	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
56	88499928	Signal Four Analytics	9/1/2021	9:35:00 AM	SR-570 EXIT RAMP	SR-400 WB MM 41	Other Post, Pole or Support	Other	Dry	Daylight	Cloudy	1	0	0	0	0
57	88472077	SSOGIS	10/3/2021	1457	I 4	SR 570	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
58	88472077	Signal Four Analytics	10/4/2021	2:57:00 PM	INTERSTATE 4	STATE ROAD 570	Tree (standing)	Other	Dry	Daylight	Clear	2	0	1	0	0
59	88519638	SSOGIS	10/14/2021	47	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
60	88293255	Signal Four Analytics	11/5/2021	9:40:00 AM	WB I-4	SR 570	Motor Vehicle in Transport	Angle	Wet	Daylight	Rain	2	0	1	0	0
61	88541632	SSOGIS	11/14/2021	543	I 4	MILE MARKER #41	19 IMPACT ATTENUATOR/CRASH CUSION	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
62	88493522	Signal Four Analytics	11/19/2021	3:56:00 PM	E ROAD 400(INTERSTA	SR 570	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	3	0	0
63	88493528	SSOGIS	12/9/2021	730	SR 400	SR 570	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	2	0	0	0	0
64	88579420	SSOGIS	12/12/2021	1141	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
65	88510255	SSOGIS	12/19/2021	354	I 4	MILE MARKER #41	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
66	88579424	SSOGIS	12/29/2021	259	SR 400	SR 570	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
67	24883899	SSOGIS	1/6/2022	1217	I 4	SR 570	27 GUARDRAIL FACE	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
68	88227863	Signal Four Analytics	1/14/2022	1:55:00 PM	NTRANCE RAMP WES	SR-400 WESTBOND	Overturn/Rollover	Other	Dry	Daylight	Clear	1	0	1	0	0
69	88551424	Signal Four Analytics	1/17/2022	8:55:00 PM	SR-400 WB MM40	MM40	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	5	0	0
70	24683954	SSOGIS	2/3/2022	855	SR 570	I 4	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
71	24913869	Signal Four Analytics	3/11/2022	3:49:00 PM	INTERSTATE 4(SR400)	SR570	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
72	24884824	SSOGIS	3/22/2022	1744	SR 400	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
73	24901838	SSOGIS	3/31/2022	545	I 4	SR 570	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
74	88587761	SSOGIS	5/3/2022	1355	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
75	24955077	SSOGIS	5/13/2022	1427	I 4	MILE MARKER #41	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0

Mainline Segment: I-4 from SR 570/Polk Parkway (East) to SR 559 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	89373921	SSOGIS	1/20/2020	1530	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
2	24137860	SSOGIS	1/30/2020	410	I 4	MILE MARKER #43	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
3	88262350	SSOGIS	2/4/2020	1940	I 4	MILE MARKER #42	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
4	88170914	SSOGIS	2/26/2020	1947	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	4	0	1	0	0
5	88184257	SSOGIS	3/5/2020	2200	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
6	88275160	SSOGIS	3/13/2020	2325	I 4	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
7	88194092	SSOGIS	3/31/2020	2100	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
8	88173832	SSOGIS	4/16/2020	1901	I 4	SR 559	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
9	88251187	SSOGIS	5/29/2020	1930	SR 400	MM 44	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
10	88275171	SSOGIS	6/3/2020	619	I 4	CR 655	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
11	88322506	SSOGIS	6/7/2020	159	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
12	88235068	SSOGIS	6/8/2020	1532	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
13	88322512	SSOGIS	6/22/2020	1928	I 4	SR 570	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
14	88308384	SSOGIS	7/3/2020	2335	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	02 CLOUDY	2	0	1	0	0
15	88262710	SSOGIS	7/14/2020	1610	SR 400	SR 570	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
16	88294651	SSOGIS	7/20/2020	1647	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
17	88285044	SSOGIS	8/13/2020	1728	SR 400	SR 33	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
18	88309212	SSOGIS	8/22/2020	2059	SR 400	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
19	88390043	SSOGIS	9/7/2020	1900	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	08 WATER (STANDING/MOVING)	01 DAYLIGHT	03 RAIN	2	0	2	0	0
20	88314729	SSOGIS	9/12/2020	1140	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	0	0	0
21	88184292	SSOGIS	9/13/2020	1200	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
22	88309223	SSOGIS	9/14/2020	1001	SR 400	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	3	0	0
23	88309304	SSOGIS	10/23/2020	1405	I 4	MILE MARKER #43	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
24	88319046	SSOGIS	10/31/2020	2130	SR 400	MM 43	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	1	0	2	0	0
25	88390072	SSOGIS	11/9/2020	1345	SR 400	SR 559	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	02 CLOUDY	3	0	0	0	0
26	88314880	SSOGIS	11/9/2020	1924	I 4	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
27	88322556	SSOGIS	11/27/2020	1815	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	2	0	0
28	24139642	SSOGIS	1/28/2021	1140	I 4	SR 33	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
29	88396617	SSOGIS	2/1/2021	942	I 4	SR 559	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
30	88390096	Signal Four Analytics	2/2/2021	9:50:00 AM	SR 400 (I-4)	SR-559	Other Non-Fixed Object	Other	Dry	Daylight	Clear	1	0	0	0	0
31	88396627	Signal Four Analytics	2/18/2021	12:47:00 PM	TE 4 (STATE ROAD 400	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	3	0	4	0	0
32	88468336	Signal Four Analytics	3/7/2021	4:30:00 PM	SR 400 (I-4)	SR-559	Struck by Falling, Shifting Cargo	Other	Dry	Daylight	Clear	1	0	0	0	0
33	88365081	Signal Four Analytics	4/11/2021	1:34:00 AM	TBOUND STATE ROAD	STATE ROAD 559	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
34	88310802	SSOGIS	4/15/2021	2000	SR 400	SR 559	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
35	88474556	SSOGIS	4/22/2021	540	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
36	88310806	Signal Four Analytics	5/2/2021	1:48:00 PM	STATE ROAD 400	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
37	88487192	SSOGIS	6/5/2021	1500	I 4	MILE MARKER #43	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
38	88462031	SSOGIS	6/11/2021	1913	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
39	88402162	SSOGIS	6/16/2021	1645	I 4	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
40	88415606	SSOGIS	6/23/2021	1900	I 4	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
41	88457651	SSOGIS	7/9/2021	2351	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
42	88487202	SSOGIS	7/9/2021	2045	I 4	SR 570	31 OTHER TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	0	0	0
43	88457657	SSOGIS	7/23/2021	2233	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
44	24291695	SSOGIS	8/28/2021	248	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
45	88471792	Signal Four Analytics	8/28/2021	6:47:00 AM	TBOUND STATE ROAD	STATE ROAD 559	Overturn/Rollover	Other	Dry	Dawn	Clear	1	0	0	0	0
46	88453231	SSOGIS	9/1/2021	1715	I 4	MILE MARKER #43	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
47	88482374	Signal Four Analytics	10/2/2021	9:50:00 AM	INTERSTATE 4(SR400)	SR570	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
48	24304081	Signal Four Analytics	10/3/2021	5:05:00 AM	I-4	SR-559	Cable Barrier	<Null>	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
49	88194441	SSOGIS	10/17/2021	1930	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	1	0	0	0
50	88479738	SSOGIS	10/19/2021	826	SR 400	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
51	88493525	SSOGIS	11/23/2021	1745	I 4	SR 570	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
52	24683607	SSOGIS	1/19/2022	51	I 4	MILE MARKER #42	01 OVERTURN/ROLLOVER	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
53	24683850	SSOGIS	2/6/2022	951	I 4	MILE MARKER #42	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	88568637	Signal Four Analytics	2/13/2022	3:24:00 AM	I-4 E	SR 559	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Not Lighted	Rain	2	0	0	0	0
55	24910007	Signal Four Analytics	2/14/2022	8:10:00 AM	TATE 4 (STATE ROAD 4	STATE ROAD 559	Other Non-Fixed Object	Other	Dry	Daylight	Clear	2	0	0	0	0
56	88468674	SSOGIS	2/19/2022	600	SR 400	SR 570	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
57	89580493	SSOGIS	3/11/2022	1034	I 4	MILE MARKER #42	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
58	88587755	Signal Four Analytics	4/4/2022	11:48:00 PM	I4	SR 559	Motor Vehicle in Transport	Other	Dry	Dark - Not Lighted	Clear	1	0	1	0	0
59	24939513	Signal Four Analytics	5/5/2022	7:43:00 AM	INTERSTATE 4(SR400)	SR559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
60	24910034	Signal Four Analytics	5/19/2022	5:07:00 PM	TATE 4 (STATE ROAD 4	STATE ROAD 559	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0

Interchange: I-4 at SR 559 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88250783	SSOGIS	2/3/2020	1922	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	5	0	0	0	0
2	88220083	SSOGIS	2/9/2020	305	I 4	SR 559	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
3	88173823	SSOGIS	2/18/2020	805	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
4	88166349	SSOGIS	2/25/2020	1840	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	02 DUSK	02 CLOUDY	2	0	0	0	0
5	89374924	SSOGIS	2/25/2020	821	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
6	85895888	SSOGIS	2/26/2020	1140	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
7	89841729	SSOGIS	2/29/2020	1432	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
8	88173826	SSOGIS	3/1/2020	1842	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	88 UNKNOWN	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
9	88226817	SSOGIS	3/6/2020	1539	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
10	89373841	SSOGIS	4/1/2020	911	SR 559	FRED JONES BLVD	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
11	88327819	SSOGIS	4/4/2020	1719	I 4	SR 559	24 CURB	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
12	88262703	SSOGIS	5/21/2020	1231	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
13	89843694	SSOGIS	6/8/2020	1731	I 4	MM 44	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
14	88234397	SSOGIS	6/11/2020	500	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
15	88233587	SSOGIS	6/12/2020	1508	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
16	89842729	SSOGIS	6/22/2020	1600	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
17	89844155	SSOGIS	6/29/2020	1354	I 4	MILE MARKER #44	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
18	89843495	SSOGIS	7/1/2020	1440	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
19	88215649	SSOGIS	7/4/2020	453	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
20	88314710	SSOGIS	7/22/2020	1713	I 4	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
21	88314711	SSOGIS	7/22/2020	1746	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
22	89844592	SSOGIS	7/23/2020	410	I 4	MILE MARKER #44	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
23	88234411	SSOGIS	7/28/2020	1923	SR 400	MILE MARKER #44	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	3	0	0	0	0
24	88312587	SSOGIS	7/31/2020	1900	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
25	88312587	Signal Four Analytics	8/1/2020	7:00:00 PM	SR 400 EB EXIT RAMP	SR 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
26	88309197	SSOGIS	8/6/2020	1508	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
27	88310647	SSOGIS	8/9/2020	2230	SR 400	MM 44	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
28	88294657	SSOGIS	8/11/2020	1236	I 4	SR 559	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
29	88314717	Signal Four Analytics	8/13/2020	7:40:00 PM	STATE 4 (STATE ROAD	STATE ROAD 559	Fence	Other	Wet	Daylight	Rain	1	0	0	0	0
30	88184288	SSOGIS	8/16/2020	10	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
31	88175108	SSOGIS	8/19/2020	1450	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
32	88175109	SSOGIS	8/19/2020	1453	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
33	89844545	SSOGIS	8/27/2020	1105	SR 559	I 4	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
34	88322536	SSOGIS	8/31/2020	1754	I 4	MILE MARKER #44	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
35	89845338	SSOGIS	9/2/2020	420	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
36	89845457	SSOGIS	9/6/2020	1713	I 4	SR 559	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
37	88262397	SSOGIS	9/11/2020	1130	I 4	SR 559	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
38	88378037	SSOGIS	9/14/2020	53	SR 559	SR 400	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
39	88319036	SSOGIS	9/19/2020	1855	SR 400	MM 44	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
40	88390053	Signal Four Analytics	9/20/2020	6:55:00 PM	SR-400 (I-4)	SR-559	Tree (standing)	Other	Wet	Daylight	Cloudy	1	0	0	0	0
41	88285055	SSOGIS	9/21/2020	1054	SR 400	SR 559	17 STRUCK BY FALLING, SHIFTING CA	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
42	88369168	SSOGIS	9/26/2020	1955	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	04 DARK-LIGHTED	02 CLOUDY	2	0	1	0	0
43	88369168	Signal Four Analytics	9/27/2020	7:55:00 PM	TE ROAD 400) EXIT RA	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Cloudy	2	0	1	0	0
44	89846182	SSOGIS	9/28/2020	2034	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
45	88314734	SSOGIS	10/3/2020	850	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
46	88369171	SSOGIS	10/7/2020	1238	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
47	88369171	Signal Four Analytics	10/8/2020	12:38:00 PM	(STATE ROAD 400) EXI	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
48	24136063	SSOGIS	10/9/2020	1335	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
49	24136416	SSOGIS	10/19/2020	338	SR 559	BAY LAKE RESORT DR	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
50	88369176	SSOGIS	10/19/2020	745	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
51	24136762	SSOGIS	10/23/2020	1605	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
52	24136120	SSOGIS	10/24/2020	1311	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
53	88262278	SSOGIS	10/30/2020	623	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
54	88322552	SSOGIS	10/31/2020	2352	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	2	0	0
55	88285062	SSOGIS	11/8/2020	612	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
56	88328374	SSOGIS	11/10/2020	830	SR 400	SR 559	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
57	88404033	SSOGIS	11/10/2020	904	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	3	0	0	0	0
58	24137470	SSOGIS	11/12/2020	1912	SR 559	I 4	25 DITCH	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
59	24137267	SSOGIS	11/17/2020	50	I 4	MILE MARKER #44	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
60	24137633	SSOGIS	11/27/2020	2020	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	1	0	0
61	88404039	SSOGIS	12/5/2020	1910	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
62	84892106	SSOGIS	12/15/2020	2038	SR 400	SR 559	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
63	88355132	Signal Four Analytics	12/16/2020	3:50:00 PM	SR-400 EXIT RAMP	CR-559	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
64	24138700	SSOGIS	12/18/2020	1936	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
65	85896273	SSOGIS	12/18/2020	1800	SR 559	FRED JONES BLVD	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
66	85156099	SSOGIS	12/22/2020	346	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
67	24138887	SSOGIS	12/28/2020	2022	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
68	88392881	SSOGIS	1/23/2021	1055	SR 559	SR 400	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
69	88359463	Signal Four Analytics	1/24/2021	12:15:00 PM	STATE 4 (STATE ROAD	STATE ROAD 559	Ditch	Other	Dry	Daylight	Clear	1	0	0	0	0
70	88404069	SSOGIS	1/29/2021	33	SR 400	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
71	87251595	Signal Four Analytics	2/3/2021	6:52:00 PM	TE ROAD 400 EXIT RA	SR 559	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
72	24140184	SSOGIS	3/3/2021	211	SR 559	CR 557A	10 PEDESTRIAN	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	1	0	1	0
73	88468334	Signal Four Analytics	3/5/2021	4:35:00 PM	400 (I-4) EB EXIT RAN	SR-559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	2	0	0
74	88468337	Signal Four Analytics	3/7/2021	8:30:00 PM	SR-400 (I-4) WB	SR-559	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
75	88398998	Signal Four Analytics	3/19/2021	7:36:00 AM	STATE ROAD 559	INTERSTATE 4 (STATE ROAD 400)	Motor Vehicle in Transport	Front to Front	Dry	Daylight	Clear	2	0	2	0	0
76	88474548	SSOGIS	4/2/2021	1239	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
77	88306779	Signal Four Analytics	4/8/2021	5:55:00 PM	ATE 4(SR 400) WB EX	STATE ROAD 559(SR 559)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
78	88399003	Signal Four Analytics	4/8/2021	6:03:00 PM	STATE 4 (STATE ROAD	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
79	88449311	SSOGIS	4/15/2021	813	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	2	0	1	0	0
80	88399008	SSOGIS	4/22/2021	2340	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
81	88162829	SSOGIS	5/14/2021	457	SR 559	BAY LAKE RESORT DR	24 CURB	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
82	88431614	Signal Four Analytics	5/19/2021	9:00:00 PM	SR-400 EXIT RAMP	SR-559	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Lighted	Clear	2	0	0	0	0
83	88493989	Signal Four Analytics	6/11/2021	7:25:00 AM	INTERSTATE 4(SR 400)	STATE ROAD(SR 570)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	1	0	0
84	88493992	SSOGIS	6/12/2021	606	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	1	0	0
85	88412155	Signal Four Analytics	6/13/2021	6:44:00 AM	STATE 4 (STATE ROAD	STATE ROAD 559	Parked Motor Vehicle	Sideswipe, Same Direction	Dry	Dawn	Clear	2	0	1	0	0
86	88525148	Signal Four Analytics	6/15/2021	5:38:00 PM	T RAMP FROM I-4 TO	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
87	88493998	SSOGIS	6/23/2021	1817	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
88	88487197	SSOGIS	6/23/2021	700	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
89	88374314	SSOGIS	6/23/2021	2240	I 4	MILE MARKER #43	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	3	0	7	0	0

Interchange: I-4 at SR 559 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
90	88449325	Signal Four Analytics	6/24/2021	6:22:00 PM	STATE 4 (STATE ROAD	STATE ROAD 559	Motor Vehicle in Transport	Other	Wet	Dawn	Rain	2	0	0	0	0
91	88449336	SSOGIS	7/6/2021	429	I 4	SR 559	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
92	88487201	SSOGIS	7/6/2021	655	I 4	SR 559	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	1	0	0
93	88293245	Signal Four Analytics	7/14/2021	3:00:00 PM	EB I-4 EXIT RAMP	SR 559	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	1	0	0
94	88454946	SSOGIS	7/18/2021	1540	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
95	88510222	SSOGIS	7/26/2021	1114	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
96	88428803	SSOGIS	7/28/2021	1400	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
97	24291312	Signal Four Analytics	8/1/2021	2:20:00 AM	HWY 559	0	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
98	24290607	SSOGIS	8/3/2021	1650	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
99	24290610	SSOGIS	8/3/2021	1650	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
100	88487216	Signal Four Analytics	8/26/2021	6:40:00 AM	STATE ROAD 559	INTERSTATE 4 (STATE ROAD 400)	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	1	0	0
101	88525179	SSOGIS	8/29/2021	2249	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	0	0	0
102	88568620	Signal Four Analytics	9/14/2021	9:00:00 AM	I-4 E	SR 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
103	88491130	Signal Four Analytics	10/8/2021	6:37:00 AM	SR-400(I-4)	STATE ROAD-559	Motor Vehicle in Transport	Other	Other	Dark - Lighted	Clear	2	0	0	0	0
104	24291654	SSOGIS	10/11/2021	1737	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
105	24291654	Signal Four Analytics	10/12/2021	5:37:00 PM	00 EB EXIT RAMP TO S	SR 559	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	1	0	0	0	0
106	24680529	Signal Four Analytics	10/19/2021	12:03:00 AM	HWY 559	0	Motor Vehicle in Transport	Angle	Dry	Dark - Not Lighted	Clear	2	0	3	0	0
107	88527588	SSOGIS	10/24/2021	115	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	2	0	0
108	88579410	Signal Four Analytics	10/29/2021	8:55:00 AM	STATE ROAD 559	WB EXIT RAMP FROM SR-400	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	1	0	0
109	88513135	SSOGIS	11/4/2021	410	I 4	SR 559	27 GUARDRAIL FACE	88 UNKNOWN	02 WET	02 DUSK	03 RAIN	2	0	0	0	0
110	88497947	Signal Four Analytics	11/5/2021	6:15:00 AM	4 EXIT RAMP EB CR 55	CR 559	Motor Vehicle in Transport	Front to Rear	Wet	Dark - Lighted	Rain	2	0	0	0	0
111	24681121	Signal Four Analytics	11/12/2021	2:51:00 PM	HWY 559	0	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
112	88293257	SSOGIS	11/14/2021	1407	SR 559	I 4	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
113	88529176	Signal Four Analytics	11/22/2021	6:12:00 AM	ENTRANCE RAMP MM	SR 559	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Fog, Smog, Smoke	2	0	0	0	0
114	24881601	Signal Four Analytics	12/19/2021	6:43:00 PM	SR559	INTERSTATE 4(SR400)	Motor Vehicle in Transport	Angle	Dry	Dark - Lighted	Clear	2	0	0	0	0
115	88493556	Signal Four Analytics	12/28/2021	8:21:00 PM	STATE 4 (STATE ROAD	STATE ROAD 559	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Lighted	Clear	2	0	0	0	0
116	24682858	SSOGIS	1/2/2022	2020	SR 559	I 4	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
117	24683219	SSOGIS	1/9/2022	1723	I 4	MILE MARKER #44	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
118	88405051	SSOGIS	1/15/2022	800	I 4	MILE MARKER #44	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
119	88162837	Signal Four Analytics	1/19/2022	11:43:00 AM	TBOUND I-4 RAMP EX	STATE ROAD 559	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	1	0	0
120	24895952	Signal Four Analytics	2/13/2022	6:35:00 PM	4 (SR 400) EB EXIT RA	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	2	0	0
121	25108383	SSOGIS	2/14/2022	1345	I 4	MILE MARKER #44	19 IMPACT ATTENUATOR/CRASH CUSION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
122	25108221	SSOGIS	2/22/2022	2143	I 4	SR 559	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
123	24906183	SSOGIS	3/11/2022	1025	I 4	SR 559	09 OTHER NON-COLLISION	88 UNKNOWN	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
124	24884822	Signal Four Analytics	3/18/2022	5:53:00 PM	EXIT RAMP 44	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	2	0	0
125	24934793	SSOGIS	4/1/2022	1849	SR 400	SR 559	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
126	25109201	SSOGIS	4/6/2022	1630	SR 559	BAY LAKE RESORT DR	33 UTILITY POLE/LIGHT SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
127	24901958	SSOGIS	4/6/2022	1440	I 4	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
128	24927666	Signal Four Analytics	4/30/2022	3:41:00 PM	NTERSTATE 4 EXIT RAM	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	2	0	0
129	24907575	Signal Four Analytics	5/16/2022	3:41:00 PM	STATE 4 (STATE ROAD	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0

Mainline Segment: I-4 from SR 559 to SR 557 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88140512	SSOGIS	1/1/2020	2316	SR 400	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
2	88253844	Signal Four Analytics	1/6/2020	9:30:00 PM	SR 400 (I-4)	SR 559 (EXIT 44)	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
3	88253848	SSOGIS	1/15/2020	2215	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
4	88170512	SSOGIS	1/19/2020	1220	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
5	88142670	SSOGIS	1/20/2020	1541	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
6	88230906	SSOGIS	1/24/2020	2111	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	4	0	0
7	88142675	SSOGIS	1/29/2020	1122	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
8	88168961	SSOGIS	2/3/2020	2222	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
9	88235042	SSOGIS	2/3/2020	1724	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
10	88275147	SSOGIS	2/14/2020	1245	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
11	88170911	SSOGIS	2/25/2020	1555	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
12	88233563	SSOGIS	3/12/2020	1417	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
13	88251179	SSOGIS	4/5/2020	1740	SR 400	MM 48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
14	88226826	SSOGIS	4/16/2020	143	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
15	88226827	SSOGIS	4/18/2020	2245	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
16	88250808	SSOGIS	6/5/2020	1720	SR 400	MM 46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
17	88250809	SSOGIS	6/5/2020	2045	SR 400	MM 46	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
18	88234396	SSOGIS	6/5/2020	2024	I 4	SR 559	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
19	88250811	SSOGIS	6/7/2020	2118	SR 400	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
20	88310635	SSOGIS	6/22/2020	810	SR 400	MM 46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
21	88234401	SSOGIS	7/1/2020	1534	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
22	89844588	SSOGIS	7/17/2020	920	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
23	88312585	SSOGIS	7/17/2020	1819	SR 400	MILE MARKER #47	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
24	88310640	SSOGIS	7/20/2020	2015	SR 400	MM 46	10 PEDESTRIAN	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
25	88294652	SSOGIS	7/23/2020	1933	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
26	88262388	Signal Four Analytics	7/24/2020	3:40:00 AM	I-4 W	CR 557	Traffic Sign Support	Other	Wet	Dark - Not Lighted	Rain	1	0	0	0	0
27	88294653	SSOGIS	7/27/2020	1444	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
28	89843647	SSOGIS	8/4/2020	1705	I 4	MILE MARKER #46	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
29	88262259	SSOGIS	8/13/2020	428	I 4	CR 557A	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
30	89845138	SSOGIS	8/13/2020	545	I 4	MILE MARKER #45	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
31	88309207	SSOGIS	8/16/2020	1500	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
32	88322532	SSOGIS	8/21/2020	135	I 4	SR 559	29 CABLE BARRIER	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
33	88215654	SSOGIS	8/29/2020	1800	I 4	MILE MARKER #47	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
34	88314726	Signal Four Analytics	9/5/2020	12:19:00 PM	STATE 4 (STATE ROAD	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
35	88294666	SSOGIS	9/14/2020	1631	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
36	88285061	SSOGIS	10/25/2020	1327	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	2	0	0
37	88253809	SSOGIS	10/28/2020	2114	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
38	88285064	SSOGIS	11/15/2020	632	SR 400	SR 559	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
39	88253814	SSOGIS	12/4/2020	2253	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	2	0	0	0	0
40	24137918	SSOGIS	12/13/2020	1340	I 4	MILE MARKER #47	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
41	88404053	SSOGIS	12/30/2020	832	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
42	88312624	SSOGIS	1/15/2021	1845	SR 400	MILE MARKER #47	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	2	0	0
43	88335714	Signal Four Analytics	1/27/2021	4:46:00 AM	TERSTATE 4 WB EXIT	CR 557	Other Post, Pole or Support	Other	Wet	Dark - Not Lighted	Fog, Smog, Smoke	1	0	1	0	0
44	88359467	Signal Four Analytics	2/5/2021	11:00:00 AM	STATE 4 (STATE ROAD	STATE ROAD 559	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
45	88390098	Signal Four Analytics	2/7/2021	7:15:00 AM	SR 400 (I-4) EB	CR-557 (OLD GRADE RD)	Cable Barrier	Other	Wet	Dawn	Rain	1	0	0	0	0
46	88390104	SSOGIS	2/10/2021	600	SR 400	CR 557	30 CONCRETE TRAFFIC BARRIER	04 SIDESWIPE, SAME DIRECTION	01 DRY	04 DARK-LIGHTED	04 FOG, SMOG, SMOKE	2	0	0	0	0
47	88308452	Signal Four Analytics	2/14/2021	8:37:00 AM	TBOUND STATE ROAD	STATE ROAD 559	Overturn/Rollover	Other	Wet	Daylight	Rain	1	0	0	0	0
48	88262290	SSOGIS	2/26/2021	2200	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	3	0	5	0	0
49	24288114	SSOGIS	4/8/2021	2145	I 4	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
50	88365065	SSOGIS	4/10/2021	1220	I 4	CR 557A	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
51	88493977	Signal Four Analytics	4/25/2021	8:09:00 AM	NTERSTATE 4(SR 400	COUNTY ROAD 557(CR 557)	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
52	24288631	SSOGIS	5/1/2021	1237	SR 400	MILE MARKER #45	06 FELL/JUMPED FROM MOTOR VEHICLE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
53	88471763	SSOGIS	6/19/2021	917	SR 400	SR 559	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
54	88471764	SSOGIS	6/22/2021	1940	I 4	REST AREA	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
55	88493997	Signal Four Analytics	6/23/2021	3:08:00 PM	ATE 4(SR 400) WB EX	COUNTY ROAD 557(CR 557)	Other Non-Collision	Other	Dry	Daylight	Cloudy	1	0	1	0	0
56	24290378	SSOGIS	6/30/2021	2224	I 4	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	04 DARK-LIGHTED	01 CLEAR	2	0	2	0	0
57	24290438	SSOGIS	7/6/2021	526	I 4	MILE MARKER #47	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
58	88471782	SSOGIS	8/3/2021	1701	SR 400	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
59	88471788	Signal Four Analytics	8/12/2021	4:22:00 PM	TBOUND STATE ROAD	STATE ROAD 559	Other Non-Collision	Other	Wet	Daylight	Rain	1	0	0	0	0
60	88510228	SSOGIS	8/19/2021	1905	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
61	88479730	SSOGIS	8/31/2021	1311	SR 400	SR 559	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
62	88470259	SSOGIS	11/12/2021	244	SR 400	MILE MARKER #47	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	5	0	0
63	24906176	SSOGIS	2/8/2022	2001	I 4	MM 48	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	1	0	0
64	24910011	Signal Four Analytics	2/20/2022	5:58:00 PM	TATE 4 (STATE ROAD 4	STATE ROAD 559	Motor Vehicle in Transport	Front to Rear	Dry	Dusk	Clear	2	0	1	0	0
65	25109359	SSOGIS	4/26/2022	2211	I 4	MILE MARKER #45	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
66	24940649	SSOGIS	4/28/2022	1750	I 4	SR 559	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
67	24910031	Signal Four Analytics	5/5/2022	7:06:00 AM	TATE 4 (STATE ROAD 4	COUNTY ROAD 557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
68	24909369	SSOGIS	5/7/2022	1142	I 4	MILE MARKER #47	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
69	24935829	SSOGIS	5/12/2022	145	SR 400	MILE MARKER #46	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	04 DARK-LIGHTED	01 CLEAR	3	0	1	0	0

Interchange: I-4 at SR 557 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88262341	SSOGIS	1/11/2020	1050	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
2	88275134	Signal Four Analytics	1/17/2020	12:25:00 PM	STATE 4 (STATE ROAD	COUNTY ROAD 557(OLD GRADE ROAD)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
3	89372914	SSOGIS	1/20/2020	636	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	02 DUSK	01 CLEAR	2	0	0	0	0
4	88262346	SSOGIS	1/23/2020	650	I 4	CR 557	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
5	88140517	SSOGIS	1/23/2020	712	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
6	88251172	SSOGIS	2/3/2020	1550	SR 400	MM 48	20 BRIDGE OVERHEAD STRUCTURE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
7	88171479	Signal Four Analytics	2/27/2020	5:51:00 PM	OLD GRADE ROAD	EASTBOUND SR 400 ENTRANCE RAMP	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
8	89372847	SSOGIS	3/8/2020	729	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
9	88233567	SSOGIS	3/30/2020	1138	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
10	88233575	SSOGIS	5/9/2020	2002	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
11	88308373	SSOGIS	5/12/2020	1555	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
12	88262242	SSOGIS	5/22/2020	1245	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
13	88162195	SSOGIS	6/4/2020	2220	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
14	88184278	SSOGIS	7/9/2020	725	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
15	89844548	SSOGIS	7/20/2020	141	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
16	88314709	SSOGIS	7/22/2020	1505	I 4	CR 557	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
17	88234408	SSOGIS	7/22/2020	1735	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
18	88262388	SSOGIS	7/23/2020	340	I 4	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
19	88322516	Signal Four Analytics	7/28/2020	8:02:00 AM	R-557 ENTRANCE RAM	EB I-4	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
20	88262255	SSOGIS	8/1/2020	1309	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	01 DAYLIGHT	03 RAIN	2	0	1	0	0
21	88184286	SSOGIS	8/8/2020	0	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
22	88294656	SSOGIS	8/11/2020	611	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
23	89845079	SSOGIS	8/15/2020	1320	I 4	CR 557	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
24	88319024	SSOGIS	8/24/2020	1000	SR 400	MM 48	20 BRIDGE OVERHEAD STRUCTURE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
25	88285049	SSOGIS	8/28/2020	2138	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
26	89845045	SSOGIS	8/29/2020	2045	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
27	88310650	SSOGIS	8/31/2020	140	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
28	88310650	Signal Four Analytics	9/1/2020	1:40:00 AM	R-400 EB EXIT 48 RAM	CR-557	Traffic Sign Support	Other	Wet	Dark - Not Lighted	Cloudy	1	0	0	0	0
29	88378038	SSOGIS	9/14/2020	526	SR 400	CR 557	34 TRAFFIC SIGN SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
30	88285054	SSOGIS	9/15/2020	645	SR 400	CR 557	04 JACKKNIFE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
31	88369164	SSOGIS	9/20/2020	1403	I 4	CR 557	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
32	88288835	SSOGIS	10/1/2020	746	I 4	CR 557	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
33	88262268	SSOGIS	10/1/2020	757	I 4	CR 557	09 OTHER NON-COLLISION	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	2	1	0
34	88288835	Signal Four Analytics	10/2/2020	7:46:00 AM	I-4 EXIT RAMP MM 48	CR 557	Other Post, Pole or Support	Other	Dry	Daylight	Clear	1	0	0	0	0
35	88288838	SSOGIS	10/3/2020	1320	I 4	CR 557	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
36	88322541	SSOGIS	10/3/2020	1445	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
37	88288838	Signal Four Analytics	10/4/2020	1:20:00 PM	I-4 EB EXIT RAMP 48	CR 557	Ditch	Other	Wet	Daylight	Rain	1	0	0	0	0
38	88253807	SSOGIS	10/10/2020	1141	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
39	24136132	SSOGIS	10/12/2020	1705	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
40	24136361	SSOGIS	10/17/2020	2320	I 4	CR 557	25 DITCH	02 FRONT TO FRONT	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
41	88349884	SSOGIS	10/17/2020	32	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
42	88288846	SSOGIS	11/3/2020	1730	I 4	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
43	88349892	SSOGIS	11/9/2020	550	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	02 CLOUDY	1	0	0	0	0
44	88308071	SSOGIS	11/24/2020	1515	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	6	0	0
45	88355122	SSOGIS	11/28/2020	803	SR 400	CR 557	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
46	88390077	SSOGIS	11/29/2020	1010	SR 400	CR 557	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
47	88355122	Signal Four Analytics	11/29/2020	8:03:00 AM	SR400 EXIT RAMP	CR-557	Ditch	Other	Dry	Daylight	Clear	1	0	0	0	0
48	88390077	Signal Four Analytics	11/30/2020	10:10:00 AM	400 (I-4) EXIT 48 RAN	CR-557 (OLD GRADE RD)	Other Fixed Object	Other	Wet	Daylight	Rain	1	0	0	0	0
49	88390079	SSOGIS	12/1/2020	825	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
50	88308075	SSOGIS	12/1/2020	1210	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
51	24137926	SSOGIS	12/7/2020	1728	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
52	88390082	Signal Four Analytics	12/8/2020	12:35:00 PM	SR 400 (I-4)	CR-557 (OLD GRADE RD)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
53	88355128	SSOGIS	12/10/2020	1214	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
54	24138374	SSOGIS	12/17/2020	2157	I 4	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
55	88322561	SSOGIS	12/18/2020	1428	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
56	88425405	SSOGIS	1/14/2021	1925	I 4	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	04 DARK-LIGHTED	03 RAIN	1	0	0	0	0
57	88359461	Signal Four Analytics	1/20/2021	6:45:00 PM	STATE 4 (STATE ROAD	COUNTY ROAD 557	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
58	88335714	SSOGIS	1/26/2021	446	I 4	CR 557	36 OTHER POST, POLE, OR SUPPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	04 FOG, SMOG, SMOKE	1	0	1	0	0
59	88408486	SSOGIS	3/1/2021	654	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
60	88308457	SSOGIS	3/9/2021	1416	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
61	88308460	Signal Four Analytics	3/17/2021	3:37:00 PM	TBOUND STATE ROAD	COUNTY ROAD 557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
62	88392897	SSOGIS	4/2/2021	104	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
63	88308465	Signal Four Analytics	4/8/2021	6:19:00 PM	TBOUND STATE ROAD	COUNTY ROAD 557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	1	0	0
64	88306781	Signal Four Analytics	4/10/2021	6:34:00 AM	INTERSTATE 4(SR 400	COUNTY ROAD 557(CR 557)	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	4	0	0	0	0
65	88493976	SSOGIS	4/21/2021	1424	I 4	CR 557	19 IMPACT ATTENUATOR/CRASH CUSION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	3	0	0
66	24287859	SSOGIS	4/27/2021	1411	SR 400	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
67	88374016	Signal Four Analytics	5/5/2021	5:45:00 AM	WB EXIT 48 ENTRANC	MM47	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	1	0	0
68	88493984	Signal Four Analytics	5/22/2021	11:45:00 AM	INTERSTATE 4(SR 400	COUNTY ROAD 557(CR 557)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
69	88454929	SSOGIS	6/3/2021	1344	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	2	0	0
70	88468648	SSOGIS	6/4/2021	2100	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	04 DARK-LIGHTED	03 RAIN	2	0	2	0	0
71	24289718	Signal Four Analytics	6/5/2021	4:05:00 PM	CR-557	INTERSTATE 4 E	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Rain	2	0	0	0	0
72	88493991	Signal Four Analytics	6/12/2021	6:54:00 AM	INTERSTATE 4(SR 400	COUNTY ROAD 557(CR 557)	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	3	0	0	0	0
73	88471762	Signal Four Analytics	6/17/2021	8:24:00 PM	TBOUND STATE ROAD	COUNTY ROAD 557	Other Non-Fixed Object	Other	Dry	Dark - Lighted	Clear	1	0	0	0	0
74	88493997	SSOGIS	6/22/2021	1508	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
75	24290100	SSOGIS	6/22/2021	1919	I 4	MILE MARKER #48	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	1	0	0
76	88529151	SSOGIS	6/29/2021	330	I 4	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	0	0	0
77	88494021	SSOGIS	8/7/2021	1017	SR 400	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
78	24291474	Signal Four Analytics	8/16/2021	6:40:00 PM	INTERSTATE 4	CR 557	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	1	0	0	0	0
79	88499918	SSOGIS	8/17/2021	733	SR 400	MILE MARKER #48	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
80	88510230	Signal Four Analytics	8/22/2021	4:46:00 PM	ROAD 557 (OLD GRAD	WB I-4 (STATE ROAD 400) EXIT RAMP	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	1	0	0
81	88453232	Signal Four Analytics	9/2/2021	7:00:00 PM	SB CR-557	INTERSTATE 4 ENT RAMP MM 48	Motor Vehicle in Transport	Sideswipe, Opposite Direction	Wet	Dusk	Rain	2	0	0	0	0
82	88454957	SSOGIS	9/18/2021	2146	I 4	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
83	24679720	SSOGIS	9/23/2021	550	SR 557	I 4	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
84	24681021	SSOGIS	10/27/2021	1945	I 4	MILE MARKER #48	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
85	88519640	Signal Four Analytics	11/3/2021	11:00:00 AM	STATE ROAD 400	COUNTY ROAD557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
86	88497948	SSOGIS	11/4/2021	830	I 4	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
87	88484401	SSOGIS	11/4/2021	1616	I 4	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	2	0	0
88	88487456	Signal Four Analytics	11/12/2021	9:00:00 AM	STATE 4 (STATE ROAD	COUNTY ROAD 557	Concrete Traffic Barrier	Other	Dry	Daylight	Clear	1	0	0	0	0
89	24682283	Signal Four Analytics	12/9/2021	9:10:00 AM	CR 557	SR 400 (I-4)	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0

Interchange: I-4 at SR 557 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
90	88519644	Signal Four Analytics	12/10/2021	3:02:00 PM	STATE ROAD 400	COUNTY ROAD 557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	3	0	0	0	0
91	88527598	SSOGIS	12/13/2021	1930	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
92	88588496	SSOGIS	12/20/2021	723	SR 400	MILE MARKER #48	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
93	24682720	Signal Four Analytics	12/21/2021	10:40:00 PM	CR 557	INTERSTATE 4	Motor Vehicle in Transport	Other	Wet	Dark - Not Lighted	Clear	1	0	0	0	0
94	88507231	SSOGIS	1/15/2022	810	I 4	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
95	24884808	Signal Four Analytics	1/21/2022	8:35:00 AM	TATE ROAD 400(INTER	STATE ROAD 557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
96	24885021	Signal Four Analytics	3/11/2022	10:48:00 PM	STATE ROAD 400	COUNTY ROAD 557	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
97	25110361	Signal Four Analytics	5/3/2022	11:20:00 AM	CR 557	SR 400 (I4) EB EXIT RAMP	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	2	0	0
98	24914826	Signal Four Analytics	5/21/2022	1:55:00 PM	I-4 EB EXIT RAMP 557	CR 557	Motor Vehicle in Transport	Other	Dry	Daylight	Clear	2	0	0	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
1	88142667	SSOGIS	1/2/2020	1403	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
2	88235033	SSOGIS	1/2/2020	1037	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
3	89373297	SSOGIS	1/2/2020	517	I 4	MILE MARKER #49	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	4	0	1	0	0
4	88168953	SSOGIS	1/6/2020	1931	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
5	88250771	SSOGIS	1/6/2020	1100	SR 400	MM 50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
6	88250780	SSOGIS	1/20/2020	734	I 4	MM 54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
7	88251168	SSOGIS	1/24/2020	1615	SR 400	MM 52	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
8	88220079	SSOGIS	1/26/2020	2355	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
9	89374214	SSOGIS	2/6/2020	1502	I 4	MM 51	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
10	88142681	SSOGIS	2/16/2020	845	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	3	0	0
11	88262357	SSOGIS	2/23/2020	1030	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
12	89374857	SSOGIS	2/27/2020	1805	I 4	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
13	88275153	SSOGIS	2/27/2020	818	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	0	0	0
14	88262360	SSOGIS	2/28/2020	1256	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
15	88175072	SSOGIS	2/28/2020	2220	SR 400	MM 49	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	1	0	0
16	89374385	SSOGIS	2/29/2020	351	I 4	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
17	88275155	SSOGIS	2/29/2020	850	I 4	US 27	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
18	89841733	SSOGIS	3/3/2020	820	I 4	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
19	88226816	SSOGIS	3/6/2020	1436	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
20	87188782	SSOGIS	3/12/2020	1520	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
21	89841870	SSOGIS	3/12/2020	2346	I 4	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
22	88190767	SSOGIS	3/16/2020	640	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	1	0	0
23	88314313	SSOGIS	3/26/2020	30	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
24	88173830	SSOGIS	4/12/2020	1306	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
25	88171482	SSOGIS	4/15/2020	1525	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
26	88327821	SSOGIS	4/23/2020	815	I 4	MILE MARKER #51	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
27	88253868	Signal Four Analytics	5/23/2020	3:25:00 PM	SR 400 (I-4)	CR 557 (EXIT 48)	Motor Vehicle in Transport	Angle	Dry	Daylight	Cloudy	2	0	0	0	0
28	88327825	SSOGIS	5/24/2020	2332	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
29	89842901	SSOGIS	5/24/2020	933	I 4	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
30	88215639	SSOGIS	5/24/2020	937	SR 400	MILE MARKER #52	15 PARKED MOTOR VEHICLE	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
31	88215637	SSOGIS	5/24/2020	725	SR 400	MM 52	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
32	88262243	SSOGIS	5/26/2020	1926	I 4	CR 557	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	1	0	0
33	88275172	SSOGIS	6/3/2020	705	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	2	0	0	0	0
34	88262245	SSOGIS	6/10/2020	1522	I 4	CR 557	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
35	88215643	SSOGIS	6/12/2020	2251	SR 400	MM 50	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
36	88308381	SSOGIS	6/19/2020	210	I 4	CR 557	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	0	1	0	0
37	89843910	SSOGIS	6/26/2020	2313	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	02 CLOUDY	3	0	0	0	0
38	88184277	SSOGIS	7/6/2020	1735	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
39	88294643	SSOGIS	7/7/2020	1207	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
40	88215650	SSOGIS	7/9/2020	607	SR 400	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	4	0	0	0	0
41	88314707	SSOGIS	7/17/2020	1305	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
42	88361439	SSOGIS	7/19/2020	1623	I 4	CR 557	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
43	88294650	SSOGIS	7/20/2020	1352	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
44	89844700	SSOGIS	7/21/2020	1718	SR 400	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
45	88309188	SSOGIS	7/22/2020	524	SR 400	US 92	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
46	88309189	SSOGIS	7/23/2020	536	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
47	88233594	SSOGIS	7/23/2020	340	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
48	88184285	SSOGIS	7/23/2020	810	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
49	89844586	SSOGIS	7/28/2020	625	I 4	MILE MARKER #50	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0
50	88262389	SSOGIS	7/29/2020	43	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
51	88262254	SSOGIS	7/31/2020	821	I 4	US 27	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
52	88322524	SSOGIS	8/5/2020	1018	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	3	0	0	0	0
53	88312588	SSOGIS	8/11/2020	1040	SR 400	MILE MARKER #51	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
54	88314718	SSOGIS	8/15/2020	1310	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	03 RAIN	2	0	0	0	0
55	89845262	SSOGIS	8/17/2020	25	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
56	88314722	SSOGIS	8/29/2020	600	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	1	0	0
57	88310649	SSOGIS	8/29/2020	2209	SR 400	MM 49	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
58	88312592	SSOGIS	8/30/2020	645	SR 400	MILE MARKER #49	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	03 DAWN	01 CLEAR	1	0	0	0	0
59	88294659	SSOGIS	9/4/2020	1527	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
60	88294664	SSOGIS	9/7/2020	2037	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	05 SIDESWIPE, OPPOSITE DIRECTION	02 WET	03 DAWN	02 CLOUDY	2	0	0	0	0
61	88262398	SSOGIS	9/12/2020	1005	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	01 DAYLIGHT	02 CLOUDY	3	0	1	0	0
62	88306760	SSOGIS	9/12/2020	320	SR 400	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
63	88314731	SSOGIS	9/22/2020	1957	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
64	88262272	SSOGIS	10/6/2020	1336	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
65	88294674	SSOGIS	10/20/2020	240	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
66	88314741	SSOGIS	10/28/2020	2203	I 4	US 27	29 CABLE BARRIER	04 SIDESWIPE, SAME DIRECTION	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
67	89846092	SSOGIS	10/31/2020	2312	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
68	24136281	SSOGIS	11/1/2020	1845	I 4	MILE MARKER #54	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
69	88306769	Signal Four Analytics	11/1/2020	8:40:00 AM	SR-400	CR-557	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
70	88314878	SSOGIS	11/8/2020	1853	SR 400	CR 557	37 FENCE	77 OTHER (SEE NARRATIVE)	02 WET	03 DAWN	03 RAIN	1	0	0	0	0
71	88312611	SSOGIS	11/10/2020	2354	SR 400	MM 52	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
72	88322555	SSOGIS	11/14/2020	2202	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
73	24136217	SSOGIS	11/19/2020	1400	I 4	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	1	0	0
74	88390074	SSOGIS	11/20/2020	1400	SR 400	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
75	88309306	SSOGIS	11/23/2020	830	SR 400	MILE MARKER #49	29 CABLE BARRIER	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
76	88262281	Signal Four Analytics	11/25/2020	2:15:00 PM	INTERSTATE 4(SR 400	COUNTY ROAD 557(CR 557)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
77	88314886	SSOGIS	11/29/2020	1133	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
78	88308076	SSOGIS	12/3/2020	645	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
79	88383400	SSOGIS	12/6/2020	1155	SR 400	MM 54	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	02 CLOUDY	1	0	0	0	0
80	88404041	SSOGIS	12/7/2020	1829	I 4	US 92	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	1	0	0
81	88308079	SSOGIS	12/11/2020	1330	I 4	US 27	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
82	24138445	SSOGIS	12/11/2020	1540	I 4	MILE MARKER #51	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
83	88314891	SSOGIS	12/16/2020	559	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	2	0	0	0	0
84	24138682	SSOGIS	12/18/2020	1401	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	4	0	3	0	0
85	88309312	SSOGIS	12/19/2020	2257	SR 400	MILE MARKER #52	39 OTHER FIXED OBJECT (WALL, BUIL	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	2	0	0	0	0
86	24137890	SSOGIS	12/21/2020	2005	I 4	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	0	0	0
87	88314894	SSOGIS	12/25/2020	1342	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
88	88445444	SSOGIS	12/26/2020	1412	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
89	88318922	SSOGIS	12/31/2020	115	SR 400	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0

Mainline Segment: I-4 from SR 557 to West of US 27 (January 2020 - May 2022)

#	HSMV Report Number	Data Source	Crash Date	Crash Time	Crash Street	Intersecting Street	First Harmful Event	Impact Type	Roadway Surface Conditions	Lighting Conditions	Weather Conditions	Vehicles	Fatalities	Injuries	Pedestrians	Bicyclists
90	88390087	SSOGIS	1/1/2021	150	SR 400	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	2	0	0
91	88390089	SSOGIS	1/9/2021	306	SR 400	SR 25	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	1	1	0	0
92	88408471	SSOGIS	1/22/2021	2053	SR 400	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
93	24139873	SSOGIS	2/6/2021	427	I 4	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	2	0	0	0	0
94	24139409	SSOGIS	2/6/2021	2344	I 4	MILE MARKER #50	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	1	0	0
95	88390100	Signal Four Analytics	2/8/2021	7:20:00 AM	SR 400 (I-4)	CR-557 (OLD GRADE RD)	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
96	88359470	SSOGIS	2/12/2021	953	I 4	US 27	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
97	88359472	Signal Four Analytics	2/13/2021	11:38:00 AM	STATE 4 (STATE ROAD	COUNTY ROAD 557	Motor Vehicle in Transport	Front to Rear	Wet	Daylight	Cloudy	2	0	0	0	0
98	88328400	SSOGIS	2/20/2021	2320	SR 400	SR 25	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
99	87251606	Signal Four Analytics	3/5/2021	3:26:00 PM	I-4 E	CR 557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	3	0	0
100	87251612	Signal Four Analytics	3/15/2021	12:27:00 PM	I-4 E	CR557	Ran into Water/Canal	Other	Dry	Daylight	Clear	1	0	0	0	0
101	88392899	Signal Four Analytics	4/3/2021	9:50:00 PM	SR400	US-27	Animal	Other	Dry	Dark - Not Lighted	Clear	1	0	0	0	0
102	88308464	SSOGIS	4/7/2021	1622	SR 400	CR 557	27 GUARDRAIL FACE	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
103	88365083	Signal Four Analytics	4/15/2021	3:31:00 PM	TBOUND STATE ROAD	COUNTY ROAD 557	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Daylight	Clear	2	0	0	0	0
104	88365087	SSOGIS	4/24/2021	857	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
105	88493978	SSOGIS	4/24/2021	1218	I 4	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	1	0	0
106	88310805	Signal Four Analytics	4/27/2021	5:40:00 PM	STATE ROAD 400	US HIGHWAY27	Other Non-Collision	Other	Dry	Daylight	Clear	4	0	1	0	0
107	88399009	Signal Four Analytics	4/30/2021	11:00:00 PM	STATE 4 (STATE ROAD	COUNTY ROAD 557	Motor Vehicle in Transport	Sideswipe, Same Direction	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
108	88431612	SSOGIS	5/11/2021	1800	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
109	88408507	SSOGIS	5/14/2021	205	SR 400	US 27	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	04 DARK-LIGHTED	01 CLEAR	1	0	0	0	0
110	88430526	SSOGIS	5/23/2021	1150	SR 400	CR 557	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
111	88402156	SSOGIS	5/28/2021	855	I 4	US 27	29 CABLE BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
112	88499893	SSOGIS	6/4/2021	1616	I 4	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	02 WET	01 DAYLIGHT	03 RAIN	2	0	2	0	0
113	88518789	SSOGIS	6/8/2021	520	I 4	US 27	37 FENCE	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
114	88399018	SSOGIS	6/10/2021	1125	I 4	US 27	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
115	24290072	SSOGIS	6/17/2021	1959	I 4	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	02 DUSK	02 CLOUDY	2	0	3	0	0
116	24288974	Signal Four Analytics	6/22/2021	3:03:00 PM	SR 400 EB	HWY 27	Impact Attenuator/Crash Cushion	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
117	88449329	SSOGIS	6/26/2021	900	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	4	0	0
118	88462038	SSOGIS	6/28/2021	1928	I 4	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	02 WET	02 DUSK	03 RAIN	1	0	0	0	0
119	24290167	SSOGIS	6/28/2021	1735	SR 400	US 27	14 MOTOR VEHICLE IN TRANSPORT	02 FRONT TO FRONT	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
120	88457652	SSOGIS	7/13/2021	2340	I 4	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
121	88471781	Signal Four Analytics	7/28/2021	5:22:00 PM	TBOUND STATE ROAD	COUNTY ROAD 557	Motor Vehicle in Transport	Angle	Dry	Daylight	Clear	2	0	0	0	0
122	24290946	SSOGIS	8/15/2021	354	I 4	MILE MARKER #52	25 DITCH	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
123	24291548	SSOGIS	8/26/2021	201	I 4	MILE MARKER #51	14 MOTOR VEHICLE IN TRANSPORT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
124	24290437	SSOGIS	9/14/2021	1600	I 4	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	1	0	1	0	0
125	88453052	SSOGIS	9/17/2021	802	SR 400	US 27	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
126	88454958	SSOGIS	9/19/2021	2125	I 4	CR 557	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	2	2	0	0
127	24291558	SSOGIS	9/24/2021	1545	SR 400	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
128	88579405	SSOGIS	10/9/2021	1703	SR 400	CR 557	30 CONCRETE TRAFFIC BARRIER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	02 CLOUDY	4	0	5	0	0
129	88499945	SSOGIS	10/25/2021	703	SR 400	MILE MARKER #54	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	03 DAWN	01 CLEAR	3	0	4	0	0
130	89844282	Signal Four Analytics	10/29/2021	5:15:00 PM	INTERSTATE 4	CR 557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Clear	2	0	0	0	0
131	88479744	SSOGIS	11/4/2021	400	SR 400	CR 557	30 CONCRETE TRAFFIC BARRIER	88 UNKNOWN	02 WET	05 DARK-NOT LIGHTED	03 RAIN	1	0	0	0	0
132	88487455	Signal Four Analytics	11/11/2021	12:30:00 PM	STATE 4 (STATE ROAD	COUNTY ROAD 557	Motor Vehicle in Transport	Front to Rear	Dry	Daylight	Cloudy	2	0	0	0	0
133	88513137	SSOGIS	11/23/2021	100	I 4	CR 557	29 CABLE BARRIER	88 UNKNOWN	01 DRY	02 DUSK	01 CLEAR	1	0	1	0	0
134	88511616	SSOGIS	12/11/2021	1238	SR 400	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	0	0	0
135	88588495	SSOGIS	12/12/2021	1323	SR 400	SR 25	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	01 CLEAR	2	0	0	0	0
136	88405050	SSOGIS	1/9/2022	1540	SR 400	MM 52	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	0	0	0	0
137	89591053	SSOGIS	1/14/2022	1547	I 4	MILE MARKER #53	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	01 DAYLIGHT	01 CLEAR	5	0	0	0	0
138	24683823	SSOGIS	1/24/2022	1020	I 4	US 27	32 TREE (STANDING)	77 OTHER (SEE NARRATIVE)	02 WET	01 DAYLIGHT	03 RAIN	1	1	1	0	0
139	89586710	SSOGIS	2/15/2022	1801	SR 400	MM 54	09 OTHER NON-COLLISION	77 OTHER (SEE NARRATIVE)	01 DRY	01 DAYLIGHT	01 CLEAR	1	0	1	0	0
140	24885015	Signal Four Analytics	2/17/2022	11:38:00 PM	STATE ROAD 400	COUNTY ROAD 557	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
141	25108628	Signal Four Analytics	2/27/2022	4:25:00 AM	SR 400 WB	US HWY 27	Overturn/Rollover	Other	Dry	Dark - Not Lighted	Fog, Smog, Smoke	1	0	1	0	0
142	24885018	Signal Four Analytics	3/3/2022	4:53:00 AM	STATE ROAD 400	COUNTY ROAD 557	Motor Vehicle in Transport	Front to Rear	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
143	24885019	Signal Four Analytics	3/5/2022	2:45:00 AM	STATE ROAD 400	COUNTY ROAD 557	Motor Vehicle in Transport	Angle	Dry	Dark - Not Lighted	Clear	2	0	0	0	0
144	24916738	SSOGIS	3/7/2022	804	I 4	MM 50	14 MOTOR VEHICLE IN TRANSPORT	04 SIDESWIPE, SAME DIRECTION	01 DRY	01 DAYLIGHT	02 CLOUDY	2	0	1	0	0
145	25108813	SSOGIS	3/17/2022	133	I 4	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	01 FRONT TO REAR	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	2	0	2	0	0
146	25109859	SSOGIS	4/4/2022	835	SR 400	MILE MARKER #52	14 MOTOR VEHICLE IN TRANSPORT	03 ANGLE	01 DRY	01 DAYLIGHT	04 FOG, SMOG, SMOKE	2	0	0	0	0
147	25109965	SSOGIS	4/6/2022	1928	I 4	US 27	01 OVERTURN/ROLLOVER	77 OTHER (SEE NARRATIVE)	01 DRY	02 DUSK	01 CLEAR	1	2	1	0	0
148	25110157	SSOGIS	4/20/2022	1	I 4	MILE MARKER #51	18 OTHER NON-FIXED OBJECT	77 OTHER (SEE NARRATIVE)	01 DRY	05 DARK-NOT LIGHTED	01 CLEAR	1	0	0	0	0
149	24945430	SSOGIS	5/19/2022	2248	I 4	CR 557	25 DITCH	77 OTHER (SEE NARRATIVE)	02 WET	05 DARK-NOT LIGHTED	02 CLOUDY	1	0	1	0	0

Appendix B – Additional Crash Data Maps

N

0 0.25 0.5 Miles

BEGIN STUDY

INTERSTATE 4

TOLL 570


POLK PKWY

92

COUNTY LINE RD

ALLEN K BREED HWY

OLD TAMPA HWY/CR542



Sheet 1 of 22

FDOT


Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 2 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

N GALLOWAY RD

W 10TH ST

WABASH AVE

W MEMORIAL BLVD

INTERSTATE 4

546

92

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 3 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

KNIGHTS STATION RD

GRIFFIN RD

KATHLEEN RD

PROVIDENCE RD

INTERSTATE 4


539

W 10TH ST

WABASH AVE

N BRUNNELL PKWY

N GALLOWAY RD



Sheet 4 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

98

INTERSTATE 4

33

LAKELAND HILLS BLVD


GRIFFIN RD

N FLORIDA AVE

KATHLEEN RD

PROVIDENCE RD

539



Sheet 5 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


0 0.25 0.5 Miles

98

33

INTERSTATE 4

LAKELAND HILLS BLVD



Sheet 6 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


0 0.25 0.5 Miles

N SOCRUM LOOP RD

INTERSTATE 4

33

OLD COMBEE RD



Sheet 7 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


0 0.25 0.5 Miles

N SOCRUM LOOP RD

OLD POLK CITY RD

INTERSTATE 4

33




Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 9 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


Miles
0 0.25 0.5

OLD POLK CITY RD

33

INTERSTATE 4

UNIVERSITY BLVD



Sheet 10 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles


OLD POLK CITY RD

33

INTERSTATE 4

RESEARCH WAY

UNIVERSITY BLVD



Sheet 11 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

OLD POLK CITY RD

33


INTERSTATE 4

MOUNT OLIVE RD

POLK PKWY

TOLL 570

RESEARCH WAY



Sheet 12 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

INTERSTATE 4


MOUNT OLIVE RD

BERKLEY RD/SR-559

559

POLK PKWY

TOLL 570



Sheet 13 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

0 0.25 0.5 Miles

BERKLEY RD/SR-559

559

INTERSTATE 4



Sheet 14 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

CR 557A

559

INTERSTATE 4

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 15 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map


Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

CR 557A

INTERSTATE 4




Sheet 16 of 22

FDOT

Crash Density
Low
High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 17 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

Miles
0 0.25 0.5

557

INTERSTATE 4

CR-557



Sheet 18 of 22

FDOT

Crash Density

Low


High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles



Sheet 19 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles

0 0.25 0.5



Sheet 20 of 22

FDOT

Crash Density

Low

High


Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles

0 0.25 0.5



Sheet 21 of 22

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

END STUDY

27

INTERSTATE 4

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

Sheet 22 of 22

FDOT

Crash Density

Low

High

Figure B-1: I-4 Master Plan Study
Wet Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

BEGIN STUDY

INTERSTATE 4

POLK PKWY


92

TOLL 570

COUNTY LINE RD

ALLEN K BREED HWY

OLD TAMPA HWY/CR542



Sheet 1 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


0 0.25 0.5 Miles

N GALLOWAY RD

546

INTERSTATE 4

92



Sheet 2 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

N GALLOWAY RD


INTERSTATE 4

W 10TH ST

WABASH AVE

546

92



Sheet 3 of 22

FDOT

Crash Density
Low
High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

KNIGHTS STATION RD

GRIFFIN RD

PROVIDENCE RD

539

INTERSTATE 4


KATHLEEN RD

W 10TH ST

WABASH AVE

N BRUNNELL PKWY

N GALLOWAY RD



Sheet 4 of 22

FDOT


Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


Miles
0 0.25 0.5

98

INTERSTATE 4

33

LAKELAND HILLS BLVD



Sheet 6 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


0 0.25 0.5 Miles

N SOCRUM LOOP RD

INTERSTATE 4

33

OLD COMBEE RD



Sheet 7 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

N SOCRUM LOOP RD

OLD POLK CITY RD

INTERSTATE 4

33

98

Lakeland

Auburndale

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 8 of 22

FDOT


Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 9 of 22


Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)



Sheet 10 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles


OLD POLK CITY RD

33

INTERSTATE 4

RESEARCH WAY

UNIVERSITY BLVD



Sheet 11 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

OLD POLK CITY RD

33


INTERSTATE 4

MOUNT OLIVE RD

POLK PKWY

TOLL 570

RESEARCH WAY



Sheet 12 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

INTERSTATE 4


MOUNT OLIVE RD

BERKLEY RD/SR-559

559

POLK PKWY

TOLL 570



Sheet 13 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

0 0.25 0.5 Miles

559

INTERSTATE 4

BERKLEY RD/SR-559



Sheet 14 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

0 0.25 0.5 Miles

CR 557A

559

INTERSTATE 4



Sheet 15 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study Dark Condition Crashes Heat Map


Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

CR 557A

INTERSTATE 4



Sheet 16 of 22

FDOT

Crash Density
Low
High

Figure B-2: I-4 Master Plan Study Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

557

INTERSTATE 4

CR-557

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 17 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

557

INTERSTATE 4

CR-557

98 Auburndale Lakeland City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 18 of 22

FDOT


Crash Density
Low
High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles



Sheet 19 of 22

Crash Density

Low

High


Figure B-2: I-4 Master Plan Study Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

INTERSTATE 4



Sheet 20 of 22

FDOT

Crash Density

Low


High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5



Sheet 21 of 22

Crash Density
Low
High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

END STUDY

27

4

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

Sheet 22 of 22

FDOT

Crash Density

Low

High

Figure B-2: I-4 Master Plan Study
Dark Condition Crashes Heat Map

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

BEGIN STUDY

INTERSTATE 4

POLK PKWY


92

TOLL 570

COUNTY LINE RD

ALLEN K BREED HWY

OLD TAMPA HWY/CR542



Sheet 1 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

N GALLOWAY RD

W MEMORIAL BLVD

546

INTERSTATE 4

92

98

Auburndale

Lakeland

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 2 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles

0 0.25 0.5

W 10TH ST

N GALLOWAY RD


INTERSTATE 4

WABASH AVE

92

546

W MEMORIAL BLVD



Sheet 3 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

KNIGHTS STATION RD

GRIFFIN RD

PROVIDENCE RD

539

INTERSTATE 4


KATHLEEN RD

W 10TH ST

WABASH AVE

N BRUNNELL PKWY

N GALLOWAY RD



Sheet 4 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

98

LAKELAND HILLS BLVD

33

GRIFFIN RD


INTERSTATE 4

N FLORIDA AVE

KATHLEEN RD

PROVIDENCE RD

539



Sheet 5 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


Miles
0 0.25 0.5

98

INTERSTATE 4

LAKELAND HILLS BLVD

33



Sheet 6 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N


0 0.25 0.5 Miles

N SOCRUM LOOP RD

INTERSTATE 4

33

OLD COMBEE RD



Sheet 7 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

N SOCRUM LOOP RD

OLD POLK CITY RD

INTERSTATE 4

33

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 8 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

0 0.25 0.5 Miles

UNIVERSITY BLVD

INTERSTATE 4

33



Sheet 9 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles

0 0.25 0.5

OLD POLK CITY RD

33

INTERSTATE 4

UNIVERSITY BLVD

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 10 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles


OLD POLK CITY RD

33

INTERSTATE 4

RESEARCH WAY

UNIVERSITY BLVD



Sheet 11 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

OLD POLK CITY RD

33


INTERSTATE 4

MOUNT OLIVE RD

POLK PKWY

TOLL 570

RESEARCH WAY



Sheet 12 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

INTERSTATE 4


MOUNT OLIVE RD

BERKLEY RD/SR-559

TOLL 570

POLK PKWY

559



Sheet 13 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

0 0.25 0.5 Miles

INTERSTATE 4

559

BERKLEY RD/SR-559



Sheet 14 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

0 0.25 0.5 Miles

CR 557A

559

INTERSTATE 4



Sheet 15 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes


Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5

CR 557A

INTERSTATE 4



Sheet 16 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

0 0.25 0.5 Miles

557

INTERSTATE 4

CR-557

98

Auburndale

Lakeland

City

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 27

Sheet 17 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

Miles
0 0.25 0.5

557

INTERSTATE 4

CR-557



Sheet 18 of 22

FDOT


Crash Density
Low
High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5



Sheet 19 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles

0 0.25 0.5



Sheet 20 of 22

FDOT

Crash Density

Low


High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)

N

Miles
0 0.25 0.5



Sheet 21 of 22

FDOT

Crash Density
Low
High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)


N

Miles
0 0.25 0.5

END STUDY

4

27



Sheet 22 of 22

FDOT

Crash Density

Low

High

Figure B-3: I-4 Master Plan Study
Heat Map of Fatal & Injury Crashes

Crash Data Source: FDOT SSOGis (2015 - 2019)