

**ADDENDUM TO THE
CULTURAL RESOURCE ASSESSMENT SURVEY
PROJECT DEVELOPMENT AND ENVIRONMENT (PD&E) STUDY**

**SR 865 (SAN CARLOS BOULEVARD) FROM NORTH OF
CRESCENT STREET TO NORTH OF HURRICANE BAY BRIDGE
LEE COUNTY, FLORIDA**

FPID No. 433726-1-22-01

FAP No.: D119 051 B

ETDM No. 14124

Prepared for:



Florida Department of Transportation
District One
801 North Broadway Avenue
Bartow, Florida 33830

The environmental review, consultation, and other actions required by applicable federal environmental laws for this project are being, or have been, carried out by FDOT pursuant to 23 U.S.C. § 327 and a Memorandum of Understanding dated December 14, 2016 and executed by FHWA and FDOT.

October 2020

**ADDENDUM TO THE
CULTURAL RESOURCE ASSESSMENT SURVEY
PROJECT DEVELOPMENT AND ENVIRONMENT (PD&E) STUDY**

**SR 865 (SAN CARLOS BOULEVARD) FROM NORTH OF
CRESCENT STREET TO NORTH OF HURRICANE BAY BRIDGE
LEE COUNTY, FLORIDA**

FPID No. 433726-1-22-01

FAP No.: D119 051 B

ETDM No. 14124

Prepared for:



Florida Department of Transportation
District One
801 North Broadway Avenue
Bartow, Florida 33830

Prepared by:

Archaeological Consultants, Inc.
8110 Blaikie Court, Suite A
Sarasota, Florida 34240

October 2020

TABLE OF CONTENTS

1. INTRODUCTION..... 1
2. ARCHAEOLOGICAL AND HISTORICAL BACKGROUND..... 3
3. SURVEY METHODOLOGY..... 3
4. SURVEY RESULTS..... 5
5. CONCLUSIONS..... 10
6. REFERENCES..... 10

LIST OF FIGURES

Figure 1. Location of the Seafarers Alternative for Estero Boulevard and Fifth Street
intersection improvements..... 2
Figure 2. Location of shovel tests and historic resources within the APE..... 6

LIST OF PHOTOS

Photo 1. Sample of the urban environment within the APE demonstrating the limited
number of shovel tests. 5
Photo 2. 1149 Estero Boulevard (8LL02835), looking southeast..... 7
Photo 3. 1133 Estero Boulevard (Bldg 1) (8LL02836), looking northeast..... 8
Photo 4. 1133 Estero Boulevard (Bldg 1) (8LL02836), looking north..... 8
Photo 5. 1133 Estero Boulevard (Bldg 2) (8LL02837), looking southwest. 9

APPENDICES

- Appendix A: SHPO Concurrence Letter
- Appendix B: Seafarers Alternative Concept Plan
- Appendix C: Florida Master Site File Forms
- Appendix D: Survey Log

1. INTRODUCTION

The Florida Department of Transportation (FDOT), District One, is conducting a Project Development and Environment (PD&E) Study to evaluate proposed improvements to SR 865 (San Carlos Boulevard) from north of Crescent Street to north of Hurricane Bay Bridge, in Lee County, Florida (**Figure 1**). Archaeological Consultants, Inc. (ACI) conducted a Cultural Resource Assessment Survey (CRAS) of SR 865 (San Carlos Boulevard) from Estero Boulevard to north of Hurricane Bay Bridge in March 2020. This CRAS document was approved by the State Historic Preservation Officer (SHPO) in April 2020; a copy of the concurrence letter is contained in **Appendix A** (Parsons 2020; Florida Division of Historic Resources [FDHR] Project File No. 2015-0962-B). The current survey is an addendum to the March report focusing on additional intersection improvements at Estero Boulevard and Fifth Street (**Appendix B**). The project was evaluated through FDOT's Efficient Transportation Decision Making (ETDM) process as project #14124. This is a federally funded project.

In partnership with Lee County, LeeTran, and Town of Fort Myers Beach, this project will incorporate Lee County's Seafarers Alternative at the intersection of Estero Boulevard and Fifth Street. Lee County presented Seafarers Alternative to Fort Myers Beach Town Council on March 2, 2020. Town Council consensus was to move forward with Lee County's intersection concept. New traffic signals will be constructed at Fifth Street to replace the existing pedestrian crosswalk signals. The posted speed limit will remain 25 mph. The reconstructed intersection will enhance public transit mobility, pedestrian safety, and provide opportunity areas for landscaping and other aesthetic features.

The purpose of the original CRAS and this Addendum was to locate and identify any cultural resources within the Area of Potential Effects (APE), and to assess their significance in terms of eligibility for listing in the National Register of Historic Places (NRHP). As defined in 36 CFR Part § 800.16(d), the APE is the “geographic area or areas within which an undertaking may directly or indirectly cause alterations in the character or use of historic properties, if any such properties exist.” The archaeological APE was defined as the area contained within the footprint of construction where the proposed design changes are to occur. The historic/architectural APE includes the footprint of construction and immediately adjacent parcels. The archaeological and historic/architectural field investigations were completed in August 2020 and any photographs taken at this time are included in this report.

All work was conducted to comply with Section 106 of the *National Historic Preservation Act* of 1966, as amended by Public Law 89-665; the *Archaeological and Historic Preservation Act*, as amended by Public Law 93-291; Executive Order 11593; and Chapter 267, *Florida Statutes (FS)*. All work was carried out in conformity with Part 2, Chapter 8 (“Archaeological and Historical Resources”) of the FDOT's *Project Development and Environment (PD&E) Manual* (FDOT 2020), and the FDHR standards contained in the *Cultural Resource Management Standards and Operational Manual* (FDHR 2003), as well as with the provisions contained in the Chapter 1A-46, *Florida Administrative Code (FAC)*. Principal Investigators meet the *Secretary of the Interior's Historic Preservation Professional Qualification Standards* (48 FR 44716) for archaeology, history, architecture, architectural history, or historic architecture.

Archaeological background research, including a review of the Florida Master Site File (FMSF) and the NRHP, indicated that no previously recorded archaeological site is located within the project APE. Although a review of relevant site locational information for environmentally similar areas within Charlotte, Hendry, and Lee Counties including the Lee County Archaeological




Figure 1. Location of the Seafarers Alternative for Estero Boulevard and Fifth Street intersection improvements.

Sensitivity Map indicated a moderate potential for prehistoric archaeological sites, the APE was determined to have a low to very low potential for prehistoric archaeological sites due to the tidal and partially inundated soils and infill. There was also a low potential for historic archaeological sites. The background research indicated that prehistoric sites, if found would be small middens or campsites; historic sites might include evidence of the nineteenth century activity. As a result of visual reconnaissance and subsurface testing, no previously unrecorded prehistoric or historic archaeological sites were found.

A review of the relevant United States Geological Survey (USGS) quadrangle map, historic aerial photographs, and the Lee County property appraiser's website data revealed the potential for three new historic resources 46 years of age or older (constructed in or prior to 1974) within the historic APE. The historical/architectural field survey resulted in the identification and evaluation of three new historic resources (8LL02835-8LL02837) within the historic APE. These include three Commercial style buildings constructed between circa (c.) 1947 and c. 1972. These resources are common examples of their respective architectural styles without significant historical associations; therefore, none appear eligible for listing in the NRHP, either individually or as part of a historic district.

Based on the background research and survey results, including the excavation of seven shovel tests, no archaeological sites or historic resources that are listed, eligible for listing, or that appear potentially eligible for listing in the NRHP were located within the APE. Therefore, it is the professional opinion of ACI that the proposed undertaking will have no involvement with cultural resources.

2. ARCHAEOLOGICAL AND HISTORICAL BACKGROUND

A review of archaeological and historical literature, records and other documents, and data pertaining to the project area was conducted. This included a review of cultural resources listed in the NRHP, the FMSF, cultural resource survey reports, published books and articles, unpublished manuscripts, aerial photographs, and maps. The FMSF information in this report was obtained in August 2020. In-depth historic and prehistoric overviews were included in the March 2020 PD&E, *A Cultural Resource Assessment Survey SR 865 (San Carlos Boulevard) from Estero Boulevard to north of Hurricane Bay Bridge, Lee County, Florida* and are not repeated here (ACI 2020). The CRAS document was submitted to and approved by the SHPO (Parsons 2020; FDHR Project File No. 2015-0962-B).

3. SURVEY METHODOLOGY

The FDHR's Module Three, *Guidelines for Use by Historic Professionals*, indicates that the first stage of archaeological field survey is a reconnaissance of the project area to "ground truth," or ascertain the validity of the predictive model (FDHR 2003). During this part of the survey, the researcher assesses whether the initial predictive model needs adjustment based on disturbance or conditions such as constructed features (i.e., parking lots, buildings, etc.), underground utilities, landscape alterations (i.e., ditches and swales, mined land, dredged and filled land, agricultural fields), or other constraints that may affect the archaeological potential. Additionally, these Guidelines indicate that non-systematic "judgmental" testing may be appropriate in urbanized environments where pavement, utilities, and constructed features make systematic testing unfeasible; in geographically restricted areas such as proposed pond sites; or within project areas

that have limited high and moderate probability zones, but where a larger subsurface testing sample may be desired. While predictive models are useful in determining preliminary testing strategies in a broad context, it is understood that testing intervals may be altered due to conditions encountered by the field crew at the time of survey.

Archaeological field survey methods consisted of surface reconnaissance combined with subsurface testing. Shovel tests were placed judgmentally throughout the APE. Shovel tests were circular and measured approximately 50 centimeters (cm) in diameter by at least 1 m in depth unless impenetrable fill material was present. All soil removed from the shovel tests was screened through a 0.64 cm mesh hardware cloth to maximize the recovery of artifacts. The locations of all shovel tests were recorded using a Juno 5B Trimble unit, and following the recording of relevant data such as stratigraphic profile, all shovel tests were refilled.

Historic/architectural field methodology consisted of a field survey of the APE to determine and verify the location of all buildings and other historic resources (i.e. bridges, roads, cemeteries) 46 years of age or older (constructed in or prior to 1974), and to establish if any such resources could be determined eligible for listing in the NRHP. The field survey focused on the assessment of existing conditions for all previously recorded historic resources located within the APE, and the presence of unrecorded historic resources within the project area. For each property, photographs were taken, and information needed for the completion of FMSF forms was gathered. In addition to architectural descriptions, each historic resource was reviewed to assess style, historic context, condition, and potential NRHP eligibility. Also, informant interviews would have been conducted, if possible, with knowledgeable persons to obtain site-specific building construction dates and/or possible associations with individuals or events significant to local or regional history.

Inadvertent/Unanticipated Discovery of Cultural Remains

Occasionally, archaeological deposits, subsurface features or unmarked human remains are encountered during the course of development, even though the project area may have previously received a thorough and professionally adequate cultural resources assessment. Such events are rare, but they do occur. In the event that human remains are encountered during the course of development, the procedures outlined in Chapter 872, *FS* must be followed. However, it was not anticipated that such sites would be found during this survey.

In the event such discoveries are made during the development process, all activities in the immediate vicinity of the discovery will be suspended, and a professional archaeologist will be contacted to evaluate the importance of the discovery. The area will be examined by the archaeologist, who, in consultation with staff of the Florida SHPO, will determine if the discovery is significant or potentially significant. In the event the discovery is found to be not significant, the work may immediately resume. If, on the other hand, the discovery is found to be significant or potentially significant, then development activities in the immediate vicinity of the discovery will continue to be suspended until such time as a mitigation plan, acceptable to SHPO, is developed and implemented. Development activities may then resume within the discovery area, but only when conducted in accordance with the guidelines and conditions of the approved mitigation plan.

Laboratory Methods/Curation

No artifacts were recovered; thus, no laboratory methods were utilized. All project-related records, including maps, field notes, and photos, will be maintained at the ACI office (P19088) in Sarasota, pending transfer for curation.

4. SURVEY RESULTS

Archaeological Results

Archaeological field survey included surface reconnaissance and the excavation of seven shovel tests (**Figure 2**). These were placed judgmentally throughout the APE and although planned to be excavated to 100 cm, most were terminated at shallow depths due to dense fill and utilities. In addition, shovel tests were limited due to impervious surfaces (**Photo 1**). The general stratigraphy of the shovel tests consisted of 0-40 cm of grey/brown gravelly sand; 40-60 cm of mottled tan, gravelly sand with shell; and 60-100 cm of light, grey/brown shell, shell hash and gravel. A reasonable and good faith effort was made per the regulations laid out in 36 CFR § 800.4(b) (1) (Advisory Council on Historic Preservation n.d.) to test all areas of the project APE.



Photo 1. Sample of the urban environment within the APE demonstrating the limited number of shovel tests.

Historical Results

The March 2020 survey identified six historic resources (8LL02650-8LL02655) within the APE. These include five Masonry Vernacular (8LL02650, 8LL02651, 8LL02653-55) and one Commercial (8LL02652) style buildings constructed between c. 1947 and c. 1967 (ACI 2020). These resources were determined ineligible for listing in the NRHP by the SHPO in 2020 (Parsons 2020). As a result of the historical/architectural field survey, three historic resources (8LL02835-8LL02837) were newly identified, recorded, and evaluated within the APE (**Figure 2**). Overall, the newly identified historic resources have been altered, lack sufficient architectural features, and are not significant embodiments of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. Thus, the resources do not appear eligible for listing in the NRHP, either individually or as a part of a historic district. Descriptions and photographs of the newly identified resources follow, and copies of the FMSF forms are included in **Appendix C**.



Figure 2. Location of shovel tests and historic resources within the APE.



Photo 2. 1149 Estero Boulevard (8LL02835), looking southeast.

8LL02835: The Commercial style building at 1149 Estero Boulevard was constructed in c. 1972 (**Photo 2**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco. The flat roof is covered with built-up roofing membrane. The main entryway is on the west elevation through two separate, single, metal frame full view doors with transom lights beneath a flat metal awning. Visible windows include a mixture of individual, single pane and two-light metal fixed units and individual two-stacked metal awning units. Distinguishing architectural features include a metal awning with metal coping and vents. Alterations include replacement roofing and siding, as well as the enclosure of a window on the north elevation and the removal of canvas awnings. Three other Commercial style buildings constructed between c. 1947 and c. 1949 are located on the parcel (8LL02652, 8LL02836, and 8LL02837). Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8LL02835 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 3. 1133 Estero Boulevard (Bldg 1) (8LL02836), looking northeast.



Photo 4. 1133 Estero Boulevard (Bldg 1) (8LL02836), looking north.

8LL02836: The Commercial style building at 1133 Estero Boulevard was constructed in c. 1947 (**Photos 3 and 4**). The one-story, irregular plan building rests on a continuous concrete block foundation and has a concrete block structural system clad in stucco. The flat roof is covered with built-up roofing membrane. The main entryways are on the south and east elevation through single or double metal frame full view doors per unit. Three retail units are present, including one on the south elevation and two on the east elevation. Visible windows include a mixture of individual, paired, and grouped (3), single pane metal fixed units. Distinguishing architectural features include a parapet with metal coping, tapered triangular wing walls, stucco trim around the windows and doors, a scalloped parapet with affixed signage, and advertising window film. Alterations include replacement roofing, windows, and siding. A flat roof addition was constructed

on the north elevation. Three other Commercial style buildings constructed between c. 1947 and c. 1972 are located on the parcel (8LL02652, 8LL02835, and 8LL02837). Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8LL02836 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.



Photo 5. 1133 Estero Boulevard (Bldg 2) (8LL02837), looking southwest.

8LL02837: The Commercial style building at 1133 Estero Boulevard was constructed in c. 1948 (**Photo 5**). The one-story, irregular plan building rests on a concrete slab foundation and has a concrete block structural system clad in stucco. The flat roof is covered with built-up roofing membrane. The main entryways are on the north elevation through single or double metal frame full view doors with transom lights per unit beneath a metal awning frame. Visible windows include a mixture of individual and paired, single pane metal fixed units and individual one-over-one metal single-hung sash units. Distinguishing architectural features include a parapet with metal coping, curved awning metal frame parapet, rectangular wall projection, stucco pilasters, and stucco trim around the windows and doors. Alterations include replacement roofing, siding, and windows, as well as the installation of awnings and painting of the windows and doors. Furthermore, the building is in fair condition where all the windows and doors have been boarded up and the canvas from the curved awning parapet has been removed. Multiple flat roof additions have been constructed on the north elevation. Three other Commercial style buildings constructed between c. 1947 and c. 1972 are located on the parcel (8LL02652, 8LL02835, and 8LL02836). Overall, the building has been altered, lacks sufficient architectural features, and is not a significant embodiment of a type, period, or method of construction. In addition, background research did not reveal any historic associations with significant persons and/or events. As a result, 8LL02837 does not appear eligible for listing in the NRHP, either individually or as part of a historic district.

5. CONCLUSIONS

ACI conducted a CRAS of SR 865 (San Carlos Boulevard) from Estero Boulevard to north of Hurricane Bay Bridge in March 2020. The CRAS document was submitted to and approved by the SHPO in April 2020 (Parsons 2020; FDHR Project File No. 2015-0962-B) (**Appendix A**). The current survey is an addendum to the March report focusing on additional intersection improvements at Estero Boulevard and Fifth Street (**Appendix B**). New traffic signals will be constructed at Fifth Street to replace the existing pedestrian crosswalk signals. The reconstructed intersection will enhance public transit mobility, pedestrian safety, and provide opportunity areas for landscaping and other aesthetic features.

Based on the background research and survey results, including the excavation of seven shovel tests, no archaeological sites that are listed, eligible for listing, or that appear potentially eligible for listing in the NRHP were located within the APE. The March 2020 survey identified six historic resources (8LL02650-8LL02655 within the APE. These include five Masonry Vernacular (8LL02650, 8LL02651, 8LL02653-55) and one Commercial (8LL02652) style buildings constructed between c. 1947 and c. 1967 (ACI 2020). These resources were determined ineligible for listing in the NRHP by the SHPO in 2020 (Parsons 2020). As a result of the historical/architectural field survey, three historic resources (8LL02835-8LL02837) were newly identified, recorded, and evaluated within the APE. These include three Commercial style buildings constructed between c. 1947 and c. 1972. These resources are common examples of their respective architectural styles without significant historical associations; therefore, none appear eligible for listing in the NRHP, either individually or as part of a historic district.

Given the results of background research and field survey, no cultural resources that are listed, eligible for listing, or that appear potentially eligible for listing in the NRHP were located within the APE. Therefore, it is the professional opinion of ACI that the proposed undertaking will have no involvement with cultural resources.

6. REFERENCES

Advisory Council on Historic Preservation

n.d. Meeting the “Reasonable and Good Faith” Identification Standard in Section 106 Review. http://www.achp.gov/docs/reasonable_good_faith_identification.pdf.

Archaeological Consultants, Inc. (ACI)

2020 *A Cultural Resource Assessment Survey SR 865 (San Carlos Boulevard) from Estero Boulevard to north of Hurricane Bay Bridge, Lee County, Florida*. ACI, Sarasota.

Florida Department of Transportation (FDOT)

2020 *Project Development and Environmental Manual Part 2, Chapter 8, “Archaeological and Historical Resources.”* FDOT, Tallahassee.

Florida Division of Historical Resources (FDHR)

2003 *Cultural Resource Management Standards and Operational Manual*. FDHR, Tallahassee.

Florida Master Site File (FMSF)

n.d. Various Florida Site File Forms from the FDHR, Tallahassee.

Parsons, Timothy

2020 SHPO Concurrence Letter, FDHR Project File No. 2015-0962-B, Cultural Resource Assessment Survey SR 865 (San Carlos Boulevard) from Estero Boulevard to North of Hurricane Bay Bridge, Lee County, Florida. ACI, Sarasota.

United States Department of Agriculture (USDA)

1944 Aerial Photograph - 4-13-1944, DCT-3C-13. PALMM, Gainesville.

1953 Aerial Photograph - 2-9-1953, DCT-3H-94. PALMM, Gainesville.

United States Geological Survey (USGS)

1972 Fort Myers Beach, Florida.

WGI

2020 Project Information, Electronic Mail, September 29.

Wilkinson, Kenneth

2020 Records Search. Lee County Property Appraiser, Fort Myers.

APPENDIX A:
SHPO Concurrence Letter



Florida Department of Transportation

RON DESANTIS
GOVERNOR

801 North Broadway Avenue
Bartow, FL 33830

KEVIN J. THIBAUT, P.E.
SECRETARY

March 24, 2020

Dr. Timothy Parsons, Director
Florida Division of Historical Resources
Department of State, R.A. Gray Building
500 South Bronough Street
Tallahassee, FL 32399-0250

Attn: Transportation Compliance Review Program

**RE: Cultural Resource Assessment Survey
SR 865 (San Carlos Boulevard) from Estero Boulevard to
North of Hurricane Bay Bridge
Lee County, Florida
FPID: 433726-1-22-01; FAP: D119 051 B; ETDM: 14124**

Dear Dr. Parsons:

The Florida Department of Transportation (FDOT) is conducting a Project Development and Environment (PD&E) study to evaluate options that will increase accessibility and enhancement of mobility and safety for vehicle and non-vehicular transportation in Lee County. A Cultural Resource Assessment Survey (CRAS) was performed within the area of potential effect (APE) SR 865 (San Carlos Boulevard) from Estero Boulevard to north of Hurricane Bay Bridge. The total project length is approximately one mile. The proposed improvements include widening the Matanzas Pass Bridge to accommodate a new shared-use path along the west side of the bridge, milling and resurfacing, new and modification to existing traffic signals and crosswalks, and the Hurricane Bay Bridge will be modified to accommodate bicycle lanes in each direction of travel and a barrier-protected sidewalk along the west side of the bridge.

The archaeological APE was defined as the area contained within the footprint of construction where the proposed design changes are to occur. The historical/architectural APE includes the footprint of construction within the existing ROW and immediately adjacent parcels on the west side of SR 865 as contained within 150-feet from the centerline of the roadway. In addition, historic resources located on immediately adjacent parcels in areas where new traffic signals are proposed (Estero Boulevard and Crescent Street; Estero Boulevard/SR 865/Fifth Street; Estero Boulevard and Old San Carlos Boulevard; and SR 865 and Main Street) will be recorded and evaluated.

This CRAS was conducted in accordance with the requirements set forth in the National Historic Preservation Act of 1966 (as amended), which are implemented by the procedures contained in 36 CFR, Part 800, as well as the provisions contained in the revised Chapter 267, *Florida Statutes*. The investigations were carried out in accordance with Part 2, Chapter 8 (Archaeological and Historical Resources) of the FDOT's PD&E Manual, FDOT's Cultural Resources Manual, and the standards contained in the Florida Division of Historical Resources (FDHR) Cultural Resource Management Standards and Operations Manual (FDHR 2003). In

Dr. Timothy Parsons, Director
Lee County, Florida
FPID: 433726-1-22-01; FAP: D119 051 B; ETDM: 14124
March 24, 2020
Page 2 of 3


addition, this survey meets the specifications set forth in Chapter 1A-46, Florida Administrative Code.

Background research and a review of the Florida Master Site File (FMSF) and the National Register of Historic Places (NRHP) indicated that one previously recorded archaeological site is located within the project APE. This site, 8LL00777, the San Carlos Island Site, is a shell midden recorded in 1987 as the result of an informant interview (FMSF). The State Historic Preservation Officer (SHPO) has not evaluated the site. Although a review of relevant site locational information for environmentally similar areas within Charlotte, Hendry, and Lee Counties including the Lee County Archaeological Sensitivity Map indicated a moderate potential for prehistoric archaeological sites, the APE was determined to have a low to very low potential for prehistoric archaeological sites due to the tidal and partially inundated soils and infill. There was also a low potential for historic archaeological sites. As a result of visual reconnaissance and subsurface testing, no evidence of 8LL00777 was located and no previously unrecorded prehistoric or historic archaeological sites were found.

No previously recorded historic resources were located within the APE. As a result of field survey, 39 newly identified historic resources (8LL02650-8LL02684, 8LL02706-9) were recorded and evaluated. The architectural styles represented include 11 Masonry Vernacular (8LL02650, 8LL02651, 8LL02653-55; 8LL02659; 8LL02661; 8LL02672, 8LL02673, 8LL02676; 8LL02679), eight Frame Vernacular (8LL02658; 8LL02660; 8LL02666; 8LL02678; 8LL02680; 8LL02682-84), two Industrial Vernacular (8LL02677; 8LL02681), five Commercial (8LL02652, 8LL02656, 8LL02657, 8LL02674, 8LL02675), nine mobile homes (no style) (8LL02662-65; 8LL02667-71); as well as four building complex resource groups (8LL02706-9) constructed between ca. 1939 and 1972. These resources are common examples of their respective architectural styles without significant historical associations; therefore, none appear eligible for listing in the NRHP, either individually or as part of a historic district.

Based on the results of the background research and field survey, there are no significant historic properties within the APE. Therefore, the project will have no effect on any prehistoric or historic archaeological sites or historic resources that are listed, eligible, or that appear to be potentially eligible for listing in the NRHP.

The CRAS Report is provided for your review and comment. If you have any questions, please do not hesitate to call me at 863.519.2805 or vivianne.cross@dot.state.fl.us



Gwen G. Pipkin, CPM
Environmental Manager


Enclosures: One original copy of the CRAS (March 2020); 40 FMSF Forms, One Completed Survey Log

CC: Henri Belrose, WGI
Joel Johnson, WGI
Marion Almy, ACI

The Florida State Historic Preservation Officer (SHPO) finds the attached Cultural Resources Assessment Survey Report complete and sufficient and concurs/ does not concur with the recommendations and findings provided in this cover letter for SHPO/FDHR Project File Number 2015-0962-B. Or, the SHPO finds the attached document contains _____ insufficient information.

SHPO Comments:


There is insufficient information to evaluate the site 8LL00777 as a whole; however, based on the current survey results, and in light of the fact that the site location and/or boundary was never archaeologically verified (local informant record only), we concur that the site is not present within the APE and, consequently, that the proposed project will have no effect on this or any resources that are listed, eligible, or appear to be potentially eligible for NRHP listing within the APE.


Dr. Timothy Parsons, Director
State Historic Preservation Officer
Florida Division of Historical Resources

April 13, 2020

Date

APPENDIX B:
Seafarers Alternative
Intersection Concept at Estero Boulevard and Fifth Street



**Seafarers Alternative -
Intersection Concept at Estero Boulevard and Fifth Street**

APPENDIX C:
Florida Master Site File Forms



HISTORICAL STRUCTURE FORM
FLORIDA MASTER SITE FILE
Version 5.0 3/19

Site#8 LL02835
Field Date 8-31-2020
Form Date 9-1-2020
Recorder #

[X] Original
[] Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the Guide to Historical Structure Forms for detailed instructions.

Site Name(s) (address if none) 1149 Estero Boulevard Multiple Listing (DHR only)
Survey Project Name CRAS Addendum SR 865 (San Carlos Blvd) Survey # (DHR only)
National Register Category (please check one) [X]building []structure []district []site []object
Ownership: [X]private-profit []private-nonprofit []private-individual []private-nonspecific []city []county []state []federal []Native American []foreign []unknown

LOCATION & MAPPING

Street Number 1149 Direction Street Name Estero Street Type Boulevard Suffix Direction
Address:
Cross Streets (nearest / between)
USGS 7.5 Map Name FORT MYERS BEACH USGS Date 1958 Plat or Other Map
City / Town (within 3 miles) Fort Myers Beach In City Limits? []yes []no [X]unknown County Lee
Township 46S Range 23E Section 24 1/4 section: []NW []SW []SE []NE Irregular-name:
Tax Parcel # 24-46-23-W3-00006.0000 Landgrant
Subdivision Name Block Lot
UTM Coordinates: Zone []16 [X]17 Easting 404885 Northing 2926191
Other Coordinates: X: Y: Coordinate System & Datum
Name of Public Tract (e.g., park)

HISTORY

Construction Year: 1972 []approximately [X]year listed or earlier []year listed or later
Original Use Commercial From (year): 1972 To (year): CURR
Current Use From (year): To (year):
Other Use From (year): To (year):
Moves: []yes [X]no []unknown Date: Original address
Alterations: [X]yes []no []unknown Date: Nature Roofing, siding, windows, awnings
Additions: []yes [X]no []unknown Date: Nature
Architect (last name first): Builder (last name first):
Ownership History (especially original owner, dates, profession, etc.)
Grand Resort - Ft Myers Beach, LLC (2015); Huntingburg Partners, Ltd. (2000); The Huntingburg Corporation (1993); Nick Karras

Is the Resource Affected by a Local Preservation Ordinance? []yes []no [X]unknown Describe

DESCRIPTION

Style Commercial Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. 3.
Roof Type(s) 1. Flat 2. 3.
Roof Material(s) 1. Built-up 2. 3.
Roof secondary strucs. (dormers etc.) 1. 2.

Windows (types, materials, etc.)
Fixed, metal, single, single pane, 2-lights; Awning, metal, single, 2-stacked

Distinguishing Architectural Features (exterior or interior ornaments)
Metal awning w/ metal coping and vents

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Three Commercial style buildings constructed between c. 1947 and c. 1949 are located on the parcel (8LL02652, 8LL02836, and 8LL02837).

Table with 3 columns: DHR USE ONLY, OFFICIAL EVALUATION, DHR USE ONLY. Contains fields for NR List Date, Owner Objection, SHPO listing criteria, and NR Criteria for Evaluation.

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. 2.
Structural System(s): 1. Concrete block 2. 3.
Foundation Type(s): 1. Slab 2.
Foundation Material(s): 1. Concrete, Generic 2.

Main Entrance (stylistic details)

W ELEV: two separate metal frame full view doors w/ transom lights, beneath a flat metal awning

Porch Descriptions (types, locations, roof types, etc.)

Condition (overall resource condition): [] excellent [x] good [] fair [] deteriorated [] ruinous

Narrative Description of Resource

A one-story Commercial style building w/ an enclosed window on the N ELEV.

Archaeological Remains [] Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- [x] FMSF record search (sites/surveys) [] library research [] building permits [] Sanborn maps
[] FL State Archives/photo collection [] city directory [] occupant/owner interview [] plat maps
[x] property appraiser / tax records [] newspaper files [] neighbor interview [] Public Lands Survey (DEP)
[] cultural resource survey (CRAS) [] historic photos [] interior inspection [] HABS/HAER record search
[x] other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
http://palmm.fcla.edu/

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? [] yes [x] no [] insufficient information
Appears to meet the criteria for National Register listing as part of a district? [] yes [x] no [] insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. 2. 3. 4. 5. 6.

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19088
2) Document type Maintaining organization
Document description File or accession #'s

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

- 1 USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
2 LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
3 PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.




PHOTOGRAPHS






AERIAL MAP



Esri, HERE, Garmin, (c) OpenStreetMap contributors, Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community. 2019



USGS Fort Myers Beach
Township 46 South, Range 23 East, Section 24





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **LL02836**
Field Date 8-31-2020
Form Date 9-1-2020
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 1133 Estero Boulevard (Bldg 1) Multiple Listing (DHR only) _____
Survey Project Name CRAS Addendum SR 865 (San Carlos Blvd) Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 1133 Direction _____ Street Name Estero Street Type Boulevard Suffix Direction _____
Address: _____
Cross Streets (nearest / between) _____
USGS 7.5 Map Name FORT MYERS BEACH USGS Date 1958 Plat or Other Map _____
City / Town (within 3 miles) Fort Myers Beach In City Limits? yes no unknown County Lee
Township 46S Range 23E Section 24 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # 24-46-23-W3-00006.0000 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 404848 Northing 2926189
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1947 approximately year listed or earlier year listed or later
Original Use Mall/Shopping center From (year): 1947 To (year): CURR
Current Use _____ From (year): _____ To (year): _____
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows, siding
Additions: yes no unknown Date: _____ Nature Flat roof
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Grand Resort - Ft Myers Beach, LLC (2015); Huntingburg Partners, Ltd. (2000); The Huntingburg Corporation (1993); Nick Karras

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Commercial Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. _____ 3. _____
Roof Type(s) 1. Flat 2. _____ 3. _____
Roof Material(s) 1. Built-up 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
Fixed, metal, single, paired, grouped (3), single pane

Distinguishing Architectural Features (exterior or interior ornaments)
Parapet w/ metal coping, tapered triangular wing walls, stucco trim around windows/doors, scalloped parapet, advertising window film

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Three Commercial style buildings constructed between c. 1947 and c. 1972 are located on the parcel (8LL02652, 8LL02835, and 8LL02837).

DHR USE ONLY		OFFICIAL EVALUATION		DHR USE ONLY	
NR List Date _____	SHPO - Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info		Date _____	Init. _____	
<input type="checkbox"/> Owner Objection	KEEPER - Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no		Date _____		
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)				

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____
 Structural System(s): 1. Concrete block 2. _____ 3. _____
 Foundation Type(s): 1. Continuous 2. _____
 Foundation Material(s): 1. Concrete Block 2. _____

Main Entrance (stylistic details)

S & E ELEV: single or double metal frame full view doors per unit

Porch Descriptions (types, locations, roof types, etc.)

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Commercial style building with a flat roof addition on the N ELEV. Three retail units are present, including one utilized as a Sheriff's office on the S ELEV and two located on the E ELEV.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- FMSF record search (sites/surveys)
- library research
- building permits
- Sanborn maps
- FL State Archives/photo collection
- city directory
- occupant/owner interview
- plat maps
- property appraiser / tax records
- newspaper files
- neighbor interview
- Public Lands Survey (DEP)
- cultural resource survey (CRAS)
- historic photos
- interior inspection
- HABS/HAER record search
- other methods (describe) USDA historic aerial photographs (PALMM)

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at: <http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient information
 Appears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see National Register Bulletin 15, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)

1. _____ 3. _____ 5. _____
 2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
 Document description Files, photos, research, documents File or accession #'s P19088
- 2) Document type _____ Maintaining organization _____
 Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants Inc
 Recorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
 (address / phone / fax / e-mail)

Required Attachments

- ❶ USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED
- ❷ LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)
- ❸ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital **AND** hard copy format (plain paper grayscale acceptable). Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.



PHOTOGRAPHS






AERIAL MAP



Esri, HERE, Garmin, (c) OpenStreetMap contributors, Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community. 2019



USGS Fort Myers Beach
Township 46 South, Range 23 East, Section 24





HISTORICAL STRUCTURE FORM

FLORIDA MASTER SITE FILE

Version 5.0 3/19

Site#8 **LL02837**
Field Date 8-31-2020
Form Date 9-1-2020
Recorder # _____

Original
 Update

Shaded Fields represent the minimum acceptable level of documentation.
Consult the *Guide to Historical Structure Forms* for detailed instructions.

Site Name(s) (address if none) 1133 Estero Boulevard (Bldg 2) Multiple Listing (DHR only) _____
Survey Project Name CRAS Addendum SR 865 (San Carlos Blvd) Survey # (DHR only) _____
National Register Category (please check one) building structure district site object
Ownership: private-profit private-nonprofit private-individual private-nonspecific city county state federal Native American foreign unknown

LOCATION & MAPPING

Street Number 1133 Direction _____ Street Name Estero Street Type Boulevard Suffix Direction _____
Address: _____
Cross Streets (nearest / between) _____
USGS 7.5 Map Name FORT MYERS BEACH USGS Date 1958 Plat or Other Map _____
City / Town (within 3 miles) Fort Myers Beach In City Limits? yes no unknown County Lee
Township 46S Range 23E Section 24 1/4 section: NW SW SE NE Irregular-name: _____
Tax Parcel # 24-46-23-W3-00006.0000 Landgrant _____
Subdivision Name _____ Block _____ Lot _____
UTM Coordinates: Zone 16 17 Easting 404858 Northing 2926235
Other Coordinates: X: _____ Y: _____ Coordinate System & Datum _____
Name of Public Tract (e.g., park) _____

HISTORY

Construction Year: 1948 approximately year listed or earlier year listed or later
Original Use Mall/Shopping center From (year): 1948 To (year): UNK
Current Use Abandoned/Vacant From (year): UNK To (year): CURR
Other Use _____ From (year): _____ To (year): _____
Moves: yes no unknown Date: _____ Original address _____
Alterations: yes no unknown Date: _____ Nature Roofing, windows, siding, awnings
Additions: yes no unknown Date: _____ Nature Flat roof
Architect (last name first): _____ Builder (last name first): _____
Ownership History (especially original owner, dates, profession, etc.)
Grand Resort - Ft Myers Beach, LLC (2015); Huntingburg Partners, Ltd. (2000); The Huntingburg Corporation (1993); Nick Karras

Is the Resource Affected by a Local Preservation Ordinance? yes no unknown Describe _____

DESCRIPTION

Style Commercial Exterior Plan Irregular Number of Stories 1
Exterior Fabric(s) 1. Stucco 2. Wood/Plywood 3. _____
Roof Type(s) 1. Flat 2. _____ 3. _____
Roof Material(s) 1. Built-up 2. _____ 3. _____
Roof secondary strucs. (dormers etc.) 1. _____ 2. _____

Windows (types, materials, etc.)
Fixed, metal, single, paired, single pane; SHS, metal, single, 1/1

Distinguishing Architectural Features (exterior or interior ornaments)
Parapet, rectangular wall projection, stucco pilasters, stucco trim around windows/doors

Ancillary Features / Outbuildings (record outbuildings, major landscape features; use continuation sheet if needed.)
Three Commercial style buildings constructed between c. 1947 and c. 1972 are located on the parcel (8LL02652, 8LL02835, and 8LL02836).

DHR USE ONLY		OFFICIAL EVALUATION	DHR USE ONLY	
NR List Date _____	SHPO - Appears to meet criteria for NR listing: <input type="checkbox"/> yes <input type="checkbox"/> no <input type="checkbox"/> insufficient info		Date _____	Init. _____
<input type="checkbox"/> Owner Objection	KEEPER - Determined eligible: <input type="checkbox"/> yes <input type="checkbox"/> no		Date _____	
	NR Criteria for Evaluation: <input type="checkbox"/> a <input type="checkbox"/> b <input type="checkbox"/> c <input type="checkbox"/> d (see <i>National Register Bulletin 15</i> , p. 2)			

DESCRIPTION (continued)

Chimney: No. 0 Chimney Material(s): 1. _____ 2. _____Structural System(s): 1. Concrete block 2. _____ 3. _____Foundation Type(s): 1. Slab 2. _____Foundation Material(s): 1. Concrete, Generic 2. _____

Main Entrance (stylistic details)

N ELEV: single or double metal frame full view door w/ transom light per unit, beneath a metal awning frame

Porch Descriptions (types, locations, roof types, etc.)

Condition (overall resource condition): excellent good fair deteriorated ruinous

Narrative Description of Resource

A one-story Commercial style building w/ several vacant retail units. Multiple flat roof additions have been added to the N ELEV over time. The windows and doors have been painted.

Archaeological Remains _____ Check if Archaeological Form Completed

RESEARCH METHODS (select all that apply)

- | | | | |
|--------------------------------------------------------------------------------------------------------------|-------------------------------------------|---------------------------------------------------|----------------------------------------------------|
| <input checked="" type="checkbox"/> FMSF record search (sites/surveys) | <input type="checkbox"/> library research | <input type="checkbox"/> building permits | <input type="checkbox"/> Sanborn maps |
| <input type="checkbox"/> FL State Archives/photo collection | <input type="checkbox"/> city directory | <input type="checkbox"/> occupant/owner interview | <input type="checkbox"/> plat maps |
| <input checked="" type="checkbox"/> property appraiser / tax records | <input type="checkbox"/> newspaper files | <input type="checkbox"/> neighbor interview | <input type="checkbox"/> Public Lands Survey (DEP) |
| <input type="checkbox"/> cultural resource survey (CRAS) | <input type="checkbox"/> historic photos | <input type="checkbox"/> interior inspection | <input type="checkbox"/> HABS/HAER record search |
| <input checked="" type="checkbox"/> other methods (describe) <u>USDA historic aerial photographs (PALMM)</u> | | | |

Bibliographic References (give FMSF manuscript # if relevant, use continuation sheet if needed)

Publication of Archival Library and Museum Materials (PALMM), accessible online at:
<http://palmm.fcla.edu/>

OPINION OF RESOURCE SIGNIFICANCE

Appears to meet the criteria for National Register listing individually? yes no insufficient informationAppears to meet the criteria for National Register listing as part of a district? yes no insufficient information

Explanation of Evaluation (required, whether significant or not; use separate sheet if needed)

The building is not a significant embodiment of a type, period, or method of construction; and has no known significant historic associations.

Area(s) of Historical Significance (see *National Register Bulletin 15*, p. 8 for categories: e.g. "architecture", "ethnic heritage", "community planning & development", etc.)1. _____ 3. _____ 5. _____
2. _____ 4. _____ 6. _____

DOCUMENTATION

Accessible Documentation Not Filed with the Site File - including field notes, analysis notes, photos, plans and other important documents

- 1) Document type All materials at one location Maintaining organization Archaeological Consultants Inc
Document description Files, photos, research, documents File or accession #'s P19088
- 2) Document type _____ Maintaining organization _____
Document description _____ File or accession #'s _____

RECORDER INFORMATION

Recorder Name Savannah Young Affiliation Archaeological Consultants IncRecorder Contact Information 8110 Blaikie Court, Ste. A / Sarasota, FL/ 34240 / aciflorida@comcast.net
(address / phone / fax / e-mail)

Required Attachments

① USGS 7.5' MAP WITH STRUCTURE LOCATION CLEARLY INDICATED

② LARGE SCALE STREET, PLAT OR PARCEL MAP (available from most property appraiser web sites)

③ PHOTO OF MAIN FACADE, DIGITAL IMAGE FILE

When submitting an image, it must be included in digital AND hard copy format (plain paper grayscale acceptable).
Digital image must be at least 1600 x 1200 pixels, 24-bit color, jpeg or tiff.



PHOTOGRAPHS






AERIAL MAP





USGS Fort Myers Beach
Township 46 South, Range 23 East, Section 24



Copyright:© 2013 National Geographic Society, i-cubed.

APPENDIX D:
Survey Log

Ent D (FMSF only) _____



Survey Log Sheet

Florida Master Site File
Version 5.0 3/19

Survey # (FMSF only) _____

Consult *Guide to the Survey Log Sheet* for detailed instructions.

Manuscript Information

Survey Project (name and project phase)

CRAS Addendum SR 865 (San Carlos Blvd) from North of Crescent Street to North of Hurricane Bay Bridge

Report Title (exactly as on title page)

Addendum to the Cultural Resource Assessment Survey, PD&E Study SR 865 (San Carlos Blvd) from North of Crescent Street to North of Hurricane Bay Bridge, Lee County, Florida (FPID No. 433726-1-22-01)

Report Authors (as on title page)

1. ACI 3. _____
2. _____ 4. _____

Publication Year 2020

Number of Pages in Report (do not include site forms) 18

Publication Information (Give series, number in series, publisher and city. For article or chapter, cite page numbers. Use the style of *American Antiquity*.)

P19088, ACI, Sarasota

Supervisors of Fieldwork (even if same as author) Names Marion Almy

Affiliation of Fieldworkers: Organization Archaeological Consultants Inc City Sarasota

Key Words/Phrases (Don't use county name, or common words like *archaeology, structure, survey, architecture, etc.*)

1. SR 865 3. _____ 5. _____ 7. _____
2. San Carlos Boulevard 4. _____ 6. _____ 8. _____

Survey Sponsors (corporation, government unit, organization, or person funding fieldwork)

Name _____ Organization Florida Dept of Transportation - District 1

Address/Phone/E-mail 801 N Broadway Avenue, Bartow Florida 33830-3809

Recorder of Log Sheet Kim Irby Date Log Sheet Completed 9-2-2020

Is this survey or project a continuation of a previous project? No Yes: Previous survey #s (FMSF only)

Project Area Mapping

Counties (select every county in which field survey was done; attach additional sheet if necessary)

1. Lee 3. _____ 5. _____
2. _____ 4. _____ 6. _____

USGS 1:24,000 Map Names/Year of Latest Revision (attach additional sheet if necessary)

1. Name FORT MYERS BEACH Year 1972 4. Name _____ Year _____
2. Name _____ Year _____ 5. Name _____ Year _____
3. Name _____ Year _____ 6. Name _____ Year _____

Field Dates and Project Area Description

Fieldwork Dates: Start 8-31-2020 End 8-31-2020 Total Area Surveyed (fill in one) _____ hectares 0.80 acres

Number of Distinct Tracts or Areas Surveyed 1

If Corridor (fill in one for each) Width: _____ meters _____ feet Length: _____ kilometers _____ miles

Research and Field Methods

Types of Survey (select all that apply): [X]archaeological [X]architectural [X]historical/archival []underwater []damage assessment []monitoring report []other(describe): _____

Scope/Intensity/Procedures

Background research; shovel testing: 19 judgmentally; 50 cm diameter, 1 m deep, 1/4" screen; report preparation

Preliminary Methods (select as many as apply to the project as a whole)

[]Florida Archives (Gray Building) []library research- local public [X]local property or tax records [X]other historic maps []LIDAR []Florida Photo Archives (Gray Building) []library-special collection []newspaper files [X]soils maps or data []other remote sensing [X]Site File property search []Public Lands Survey (maps at DEP) [X]literature search [X]windshield survey [X]Site File survey search []local informant(s) []Sanborn Insurance maps [X]aerial photography []other (describe): _____

Archaeological Methods (select as many as apply to the project as a whole)

[]Check here if NO archaeological methods were used. []surface collection, controlled []shovel test-other screen size []block excavation (at least 2x2 m) []metal detector []surface collection, uncontrolled []water screen []soil resistivity []other remote sensing [X]shovel test-1/4" screen []posthole tests []magnetometer [X]pedestrian survey []shovel test-1/8" screen []auger tests []side scan sonar []unknown []shovel test 1/16" screen []coring []ground penetrating radar (GPR) []shovel test-unscreened []test excavation (at least 1x2 m) []LIDAR []other (describe): _____

Historical/Architectural Methods (select as many as apply to the project as a whole)

[]Check here if NO historical/architectural methods were used. []building permits []demolition permits []neighbor interview [X]subdivision maps []commercial permits [X]windshield survey []occupant interview []tax records []interior documentation [X]local property records []occupation permits []unknown []other (describe): _____

Survey Results

Resource Significance Evaluated? [X]Yes []No

Count of Previously Recorded Resources 0 Count of Newly Recorded Resources 3


List Previously Recorded Site ID#s with Site File Forms Completed (attach additional pages if necessary)

List Newly Recorded Site ID#s (attach additional pages if necessary) LL02835-LL02837

Site Forms Used: []Site File Paper Forms [X]Site File PDF Forms

REQUIRED: Attach Map of Survey or Project Area Boundary

SHPO USE ONLY SHPO USE ONLY SHPO USE ONLY Origin of Report: []872 []Public Lands []UW []1A32 # _____ []Academic []Contract []Avocational []Grant Project # _____ []Compliance Review: CRAT # _____ Type of Document: []Archaeological Survey []Historical/Architectural Survey []Marine Survey []Cell Tower CRAS []Monitoring Report []Overview []Excavation Report []Multi-Site Excavation Report []Structure Detailed Report []Library, Hist. or Archival Doc []Desktop Analysis []MPS []MRA []TG []Other: _____ Document Destination: Plottable Projects Plotability: _____



CRAS Addendum
 Township 46 South, Range 23 East, Sections 24 & 19
 USGS Fort Myers Beach, 2018

SR 865 (San Carlos Boulevard)
 from North of Crescent Street to North of Hurricane Bay Bridge, Lee County, Florida
 FPID No: 433726-1-22-01; FAP No.: D119 051 B